

22/03/2018

ASS. REC. BY:

REF:

CS/FC18005688/K16bn2

Special Instruction:

Surveyor:

ASSIGNMENT (Officer)

From (Person): CWS May Chua

of

FCL

Date/Time: 29/03/2018 354pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 8556E

Insured:

SHC 1090Y

at Workshop m/s

Premier

Tel:

6544 6681

of

23 Changi South Ave 2 #03-02

Policy No:

Claim No:

D18007450MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Guh

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHB 8556E - CS3/III 16018537 / Rvb52-1	DOA: 01/10/2016
	SHC 1090Y - CS3/ATN 16006063 / H126392	DOA: 01/04/2016
28/3/18	4:30pm revised to May Chua by email	





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18005688/K1qb	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 27-03-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 1090Y	Veh. Inspected	SHB 8556E
Policy No.		Coverage (\$)	0.00
Claim No.	D18002450MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	27/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	25/03/2018	Inspection Date	27/03/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002450MFSH

Date: 28 March 2018

Our Ref: CS/FCI18005688/K1qb

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8556E.**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 27/03/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,736.40</u>
Revised Estimate Amount	: S\$ <u>2,946.70</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

**Description of Damage:**

The vehicle sustained damages at the n/s front portion.



Yours faithfully

Kalvin Ang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	26-03-2018	<b>Our Ref No.</b> D18002450MFSH
<b>Accident Date</b>	25-03-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHC1090Y	<b>Third Party Vehicle.</b> SHB8556E
<b>Survey Location</b>	23 CHANGI SOUTH AVENUE 2 #03-02	
<b>Contact Person.</b>	GOH WEE DEK	
<b>Contact No.</b>	62148880/ 65446682	<b>Fax No.</b> 62141511
<b>Survey Type</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	PREMIER AUTOMOTIVE SERVICES PTE LTD	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	NA	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 28 March 2018 4:32 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18002450MFSH/1  
**Attachments:** CSFCI18005688K1qb.pdf

Dear May,

Enclosed herewith preliminary advice of SHB 8556E.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 27 March 2018 5:58 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18002450MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Tuesday, 27 March, 2018 5:54 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18002450MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

**Enquire Transaction History****Transaction History Details**

Log Date/Time:	22 Oct 2013 / 10:01:39	Receipt No.:	AACCK001-AX239-131022-000018
Asset Type:	Vehicle	Transaction Amount:	\$73,800.00
Asset ID:	SHB8556E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20131022100139982280		

Vehicle No.:	SHB8556E
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	22 Oct 2013
Original Registration Date:	22 Oct 2013
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5447417
Engine No.:	D4FDDH308113
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2013
Open Market Value:	\$19,836.00
Minimum PARF Benefit:	\$7,401.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	22 Oct 2013 10:01:39
COE No.:	2013102201000941Z
COE Expiry Date:	21 Oct 2021
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$61,324.00
Lifespan Expiry Date:	21 Oct 2021
Owner ID Type:	Company

No:AK0412



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 ( 3 LINES )    FAX : 6743 0013

Reg No: 200415052W

Date, 25/2/2018

寶 號

Messrs:

車 號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time :

01:23-02:00-02:45 AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by:



# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

26-Mar-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8556 E

1 pc	Front n/s wheel cover <i>brnd</i>	\$ 116.00
1 pc	Front n/s fender <i>brnd</i>	\$ 384.00
1 pc	Front n/s fender inner shield <i>brnd</i>	\$ 120.00
1 pc	n/s head lamp <i>brnd</i>	\$ 1,028.00
1 pc	Front bumper <i>brnd</i>	\$ 531.00
1 pc	Front bumper n/s side retainer @ \$16.00 <i>see</i>	\$ 16.00
1 pc	Front bumper n/s protector @ \$51.00 <i>see</i>	\$ 51.00
1 pc	Front bumper emblem <i>see</i>	\$ 44.00
1 pc	Front bumper n/s fog lamp cover @ \$66.00 <i>see</i>	\$ 66.00
		<hr/>
		\$ 2,356.00
	Less 10%	\$ 235.60
		<hr/>
		\$ 2,120.40

### S/NETT

1 set	Front bumper clips <i>see</i>	\$ 48.00
1 pc	Front n/s fender sticker <i>see</i>	\$ 30.00
1 set	Front n/s fender inner shield clips <i>see</i>	\$ 28.00
	Towing Fee	\$ 50.00 <i>see</i>
	Sundry <i>see</i>	\$ 50.00 <i>20</i>
	To check wiring on headlamp	\$ 60.00 <i>20</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 <i>see</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust same, etc.	\$ 650.00 <i>400</i>
	To putty and spray painting on front bumper, front n/s fender	\$ 400.00 <i>360</i>
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 <i>20</i>
		<hr/>
		\$ 3,736.40

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before start of repair
- To display 24 hours
- Parts price
- Third party
- No claim
- Super
- is sub

Account

Signature

Date

Kalvin (CKK)  
27/3/18 1525h  
3000  
43  
After Repair path




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18005688/K1qbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 05-04-2018	
			Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 1090Y	Veh. Inspected	SHB 8556E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002450MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	27/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KNAGM414ME5447417	Colour	SILVER	
Odometer	565552	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	HANKOOK	7 mm	
L/H Front Tyre	205/65 R16	HANKOOK	7 mm	
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/03/2018	Inspection Date	27/03/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
<b>5a. Remarks</b>				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8556E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT N/S WHEEL COVER	GRAZED	116.00	116.00
1	FRONT N/S FENDER	DENTED	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	TORN	120.00	120.00
1	N/S HEAD LAMP	GRAZED	1,028.00	1,028.00
1	FRONT BUMPER	DEFORMED	531.00	531.00
1	FRONT BUMPER N/S SIDE RETAINER	SERVICEABLE	16.00	-
1	FRONT BUMPER N/S PROTECTOR	SERVICEABLE	51.00	-
1	FRONT BUMPER EMBLEM	NECESSARY	44.00	44.00
1	FRONT BUMPER N/S FOG LAMP COVER	SERVICEABLE	66.00	-
	LESS 10% DISCOUNT		-235.60	-222.30
			2,120.40	2,000.70
<b>SPECIAL NETT ITEMS</b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NECESSARY	28.00	28.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	96.00
<b>LABOUR</b>				
	TOWING FEE.		50.00	50.00
	TO CHECK WIRING ON HEADLAMP.		60.00	20.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST SAME, ETC.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER.		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	20.00
			1,460.00	850.00

Report Ref No. CS/FCI18005688/K1qbn2



GRAND TOTAL		3,736.40	2,946.70
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,350.00

Report Ref No. CS/FCI18005688/K1qbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.