

NAI SOO TONG

File No :

Date : 26-March-2018

SINGAPORE

Estimated cost of repair for vehicle no: **SGS91D TOYOTA LEXUS**

Accident involving vehicle no: **SGS91D & SFJ6556A on 16-February-2018**

Description	Quantity	List Price
LH front fender	1	\$ <i>B₁</i> 821.70 ✓
Front bumper	1	\$ <i>B₂</i> 721.50 ✓
LH head lamp	1	\$ 2,783.65 ?
LH front bumper retainer	1	\$ <i>D₁</i> 72.50 ✓
LH front fender wheel cowling	1	\$ <i>D₂</i> 324.50 ✓
LH front fender wheel cowling clips @ 1 set	1	\$ <i>M</i> 45.00 ✓
		\$ 4,768.85
	Less 25%	\$ 1,192.21
		\$ 3,576.66
Labour to remove front bumper , LH front fender, panel beating, repair LH front door, LH head lamp inner panel, LH bumper brecket, renew , install and adjust LH front door, front bumper alignment.	1	\$ 480.00 <i>400</i>
To spray paint LH front door, front fender, front bumper and accident repair areas.	1	\$ 750.00 <i>500</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp.	1	\$ 30.00 <i>20</i>
		\$ <u>4,836.66</u>

T/Party: AXA INSURANCE PTE LTD

*Not Authorized
Resurvey B & part
4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: