



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2014 FORD FOCUS 1.6 (SKT5367Z)
Date of Loss	23 March 2018
Time of Loss	12.25
Loss Description	SKT5367Z (INSD) HIT THE REAR OF SJS7202U (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="55155"/>
Nett Loss Amount	\$18,845.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Days of work completion *	<input type="text" value="163"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SKT5367Z

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

15/06/2015



Mileage

27403

Age of Vehicle

2

CATEGORY

POLICY INFORMATION

ASSESSMENT
INFORMATIONManufacturing
Year

2014

2014

Make

FORD

FORD

Model

FOCUS 1.6

FOCUS 4DR TREI

Driver Details

CATEGORY

FNOL INFORMATION

POST SURVEY
INFORMATION

Driver Name

TAN YONG XIANG AMBROSE

Date of Birth

2 November 1986

dd/mm/



Age

32

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No	WF04XXGCC4EA34362	<input type="text" value="WF04XXGCC4EA"/>
Engine No	EA34362	<input type="text" value="EA34362"/>
Engine Capacity		<input type="text" value="1596"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="74000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	13	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="dd/mm/"/>
License Expiration Date		<input type="text" value="dd/mm/"/>
Address	BLK 893B, WOODLANDS DRIVE 50, #04-111, 731893, Singapore	<input type="text" value=""/>
Address type	Residential	<input type="text" value=""/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Male	<input type="text"/>
Marital status	Single	<input type="text"/>
Identification #	S8630988B	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

29/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

205/55R16

Rear Tyre Size

205/55R16

Front left side

MICHELIN6mm

Rear left side

MICHELIN6mm

Front right side

MICHELIN6mm

Rear right side

MICHELIN6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			FRONT BUMPER			Deformed	0				0	Reviewing	
		2	1			FRONT BUMPER 'FORD' EMBLEM			Serviceable	0	0	0	0	0	Deny	
		3	1			FRONT GRILLE & FRONT GRILLE CHROME			Serviceable	0	0	0	0	0	Deny	
		4	1			FRONT BUMPER REINFORCEMENT			Dented	0				0	Reviewing	
		5	1			HEADLAMP LHS			Serviceable	0	0	0	0	0	Deny	
		6	1			HEADLAMP LOWER BRACKET			Serviceable	0	0	0	0	0	Deny	
		7	1			SUPPORT PANEL			Repair	0	0	0	0	0	Deny	
		8	1			FRONT BUMPER RETAINER LHS			Serviceable	0	0	0	0	0	Deny	
		9	1			BONNET			Repair	0	0	0	0	0	Deny	
		10	1			AIRCON CONDENSER			Serviceable	0	0	0	0	0	Deny	
		11	1			RADIATOR			Serviceable	0	0	0	0	0	Deny	

Labour













Add

Approve

Deny

Submit All

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		Labour charges to remove & install front end attachments and fittings to enable repairs; to straighten & repairs front panel, reinforcement, to adjust & re-align bonnet, to replace damaged parts as listed	500	0	0	Reviewing		

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		2		To spray painting on: bonnet (inner & outer), front bumper	400	0	0	Reviewing		
		3		To remove & replace LHS headlamp; to check electrical wirings and light function, including focus headlamp	30	0	0	Reviewing		
		4		To remove & install A/C condenser & fittings to enable repairs and charge up gas	0	0	0	Deny		
		5		To remove & install radiator, electric fan C/W cowl and hoses to enable repairs; to pressurize cooling system	0	0	0	Deny		

Assessment Details
















General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE	
		1	PARTS SUPPLIED BY AXAS SUPPLIER \$1,020.00	Reviewing			
		2	FRONT BUMPER CLIPS-10PCS	Reviewing	30	NECESSARY	
		3	FRONT BUMPER NUMBER PLATE WITH HOLDER	Reviewing	45	CUT	
		4	FOG LAMP LH (ADDITIONAL)	Reviewing		CRACKED	
		5	AIR DUCT LH (ADDITIONAL)	Reviewing		CRACKED	

Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Claim Amount	\$605.00			Claim Amount	\$605.00			

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$930.00	\$930.00
Miscellaneous	\$75.00	\$75.00
Excess	-\$400.00	-\$400.00

Submit for Review