

23/03/2003

ASS. REC. BY:

REF:

CS/CTI18005739/R19d3

n2

Special Instruction:

Surveyor
Menmen

Rasu

ASSIGNMENT (Office)

From (Person):

Adeline Chng

of

CTI

Date/Time:

28/3/18 @ 9:12am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 4523 B

Insured:

YM 7169 L

at Workshop m/s

AAK Logistics

Tel:

6677 6227

of

Blk 153 Blk Batok St. 11 #

Policy No:

DMCVSN3063291701

Claim No:

SNM18D01556C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/02/2018

CA / REV / REP. / REV 24 HRS / wp

H.O.D. Endorsement:

Date/Time:

12pm @ 28/3/18

Person Contacted:

peijuan

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	YP 4523 B - X
	Ramun Finalised at \$1000, 3 days (red 8940, 48%).

Surveys *Am*

REF: CT1

2442H

ASSIGNMENT

From: Date: 04-04-2018

Veh No: YP 4523B Yr Regn: 2016 / OCT

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

☒ Truck / Trailer or

To inspect Vehicle No: YP 4523B

Make: ISUZU FVR C.C. 7790

at Workshop m/s

Colour: WHITE A/C: Insured / Std / NI / NA

of Ak Logistics
4 Penjung Close

Sp. Reading: 41839 T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No: 3ALFVR34767000896

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: ☒ Nil / S/Rim / STD A/Rim or

(Policy Condition)

3pm - 3:30pm

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 275/70R22.5
R: 0/0

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt: Consistent? : Yes or No

R/Bal. 8 mm R/Bal. 8/8 mm

GIA / PR Seen: Consistent? : Yes or No

L/Bal. 8 mm L/Bal. 8/8 mm

Est. Repairs: days Res.: Yes or No

D.O.A. 12/02/18 D.O.I. 04/04/18

Lump Sum: % 3 Val.: Yes or No

Survey held at AMK

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Vehicle: IN / OUT

FR d/s

Date: Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 18 JUL 2018

Am
17/7/2018

Date/Time, File Pass to? ☐ : Preli. Report

Days Of Repair: 3

11/8/18 *Am* ☐ : Final Report

Resurvey No. of Trip:

Survey Fee

Date/Time, File Return to?

Transportation

2)

Add Fee: ☐ : Site Insp (\$)

) S + RS \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 6000

TOTAL

320

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Mar 2018		28 Mar 2018 09:12 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	JAPAN HOME (RETAIL) PTE LTD, Co. Reg. No.: 201127632E		
Main Claimant:	LEGEND MOTORS & LEASING PTE. LTD., Co. Reg. No.: 200909442H		
Vehicle Reg. No.:	YP4523B	Date of Loss:	19/02/2018 12:00 - :59
Claim Type:	TP / SNM18D01556C02	Policy/Cover Note No.:	DMCVSN3063291701 (Comprehensive)
Vehicle Reg. No. (Insured):	YM7169L	Policy No. (Claimant):	T1847906
		Excess:	S\$0.00
Repairer:	Aak Logistics Services Pte Ltd (HQ) BLK 153 BUKIT BATOK ST 11, #03-292, 650153 Bukit Batok - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/04/2018]		
Driver/Custodian (Insured):	CHANDRAKASON ANANDAN (39 / Male), NRIC: G7660902R, Tel: +6592411450		
Adj Asg. Remarks:	EST \$1819, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18006047/Kqd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 03-04-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 2496X	Veh. Inspected	SLH 1223H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	DARSHENE SUPRAMANIAM	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/03/2018	Inspection Date
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aakls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

China Taiping Insurance (Singapore) Pte. Ltd. - Claims Department

3 Anson Road #15-00

Springleaf Tower

Attn: Sharon

Quotation

DATE: 04-Apr-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	UOM	QTY	UNIT PRICE	AMOUNT (\$)
	Accident Repair of YP4523B				
1	Front Right Side Panel		1	\$480.00	502 ✓ \$480.00
2	Spray Paint : Front Bumper Assy, RH Side Panel & Front Panel		1	\$500.00	450 ✓ \$500.00
3	Panel Beat : To renew side panel, to remove and install front bumper & To panel beat side panel bracket		1	\$600.00	300 ✓ \$600.00
4	Replacement 24ft truck with tailgate x 2 days		2	\$180.00	✓ \$360.00
Rasul Hp 90010068 HS 3 days 04/04/18 @ 1535 Resurvey after repair LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
E. & O. E.				SUB-TOTAL	\$1,940.00
SGD: TWO THOUSAND SEVENTY-FIVE AND CENTS EIGHTY ONLY.				7% GST	\$135.80
				TOTAL	\$2,075.80

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

AAK LOGISTICS SERVICES PTE LTD

Company Chop & Signature

Authorised Signature



AAK LOGISTICS SERVICES PTE LTD

Blk 153 Bukit Batok Street 11 #03-292 Singapore 650153

Tel: (65) 6665 0190 Fax: (65) 6561 9509

E-mail: admin@aacls.com

Company Registration No.: 201325787M

GST Reg. No.: 201325787M

TO:

China Taiping Insurance (Singapore) Pte. Ltd. - Claims Department

3 Anson Road #15-00

Springleaf Tower

Attn: Sharon

Quotation

DATE: 04-Apr-18

TERMS: 30 Days

PAGE NO.: Page 1 of 1

S/N	DESCRIPTION	UOM	QTY	UNIT PRICE	AMOUNT (\$)
	Accident Repair of YP4523B				
1	Front Right Side Panel		1	\$480.00	480
2	Spray Paint : Front Bumper Assy, RH Side Panel & Front Panel		1	\$500.00	500
3	Panel Beat : To renew side panel, to remove and install front bumper & To panel beat side panel bracket		1	\$600.00	600
4	Replacement 24ft truck with tailgate x 2 days		2	\$180.00	360
					1580
E. & O. E.				SUB-TOTAL	\$1,940.00
SGD: TWO THOUSAND SEVENTY-FIVE AND CENTS EIGHTY ONLY.				7% GST	\$135.80
				TOTAL	\$2,075.80

Note:

Cheque should be crossed and make payable to "AAK Logistics Services Pte. Ltd."

Accepted and Confirmed by

Company Chop & Signature

AAK LOGISTICS SERVICES PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

432

850

1282

2020

1025.60

4/5 - 1000

3 days

480

109

432

400

500

600

360

1580

432

850

1282

2020

1025.60

4/5 - 1000

3 days

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118005739/R1QD3N2

Date: 18/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3063291701
Claimant Vehicle No :	YP4523B	Insured Vehicle No :	YM7169L
Date of Loss:	19/02/2018	Nature of Claim:	TP
		Claim No:	SNM18D01556C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4523B	Engine No:	6HK1685628
Make & Model:	ISUZU FVR34SUQDC, 7.8 D (M)	Chassis No:	JALFVR347G7000896
Reg. Date:	01/10/2016 (Man. Year: 2016)	Odometer:	41139 km
Colour:	White		
Engine Capacity:	7790 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8/8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	480.00	408.00	72.00	15.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	850.00	250.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	1,580.00	1,258.00	322.00	20.38
Approved Total (Overridden) (\$\$)		1,000.00		
(\$\$)	1,580.00	1,000.00	580.00	36.71
+ GST 7.00/7.00% (\$\$)	110.60	70.00	40.60	36.71
Nett Amount (\$\$)	1,690.60	1,070.00	620.60	36.71

INSPECTION

Date of Assignment:	28/03/2018	
Date Inspected:	04/04/2018	Inspected At: AAK Logistics Services Pte Ltd (HQ) Blk 153 Bukit Batok St 11, #03-292 Singapore 650153

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 18 Jul 2018)	
Parts:	N/A	ISUZU FVR34SUQDC 7.8 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP4523B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RIGHT SIDE PANEL	Scratched	480.00 F	*480.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (S\$)	480.00
					- List Item Discount on L Items 0.00/15.00% (S\$)	0.00
					Total Parts (S\$)	480.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	SPRAY PAINT;FRONT BUMPER ASSY,RH SIDE PANEL & FRONT PANEL	New	500.00	450.00
2	PANEL BEAT:TO RENEW SIDE PANEL,TO REMOVE AND INSTALL FRONT BUMPER & TO PANEL BEAT SIDE PANEL BRACKET	New	600.00	400.00
Gross Labour Cost (\$\$)			1,100.00	850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >