

ASS. REC. BY:

REF: CS/ICS18005744/Avd3<sup>12</sup> Special Instruction

Surveyor  
meimen

Adrian

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ECICS

Date/Time:

27/3/2018 @ 7:37pm

Estimated Cost:

Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF81094

Insured:

at Workshop m/s

Success United

Tel:

6746 1515

of

2kaki Bkt Ave 2 #01-33/02-29

Policy No:

Claim No:

MPU16A00104900

Sum Insured:

Excess:

\$1,500.00

Make of Veh:

D.O.A.

23/03/2018

(Client's Record)

CA /  REV

REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

8:53am @ 2/3/18

Person Contacted:

Sirina

Vehicle

IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SLF81094 - CS3/ICS18005612/d3 D.O.A: 23/3/18
	Sent preli thru meimen
6/4/18	@ 11am Spoken to Janice insured will ext COE
21/6/18	@ 3:58pm Janice asking for discount on survey fee.
25/6/18	@ 2:49pm Informed Janice survey fees 10% discount
2/7/18	@ 9:38am Janice said can submit preli report 10% pay within 2 wks

27/6  
pay within 2 wks





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ECICS LTD

Ref : CS/ICS18005744/Avd3

7 TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
SINGAPORE 038987 &nbsp; &nbsp;

Date : 28-03-2018



Code : ICS

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SLF 8109U
Policy No.		Coverage (\$)	0.00
Claim No.	MPU16A00104900A	Excess (\$)	1,500.00
Assign From	JANICE GOH	Assign Date	28/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	23/03/2018	Inspection Date	28/03/2018
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

## 5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 29 Mar 2018

**Preliminary Advice**

Vehicle No	: SLF8109U	Accident Date	: 23/03/2018
Make	: TOYOTA COROLLA ALTIS	Policy No.	: MPU16A00104900
Assignment Date	: 28/03/2018	Excess	: S\$0.00
Date of Inspection	: 28/03/2018	Est. Duration of Repair	: 7.00
Inspection At	: SUCCESS UNITED PTE LTD (HQ) 2 KAKI BUKIT AVE 2 #01-33, KAKI BUKIT AUTOHUB SINGAPORE 417921		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,512.05
Revised Amount	:S\$	4,809.65
Check Items (Estimated)	:S\$	3,176.00
Total	:S\$	7,985.65
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,500.00
COE / PARF Rebate	:S\$	8,670.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,830.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : The repairer propose to repair the vehicle at LumpSum \$6,000.00. Please note that the margin repair amount is \$3,830.00.

## Nivitha (LKK Auto)

---

**From:** Janice Goh Siew Geok (ECICS, Claims) <Janice\_Goh@ecics.com.sg>  
**Sent:** Tuesday, 27 March 2018 7:37 PM  
**To:** sirina@successunited.com.sg; assignments@lkkauto.com  
**Cc:** ECICS Claims  
**Subject:** RE: OD / SLF 8109U / MPU16A00104900 / DoA 23.03.18  
**Attachments:** Driver IC, DL. PARF, COE.PDF; GIA.PDF

Dear Sirina

Thank you for your email.  
We will appoint LKK for OD survey.

Aside to LKK

Please assist to arrange OD survey and policy excess is S\$1,500.00.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

### **ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.**

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

**From:** sirina@successunited.com.sg [mailto:sirinassk@gmail.com]  
**Sent:** Tuesday, 27 March, 2018 3:28 PM  
**To:** Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims)  
**Subject:** OD / SLF 8109U / MPU16A00104900 / DoA 23.03.18

Hi

Kindly arrange for OD survey. Vehicle now lying in our workshop.

Owner in the midst of renewing COE.

Attached the necessary documents for your action.

Thank You.

**Best Regards,**

Sirina Soon

Senior Claims Executive  
Mobile: +65 9223 6288

**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2

#01-33 / #02-29

Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015

follow us on  follow us on  visit our website [ecics.com.sg](http://ecics.com.sg) 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 1625K

### Vehicle Details

Vehicle No.: SLF8109U  
Vehicle to be Exported: No  
Intended De-registration Date: 27 Mar 2018  
Vehicle Make: TOYOTA  
Vehicle Model: COROLLA ALTIS 1.6 AUTO  
Primary Colour: Blue  
Manufacturing Year: 2008  
Engine No.: 3ZZ4744270  
Chassis No.: MR053ZEE106102571  
Maximum Power Output: 80.0 kW (107 bhp)  
Open Market Value: \$16,994.00  
Original Registration Date: 05 May 2008  
First Registration Date: 05 May 2008  
Transfer Count: 2  
Actual ARF Paid: \$16,994.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 04 May 2018  
PARF Rebate Amount: \$8,497.00

### Intended COE Rebate Details

COE Expiry Date: 04 May 2018  
COE Category: A - Car (1600cc & below)  
COE Period(Years): 10  
QP Paid: \$16,930.00  
COE Rebate Amount: \$173.00  
**Total Rebate Amount: \$8,670.00**

The information contained herein is correct as at 26 Mar 2018

OK

- Volkswagen Sharan..
- COE Bidding – 2nd Round of March 2018
- Unusual or rare cars

Altis Price Range Depreciation 2008 Vehicle Type

Advanced Search

Used Car Comparison

--- Comparing 3 Vehicles ---

Toyota Corolla Altis 1.6A



Add to Shortlist

Toyota Corolla Altis 1.6A



Add to Shortlist

Toyota Corolla Altis 1.6A



Add to Shortlist



Use search bar above to search to compare.

Clear All

Add all to Shortlist

Back to search result

CAR DETAILS

<b>Price</b>	<b>\$12,800</b>	\$14,200	\$14,588	-
<b>Instalment</b>	N.A.	\$4,995	\$3,429	-
<b>Registration Date</b>	24-Apr-2008	25-Jun-2008	17-Jul-2008	-
<b>Manufactured</b>	2008	2008	2008	-
<b>Mileage</b>	148,260 km	-	-	-
<b>Transmission</b>	Auto	Auto	Auto	-
<b>Engine Cap</b>	1,598 cc	1,598 cc	1,598 cc	-
<b>Road Tax</b>	\$742 /yr	\$742 /yr	\$742 /yr	-
<b>Power</b>	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	-
<b>Curb Weight</b>	1,195 kg	1,195 kg	1,195 kg	-
<b>Features</b>	Fuel Efficient And Powerful 1.6L 16 Valve DOHC VVTi Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	Fuel Efficient And Powerful 1.6L 16 Valve DOHC Vvti Engine, Smooth Auto Transmission With Ect, Dual SRS Airbags, ABS, Digital Climate Control Aircon.	-	-
<b>Accessories</b>	Original Leather Seats, Multi Steering Control And Retractable Mirrors With Indicators.	Leather Seats, Multi Steering Control And Retractable Mirrors With Indicator.	-	-
<b>Description</b>		5 Year COE Renewal At \$36.8K, Careful Owner, Immaculate Condition, Low Depreciation, Low Mileage, Value For Money, High Trade In, View To Believe, Price Negotiable. Call Now.	Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.	-
<b>COE</b>	\$16,930	\$14,101	\$14,101	-
<b>OMV</b>	<b>\$16,994</b>	\$16,777	\$16,777	-
<b>ARF</b>	<b>\$16,994</b>	\$16,777	\$16,777	-
<b>Depreciation</b>	-	-	-	-
<b>No. of Owners</b>	2	3	1	-
<b>Type of Vehicle</b>	Sedan	Sedan	Sedan	-
<b>Category</b>	PARF Car, Direct Owner Sale	PARF Car	PARF Car	-
<b>Availability</b>	<b>Available</b>	<b>Available</b>	<b>Available</b>	-
<b>SELLER INFORMATION</b>				
<b>Seller</b>	Direct Owner	TWJ Autocarz	Boeki Auto & Marine	-
<b>Address</b>	-	50 East Coast Road #01-37	176 Sin Ming Drive #02-15	-



聯成汽車維修  
**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921  
 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015  
 www.successunited.com.sg Co. / GST Reg: 200402570G

Estimate : **OD/18-039**

M/s: **ECICS Limited**  
 7 Temasek Boulevard  
 #10-01 Suntec Tower One  
 Singapore 038987

Date : 27th March 2018

Vehicle No : **SLF 8109U**  
 Make/ Model : Toyota Altis  
 Chassis No : MR053ZEE106102571  
 Acc. Date : 23.03.18  
 Policy No : MPU16A0014900

Attn : Motor Claims

Tel: 63030167  
 Fax: 63389267

Email: [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg)

Your Ref :

S/n.	Qty	Particulars	Unit Price	Amount
<u>Materials</u>				
1	1	Bonnet <i>Distorted</i>		\$ 220.00 ✓
2	2	Bonnet Hinge L/R <i>Best</i>	\$ 30.00	\$ 60.00 ✓
3	1	Bonnet Weatherstrip		\$ 30.00 +
4	1	Bonnet Mechanism Lock <i>? Item</i>		\$ 55.00 ✓
5	1	Bonnet Stand <i>new</i>		\$ 18.00 ✓
6	2	Headlamp L/R <i>RH smashed.</i>	\$ 160.00	\$ 320.00 <i>160</i>
7	1	Headlamp Retainer RH <i>Paint</i>		\$ 30.00 ✓
8	1	Frt Bumper <i>Distorted</i>		\$ 180.00 ✓
9	10	Frt Bumper Clips <i>new</i>	\$ 1.50	\$ 15.00 ✓
10	1	Frt Bumper Side Holder RH <i>Paint</i>		\$ 30.00 ✓
11	1	Frt Bumper Reinforcement <i>Best</i>		\$ 135.00 ✓
12	1	Frt Bumper Top Rubber Moulding <i>new</i>		\$ 28.00 ✓
13	1	Frt Grille <i>at</i>		\$ 120.00 ✓
14	1	Frt Fender <i>LH → RH Bunched</i>		\$ 140.00 ✓
15	1	Frt Fender Inner Panel RH <i>Paint</i>		\$ 200.00 +
16	1	Frt Fender Inner Liner RH <i>torn</i>		\$ 65.00 ✓
17	5	Frt Fender Inner Liner Clips <i>new</i>	\$ 1.50	\$ 7.50 ✓
18	1	Frt Fender VVTi Emblem <i>new</i>		\$ 22.00 ✓
19	1	Windscreen Washer Tank <i>Rehd</i>		\$ 60.00 ✓
20	1	Windscreen Washer Motor <i>new</i>		\$ 68.00 +
21	1	Radiator Spare Tank <i>Rehd</i>		\$ 85.00 ✓
22	1	Radiator Support Panel <i>Distorted</i>		\$ 310.00 ✓
23	1	Center Brace Panel <i>?</i>		\$ 50.00 ?
24	1	Radiator <i>?</i>		\$ 280.00 ?
25	1	Radiator Auxillary Fan Assy <i>?</i>		\$ 310.00 ?
26	1	Radiator Top Hose <i>? new</i>		\$ 30.00 +
27	1	Radiator Lower Hose <i>?</i>		\$ 30.00 +
28	1	Air Con Condenser <i>?</i>		\$ 220.00 ?
29	1	Air Con Liquid Pipe <i>? new</i>		\$ 200.00 +
30	1	Air Con Discharge Hose <i>? new</i>		\$ 190.00 +
31	1	Air Con Alumimium Pipe <i>?</i>		\$ 175.00 +
32	1	ABS Pump <i>?</i>		\$ 180.00 ?
				<b>1800</b>



聯成汽車維修  
**SUCCESS UNITED PTE LTD**

2 Kaki Bukit Ave 2, #01-33 / #02-29 Kaki Bukit AutoHub Singapore 417921  
 Tel: 6746 1515 / 6747 1787 Fax: 6748 5015  
 www.successunited.com.sg Co. / GST Reg: 200402570G

33	1	Frnt Windscreen <i>cracked</i>	\$	480.00 ✓
34	1	Frnt Windscreen Moulding <i>new</i>	\$	80.00 ✓
35	1	Frnt Wiper Panel Garnish <i>cut</i>	\$	190.00 ✓
36	1	Frnt Wiper Rubber Trim Moulding <i>2nd</i>	\$	30.00 ✓
37	1	Frnt Wiper Arm <i>new</i>	\$	60.00 +
38	1	Frnt Wiper Arm Cover <i>cut</i>	\$	12.00 ✓
			\$	4,715.50
			Plus 10%	\$ 471.55
			\$	5,187.05
39	1	Windscreen Sealant <i>3 new</i>	S/Nett	\$ 40.00 ✓
40	1	ERP Bracket	S/Nett	\$ 25.00 ✓
			Parts Total	\$ 5,252.05

Labour

1	To remove, rearrange electrical wirings, check lightings	\$	60.00 - 30	
2	To remove, replace frnt windscreen.	\$	150.00 - 120	
3	To remove, replace air con parts, vacuum & refill a/con gas.	\$	200.00 - 120	
4	To remove, replace ABS pump, bleeding brake system.	\$	250.00 ?	
2	To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident.	\$	1,200.00 - 800	
3	To putty and respray painting on bonnet, frnt bumper, frnt fender L/R, support panel, wheel house RH, frnt door RH.	\$	1,400.00 - 1000	
			Labour Total :	\$ 3,260.00

**Total Parts & Labour \$ 8,512.05**

10294.05

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Success United Pte Ltd damaged part(s) during resurvey

No of Days

Re-Survey Before/After Paint repair

Part By Part/Lump Sum

Date:

Surveyed By \_\_\_\_\_ Contact No. \_\_\_\_\_

Date of Survey \_\_\_\_\_ Fax No. \_\_\_\_\_

Adrian Lij  
 1/s 28/03/18  
 Not Authorised  
 Excess \$1500.  
 07 days.

NOTE: LUMP SUM WILL BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited  
7 Temasek Boulevard, #10-01 Suntec Tower One  
Singapore 038987

**Our File No:** CS/ICS18005744/AVD3N2

**Date:** 05/07/2018

#### REFERENCE

<b>Insured/Claimant:</b>	YUNOS TRANSPORTATION	<b>Policy No:</b>	MPU16A00104900
<b>Date of Loss:</b>	23/03/2018	<b>Nature of Claim:</b>	OD
			<b>Claim No:</b> N/A

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SLF8109U	<b>Engine No:</b>	3ZZ4744270
<b>Make &amp; Model:</b>	TOYOTA COROLLA ALTIS, 1.6 (A)	<b>Chassis No:</b>	MR053ZEE106102571
<b>Reg. Date:</b>	05/05/2008 (Man. Year: 2008)	<b>Odometer:</b>	179359 km
<b>Colour:</b>	Blue		
<b>Engine Capacity:</b>	1598 cc		
<b>Market Value/New Car Price:</b>	S\$12,500.00		
<b>Sum Insured (S\$):</b>	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>	<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

#### CONDITION OF TYRES

<b>Front Tyre Size:</b>	195/65 R15	<b>Rear Tyre Size:</b>	195/65 R15
<b>Front Left Side:</b>	Dunlop 6 mm	<b>Rear Left Side:</b>	Dunlop 6 mm
<b>Front Right Side:</b>	Dunlop 6 mm	<b>Rear Right Side:</b>	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,034.05	2,739.65	4,294.40	61.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,260.00	2,070.00	1,190.00	36.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,294.05</b>	<b>4,809.65</b>	<b>5,484.40</b>	<b>53.28</b>
<b>- Excess (S\$)</b>	<b>1,500.00</b>	<b>1,500.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,794.05</b>	<b>3,309.65</b>	<b>5,484.40</b>	<b>62.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>615.58</b>	<b>231.68</b>	<b>383.90</b>	<b>62.36</b>
<b>Nett Amount (S\$)</b>	<b>9,409.63</b>	<b>3,541.33</b>	<b>5,868.30</b>	<b>62.36</b>

#### INSPECTION

**Date of Assignment:** 27/03/2018

**Date Inspected:** 28/03/2018 **Inspected At:**

Success United Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit  
AutoHub  
Singapore 417921

**Estimated Period of Repair:** 7.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)  
(EXCLUDE CHECK ITEMS S\$3,176.00 NETT)

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2018)
<b>Parts:</b> 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLF8109U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET (WCP)	Distorted	220.00 F	*220.00 F
2	2		*BONNET HINGE L/R (WCP)	Bent	60.00 F	*60.00 F
3	1		*BONNET WEATHERSTRIP (WCP)	Not Necessary	30.00 F	*- F
4	1		*BONNET MECHANISM LOCK (WCP)	Not Necessary	55.00 F	*- F
5	1		*BONNET STAND (WCP)	Not Necessary	18.00 F	*- F
6	1		*HEADLAMP L/R (WCP)	O/s Smashed	320.00 F	*160.00 F
7	1		*HEADLAMP RETAINER RH (WCP)	Damaged	30.00 F	*30.00 F
8	1		*FRT BUMPER (WCP)	Distorted	180.00 F	*180.00 F
9	10		*FRT BUMPER CLIPS (WCP)	Necessary	15.00 F	*15.00 F
10	1		*FRT BUMPER SIDE HOLDER RH (WCP)	Damaged	30.00 F	*30.00 F
11	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	135.00 F	*135.00 F
12	1		*FRT BUMPER TOP RUBBER MOULDING (WCP)	Not Necessary	28.00 F	*- F
13	1		*FRT GRILLE (WCP)	Cut	120.00 F	*120.00 F
14	1		*FRT FENDER RH (WCP)	Buckled	140.00 F	*140.00 F
15	1		*FRT FENDER INNER PANEL RH (WCP)	Repair	200.00 F	*- F
16	1		*FRT FENDER INNER LINER RH (WCP)	Torn	65.00 F	*65.00 F
17	5		*FRT FENDER INNER LINER CLIPS (WCP)	Necessary	7.50 F	*7.50 F
18	1		*FRT FENDER VVTI EMBLEM (WCP)	Necessary	22.00 F	*22.00 F
19	1		*WINDSCREEN WASHER TANK (WCP)	Deformed	60.00 F	*60.00 F
20	1		*WINDSCREEN WASHER MOTOR (WCP)	Not Necessary	68.00 F	*- F
21	1		*RADIATOR SPARE TANK (WCP)	Deformed	85.00 F	*85.00 F
22	1		*RADIATOR SUPPORT PANEL (WCP)	Distorted	310.00 F	*310.00 F
23	1		*CENTER BRACE PANEL (WCP)	*Check	50.00 F	*- F
24	1		*RADIATOR (WCP)	*Check	280.00 F	*- F
25	1		*RADIATOR AUXILLARY FAN ASSY (WCP)	*Check	310.00 F	*- F
26	1		*RADIATOR TOP HOSE (WCP)	Not Necessary	30.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*RADIATOR LOWER HOSE (WCP)	Not Necessary	30.00 F	*- F
28	1		*AIR CON CONDENSER (WCP)	*Check	220.00 F	*- F
29	1		*AIR CON LIQUID PIPE (WCP)	Not Necessary	200.00 F	*- F
30	1		*AIR CON DISCHARGE HOSE (WCP)	Not Necessary	190.00 F	*- F
31	1		*AIR CON ALUMINIUM PIPE (WCP)	Not Necessary	175.00 F	*- F
32	1		*ABS PUMP (WCP)	*Check	1,800.00 F	*- F
33	1		*FRT WINDSCREEN (WCP)	Cracked	480.00 F	*480.00 F
34	1		*FRT WINDSCREEN MOULDING (WCP)	Necessary	80.00 F	*80.00 F
35	1		*FRT WIPER PANEL GARNISH (WCP)	Cut	190.00 F	*190.00 F
36	1		*FRT WIPER RUBBER TRIM MOULDING (WCP)	Deformed	30.00 F	*30.00 F
37	1		*FRT WIPER ARM (WCP)	Not Necessary	60.00 F	*- F
38	1		*FRT WIPER ARM COVER (WCP)	Cut	12.00 F	*12.00 F
39	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
40	1		*ERP BRACKET	Necessary	25.00 FS	*25.00 FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>6,400.50</b>	<b>2,496.50</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	<b>633.55</b>	<b>243.15</b>
<b>Total Parts (\$\$)</b>	<b>7,034.05</b>	<b>2,739.65</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTINGS	New	60.00	30.00
2	TO REMOVE,REPLACE FRT WINDSCREEN	New	150.00	120.00
3	TO REMOVE,REPLACE AIR CON PARTS,VACUUM & REFILL A/CON GAS	New	200.00	120.00
4	TO REMOVE,REPLACE ABS PUMP,BLEEDING BRAKE SYSTEM (*Check)	New	250.00	-
5	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
6	TO PUTTY AND RESPRAY PAINTING ON BONNET,FRT BUMPER,FRT FENDER L/R,SUPPORT PANEL,WHEEL HOUSE RH,FRT DOOR RH	New	1,400.00	1,000.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,260.00</b>	<b>2,070.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >