

SS. REC. BY:

REF:

CS/MS(118005745 / K1b2

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Maimen

From (Person):

Monica Chung

of

MSLH

Date/Time:

28032018 1:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 2351Y

Insured:

SLH 5458B

at Workshop m/s

Alan's United

Tel:

6453 8686

of

Blk 7 Sin Ming

Ind Est

#01-76

Policy No:

MSD/VPCP/17-002264-00

Claim No:

MSC/V/18-000451

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23032018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

28032018 2:01pm

Person Contacted:

Kenny

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SKW 2351Y - X

SLH 5458B - X

Part by Part \$4996.60 (Red: 33.95.95; 40%)

ASS. REC. BY:

REF: MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____ Alan's

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1-131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKW23514 Yr Regn: 10, 15Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota c.c. 1986Colour: Black A/C: Insured / Std / NI / NASp. Reading: 60172 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FSU60-0055403Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / ATRIA orTyre Size: F: PirR: 235/55R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 23/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/3 File pass to Catherine

RECEIVED 08 APR 2018

Date/Time, File Pass to?

1) 6/4 TYPST

Date/Time, File Return to?

2) _____

☐ : Prel. Report☒ : Final ReportDays Of Repair: 5Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation: 200
S + RS: 10

Photos

Others

TOTAL

210

Report Format: TP

Lump Sum / I.B.I. (\$) 4996.60



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18005745/Ktb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 28-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 5458B	Veh. Inspected	SKW 2351Y
Policy No.	MSD/VPCP/17-002264-00	Coverage (\$)	0.00
Claim No.	MSC/V/18-000451	Excess (\$)	0.00
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	28/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	23/03/2018	Inspection Date	28/03/2018
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Mar 2018		28 Mar 2018 13:17 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	HITACHI CAPITAL ASIA PACIFIC PTE LTD, Co. Reg. No.: 199400399N		
Main Claimant:	LOKMAN BIN MOHAMED HASSAN, ID: S1675027A		
Vehicle Reg. No.:	SKW2351Y	Date of Loss:	23/03/2018 22:00 - :59
Claim Type:	TP / MSC/V/18-000451	Policy/Cover Note No.:	MSD/VPCP/17-002264-00 (Comprehensive) Coverage: 04/10/2017 - 03/10/2018
Vehicle Reg. No. (Insured):	SLG5458B	Policy No. (Claimant):	
	Excess:		
Repairer:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76, 575642 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/03/2018]		
Driver/Custodian (Insured):	SEAN DING LI JIE (), NRIC: S95088751, Tel: +6596920380		

ASSOCIATED MAIL RECEIVED View All Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 03 Apr 2018

Preliminary Advice

Insured Vehicle No	: SLG5458B	Accident Date	: 23/03/2018
TP Vehicle No	: SKW2351Y	Assignment Date	: 28/03/2018
Make	: TOYOTA HARRIER	Est. Duration of Repair	: 5.00
Date of Inspection	: 29/03/2018		
Inspection At	: ALANS UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	8,392.55
Revised Amount	:SS	4,655.75
Check Items (Estimated)	:SS	2,482.08
Total	:SS	7,137.83

Lump Sum Repair :SS

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

0% 25% 50% 75% 100%

Register New Vehicle (Acknowledgement)

Vehicle Particulars

Vehicle No.:	SKW2351Y		
Vehicle Type:	P11 - Passenger Station Wagon/Jeep/Land Rover	Vehicle Scheme:	Normal
Vehicle Attachment 1:	With Sun Roof		
Vehicle Attachment 2:	-	Vehicle Attachment 3:	-
Vehicle Make:	TOYOTA	Vehicle Model:	HARRIER PREMIUM 2.0 A
Chassis No.:	ZSU600055403	Engine No.:	3ZRB626820
Motor No.:	-	Trailer Chassis No.:	-
Propellant:	Petrol	Passenger Capacity:	4
Engine Capacity:	1986 cc	Power Rating:	-
Maximum Power Output:	111.0 kW (148 bhp)		
Unladen Weight:	1610 kg	Maximum Laden Weight:	1885 kg
Primary Colour:	Black	Secondary Colour:	-
First Registration Date:	22 Oct 2015	Original Registration Date:	22 Oct 2015
Manufacturing Year:	2015	Open Market Value:	\$28,884.00
PARF Eligibility:	Yes	Minimum PARF Benefit:	\$13,719.00
No. of Transfers:	0	Additional Registration Fee Rate:	First \$20,000.00 (100%), next \$8,884.00 (140%)

Owner Particulars

Owner Name: LOKMAN BIN MOHAMED HASSAN

Owner ID Type: Singapore NRIC

Owner ID: S1675027A

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 886

Registered Street Name: UPPER BUKIT TIMAH ROAD

Registered Unit No.: # 06 - 13

Registered Building Name: -

Registered Postal Code: 678184

COE No. / Expiry Date: 2015090107000320Z / 21 Oct 2025

COE Bid Category: E - Open Category

QP Paid: \$57,885.00

Transaction Details

Business Transaction Ref. No.: 20151022153317488823

Business Transaction Date: 22 Oct 2015

Business Transaction Time: 15:33:17

Message

The above vehicle has been successfully registered.

Please note that \$75,942.00 will be deducted from your GIRO account.

The notification delivery date will be subject to validation of address with source agency.

OK

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLG 5458B
Accident Date : 23-Mar-2018

No. : 05755

Date : 27-Mar-2018

Our Ref : 218060 (MSIG) / CHAN

PAGE : 1

LOKMAN BIN MOHAMED HASSAN
886 UPPER BUKIT TIMAH ROAD
#06-13, THE LINEAR
Singapore 678184

*Not Authored
Returning B & paint
4-5 days*

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER PREMIUM 2.0A SKW2351Y

1 pc	Tail gate		R	1,369.00	✓
1 pc	Tail gate "HARRIER" emblem		sn	72.10	✓
1 pc	Tail gate logo		sn	52.20	✓
1 pc	Tail gate glass moulding		sn	81.70	✓
1 pc	Tail gate rubber		sn	390.90	x
1 pc	Tail gate inner lock		sn	963.10	✓
1 pc	Rear bumper fascia		Bu	1,381.50	✓
2 pcs	Rear bumper side retainer	@ S\$ 90.80	sn	181.60	x
1 pc	Rear bumper lower spoiler		Bu	366.20	✓
4 pcs	Rear lower spoiler clip	@ S\$ 3.80	sn	15.20	✓
2 pcs	Rear lower spoiler reflector	@ S\$ 54.10	sn	108.20	x x
1 pc	Rear bumper inner sponge		CM	187.80	✓
1 pc	Rear end panel		sn	715.00	x x
1 pc	End panel top garnish		sn	353.80	x
1 pc	Spare tyre panel		R	965.10	x x
				7,203.40	4488.80
Less 25% :				1,800.85	1122.20
					3366.60

- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear w/s glass sealant

sn 5,402.55 220sn
sn 300.00 sn
sn 60.00 sn

To remove & refix rear windscreen glass and conduct water leak test.

150.00 1200

To remove roof lining, front and rear seats, trim board and carpet

120.00 600

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLG 5458B

Page : 2

To apply undersealing

100.00 301

To remove and renew exhaust
silencer box

~ 60.00 X

To putty and spray replaced parts

1,200.00 660

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

500L ~~800~~

1,000.00 7

Total : S\$ 8,392.55
=====

Singapore Dollars Eight Thousand Three Hundred
and Ninety Two and Cents Fifty Five Only

P 3366.60

SN 260.00

L 1370.00

4996.60 ✓ ok

①

5 days

→
KENNETH PLS confirm
Tks.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05755

Vehicle Insured : SLG 5458B
Accident Date : 23-Mar-2018

Date : 27-Mar-2018

Our Ref : 218060 (MSIG) / CHAN

PAGE : 1

LOKMAN BIN MOHAMED HASSAN
886 UPPER BUKIT TIMAH ROAD
#06-13, THE LINEAR
Singapore 678184

Not Notified
Resurvey B & paint 4-5 days

3/4/18

ESTIMATED COST OF REPAIR FOR TOYOTA HARRIER PREMIUM 2.0A SKW2351Y

- 1 pc Tail gate
- 1 pc Tail gate "HARRIER" emblem
- 1 pc Tail gate logo
- 1 pc Tail gate glass moulding
- 1 pc Tail gate rubber
- 1 pc Tail gate inner lock
- 1 pc Rear bumper fascia
- 2 pcs Rear bumper side retainer
- 1 pc Rear bumper lower spoiler
- 4 pcs Rear lower spoiler clip
- 2 pcs Rear lower spoiler reflector
- 1 pc Rear bumper inner sponge
- 1 pc Rear end panel
- 1 pc End panel top garnish
- 1 pc Spare tyre panel

R	1,369.00	✓
Re	72.10	✓
Re	52.20	✓
Re	81.70	✓
Re	390.90	X
Re	963.10	✓
Re	1,381.50	✓
Re	181.60	X
Re	366.20	✓
Re	15.20	✓
@ S\$ 90.80	108.20	?
@ S\$ 3.80	187.80	?
@ S\$ 54.10	715.00	?
	353.80	X
	965.10	?
	7,203.40	
Less 25% :	1,800.85	

too high

- 1 pc Rear bumper reverse sensor(set
- 1 pc Rear w/s glass sealant

5,402.55 220sn
Re 300.00 sn
Re 40sn 60.00 sn

To remove & refix rear windscreen glass and conduct water leak test.

150.00 120

To remove roof lining, front and rear seats, trim board and carpet

120.00 60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed

Signature: _____ Date: _____

Acknowledged by: _____

Sig

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLG 5458B

Page : 2

To apply undersealing	100.00 301
To remove and renew exhaust silencer box	nn 60.00 X
To putty and spray replaced parts	1,200.00 6601
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00 7
Total :	----- S\$ 8,392.55 =====

Singapore Dollars Eight Thousand Three Hundred
and Ninety Two and Cents Fifty Five Only

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18005745/KTBN2

Date: 09/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VPCP/17-002264-00	
Claimant Vehicle No :	SKW2351Y	Insured Vehicle No :	SLG5458B	
Date of Loss:	23/03/2018	Nature of Claim:	TP	Claim No: MSC/V/18-000451

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW2351Y	Engine No:	3ZRB626820
Make & Model:	TOYOTA HARRIER, 2.0 Premium (A)	Chassis No:	ZSU600055403
Reg. Date:	22/10/2015 (Man. Year: 2015)	Odometer:	60172 km
Colour:	Metallic Black		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55R18	Rear Tyre Size:	235/55R18
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Bridgestone 7 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,762.55	3,626.60	2,135.95	37.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	1,370.00	1,260.00	47.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,392.55	4,996.60	3,395.95	40.46
+ GST 7.00/7.00% (S\$)	587.48	349.76	237.72	40.46
Nett Amount (S\$)	8,980.03	5,346.36	3,633.67	40.46

INSPECTION

Date of Assignment:	28/03/2018	
Date Inspected:	28/03/2018 Inspected At:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Singapore 575642

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Apr 2018)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW2351Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Bent	1,369.00 FL	*1,369.00 FL
2	1		*TAIL GATE HARRIER EMBLEM	Necessary	72.10 FL	*72.10 FL
3	1		*TAIL GATE LOGO	Necessary	52.20 FL	*52.20 FL
4	1		*TAIL GATE GLASS MOULDING	Necessary	81.70 FL	*81.70 FL
5	1		*TAIL GATE RUBBER	Serviceable	390.90 FL	*- FL
6	1		*TAIL GATE INNER LOCK	Dented	963.10 FL	*963.10 FL
7	1		*REAR BUMPER FASCIA	Buckled	1,381.50 FL	*1,381.50 FL
8	2		*REAR BUMPER SIDE RETAINER	Serviceable	181.60 FL	*- FL
9	1		*REAR BUMPER LOWER SPOILER	Bent	366.20 FL	*366.20 FL
10	4		*REAR LOWER SPOILER CLIP	Necessary	15.20 FL	*15.20 FL
11	2		*REAR LOWER SPOILER REFLECTOR	Serviceable	108.20 FL	*- FL
12	1		*REAR BUMPER INNER SPONGE	Cracked	187.80 FL	*187.80 FL
13	1		*REAR END PANEL	Repair	715.00 FL	*- FL
14	1		*END PANEL TOP GARNISH	Serviceable	353.80 FL	*- FL
15	1		*SPARE TYRE PANEL	Repair	965.10 FL	*- FL
16	1		*SET REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*220.00 FS
17	1		*REAR W/S GLASS SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	7,563.40	4,748.80
- List Item Discount on L Items 25.00/25.00% (S\$)	1,800.85	1,122.20
Total Parts (S\$)	5,762.55	3,626.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	150.00	120.00
2	TO REMOVE ROOF LINING,FRONT AND REAR SEATS,TRIM BOARD AND CARPET	New	120.00	60.00
3	TO APPLY UNDERSEALING	New	100.00	30.00
4	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	60.00	-
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,200.00	660.00
6	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,000.00	500.00
Gross Labour Cost (S\$)			2,630.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >