

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/RTTR%	DISCOUNT%	SALVAGE%	PART PRICE(NET)	ACTIO (PART)
<input type="checkbox"/>	8	1			REAR BOOT INNER RUBBER			Damaged	35				35	Revis
<input type="checkbox"/>	9	1			REAR BUMPER			Damaged	125				125	Revis
<input type="checkbox"/>	10	2			REAR BUMPER SIDE RETAINER			Bent	10				20	Revis
<input type="checkbox"/>	11	10			REAR BUMPER CLIP			Necessary	1.5				15	Revis
<input type="checkbox"/>	12	1			REAR TAIL LAMP LH			Cracked	70				70	Revis
<input type="checkbox"/>	13	1			REAR END PANEL			Damaged	185				185	Revis
<input type="checkbox"/>	14	1			END PANEL TOP GRANISH			Damaged	35				35	Revis
<input type="checkbox"/>	15	2			TAIL LAMP SEAL			Necessary	15				30	Revis

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R
<input type="checkbox"/>	1		WIRE CHECKING.	20	0	0	Reviewing		
<input type="checkbox"/>	2		LABOUR CHARGE.	600	0	0	Reviewing		
<input type="checkbox"/>	3		SPRAY PAINTING.	600	0	0	Reviewing		

Detailed Assessment

Inspection Date *

04/02/2018



Total Loss

Yes No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

300

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good

Steering (Serviceable)

Yes No

Footbrake (Serviceable)

Yes No

Handbrake (Serviceable)

Yes No

Engine Modification

Yes No

Pre-accident condition

-- none --

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

175/65R14

Rear Tyre Size

175/65R14

FNOL INFORMATI... BLK 661 JALAN DAMAI #06-123,
410661, Singapore

POST SURVEY INF ...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF ...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF ...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF ...

CATEGORY Identification #

FNOL INFORMATI... S9033917F

CATEGORY Make

POLICY INFORMAT... TOYOTA

CATEGORY Date of Birth

ASSESSMENT INFO... TOYOTA

FNOL INFORMATI... September 16, 1990

CATEGORY Model

POST SURVEY INF...

POLICY INFORMAT... VIOS 1.5

CATEGORY Age

ASSESSMENT INFO... VIOS 1.5E A

FNOL INFORMATI... 27

CATEGORY Type

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Occupation

ASSESSMENT INFO...

FNOL INFORMATI... Unknown

CATEGORY Type of Paint

POST SURVEY INF...

POLICY INFORMAT...

CATEGORY Education Qualification

ASSESSMENT INFO...

FNOL INFORMATI... Other

CATEGORY Chassis No

POST SURVEY INF...

POLICY INFORMAT... MR053HY4204208541

CATEGORY Driving Experience

Accelerated survey and authorize

Claim Handler

WANG Peter

peter.wang@axa.com.sg

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Add

Additional Instructions

Wkshop: SME Motor Excess: \$300

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
WANG Peter	3/27/18 11:26 AM	1968	1968	Open	Share	Clone

Accelerated survey and authorize

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Messages Invoices History Documents

Additional Instructions

Assessment Metrics Notes

Wkshop: SME Motor Excess: \$300

Document Type

Document Sub Type

Upload Documents.

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
WORKSHOP INVOICE.pdf	Invoice	Repairer	LKK AUTO CONSULTANTS PTE LTD (OD)	May 15, 2018
SGN2792C resurvey photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 19, 2018
SGN2792C photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 19, 2018