

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG18005801/AVBE2

Date: 06/05/2020

REFERENCE

Insured/Claimant:	LING YONG WAH	Policy No:	
Date of Loss:	23/03/2018	Nature of Claim:	OD Claim No: 2940864180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGU3899K	Engine No:	CGW043655
Make & Model:	AUDI RS5, 4.2 FSI quattro (A)	Chassis No:	WAUZZZ8F2CN012309
Reg. Date:	10/07/2012 (Man. Year: 2012)	Odometer:	107906 km
Colour:	White		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	S\$115,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,860.00	14,515.00	7,345.00	33.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,272.00	7,822.00	2,450.00	23.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	32,132.00	22,337.00	9,795.00	30.48
- Excess (S\$)	2,000.00	2,000.00	0.00	0.00
(S\$)	30,132.00	20,337.00	9,795.00	32.51
+ GST 7.00/7.00% (S\$)	2,109.24	1,423.59	685.65	32.51
Nett Amount (S\$)	32,241.24	21,760.59	10,480.65	32.51

INSPECTION

Date of Assignment:	28/03/2018		
Date Inspected:	28/03/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,635.00 FS	*2,108.00 FS
2	1		*LOWER GRILLE	Not Necessary	295.00 FS	*- FS
3	1		*AIR GRILLE - RHS / LHS	O/S Missing / N/S Not Necessary	614.00 FS	*245.20 FS
4	1		*RADIATOR GRILLE	Cracked	1,954.00 FS	*1,563.20 FS
5	1		*FOAM PIECE	Deformed	109.00 FS	*87.20 FS
6	1		*FRONT REINFORCEMENT BEAM	Bent	770.00 FS	*616.00 FS
7	2		*REINFORCEMENT BRACKET - LHS / RHS	Not Necessary	390.00 FS	*- FS
8	1		*BUMPER SUPPORT	Damaged	21.00 FS	*16.80 FS
9	1		*TOP COVER	Cracked	109.00 FS	*87.20 FS
10	1		*CAUTION SIGN	Necessary	12.00 FS	*9.28 FS
11	2		*FRONT FENDER - LHS / RHS	Buckled	1,860.00 FS	*744.00 FS
12	2		*FRONT FENDER INNER BRACKET - LHS / RHS	Not Necessary	100.00 FS	*- FS
13	2		*FRONT FENDER OUTER BRACKET - LHS / RHS	Not Necessary	100.00 FS	*- FS
14	16		*RIVET	Necessary	48.00 FS	*38.40 FS
15	2		*FRONT FENDER BRACE - LHS / RHS	Not Necessary	212.00 FS	*- FS
16	1		*V6T EMBLEM	Necessary	215.00 FS	*172.00 FS
17	2		*HEADLIGHT - LHS / RHS	Cracked	4,682.00 FS	*3,745.60 FS
18	1		*HEADLIGHT BRACKET - LHS / RHS	O/S Cracked	184.00 FS	*73.52 FS
19	2		*HEADLIGHT MOUNTING - LHS / RHS	Cracked	218.00 FS	*174.40 FS
20	2		*HEADLIGHT WASHER - LHS / RHS	Not Necessary	482.00 FS	*- FS
21	1		*PARKING AID	Missing	211.00 FS	*168.40 FS
22	2		*ELBOW FITTING	Not Necessary	45.00 FS	*- FS
23	1		*BONNET	Distorted	2,499.00 FS	*1,999.20 FS
24	1		*BONNET CATCH HOOK	Not Necessary	122.00 FS	*- FS
25	1		*BONNET SEAL	Necessary	24.00 FS	*18.88 FS
26	1		*BONNET SWITCH	Not Necessary	188.00 FS	*- FS
27	1		*A/C STICKER	Necessary	21.00 FS	*16.16 FS
28	1		*LOCK CARRIER	Cracked	923.00 FS	*738.40 FS
29	2		*LOCK CARRIER AIR GUIDE - LHS / RHS	Deformed	40.00 FS	*31.84 FS
30	1		*A/C CONDENSER	Bent	461.00 FS	*520.40 FS
31	1		*A/C CONDENSER VALVE	Not Necessary	46.00 FS	*- FS
32	1		*PRESSURE SENDER	Not Necessary	165.00 FS	*- FS
33	1		*RADIATOR	Bent	1,439.00 FS	*1,151.20 FS
34	6		*RADIATOR BUSH	Not Necessary	41.00 FS	*- FS
35	1		*RADIATOR SUPPORT	Not Necessary	66.00 FS	*- FS
36	1		*COOLANT	Necessary	134.00 FS	*106.24 FS
37	1		*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
38	1		*SUNDRIES	Necessary	400.00 FS	*58.48 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 21,860.00 14,515.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORN, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIRCOND CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIZE COOLING SYSTEM	New	1,200.00	1,200.00
3	TO DISMANTLE FRONT BUMPER, BOTH FRONT FENDER AND BONNET. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RENEW FRONT BUMPER, RHS FRONT FENDER, HEADLIGHTS AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,400.00	3,750.00
4	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER AND BONNET	New	3,000.00	2,200.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
			Gross Labour Cost (S\$)	7,822.00
			10,272.00	7,822.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >