

22/03/2018

ASS. REC. BY:

REF: CS / CTL 000 581 / 140 / Special Instruction:

Surveyor:

M/Min

Person): Irene Tay

ASSIGNMENT (Office)

of CTL

Date/Time: 28/03/2018 4:43pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKA 1122A

Insured:

GX 5506R

at Workshop m/s

Cycle & Camage

Tel:

9186 5109

of

188 Pandan Loop

Policy No:

DMCVS1743161700

Claim No:

SNM18D0159402

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 28/03/2018

CA / REV / REP. / REV 24 HRS WP:

07/05/2018

H.O.D. Endorsement:

Date/Time: 28/03/2018 5:02pm

Person Contacted:


Yik

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 1122A - X
	GX 5506R - NR / REP 100/19351/6
	NR-05/018
	Final Fig #12051-11, 6 days (Est #3166.41, 217%)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

(DAC Accident Report

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

6

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Yik

Tyre Size

F:

245/45R19

R:

~ 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO of

Front

6

R/Bal

mm

Rear

6

R/Bal

mm

L/Bal

6

mm

L/Bal

mm

D.O.A.

D.O.I.

2/5/18

Survey held at

18 Pandan Loop

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt / N/S

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 13 JUN 2018



CERTIFICATE OF INSURANCE

MERCEDES-BENZ MOTOR INSURANCE PRIVATE VEHICLE

Name of Policyholder : Ngee Ann Development Private Limited
Period of Insurance : 15 Oct 2017 To 14 Oct 2018
Engine No. : 27682430068552
Chassis No. : WDD2221652A060387

Vehicle No. : SKR1122A
Policy No. : 2100368820-03
Endorsement No. :
Issued Date : 18 Sep 2017

ABOUT THE COVER

Make/Model : MERCEDES BENZ S400L BE SEDAN
Engine Capacity/Tonnage : 2,996.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2014
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive*

Any person who is driving on the Policyholder's order or with their permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 2000cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$2000 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Eunice Service Center (For accident reporting only) Add: 350 Ubi Road, 3 Singapore 408650 67412335

2. Pandan Loop Service Center - Body Care & Repair (For accident repair & accident reporting) Add: 168 Pandan Loop Singapore 128378 67778388

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500660351

CYCLE & CARRIAGE - JACQHO
 239 ALEXANDRA ROAD
 SINGAPORE 159930 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Mobile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SECRET

REPUBLIC OF SINGAPORE **DRIVING LICENCE**



Licence Number: **S1073289A**
Name: **LO PIA LENG**

Birth Date: **11 Jan 1945**
Issue Date: **27 Mar 2003**

1000328754H

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	PASS DATE 16 Apr 1969
---------	--	--------------------------

FOR C&C USE ONLY

NP 428A





Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKR1122A

Ngee Ann Development Pte Ltd

391A Orchard Road
#26-01 Ngee Ann City
Singapore 238873

62339991

Vehicle & Document Information

WIP No **22329**
Reg No/Reg Date **SKR1122A / 15/10/2014**
Date In/Mileage **/ 0**
Chassis No **WDD2221652A080387**
Engine No **27682430068552**
Make/Model **MB/S 400 L BlueEFFICIENCY SE**
Colour/Trim **027 775 Iridium sil/ 048 814 Leather Cap**

Account No	Terms	Date/Time Printed	CSE	Operator
WN000265	Credit	26/03/2018/ 18:28	YK	395 / Yik Chan Hoe

Description of Goods / Services

Qty Unit Price Disc% Amount

M BPNSUN

POLICY NO/ACC DATE : 2100388820 // 25/03/2018
DRIVE IN/EXCESS : 26/03/2018 // TP VEH NO GX5506R CHINA TAIPING
DATE IN/DATE SURVEY:
BY/AUTHORIZED ON :

A BPILAB

PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW
BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY FRONT BUMPER AND LEFT FRONT FENDER

A BPILAB

USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO
STANDARD SETTINGS.

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT, NETT

M LEFT HEADLAMP VOLTAGE CONVERTER

1.00 1218.34 00.00

M LEFT HEADLAMP CONTROL UNIT

1.00 705.44 00.00

M LEFT HEADLAMP UNIT

1.00 5704.20 00.00

M LEFT FRONT BUMPER SIDE MOUNTING RAIL

1.00 11.38 00.00

M LEFT FRONT BASIC MOUNTING FOR BUMPER

1.00 282.63 00.00

M FRONT BUMPER

1.00 1833.85 00.00

M LEFT FRONT FENDER

1.00 1238.05 00.00

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

No local modification(s) is allowed

Supplementary item(s) must be received and

Signed by:

Date:

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorized Dealer
Company No. 195400367W
GST Reg No. MR-8500111-X

TAX INVOICE

Invoice Name & Address		Owner Name & Vehicle Info	
CHINA TAIPING INSURANCE (S) PTE LTD ATTN: MOTOR CLAIM DEPARTMENT 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909		Cust No/Name	WN000265/Ngee Ann Development Pte Ltd
Contact No 62222366		Reg No/Reg Date	SKR1122A / 15/10/2014
		Date In/Mileage	07/05/2018/ 24993
		Chassis No	WDD2221652A080387
		Engine No	27682430068552
		Make/Model	MB/S 400 L BlueEFFICIENCY SE
		Colour/Trim	027 775 Iridium sil/ 048 814 Leather Cap

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Invoice/Credit Note No
WC000668	Credit	30/05/2018/ 18:25	YK	395 / Yik Chan Hoe	22329	28142692

Description of Goods / Services	Qty	Unit Price S\$	Amount S\$
M BPNSUN			F.O.C.
POLICY NO/ACC DATE : 2100388820 // 25/03/2018			
DRIVE IN/EXCESS : 26/03/2018 // TP VEH NO GX5506R CHINA TAIPING			
DATE IN/DATE SURVEY: 07/05/2018 @ 1245 // TAUFIKH LKK			
BY/AUTHORIZED ON : DIRECT SETTLEMENT // IRENE TAY CHINA			
A BPILAB			1440.00
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.			
A BPIRES			1200.00
RESPRAY FRONT BUMPER AND LEFT FRONT FENDER			
A BPILAB			480.00
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			
A BPILAB			120.00
CHECK HEADLAMP WITH FOCUS ADJUSTMENT,NETT			
X LEFT HEADLAMP UNIT	1.00	5704.20	5704.20
X LEFT FRONT BUMPER SIDE MOUNTING RAIL	1.00	11.38	11.38
X FRONT BUMPER	1.00	1833.85	1833.85
X LEFT FRONT FENDER	1.00	1238.05	1238.05
X MOUNTING CLIP	2.00	2.83	5.66
X MOUNTING CLIP	1.00	7.09	7.09
X HEXALOBULAR BOLT	2.00	5.44	10.88

Parts	8,811.11	Nett	12,051.11
Labour	3,240.00	7% GST on	843.58
Standard Menu	0.00		
Specialist Job	0.00	Total Payable	12,894.69
Diagnostics Job	0.00	Paid	0.00
Sundry/Others	0.00	Total Due	12,894.69
Total (w/o GST)	12,051.11		

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Mar 2018		28 Mar 2018 16:43 Edit Adj Rpt	S\$12,051.11 Edit Estimates	S\$12,051.11 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	HAK KIAN ENTERPRISE PTE LTD, Co. Reg. No.: 199205373W	
Main Claimant:	NGEE ANN DEVELOPMENT PRIVATE LIMITED, Co. Reg. No.: 198804548D	
Vehicle Reg. No.:	SKR1122A	Date of Loss: 25/03/2018 15:00 - :59 [41 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D01594C02	Policy/Cover Note No.: DMCVSN1743161700 (Comprehensive)
Vehicle Reg. No. (Insured):	GX5506R	Policy No. (Claimant): 2100388820-03
		Excess: S\$0.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]	
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 09/04/2018]	
Driver/Custodian (Insured):	LOCK MOON CHEONG (50 / Male), NRIC: S1824158G, Tel: +6582008552	
Adj Asg. Remarks:	EST \$16,257.46, CASE WITH SJE	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SKR1122A (SNM18D01594C02)**
[GX5506R]

TP

NGEE ANN DEVELOPMENT PRIVATE LIMITED

Mar 25 2018 3:00PM

[HAK KIAN ENTERPRISE PTE LTD]

Cycle & Carriage Industries Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser		
Assessment Reports			1 per page	☒	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)		Thumbnail	Print
1	26/03/18 15:21	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)		Thumbnail	Print
1	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
2	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
3	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
4	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
5	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
6	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
7	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
8	26/03/18 15:20	Accident Photo [Linked Accident Report Documents]	1	Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	13/06/18 10:10	Chassis Number	1	Load JPG	☒
2	13/06/18 10:10	Odometer Reading	1	Load JPG	☒
3	13/06/18 10:10	General View	1	Load JPG	☒
4	13/06/18 10:10	General View	1	Load JPG	☒
5	13/06/18 10:10	General View	1	Load JPG	☒
6	13/06/18 10:10	General View	1	Load JPG	☒
7	13/06/18 10:10	General View	1	Load JPG	☒
8	13/06/18 10:10	General View	1	Load JPG	☒
9	13/06/18 10:10	General View	1	Load JPG	☒
10	13/06/18 10:10	General View	1	Load JPG	☒
11	13/06/18 10:10	General View	1	Load JPG	☒
12	13/06/18 10:10	General View	1	Load JPG	☒
13	13/06/18 10:10	General View	1	Load JPG	☒
14	13/06/18 10:10	General View	1	Load JPG	☒
15	13/06/18 10:10	General View	1	Load JPG	☒
16	13/06/18 10:10	General View	1	Load JPG	☒
17	13/06/18 10:10	General View	1	Load JPG	☒
18	13/06/18 10:10	General View	1	Load JPG	☒
19	13/06/18 10:10	General View	1	Load JPG	☒
20	13/06/18 10:10	General View	1	Load JPG	☒
21	13/06/18 10:10	General View	1	Load JPG	☒
22	13/06/18 10:10	General View	1	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
23	13/06/18 10:10	General View		Load JPG ☒
24	13/06/18 10:10	General View		Load JPG ☒
25	13/06/18 10:10	General View		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	28/03/18 16:42	REPAIR EST		Load PDF ☒
2	28/03/18 16:42	OI GIA REPORT		Load PDF ☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/03/18 15:20	Sketch Plan [Linked Accident Report Documents]		Load JPG ☒
2	26/03/18 15:20	Sketch Plan #2 [Linked Accident Report Documents]		Load JPG ☒
3	26/03/18 15:20	Sketch Plan #3 [Linked Accident Report Documents]		Load JPG ☒
4	26/03/18 15:20	Sketch Plan #4 [Linked Accident Report Documents]		Load JPG ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 15:04	SUPPLEMENTARY PART		Load PDF ☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/03/18 15:21	Accident Statement		Load HTM ☒
Photos/Images			3 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/03/18 15:20	Accident Photo		Load JPG ☒
2	26/03/18 15:20	Accident Photo		Load JPG ☒
3	26/03/18 15:20	Accident Photo		Load JPG ☒
4	26/03/18 15:20	Accident Photo		Load JPG ☒
5	26/03/18 15:20	Accident Photo		Load JPG ☒
6	26/03/18 15:20	Accident Photo		Load JPG ☒
7	26/03/18 15:20	Accident Photo		Load JPG ☒
8	26/03/18 15:20	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Cycle & Carriage Industries Pte Ltd (Pandan Loop)	Thumbnail	Print
1	26/03/18 15:20	Sketch Plan		Load JPG ☒
2	26/03/18 15:20	Sketch Plan #2		Load JPG ☒
3	26/03/18 15:20	Sketch Plan #3		Load JPG ☒
4	26/03/18 15:20	Sketch Plan #4		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
--

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18005811/T1QBQ2

Date: 13/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1743161700

Claimant Vehicle
No: SKR1122AInsured Vehicle
No: GX5506R

Date of Loss: 25/03/2018

Nature of Claim: TP

Claim
No: SNM18D01594C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR1122A

Make & Model: MERCEDES-BENZ S400L, 3.0 (A)

Engine No: 27682430068552

Reg. Date: 15/10/2014 (Man. Year: 2014)

Chassis No: WDD2221652A080387

Colour: Silver

Odometer: 24993 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R19

Rear Tyre Size: 245/45 R19

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,017.52	8,811.11	2,206.41	20.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,200.00	3,240.00	960.00	22.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,217.52	12,051.11	3,166.41	20.81
+ GST 7.00/7.00% (S\$)	1,065.23	843.58	221.65	20.81
Nett Amount (S\$)	16,282.75	12,894.69	3,388.06	20.81

INSPECTION

Date of Assignment: 28/03/2018

Date Inspected: 07/05/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2018)
Parts:	143	MERCEDES-BENZ S400L 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1122A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT HEADLAMP VOLTAGE CONVERTER	Not Necessary	1,218.34 FS	*- FS
2	1		*LEFT HEADLAMP CONTROL UNIT	Not Necessary	705.44 FS	*- FS
3	1		*LEFT HEADLAMP UNIT	Cracked	5,704.20 FS	*5,704.20 FS
4	1		*LEFT FRONT BUMPER SIDE MOUNTING RAIL	Necessary	11.38 FS	*11.38 FS
5	1		*LEFT FRONT BASIC MOUNTING FOR BUMPER	Not Necessary	282.63 FS	*- FS
6	1		*FRONT BUMPER	Deformed	1,833.85 FS	*1,833.85 FS
7	1		*LEFT FRONT FENDER	Bent	1,238.05 FS	*1,238.05 FS
8	2		*MOUNTING CLIP	Necessary	5.66 FS	*5.66 FS
9	1		*MOUNTING CLIP	Necessary	7.09 FS	*7.09 FS
10	2		*HEXALOBULAR BOLT	Necessary	10.88 FS	*10.88 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	11,017.52	8,811.11
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING TO REPAIR AFFECTED ,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,800.00	1,440.00
2	RESPRAY FRONT BUMPER AND LEFT FRONT FENDER	New	1,800.00	1,200.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET MEMORY TO STANDARD SETTINGS	New	480.00	480.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
Gross Labour Cost (S\$)			4,200.00	3,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >