



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
5 Benoi Place Singapore 629926
Tel: 6861 0908 Fax: 6515 2948

Date: 26.03.2018

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SLS9674D TOYOTA AXIO HYBRID (2017)

To Supply

- 1) 1pc Rear bumper

def \$ 700.00

Sub total Parts	\$	700.00
Less: 25% discount	\$	175.00
	\$	525.00

L/charges

- 1) To remove and replace rear bumper. Align & adjust rear bumper.
- 2) To putty, respray painting rear bumper. To polish.

\$180 ~~200.00~~
\$270 ~~250.00~~

Sub total L/charges	\$	450.00
Estimated Grand Total	\$	975.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*Not Authorised
LKK Repair
After paint job
LKK Auto (MA)
28/3/2018
2w days*

*# 700.00
2w days*