

REF: LPC

ASSIGNMENT

From: _____ Date: 29/03/2018

Estimated Cost: _____

OD / (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJK 2039A

at Workshop m/s: Perfect Power.

of: 1 Bukit Batok Crescent # 06-12

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Ezuwan - 8811 1110

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 13,500

IDAC Accident Rpt: _____ Consistent?: Yes or No


GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: 20. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT



Veh No: SJK 2039A Tr Regn: OCT / 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: TOYOTA DELICA c.c 1496

Colour: Blue A/C: Insured / Std / NI / NA

Sp.Reading: 279277. T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NZT2603022573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or MIC

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 24/3/2018 D.O.I. 29/3/2018

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	4s: + 4,300 (RED: + 8,408 65%)
	Mkt. v : + 13,500
	DPA : + 8,415
	Net : + 5,085

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to? _____

2) _____

Report Format : _____

Lump Sum / I.B.I: (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

(\$ + R5.00)

Photos: _____

Others: _____

Other: _____

Other: _____

Other: _____

TOTAL: _____

Add Fee: Site Insp (\$ _____)

Interview (\$ _____)

Tech. Invs (\$ _____)

Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18005831/M1eb3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 29-03-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY (FOLLOW THROUGH INSPECTION)

Insured Veh.	SJY 4594B	Veh. Inspected	SJK 2039A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	24/03/2018	Inspection Date	
Survey held at	VIFI PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1 #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/LPC18005831/M1eb3

Date: 03.04.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJK2039A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 29.03.2018 at the premises of M/s Vifi Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	12,908.00
Revised Estimate Amount	: S\$	8,454.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9 days

Yours faithfully,

MA CHIN FOOK
Licensed Appraiser

VIFI PTE LTD

Your Ref: SJY4594B

Our Ref: SJK2039A

To: LONPAC INSURANCE BHD

Date: 28/3/2018

From: Ezuwan

CC

Contact: 88111110

Email

Make / Model: TOYOTA ALLION A15 A

Fax

Chassis No.: NZT2603022573

Engine No.: 1NZC993374

Year of Make: 2008

Accident Date: 24/3/2018

ESTIMATE FOR VEHICLE NO. : SJK2039A

DESCRIPTION	QTY		List Price
✓ REAR BUMPER <i>det</i>	1	\$	1,250.00
✓ REAR BUMPER CLIPS <i>hec</i>	10	\$	50.00
✓ REAR RIGHT TAIL LAMP <i>ovc</i>	1	\$	325.00
✓ REAR LEFT TAIL LAMP <i>ovc</i>	1	\$	325.00
✓ SPARE TYRE COMPARTMENT <i>R</i>	1	\$	850.00
✓ REAR BOOT COVER - 16440 <i>det</i>	1	\$	350.00
✓ REAR BOOT COVER CLIP <i>hec</i>	10	\$	50.00
✓ REAR BOOT WEATHER STRIP 64401 <i>dis</i>	1	\$	195.00
✓ REAR BOOT <i>wt</i>	1	\$	980.00
✓ REAR CAMERA <i>ovc</i>	1	\$	650.00
✓ REAR BOOT LOCK HINGE 64610 <i>wt</i>	1	\$	160.00
✓ REAR BOOT MOULDING PROTECTOR 53B7 <i>dis</i>	1	\$	140.00
✓ REAR BUMPER REFLECTIVE LEFT <i>ovc</i>	1	\$	60.00
✓ REAR BUMPER RETAINER <i>dis</i>	2	\$	160.00
✓ REAR BOOT TOYOTA LOGO <i>hec</i>	1	\$	50.00
✓ REAR BOOT ALLION LOGO <i>hec</i>	1	\$	50.00
✓ REAR BOOT A15 LOGO <i>hec</i>	1	\$	40.00
✓ REAR BOOT CHROME GARNISH <i>ovc</i>	1	\$	135.00
✓ REAR END PANEL <i>wt</i>	1	\$	375.00
✓ REAR BUMPER SPONGE <i>klsp</i>	3	\$	180.00
✓ REAR BOOT PLATFORM 64711 <i>ovc</i>	1	\$	150.00
✓ FRONT BUMPER <i>det</i>	1	\$	600.00
✓ FRONT BUMPER CLIP <i>hec</i>	10	\$	50.00
✓ FRONT BUMPER RETAINER <i>dis</i>	2	\$	160.00
✓ FRONT BUMPER UPPER GRILLE <i>ovc</i>	1	\$	385.00
✓ FRONT BUMPER LOWER GRILLE <i>det</i>	1	\$	190.00
✓ FRONT REINFORCEMENT PANEL <i>ovc</i>	1	\$	215.00
✓ FRONT END PANEL <i>R</i>	1	\$	375.00
✓ FRONT SUPPORT PANEL <i>R</i>	1	\$	300.00
✓ FRONT LEFT HEADLAMP <i>ovc</i>	1	\$	550.00
✓ FRONT RIGHT HEADLAMP <i>ovc</i>	1	\$	550.00
FRONT BUMPER LOGO <i>x MIN</i>	1	\$	60.00

X RADIATOR ASSY *err*
 AC Condenser *✓* *bt*

1	\$	600.00
Total:		\$ 10,560.00
LESS 20%:		\$ (2,112.00)
Parts Total:		\$ 8,448.00

SPECIAL NETT

ANTI RUST COATING
 BODY SEALANT
 REAR REVERSE SENSOR
 FRONT NUMBER PLATE WITH CASING
 REAR NUMBER PLATE WITH CASING

1	\$	<i>net</i> 60 80.00
1	\$	<i>net</i> 60 60.00
1	\$	<i>net</i> 220 350.00
1	\$	<i>bt</i> 40 60.00
1	\$	<i>bt</i> 40 60.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS
 TO DISMANTLE & TRANSFER REAR BOOT FITTINGS & MECHANISM TO FACILITATE REPAIR
 TO CUT AND WELD REAR SPARE TYRE COMPARTMENT
 TO CHECK & RECONNECT ALL NECESSARY WIRING
 TO SPRAY PAINTING ON THE AFFECTED AREA

\$	<i>1200</i> 1,500.00
\$	<i>40</i> 100.00
\$	<i>x</i> 350.00
\$	<i>30</i> 100.00
\$	<i>1200</i> 1,800.00

Total:	\$	12,908.00
7% GST:	\$	903.56
Total:	\$	13,811.56
Lumsump -20%:	\$	(2,762.31)
Grand Total:	\$	11,049.25

Please survey the vehicle at :-
 1 Bukit Batok Crescent
 #06-12, WCEGA PLAZA
 SINGAPORE 658064
 (Kindly contact Ezuwan @ 8833 6463)

Not Auction
HS Repair
AAE PATA Photo
HKK Auto (net)
7 working days
29/3/2018

VIFI PTE LTD
 1 BUKIT BATOK CRESCENT
 #06-12, WCEGA PLAZA
 t 67670011
 Company Registration Number : 201315095D

MM

MMX \$14500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

7 working days

etc

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Wednesday, 28 March, 2018 2:26 PM
To: Ezuwan Huzaini; assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: 'Vic'; MT_Claim_SG
Subject: RE: LONPAC Insurance BHD 3rd Party Claim SJK2039A & SJY4594B 24/03/2018 WOODLANDS AVE 12 Our Ref: 18/18/18/VP05/020486
Attachments: SJK2039A GIA Report.pdf; SJK2039A Estimate.pdf

Without Prejudice

Dear Ezuwan Huzaini

We will appoint LKK Auto Consultants Pte Ltd to survey your client's vehicle. Please liaise with them on the quantum and liability.

Dear Catherine/Vic

Please handle.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

*1 Bukit Batok Crescent
#06-12, WCEGA PLAZA
Ezuwan @ 8811 1110*

29/03/2018

MA

From: Ezuwan Huzaini [mailto:ezuwan@perfectpower.sg]
Sent: Wednesday, 28 March, 2018 2:08 PM
To: ONG LI LI; CHEW BENG KEE; GERALD POH WEE BIN
Cc: 'Vic'
Subject: LONPAC Insurance BHD 3rd Party Claim SJK2039A & SJY4594B 24/03/2018 WOODLANDS AVE 12

Good Afternoon Sir / Mdm,

Regards on the above mention vehicle, we would like to arrange for surveyor to survey on vehicle to claim towards your insured

Meanwhil, I would like to propose direct settlement for this accident. I have attached the GIA Report and also the estimate for your perusal.

Claiming Party: SJK2039A
LONPAC Insured: SJY4594B

Thank you

Regards,

Ezuwan Huzaini

Service Advisor / Claims Advisor

+65 8811 1110

e-mail: ezuwan@perfectpower.sg



1 Bukit Batok Crescent

#06-12 WCEGA PLAZA

Singapore 658064

T :67670011 F :66590111

www.perfectpower.sg

 www.facebook.com/driftng.specialist

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 13 April 2018 12:07 PM
To: 'ezuwan@perfectpower.sg'
Cc: Vic (LKKAuto)
Subject: ACCIDENT INVOLVING SJK 2039A & SJY 4594B ON 24/03/2018

Without Prejudice

Your Ref: SJK 2039A
Our Ref: CC4/LPC18005831/M1eb3

Dear Sirs,

ACCIDENT INVOLVING SJK 2039A & SJY 4594B ON 24/03/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported 2 vehicle chain collision, your client reported 3 vehicle chain collision.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.


Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



SATISFACTION VOUCHER

Vehicle No : SJK2039A

This is to certify that **VIFI PTE LTD** has repaired the abovementioned vehicle to my satisfaction and I had taken delivery at 1330 hrs on this date 10/4/18.

A handwritten signature in black ink is written over a horizontal line. The signature is stylized and appears to be 'S. J. K. 2039A'.

Owner Signature & Co. Stamp (If applicable)

We **VIFI PTE LTD** hereby guarantee the workmanship of the repairs carried out on the accident portion of your vehicle. The guarantee is valid for a period of 6 month from the date of discharge and it is non-transferable. We will promptly carry out any necessary rectification work.

VIFI Pte Ltd
1 Bukit Batok Crescent
#06-12
WCEGA Plaza Singapore 658064
t 6767 0011 f 6659 0111
Company Registration Number : 201315095D



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18005831/M1eb3s2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 25-06-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJY 4594B	Veh. Inspected	SJK 2039A
Policy No.	Z18VP05017316	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020486	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALLION	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603022573	Colour	BLUE
Odometer	279277	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	7 mm
L/H Front Tyre	205/55R16	MICHELIN	7 mm
R/H Rear Tyre	205/55R16	MICHELIN	7 mm
L/H Rear Tyre	205/55R16	MICHELIN	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/03/2018	Inspection Date	29/03/2018
Survey held at	VIFI PTE LTD 1 BUKIT BATOK CRESCENT #06-12, WCEGA PLAZA SINGAPORE 658064		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 2039A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,250.00	1,250.00
10	REAR BUMPER CLIPS	NECESSARY	50.00	40.00
1	REAR RIGHT TAIL LAMP	SERVICEABLE	325.00	-
1	REAR LEFT TAIL LAMP	CRACKED	325.00	325.00
1	SPARE TYRE COMPARTMENT	TO REPAIR SEE LABOUR	850.00	-
1	REAR BOOT COVER - 164401	DENTED	350.00	350.00
10	REAR BOOT COVER CLIP	NECESSARY	50.00	40.00
1	REAR BOOT WEATHER STRIP 64401	DISTORTED	195.00	195.00
1	REAR BOOT	BENT	980.00	980.00
1	REAR CAMERA	SHORTED	650.00	650.00
1	REAR BOOT LOCK HINGE 64610	BENT	160.00	160.00
1	REAR BOOT MOULDING PROTECTOR 53B7	DISTORTED	140.00	140.00
1	REAR BUMPER REFLECTOR LEFT	CRACKED	60.00	60.00
2	REAR BUMPER RETAINER	DISTORTED	160.00	160.00
1	REAR BOOT TOYOTA LOGO	NECESSARY	50.00	50.00
1	REAR BOOT ALLION LOGO	NECESSARY	50.00	50.00
1	REAR BOOT A1.5 LOGO	NECESSARY	40.00	40.00
1	REAR BOOT CHROME GARNISH	SERVICEABLE	135.00	-
1	REAR END PANEL	BENT	375.00	375.00
3	REAR BUMPER SPONGE	NO SUCH PARTS	180.00	-
1	REAR BOOT PLATFORM 64711	SERVICEABLE	150.00	-
1	FRONT BUMPER	DEFORMED	600.00	600.00
10	FRONT BUMPER CLIP	NECESSARY	50.00	40.00
2	FRONT BUMPER RETAINER	DISTORTED	160.00	160.00
1	FRONT BUMPER UPPER GRILLE	SERVICEABLE	385.00	-
1	FRONT BUMPER LOWER GRILLE	DEFORMED	190.00	190.00
1	FRONT REINFORCEMENT PANEL	SERVICEABLE	215.00	-
1	FRONT END PANEL	TO REPAIR SEE LABOUR	375.00	-
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	300.00	-

Report Ref No. CC4/LPC18005831/M1eb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT HEADLAMP	CRACKED	550.00	550.00
1	FRONT RIGHT HEADLAMP	CRACKED	550.00	550.00
1	FRONT BUMPER LOGO	NOT NECESSARY	60.00	-
1	RADIATOR ASSY	SERVICEABLE	600.00	-
1	A/C CONDENSOR (NPA)	BENT	-	-
	LESS 20% DISCOUNT		-2,112.00	-1,391.00
			8,448.00	5,564.00
	<u>SPECIAL NETT ITEMS</u>			
1	ANTI RUST COATING (SN)	NECESSARY	80.00	60.00
1	BODY SEALANT (SN)	NECESSARY	60.00	60.00
1	REAR REVERSE SENSOR (SN)	SHORTED	350.00	220.00
1	FRONT NUMBER PLATE WITH CASING (SN)	BENT	60.00	40.00
1	REAR NUMBER PLATE WITH CASING (SN)	BENT	60.00	40.00
			610.00	420.00
	<u>LABOUR</u>			
	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF SPARE TYRE COMPARTMENT, FRONT END PANEL AND FRONT SUPPORT PANEL.		1,500.00	1,200.00
	TO DISMANTLE & TRANSFER REAR BOOT FITTINGS & MECHANISM TO FACILITATE REPAIR.		100.00	40.00
	TO CUT AND WELD REAR SPARE TYRE COMPARTMENT.	NOT NECESSARY	350.00	-
	TO CHECK & RECONNECT ALL NECESSARY WIRING.		100.00	30.00
	TO SPRAY PAINTING ON THE AFFECTED AREA.		1,800.00	1,200.00
			3,850.00	2,470.00
GRAND TOTAL			12,908.00	8,454.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/LPC18005831/M1eb3s2

MA CHIN FOOK

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.