


Copy



MAXXIS RECOVERY

Blk 411A Fernvale Road #06-74

Singapore 791411

Co. Reg. No: 53239862M

Email: maxxis_recovery@yahoo.com.sg

H/P : 9488 8856

No.: 8116

Date: 28/03/18

CASH SALES / WORK ORDER

Messrs: CASH

Vehicle No: GBG 5455C Model No: NISSAN NV200

From: TOA PAYOH

To: SIN MING

Time: (day/night) _____ Order by: _____

Cash \$: 60/- Remarks: _____

Issued by: [Signature] Received by: _____

Note: The recipient of service or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damage(s) to the car nor missing item(s) from the same.

- Accident / Overturn
- Crane Up / Winch Out
- Door Opening Service
- Jump Start
- King Dolly
- Low Body Kit
- Multi/Basement Carpark
- Transport Charge
- Tyre Replacement
- With Load / Cargo Box

LKK AUTO CONSULTANTS PTE LTD (TP) ▾

◀ Service Request Details

Claim

S8M00C96

Reference

None 

Loss Date

March 28, 2018

Request Date

March 28, 2018

Due Date

April 5, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*3/28/2018 @ 9:22am
Mr. Chia. veh in.
Mr. Ma.*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBG5455C

Make

TPVD UNKNOWN

Service Address

...

Primary Contact/Insured

CAROLINA BIOLOGICAL SUPPLY (S) PTE LTD
49 JALAN PEMIMPIN, #01-06, 577203, Singapore

KERK@CAROLINA.COM.SG

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Carolina Biological Supply (S) Pte Ltd

49 Jalan Pemimpin #01-06 APS Industrial Building Singapore (577203)
Tel: (65) 6483 5312 Fax (65) 6483 4213 Email: sales@carolinasingapore.com

Co. Reg No.: 200204548C

Teamed With Teachers

Letter of Authorization

I, Melvyn Tan Tzen Huang (S7581022I), the Manager for Carolina Biological Supply (S) Pte Ltd, authorize Toh Chwee Aik (S6829538F) to drive our vehicle GBG 1620T, on behalf of our company.

Toh Chwee Aik is employed by our company as driver.

Thank you.

Yours Sincerely,

(Melvyn Tan)

Manager

29th Mar 2018



◀ MANDATE REQUEST FOR S8M00C96

Type

📍 Question

Message

Liability: Insured rear ended third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$4,975.50 Loss of Rental: \$600.00 (6days x \$100) LTA Search: \$7.45 Total: \$5,582.95 Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (10/01/2019)

Reply



Re:MANDATE REQUEST FOR S8M00C96

Type

🔔 Question

Message

pls proceed

Reply

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO: 201316380R

M/S TREESCAPES PTE LTD

Date : 17-Aug-2018

AXA Insurance Singapore Pte Ltd
Motor Claim Department
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Without Prejudice

Date of Accident : 28-Mar-2018
Our Client's Vehicle Number : GBG 5455C
Vehicle Make / Model : NISSAN NV 200
Your Insurer : GBG 1620T

DESCRIPTION	SUB-AMOUNT	GST 7%	AMOUNT (SGD)
Lump Sum Repair Cost (Recommended by LKK Mr Ma)	4,650.00	325.50	4,975.50 SR
LTA Fee	6.96	0.49	7.45 SR
Loss of (Rental/Use) (6 days x \$ 120)	720.00		720.00 ES

SGD (Five Thousand Seven Hundred Two And Cents
Ninety-Five only)

GRAND TOTAL

5,702.95

Subject to 7% GST

325.99



Authorised Signature and Company Stamp



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18005843/M1ea3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 10-09-2019	
ATTN: STACEY NG		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBG 1620T	Veh. Inspected	GBG 5455C
Policy No.	CN834792	Coverage (\$)	0.00
Claim No.	S8M00C96	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	28/03/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0146076	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	175/70R14	GOODYEAR	7 mm
L/H Front Tyre	175/70R14	GOODYEAR	7 mm
R/H Rear Tyre	175/70R14	GOODYEAR	7 mm
L/H Rear Tyre	175/70R14	GOODYEAR	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/03/2018	Inspection Date	29/03/2018
Survey held at	EM-1 AUTO PTE LTD BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C #01-68 SINGAPORE 575643		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 5455C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LH (CONSISTENT)	BENT	1,404.90	1,404.90
1	TAILGATE RH (CONSISTENT)	BENT	1,093.60	1,093.60
1	REAR BUMPER (CONSISTENT)	DENTED	820.00	820.00
	LESS 30% DISCOUNT		-995.55	-995.55
			2,322.95	2,322.95
NETT ITEMS				
1	TAILGATE WINDSCREEN INNER SEAL LH (N) (CONSISTENT)	NECESSARY	60.00	60.00
1	TAILGATE BADGE (N) (CONSISTENT)	NECESSARY	155.90	155.90
1	TAILGATE EMBLEM NV200 (N) (CONSISTENT)	NECESSARY	163.50	163.50
1	TAILGATE INNER BOTTOM LOCK LH (N) (CONSISTENT)	SERVICEABLE	172.50	-
1	TAILGATE INNER BOTTOM LOCK CATCH LH (N) (CONSISTENT)	TO REPAIR SEE LABOUR	46.20	-
1	TAILGATE WEATHERSTRIP (N) (CONSISTENT)	NECESSARY	169.80	169.80
2	TAILGATE HINGE LH @ \$62.00 (N) (CONSISTENT)	SERVICEABLE	124.00	-
1	TAILGATE CHECKER LH (N) (CONSISTENT)	SERVICEABLE	58.00	-
1	TAILGATE SIDE RUBBER RH (N) (CONSISTENT)	NECESSARY	92.10	92.10
1	TAILGATE WINDSCREEN INNER SEAL RH (N) (CONSISTENT)	NECESSARY	60.00	60.00
1	TAILGATE INNER BOTTOM LOCK RH (N) (CONSISTENT)	BENT	172.50	172.50
1	TAILGATE INNER BOTTOM LOCK CATCH RH (N) (CONSISTENT)	SERVICEABLE	46.20	-
2	REAR BUMPER SIDE RETAINERS @ \$39.00 (N) (CONSISTENT)	NECESSARY	78.00	78.00
1	SET REAR BUMPER CLIPS (N) (CONSISTENT)	NECESSARY	50.00	40.00
1	REAR BUMPER SPONGE (N) (CONSISTENT)	CRACKED	163.00	163.00
2	REAR BUMPER REFLECTORS @ \$67.90 (N) (CONSISTENT)	N/S CRACKED / O/S NOT NECESSARY	135.80	67.90
2	TAILLAMPS @ \$265.70 (N) (CONSISTENT)	SERVICEABLE	531.40	-
2	TAILLAMPS INNER SEALER @ \$36.00 (N) (CONSISTENT)	NOT NECESSARY	72.00	-
2	SET TAILLAMP CLIPS @ \$25.00 (N) (CONSISTENT)	NOT NECESSARY	50.00	-
1	END PANEL (N) (CONSISTENT)	TO REPAIR SEE LABOUR	562.50	-

Report Ref No. CC4/ASM18005843/M1ea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL TOP TRIM (N) (CONSISTENT)	NOT NECESSARY	142.50	-
1	SET END PANEL TOP TRIM CLIPS (N) (CONSISTENT)	NOT NECESSARY	30.00	-
	LESS 10% DISCOUNT		-313.59	-122.27
			2,822.31	1,100.43
	<u>SPECIAL NETT ITEMS</u>			
1	SET TAILGATE COMPANY LETTERING (SN) (CONSISTENT)	NECESSARY	450.00	250.00
2	TAILGATE GLASS SEALANT @ \$60.00 (SN) (CONSISTENT)	NECESSARY	120.00	80.00
1	TAILGATE STICKER 70KM/H (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	TAILGATE STICKER 5 PAX (SN) (CONSISTENT)	NECESSARY	15.00	15.00
1	REAR NUMBER PLATE WITH COVER (SN) (CONSISTENT)	SERVICEABLE	70.00	-
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	250.00	220.00
1	BODY PANEL JOINT SEALANT (SN) (CONSISTENT)	NOT NECESSARY	120.00	-
			1,040.00	580.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF TAILGATE INNER BOTTOM LOCK CATCH LH AND END PANEL.		1,000.00	600.00
	SPRAY PAINTING.		1,000.00	600.00
	CHECK WIRING.		50.00	30.00
	ANTI RUST.		100.00	40.00
	TOWING FEES.		70.00	60.00
	REMOVE AND INSTALL BOTH TAILGATE GLASS.		240.00	160.00
	REMOVE AND INSTALL BOTH TAILGATE PARTS.		180.00	120.00
	REMOVE AND INSTALL CARPET AND INTERIOR.		120.00	60.00
	REMOVE AND INSTALL REVERSE SENSOR.		90.00	60.00
	REMOVE AND INSTALL REVERSE CAMERA.		150.00	60.00
			-	-
			-	-
			-	-
			3,000.00	1,790.00
GRAND TOTAL			9,185.26	5,793.38

Report Ref No. CC4/ASM18005843/M1ea3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00
---	--	--	----------

Report Ref No. CC4/ASM18005843/M1ea3s2

MA CHIN FOOK
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.