

ASS. REC. BY:

REF: CS/EQT18005846/Kvbs<sup>2</sup> Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

Date/Time: 29/3/2018 11:34am

From (Person):

Francis Ng

of EQ1

Bill to:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

CBE 4115 B

Insured:

at Workshop m/s

K Kim Hin Auto

Tel:

6452 7018

Policy No:

DmCPH18-001014

Claim No:

Excess:

\$ 500.00

Sum Insured:

D.O.A.

25/3/2018

Make of Veh: (Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

29/3/2018 1:12pm

Person Contacted:

Sandra

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	CBE 4115B - X
2/4/18	Revert by merimen
2/4/18	Rece approved from Francis Ng by merimen
2/4/18	Informed Simon c/A ex \$500 by email
13/7/18	@ 243pm Meng Huet will check





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CS/EQI18005846/Kvb

5 MAXWELL ROAD  
#17-00 TOWER BLOCK  
MND COMPLEX SINGAPORE 069110

Date : 29-03-2018



Code : EQI

## 1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBE 4115B
Policy No.	DMCPHQ18-001014	Coverage (\$)	0.00
Claim No.		Excess (\$)	500.00
Assign From	MERIMEN (FRANCIS NG)	Assign Date	29/03/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	25/03/2018	Inspection Date	29/03/2018
Survey held at	160 SIN MING DRIVE #02-20		
Repairer	K KIM HIN AUTOMOTIVE PTE LTD		

## 5a. Remarks

--

**...CLAIM SUBFOLDER...(New Assignment)**

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 09:48 Sendback Est	29 Mar 2018 10:58 S\$16,362.25	29 Mar 2018 11:34 Assign				<b>New Assignment</b> Cancel Case

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

<b>Insured:</b>	THRONE LANDSCAPE & CONSTRUCTION PTE LTD, Co. Reg. No.: 201001166R		
<b>Vehicle Reg. No.:</b>	GBE4115B	<b>Date of Loss:</b>	25/03/2018 14:00 - :59
<b>Claim Type:</b>	OD	<b>Policy/Cover Note No.:</b>	DMCPHQ18-001014 (Comprehensive)
		<b>Excess:</b>	S\$500.00
<b>Repairer:</b>	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
<b>Handling Insurer:</b>	EQ Insurance Company Ltd (HQ) - Tel: 6223 9433 ... [Handled by Francis Ng]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 10/04/2018]		
<b>Driver/Custodian:</b>	SIVALINGAM SURESH (34 / Male), NRIC: G2189807X, Tel: +6597752384		
<b>Adj Asg. Remarks:</b>	Please try to survey by today, 29.03.2018 Excess: \$500.00		

**ASSOCIATED MAIL RECEIVED**

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## ...CLAIM SUBFOLDER...(Pending for Approval)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Estimates	Est Submitted	Adj Assigned	Ins Auth'ed	Status
Main	29 Mar 2018 09:48		29 Mar 2018 10:58 <b>S\$16,362.25</b>			<b>Pending for Approval</b>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	<b>THRONE LANDSCAPE &amp; CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201001166R		
Vehicle Reg. No.:	<b>GBE4115B</b>	Date of Loss:	25/03/2018 14:00 - :59
Claim Type:	<b>OD</b>	Policy/Cover Note No.:	DMCPHQ18-001014 (Comprehensive)
		Excess:	
Repairer:	<b>K Kim Hin Auto Pte Ltd (HQ)</b> <a href="#">PROFILE</a> 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433		
Driver/Custodian:	SIVALINGAM SURESH (34 / Male), NRIC: G2189807X, Tel: +6597752384		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 2 April 2018 3:11 PM  
**To:** 'service@kkimhin.com.sg'; SUR; simon@kkimhin.com.sg  
**Subject:** GBE 4115B-DOA: 25/3/2018 (EQI OD)

Dear Simon,

As instructed by our client EQI , please proceed to repair the insured vehicle **GBE 4115B (Excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## View Received Message

This mail is associated with :

**GBE4115B**

OD

Mar 25 2018 2:00PM

[THRONE LANDSCAPE & CONSTRUCTION PTE LTD]

K Kim Hin Auto Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** EQ Insurance Company Ltd (HQ) (EQI\_HQ), sent on **02/04/2018 14:01 PM**.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$14656.00) - GBE4115B - Claim Handler: Francis Ng

Approved:14656.00.

### DOCUMENTS SUMMARY

There are no documents.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

<b>To:</b> EQ Insurance Company Ltd 5 Maxwell Road,#17-00 Tower Block MND Complex Singapore 069110	<b>From:</b> LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
<b>Attn:</b> Francis Ng	<b>Date:</b> 02 Apr 2018
<b><u>Preliminary Advice</u></b>	

Vehicle No	: GBE4115B	Accident Date	: 25/03/2018
Make	: TOYOTA DYNA	Policy No.	: DMCPHQ18-001014
Assignment Date	: 29/03/2018	Excess	: S\$500.00
Date of Inspection	: 29/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,362.25
Revised Amount	:S\$	9,507.00
Check Items (Estimated)	:S\$	5,149.00
<b>Total</b>	<b>:S\$</b>	<b>14,656.00</b>
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	35,142.00
Salvage Value	:S\$	
<b>Margin for Repair</b>	<b>:S\$</b>	<b>26,858.00</b>

### Remarks

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/03/2018 11:54
Date Of Accident	25/03/2018 14:40
Exact Location Of Accident	COMMON WEALTH AVE WEST
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE4115B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	THRONE LANDSCAPE & CONSTRUCTION PTE LTD
Co Reg No	201001166R
Email Address	SUGU@THRONE.COM.SG
Mobile Phone No	(LOCAL) +65-96779455
Alternative Phone No	OFFICE-67784018

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA-3.0 D TURBO M/T 2WD (M)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCPHQ18-001014
Cover Note Number	

### Driver

Name of Driver	SIVALINGAM SURESH
Passport No/FIN	G2189807X
Date Of Birth	21/05/1983
Occupation	INDOOR
Date Of Driving Pass	12/05/2014
Driving Experience	3 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97752384
Fax Number	
Contact Number	
EEmail Address	NOEMAIL


**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1166R
<b>Vehicle Details</b>	
Vehicle No.:	GBE4115B
Vehicle to be Exported:	No
Intended De-registration Date:	27 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 DIESEL TURBO M/T 2WD LORRY
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2557124
Chassis No.:	KDY2318021649
Maximum Power Output:	-
Open Market Value:	\$30,450.00
Original Registration Date:	24 Nov 2015
First Registration Date:	24 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$1,523.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	23 Nov 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$45,890.00
COE Rebate Amount:	\$35,142.00
<b>Total Rebate Amount:</b>	<b>\$35,142.00</b>

The information contained herein is correct as at 27 Mar 2018

OK

CO. REG. NO: 199402370D

GST NO: M2-0123250-3


**KIM HIN AUTO PTE LTD**

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)**

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-001014	Date of Loss:	25/03/2018
Vehicle Reg. No.:	GBE4115B	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THRONE LANDSCAPE & CONSTRUCTION PTE LTD		
Driver:	SIVALINGAM SURESH		

Make/Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Vehicle Reg. Date:	24/11/2015
Vehicle Colour:	SILVER	Chassis No:	KDY2318021649
Engine No:	1KD2557124		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		

*151 N/S*  


*Not Authorized  
1.B.1  
Resurvey B4 paint  
Ex @ 500.*

*Ex @ 625643/5*

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN.

Remarks: VEHICLE IS IN THE WORKSHOP AWAITING FOR SURVEY AND REPAIRS. PLS KINDLY APPOINT SURVEYOR TODAY. MANY THANKS - SANDRA

Present Location: K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	13,422.25
Miscellaneous Items	0.00
Labour	2,940.00
Paintwork Labour	0.00
Towing	16,488.18
<b>Gross Total (S\$)</b>	<b>16,362.25</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,145.36</b>
<b>Nett Amount (S\$)</b>	<b>17,507.61</b>

This claim is handled by: **SANDRA KHONG YEE TENG**



## REPAIR DETAILS

## Reference

Part Source: (Last Synchronised: 29 Mar 2018)

Parts: N/A TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBE4115B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT BUMPER	R <sub>1</sub>	0.00	0.00	*280.00 F	✓
2	1		*N/S FRONT BUMPER BRACKET	R <sub>1</sub>	0.00	0.00	*100.00 F	✓
3	1		*N/S FRONT BUMPER FOGLAMP		0.00	0.00	*120.00 F	?X
4	1		*N/S FRONT BUMPER FOGLAMP COVER	N <sub>1</sub>	0.00	0.00	*135.00 F	✓
5	1		*FRONT GRILLE	N <sub>3</sub> CM	0.00	0.00	*160.00 F	✓
6	10		*FRONT GRILLE CLIPS	N <sub>1</sub>	0.00	0.00	*15.00 F	✓
7	1		*FRONT GRILLE LOGO	N <sub>1</sub>	0.00	0.00	*35.00 F	✓
8	1		*FRONT GRILLE TOP SEAL	L <sub>1</sub>	0.00	0.00	*30.00 F	✓
9	1		*FRONT PANEL	R <sub>1</sub>	0.00	0.00	*380.00 F	✓
10	1		*FRONT PANEL DYNA STICKER	N <sub>1</sub>	0.00	0.00	*30.00 F	✓
11	1		*FRONT PANEL TOP CENTRE GARNISH (BLACK)	S <sub>1</sub>	0.00	0.00	*110.00 F	X
12	1		*N/S FRONT CORNER PANEL	R <sub>1</sub> L <sub>1</sub>	0.00	0.00	*75.00 F	✓
13	1		*N/S FRONT CORNER PANEL PROTECTOR	L <sub>1</sub>	0.00	0.00	*110.00 F	✓
14	1		*N/S FRONT CORNER PANEL TOP GARNISH (BLACK)	CM	0.00	0.00	*110.00 F	✓
15	1		*FRONT WINDSCREEN GLASS	S <sub>1</sub>	0.00	0.00	*480.00 F	X
16	1		*FRONT WINDSCREEN GLASS RUBBER	N <sub>1</sub>	0.00	0.00	*115.00 F	✓
17	1		*N/S FRONT DOOR	R <sub>1</sub>	0.00	0.00	*600.00 F	✓
18	1		*N/S FRONT DOOR HINGES - TOP	R <sub>1</sub>	0.00	0.00	*55.00 F	✓
19	1		*N/S FRONT DOOR HINGES - BOTTOM	R <sub>1</sub>	0.00	0.00	*55.00 F	✓
20	1		*N/S FRONT DOOR CHECKER	R <sub>1</sub>	0.00	0.00	*65.00 F	✓
21	1		*N/S FRONT DOOR WINDOW GLASS	S <sub>1</sub>	0.00	0.00	*220.00 F	X
22	1		*N/S FRONT DOOR WINDOW GLASS RUN CHANNEL		0.00	0.00	*80.00 F	?X
23	1		*N/S FRONT DOOR WINDOW GLASS OUTER MOULDING	R <sub>1</sub>	0.00	0.00	*55.00 F	✓
24	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR	R <sub>1</sub> L <sub>1</sub>	0.00	0.00	*120.00 F	✓
25	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR MOTOR	L <sub>1</sub>	0.00	0.00	*200.00 F	✓
26	1		*N/S FRONT DOOR SIGNALLAMP	S <sub>1</sub>	0.00	0.00	*30.00 F	X
27	1		*N/S FRONT DOOR WEATHERSTRIP	L <sub>1</sub>	0.00	0.00	*75.00 F	✓
28	1		*N/S FRONT DOOR LOWER SEAL	R <sub>1</sub>	0.00	0.00	*45.00 F	✓
29	1		*N/S FRONT DOOR FRONT SEAL		0.00	0.00	*45.00 F	?X
30	1		*N/S FRONT DOOR OUTER 1/4 GARNISH	S <sub>1</sub>	0.00	0.00	*75.00 F	X
31	1		*N/S FRONT DOOR OUTER HANDLE	S <sub>1</sub>	0.00	0.00	*85.00 F	X
32	1		*N/S FRONT DOOR INNER HANDLE		0.00	0.00	*35.00 F	?X
33	1		*N/S FRONT DOOR LOCK	N <sub>1</sub>	0.00	0.00	*185.00 F	✓
34	1		*N/S FRONT DOOR LOCK CATCH	L	0.00	0.00	*35.00 F	X
35	1		*N/S FRONT DOOR LOCK ACTUATOR		0.00	0.00	*85.00 F	?X
36	1		*N/S FRONT DOOR INNER TRIM BOARD	R <sub>1</sub>	0.00	0.00	*650.00 F	✓
37	1		*N/S FRONT DOOR SPEAKER		0.00	0.00	*215.00 F	?X
38	1		*N/S FRONT DOOR PILLAR		0.00	0.00	*220.00 F	?X
39	1		*N/S HEADLAMP ASSY	CM	0.00	0.00	*400.00 F	✓
40	1		*N/S HEADLAMP LOWER RUBBER LID	L <sub>1</sub>	0.00	0.00	*30.00 F	✓
41	1		*AIR CON CONDENSER C/W BRACKET	R <sub>1</sub>	0.00	0.00	*980.00 F	✓
42	1		*AIR CON CONDENSER FAN ASSY	CM	0.00	0.00	*300.00 F	✓
43	1		*AIR CON CONDENSER DISCHARGE PIPE		0.00	0.00	*380.00 F	?X
44	1		*AIR CON CONDENSER LIQUID PIPE	R <sub>1</sub>	0.00	0.00	*550.00 F	✓
45	1		*AIR CON CONDENSER SUCTION PIPE		0.00	0.00	*550.00 F	?X

Report was unsubmitted during this print-out.

Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	1		*AIR CON BLOWER C/W COOLING COIL	0.00	0.00	*1,700.00	F ? ✓
47	1		*DASHBOARD	0.00	0.00	*650.00	F ? X
48	1		*N/S DASHBOARD COMPARTMENT BOX	0.00	0.00/55	*180.00	F ? ✓
49	1		*N/S DASHBOARD LOWER COVER	<i>Dis</i> 0.00	0.00	*140.00	F ✓
50	1		*FRONT NUMBER PLATE	<i>Sp</i> 0	0.00	*40.00	FS X
51	1		*FRONT PANEL INSULATOR COAT	<i>na</i> 0	0.00	*250.00	FS ? X
52	1		*ERP BRACKET	<i>na</i> 0	0.00	*26.00	FS X
53	1		*N/S FRONT DOOR COMPANY REGISTRATION STICKER	<i>na</i> 0	0.00	*25.00	FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	11,716.00
+ Margin on L,N Items 15.00% (\$\$)	1,706.25
<b>Total Parts (\$\$)</b>	<b>13,422.25</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	900.00 ✓
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	201 50.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	601 120.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	1001 120.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS	New	100.00 ✓
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	2501 350.00
7	TO REMOVE DOORS FITTINGS	New	601 100.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	10001 1,100.00
9	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	nn 100.00 X
<b>Gross Labour Cost (S\$)</b>			<b>2,940.00</b>

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

KIM HIN AUTO PTE LTD

## 金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,  
Sin Ming AutoCity, Singapore 575722  
Tel: 6452 7018 Fax: 6458 3895  
Email: service@kkimhin.com.sg

INSURER: EQ Insurance Company Ltd (HQ)

### PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-001014	Date of Loss:	25/03/2018
Vehicle Reg. No.:	GBE4115B	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THRONE LANDSCAPE & CONSTRUCTION PTE LTD		
Driver:	SIVALINGAM SURESH		

Make/Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Vehicle Reg. Date:	24/11/2015
Vehicle Colour:	SILVER	Chassis No:	KDY2318021649
Engine No:	1KD2557124		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		

*151 N/S*  
*Not Authorized*  
*1-B.1*  
*Resuming B4 paint*  
*Ex @ 500.*

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN.

Remarks: VEHICLE IS IN THE WORKSHOP AWAITING FOR SURVEY AND REPAIRS. PLS KINDLY APPOINT SURVEYOR TODAY. MANY THANKS - SANDRA

Present Location: K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	13,422.25
Miscellaneous Items	0.00
Labour	2,940.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>16,362.25</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,145.36</b>
<b>Nett Amount (S\$)</b>	<b>17,507.61</b>

This claim is handled by: SANDRA KHONG YEE TENG

16488.18

**REPAIR DETAILS**

**Reference**

Part Source: (Last Synchronised: 29 Mar 2018)  
 Parts: N/A TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: (Unsubmitted, no print-code for GBE4115B)  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	R1	0.00	0.00 ✓*280.00 F ✓
2	1		*N/S FRONT BUMPER BRACKET	R1	0.00	0.00 ✓100.00 F ✓
3	1		*N/S FRONT BUMPER FOGLAMP X	R1	0.00	0.00 ✓120.00 F ✓
4	1		*N/S FRONT BUMPER FOGLAMP COVER	R1	0.00	0.00 ✓135.00 F ✓
5	1		*FRONT GRILLE	MTG C/M	0.00	0.00 ✓160.00 F ✓
6	10		*FRONT GRILLE CLIPS	R1	0.00	0.00 ✓15.00 F ✓
7	1		*FRONT GRILLE LOGO	R1	0.00	0.00 ✓35.00 F ✓
8	1		*FRONT GRILLE TOP SEAL	C/M	0.00	0.00 ✓30.00 F ✓
9	1		*FRONT PANEL	R1	0.00	0.00 ✓380.00 F ✓
10	1		*FRONT PANEL DYNA STICKER	R1	0.00	0.00 ✓30.00 F ✓
11	1		*FRONT PANEL TOP CENTRE GARNISH (BLACK)	R1	0.00	0.00 ✓110.00 F ✓
12	1		*N/S FRONT CORNER PANEL	R1	0.00	0.00 ✓75.00 F ✓
13	1		*N/S FRONT CORNER PANEL PROTECTOR	R1	0.00	0.00 ✓110.00 F ✓
14	1		*N/S FRONT CORNER PANEL TOP GARNISH (BLACK)	C/M	0.00	0.00 ✓110.00 F ✓
15	1		*FRONT WINDSCREEN GLASS	R1	0.00	0.00 ✓480.00 F ✓
16	1		*FRONT WINDSCREEN GLASS RUBBER	R1	0.00	0.00 95*115.00 F ✓
17	1		*N/S FRONT DOOR	R1	0.00	0.00 ✓600.00 F ✓
18	1		*N/S FRONT DOOR HINGES - TOP	R1	0.00	0.00 ✓55.00 F ✓
19	1		*N/S FRONT DOOR HINGES - BOTTOM	R1	0.00	0.00 ✓55.00 F ✓
20	1		*N/S FRONT DOOR CHECKER	R1	0.00	0.00 ✓65.00 F ✓
21	1		*N/S FRONT DOOR WINDOW GLASS ✓ See picture mtg cra	R1	0.00	0.00 ✓220.00 F ✓
22	1		*N/S FRONT DOOR WINDOW GLASS RUN CHANNEL	R1	0.00	0.00 ✓80.00 F ✓
23	1		*N/S FRONT DOOR WINDOW GLASS OUTER MOULDING	R1	0.00	0.00 ✓55.00 F ✓
24	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR	R1	0.00	0.00 ✓120.00 F ✓
25	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR MOTOR	R1	0.00	0.00 ✓200.00 F ✓
26	1		*N/S FRONT DOOR SIGNALLAMP	R1	0.00	0.00 ✓30.00 F ✓
27	1		*N/S FRONT DOOR WEATHERSTRIP	R1	0.00	0.00 ✓75.00 F ✓
28	1		*N/S FRONT DOOR LOWER SEAL	R1	0.00	0.00 ✓45.00 F ✓
29	1		*N/S FRONT DOOR FRONT SEAL	R1	0.00	0.00 ✓45.00 F ✓
30	1		*N/S FRONT DOOR OUTER 1/4 GARNISH	R1	0.00	0.00 ✓75.00 F ✓
31	1		*N/S FRONT DOOR OUTER HANDLE	R1	0.00	0.00 ✓85.00 F ✓
32	1		*N/S FRONT DOOR INNER HANDLE	R1	0.00	0.00 ✓35.00 F ✓
33	1		*N/S FRONT DOOR LOCK	R1	0.00	0.00 ✓185.00 F ✓
34	1		*N/S FRONT DOOR LOCK CATCH	R1	0.00	0.00 ✓35.00 F ✓
35	1		*N/S FRONT DOOR LOCK ACTUATOR	R1	0.00	0.00 ✓85.00 F ✓
36	1		*N/S FRONT DOOR INNER TRIM BOARD	R1	0.00	0.00 ✓650.00 F ✓
37	1		*N/S FRONT DOOR SPEAKER	R1	0.00	0.00 ✓215.00 F ✓
38	1		*N/S FRONT DOOR PILLAR ✓	R1	0.00	0.00 ✓220.00 F ✓
39	1		*N/S HEADLAMP ASSY	C/M	0.00	0.00 ✓400.00 F ✓
40	1		*N/S HEADLAMP LOWER RUBBER LID	R1	0.00	0.00 ✓30.00 F ✓
41	1		*AIR CON CONDENSER C/W BRACKET	R1	0.00	0.00 ✓980.00 F ✓
42	1		*AIR CON CONDENSER FAN ASSY	C/M	0.00	0.00 ✓300.00 F ✓
43	1		*AIR CON CONDENSER DISCHARGE PIPE	R1	0.00	0.00 ✓380.00 F ✓
44	1		*AIR CON CONDENSER LIQUID PIPE	R1	0.00	0.00 ✓550.00 F ✓
45	1		*AIR CON CONDENSER SUCTION PIPE	R1	0.00	0.00 ✓550.00 F ✓

Report was unsubmitted during this print-out.  
 Generated using Merlmen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*AIR CON BLOWER C/W COOLING COIL ✓	<i>hms</i> 0.00	0.00	✓1,700.00 F ✓
47	1		*DASHBOARD	<i>su</i> 0.00	0.00	X 650.00 F =
48	1		*N/S DASHBOARD COMPARTMENT BOX ✓	<i>od</i> 0.00	0.00	SS *180.00 F ? ✓
49	1		*N/S DASHBOARD LOWER COVER	<i>dis</i> 0.00	0.00	✓140.00 F ✓
50	1		*FRONT NUMBER PLATE	<i>su</i> 0	0.00	X 40.00 FS X
51	1		*FRONT PANEL INSULATOR COAT	<i>su</i> 0	0.00	*250.00 FS ?
52	1		*ERP BRACKET	<i>su</i> 0	0.00	X 26.00 FS X
53	1		*N/S FRONT DOOR COMPANY REGISTRATION STICKER	<i>su</i> 0	0.00	*25.00 FS ✓

F=Franchise part, S=SpcNelt.

Sub Total (\$\$)	11,716.00
+ Margin on L,N Items 15.00% (\$\$)	1,706.25
<b>Total Parts (\$\$)</b>	<b>13,422.25</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

*lpc n/s Front Door Slep Garnish \$105.00*

*~~lpc n/s Front Wiper Panel Side Garnish \$110.00~~*

*lpc n/s Headlamp Clip \$4.50*

### Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	900.00 ✓
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	201 50.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	601 120.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	1001 120.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS	New	100.00 ✓
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	2501 350.00
7	TO REMOVE DOORS FITTINGS	New	601 100.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	10001 1,100.00
9	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	222 100.00 X
<b>Gross Labour Cost (S\$)</b>			<b>2,940.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

\$ 8,355.00 - Part  
 + 109.50 - Spp  


---

 \$ 8,464.50  
 + 15%  


---

 \$ 9,734.17  
 + 250.00  
 + \$ 2,490.00  


---

 \$ 12,249.17 ✓.ck

**REPAIR DETAILS**

**Reference**

**Part Source:** (Last Synchronised: 31 Aug 2018)  
**Parts:** N/A TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)  
**Labour:** Repairer's (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for GBE4115B)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S FRONT DOOR STEP GARNISH	0.00	0.00	<i>Ref</i> *105.00 F ✓
2	1		*N/S HEADLAMP CLIP	0.00	0.00	<i>m</i> *4.50 F ✓
<b>Sub Total (S\$)</b>						<b>109.50</b>
<b>+ Margin on L,N Items 15.00% (S\$)</b>						<b>16.43</b>
<b>Total Parts (S\$)</b>						<b>125.93</b>

F=Franchise part.

Report was unsubmitted during this print-out.  
 Generated using Merimen e-Claims IEAS



# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE


M/S: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE  
#02-18/19/20/21 SIN MING AUTOCITY  
SINGAPORE 575722  
GBE4115B  
MENG HUAT

NO: DLI9201591  
PAGE: 1  
DATE: 04/04/2018  
A/C CODE: LDKK241  
TERMS: CR

Part No	Description	Location	Qty	Unit Price	Amount	
1) T81973-37010	H/L S CILP	DD1A141	1	SIN 4.50	SIN 4.50	
2) T56121-25040	W/S RUBBER FR	DUIH20-3	1	95.00	95.00	
3) T51772-37131	STEP GARNISH LH -	DST1972	1	105.00	105.00	
TOTAL QUANTITY:			3	TOTAL	SIN 204.50	
					ADD GST @ 7%	14.32
					<b>GRAND TOTAL</b>	<b>SIN 218.82</b>

#02-21




case 180229

Print / MT / 04/04/2018 10:33:44 AM

ALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE



GOODS RECEIVED BY



# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

*CP*

### TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE  
#02-18/19/20/21 SIN MING AUTOCITY  
SINGAPORE 575722  
GBE4115B  
SIMON


NO: DLI9201536  
PAGE: 1  
DATE: 03/04/2018  
A/C CODE: BDKK241  
TERMS: CR


Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	T52111-37501-B1 BAR FR BPER	DB2A	1	280.00	280.00 ✓
2	T52012-37052 ARM FR BPER LH	DUIU16	1	100.00	100.00 ✓
3	T53114-37010 GRILLE	DB2DD1	1	160.00	160.00 ✓
4	T52161-0K040 CLIP	DUIAD10-10	10	1.50	15.00 ✓
5	T75315-37011 EMBLEM GRILLE	DUIAS3-41	1	35.00	35.00 ✓
6	T53119-37080-B0 PROTECTOR GRILLE	DUIAT18	1	30.00	30.00 ✓
7	T75311-25090 EMBLEM FR (DYNA) CHROME	DUIAD12-2	1	30.00	30.00 ✓
8	T55711-37051 BODY PANEL	DBIF50	1	380.00	380.00 ✓
9	T53802-37021 SIDE PANEL LH	DUIE25	1	75.00	75.00 ✓
10	T53928-37011 GARNISH	DUIF17-4	1	110.00	110.00 ✓
11	T87945-37020-B0 COVER-MIRROR LH	DUIE17	1	110.00	110.00 ✓
12	T67002-25111 FR DOOR LH	DB1KS	1	600.00	600.00 ✓
13	T68730-37010 DOOR HINGE FR TOP LH	DUIAD19-11	1	55.00	55.00 ✓
14	T68710-37020 DOOR HINGE FR TOP RH	DUIAD17-11	1	55.00	55.00 ✓
15	T68610-37030 DOOR CHECK FR RH/LH	DUIB107	1	65.00	65.00 ✓
16	T68162-37011 W/STRIP OUTER FR LH	DUIH13-22	1	55.00	55.00 ✓
17	T69802-37063 REGULATOR	DUID75-1	1	120.00	120.00 ✓
18	T85720-37120 MOTOR ASSY	DUIAF9-1	1	200.00	200.00 ✓
19	T67862-37021 DOOR W/STRIP FR LH	DUIH15-9	1	75.00	75.00 ✓
20	T67864-37010 DOOR W/STRIP FR LH	DUIH23-9	1	45.00	45.00 ✓
21	T69320-37060 INNER LOCK FR LH	DUIB117	1	185.00	185.00 ✓
22	T61132-37062 W/S PILLAR LH	DB3AA	1	220.00	220.00 ✓

Print / MT / 03/04/2018 11:55:09 AM

..Conf'd

*CP*





# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

*Handwritten initials*

### TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD


GBE 4115B

NO: DLI9201536

2/4/18

PAGE: 2

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
23	T81170-37353 ✓	HEADLAMP LH	1	400.00	400.00 ✓
24	T81193-37060 ✓	PROT,H/LAMP RH/LH	1	30.00	30.00 ✓
25	T88460-37120	CONDENSER	1	980.00	980.00 ✓
26	T16363-37100	FAN MOTOR	1	300.00	300.00 ✓
27	T88710-37120	LIQUID PIPE	1	550.00	550.00 ✓
28	T55511-37020-B1	LOWER COVER	1	140.00	140.00 ✓
29	T67620-37130-B6	FR DOOR TRIM BOARD LH	1	650.00	650.00 ✓
TOTAL QUANTITY:			38	TOTAL	SIN 6,050.00
				ADD GST @ 7%	423.50
				GRAND TOTAL	<b>SIN 6,473.50</b>



#02-21

case 180229

*Handwritten initials*

Print / MT / 03/04/2018 11:55:10 AM

SALESMAN: MT

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S: K.KIM HIN AUTO PTE LTD


160 SIN MING DRIVE  
#02-18/19/20/21 SIN MING AUTO CITY  
SINGAPORE 575722  
DYNA  
SIMON

NO: DLI9201851  
PAGE: 1  
DATE: 11-04-2018  
A/C CODE: LDKK241  
TERMS: CR

VEH NO: GBE4115B

Part No	Description	Location	Qty	Unit Price	Amount	
1	T55550-37011-B1	DDS	1	SIN 155.00	SIN 155.00	
TOTAL QUANTITY			1	TOTAL	SIN 155.00	
					ADD GST @ 7%	10.85
					<b>GRAND TOTAL</b>	<b>SIN 165.85</b>

#02-21




case 180229

Print LSK 11/4/2018 10:12:57 AM

SALESMAN: LSK

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE





# 合興汽車零件私人有限公司

## HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

### TAX INVOICE

M/S : K.KIM HIN AUTO PTE LTD

160 SIN MING DRIVE

#02-18/19/20/21 SIN MING AUTO CITY

SINGAPORE 575722

DYNA

SIMON

NO: DLI9201666

PAGE: 1

DATE: 05/04/2018


A/C CODE: LDKK241

TERMS: CR

VEH NO: GBE4115B

Part No	Description	Location	Qty	Unit Price	Amount	
1 T68102-37140	DOOR GLASS FR LH	DD2GSL	1	SIN 220.00	SIN 220.00 ✓	
TOTAL QUANTITY:			1	TOTAL	SIN 220.00	
					ADD GST @ 7%	15.40
					<b>GRAND TOTAL</b>	<b>SIN 235.40</b>

#02-21



Print / LSK / 5/4/2018 5:29:34 PM

SALESMAN: LSK

This document is computer generated. No signature required.



GOODS SOLD ARE NOT RETURNABLE



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 09:48	29 Mar 2018 10:58	29 Mar 2018 11:34	<b>S\$12,249.18</b> Edit Estimates	<b>S\$12,249.18</b> View Rpt		<b>Pending for Survey Report</b> Cancel Case
	<a href="#">Sendback Est</a>	<b>S\$16,362.25</b>	<a href="#">Edit Adj Rpt</a>				
Supp #1	31 Aug 2018 12:12	31 Aug 2018 12:13	31 Aug 2018 12:13			(Combined)	<b>Combined with Main</b> <a href="#">Uncombine Suppl.</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

### CLAIM SUBFOLDER DETAILS

Insured:	<b>THRONE LANDSCAPE &amp; CONSTRUCTION PTE LTD</b> , Co. Reg. No.: 201001166R		
Vehicle Reg. No.:	<b>GBE4115B</b>	Date of Loss:	25/03/2018 14:00 - :59 [28 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>OD</b>	Policy/Cover Note No.:	DMCPHQ18-001014 (Comprehensive)
		Excess:	S\$500.00
Repairer:	<b>K Kim Hin Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	<b>EQ Insurance Company Ltd (HQ)</b> - Tel: 6223 9433 ... [Handled by <b>Francis Ng</b> ]		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... [Final Rpt due 10/04/2018]		
Driver/Custodian:	SIVALINGAM SURESH (34 / Male), NRIC: G2189807X, Tel: +6597752384		
Adj Asg. Remarks:	Please try to survey by today, 29.03.2018 Excess: \$500.00		

### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- EQI\_HQ (02/04/2018): **Alert - Adj Mandate Approved (S\$14656.00) - GBE4115B - Claim Handler: Francis Ng**

### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# Claim Documents

**GBE4115B**  
**OD**  
**Mar 25 2018 2:00PM**  
**[THRONE LANDSCAPE & CONSTRUCTION PTE LTD]**  
**K Kim Hin Auto Pte Ltd**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

View [View in Browser](#) ▼

Video			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 19:18	<b>Video - Accident</b> [Linked Accident Report Documents]	Load MP4	

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 10:58	<b>Repairer Estimates</b>	Load HTM	
2	31/08/18 12:13	<b>Repairer Estimates Suppl. #1</b>	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 13:45	<b>Adjuster Immediate Advice</b>	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
2	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
3	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
4	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
5	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
6	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
7	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
8	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
9	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
10	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
11	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
12	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
13	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
14	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
15	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
16	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
17	02/04/18 13:27	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
18	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
19	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
20	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
21	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
22	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
23	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
24	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
25	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
26	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>
27	02/04/18 13:29	<b>General View</b>	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
28	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
29	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
31	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	25/10/18 11:54	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	29/03/18 10:53	Driver's Driving License	Load PDF	
2	29/03/18 10:53	Log card (if available)	Load PDF	
3	29/03/18 10:53	Transfer fee	Load PDF	

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/10/18 14:24	SUPPLEMENTARY	Load PDF	
2	31/10/18 13:37	PARTS INVOICE	Load PDF	

## Linked Accident Report Documents

			View	View in Browser
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 19:18	Video - Accident	Load MP4	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 19:18	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	26/03/18 19:12	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	26/03/18 19:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	26/03/18 19:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	26/03/18 19:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	26/03/18 19:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	26/03/18 19:13	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page ▼	☑
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page ▼	☑
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	26/03/18 12:24	<b>Sketch Plan</b>	 Load TIF	

## Documents Checklist

### DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

#### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:  Repairer  Handling Insurer

Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd  
5 Maxwell Road, #17-00 Tower Block, MND Complex  
Singapore 069110

**Our File No:** CS/EQI18005846/KVBS2

**Date:** 31/10/2018

### REFERENCE

Insured/Claimant: THRONE LANDSCAPE & CONSTRUCTION PTE LTD  
Date of Loss: 25/03/2018

Policy No: DMCPHQ18-001014

Nature of Claim: OD

Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBE4115B</b>	Engine No:	1KD2557124
Make & Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Chassis No:	KDY2318021649
Reg. Date:	24/11/2015 (Man. Year: 2015)	Odometer:	142315 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	155 R15X8 (D)
Front Left Side:	Yokohama 2 mm	Rear Left Side:	Yokohama 2/2 mm
Front Right Side:	Yokohama 2 mm	Rear Right Side:	Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,548.18	9,759.18	3,789.00	27.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	2,490.00	450.00	15.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>16,488.18</b>	<b>12,249.18</b>	<b>4,239.00</b>	<b>25.71</b>
- Excess (S\$)	0.00	500.00	-500.00	
<b>(S\$)</b>	<b>16,488.18</b>	<b>11,749.18</b>	<b>4,739.00</b>	<b>28.74</b>
+ GST 7.00/7.00% (S\$)	1,154.18	822.44	331.74	28.74
<b>Nett Amount (S\$)</b>	<b>17,642.36</b>	<b>12,571.62</b>	<b>5,070.74</b>	<b>28.74</b>

### INSPECTION

Date of Assignment: 29/03/2018

Date Inspected: 29/03/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)  
160 Sin Ming Drive #02-20, Sin Ming AutoCity  
Singapore 575722

Estimated Period of Repair: 8.0 days

**Adjuster:** KENNETH KONG

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 31 Oct 2018)	
<b>Parts:</b>	N/A	TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBE4115B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*FRONT BUMPER</b> (WCP)	Bent	280.00 F	*280.00 F
2	1		<b>*N/S FRONT BUMPER BRACKET</b> (WCP)	Bent	100.00 F	*100.00 F
3	1		<b>*N/S FRONT BUMPER FOGLAMP</b> (WCP)	Serviceable	120.00 F	*- F
4	1		<b>*N/S FRONT BUMPER FOGLAMP COVER</b> (WCP)	Dented	135.00 F	*135.00 F
5	1		<b>*FRONT GRILLE</b> (WCP)	Mtg Cracked	160.00 F	*160.00 F
6	10		<b>*FRONT GRILLE CLIPS</b> (WCP)	Necessary	15.00 F	*15.00 F
7	1		<b>*FRONT GRILLE LOGO</b> (WCP)	Necessary	35.00 F	*35.00 F
8	1		<b>*FRONT GRILLE TOP SEAL</b> (WCP)	Cut	30.00 F	*30.00 F
9	1		<b>*FRONT PANEL</b> (WCP)	Bent	380.00 F	*380.00 F
10	1		<b>*FRONT PANEL DYNA STICKER</b> (WCP)	Necessary	30.00 F	*30.00 F
11	1		<b>*FRONT PANEL TOP CENTRE GARNISH (BLACK)</b> (WCP)	Serviceable	110.00 F	*- F
12	1		<b>*N/S FRONT CORNER PANEL</b> (WCP)	Bent	75.00 F	*75.00 F
13	1		<b>*N/S FRONT CORNER PANEL PROTECTOR</b> (WCP)	Cut	110.00 F	*110.00 F
14	1		<b>*N/S FRONT CORNER PANEL TOP GARNISH (BLACK)</b> (WCP)	Cracked	110.00 F	*110.00 F
15	1		<b>*FRONT WINDSCREEN GLASS</b> (WCP)	Serviceable	480.00 F	*- F
16	1		<b>*FRONT WINDSCREEN GLASS RUBBER</b> (WCP)	Necessary	115.00 F	*95.00 F
17	1		<b>*N/S FRONT DOOR</b> (WCP)	Buckled	600.00 F	*600.00 F
18	1		<b>*N/S FRONT DOOR HINGES - TOP</b> (WCP)	Bent	55.00 F	*55.00 F
19	1		<b>*N/S FRONT DOOR HINGES - BOTTOM</b> (WCP)	Bent	55.00 F	*55.00 F
20	1		<b>*N/S FRONT DOOR CHECKER</b> (WCP)	Bent	65.00 F	*65.00 F
21	1		<b>*N/S FRONT DOOR WINDOW GLASS</b> (WCP)	Mtg Cracked	220.00 F	*220.00 F
22	1		<b>*N/S FRONT DOOR WINDOW GLASS RUN CHANNEL</b> (WCP)	Serviceable	80.00 F	*- F
23	1		<b>*N/S FRONT DOOR WINDOW GLASS OUTER MOULDING</b> (WCP)	Buckled	55.00 F	*55.00 F
24	1		<b>*N/S FRONT DOOR WINDOW GLASS REGULATOR</b> (WCP)	Bent / Jammed	120.00 F	*120.00 F
25	1		<b>*N/S FRONT DOOR WINDOW GLASS REGULATOR MOTOR</b> (WCP)	Jammed	200.00 F	*200.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*N/S FRONT DOOR SIGNALLAMP (WCP)	Serviceable	30.00 F	*- F
27	1		*N/S FRONT DOOR WEATHERSTRIP (WCP)	Cut	75.00 F	*75.00 F
28	1		*N/S FRONT DOOR LOWER SEAL (WCP)	Buckled	45.00 F	*45.00 F
29	1		*N/S FRONT DOOR FRONT SEAL (WCP)	Serviceable	45.00 F	*- F
30	1		*N/S FRONT DOOR OUTER 1/4 GARNISH (WCP)	Serviceable	75.00 F	*- F
31	1		*N/S FRONT DOOR OUTER HANDLE (WCP)	Serviceable	85.00 F	*- F
32	1		*N/S FRONT DOOR INNER HANDLE (WCP)	Serviceable	35.00 F	*- F
33	1		*N/S FRONT DOOR LOCK (WCP)	Dented	185.00 F	*185.00 F
34	1		*N/S FRONT DOOR LOCK CATCH (WCP)	Repair	35.00 F	*- F
35	1		*N/S FRONT DOOR LOCK ACTUATOR (WCP)	Serviceable	85.00 F	*- F
36	1		*N/S FRONT DOOR INNER TRIM BOARD (WCP)	Buckled	650.00 F	*650.00 F
37	1		*N/S FRONT DOOR SPEAKER (WCP)	Serviceable	215.00 F	*- F
38	1		*N/S FRONT DOOR PILLAR (WCP)	Bent	220.00 F	*220.00 F
39	1		*N/S HEADLAMP ASSY (WCP)	Cracked	400.00 F	*400.00 F
40	1		*N/S HEADLAMP LOWER RUBBER LID (WCP)	Torn	30.00 F	*30.00 F
41	1		*AIR CON CONDENSER C/W BRACKET (WCP)	Bent	980.00 F	*980.00 F
42	1		*AIR CON CONDENSER FAN ASSY (WCP)	Cracked	300.00 F	*300.00 F
43	1		*AIR CON CONDENSER DISCHARGE PIPE (WCP)	Serviceable	380.00 F	*- F
44	1		*AIR CON CONDENSER LIQUID PIPE (WCP)	Bent	550.00 F	*550.00 F
45	1		*AIR CON CONDENSER SUCTION PIPE (WCP)	Serviceable	550.00 F	*- F
46	1		*AIR CON BLOWER C/W COOLING COIL (WCP)	Housing Cracked	1,700.00 F	*1,700.00 F
47	1		*DASHBOARD (WCP)	Serviceable	650.00 F	*- F
48	1		*N/S DASHBOARD COMPARTMENT BOX (WCP)	Dented	180.00 F	*155.00 F
49	1		*N/S DASHBOARD LOWER COVER (WCP)	Distorted	140.00 F	*140.00 F
50	1		*FRONT NUMBER PLATE	Serviceable	40.00 FS	*- FS
51	1		*FRONT PANEL INSULATOR COAT	Serviceable	250.00 FS	*- FS
52	1		*ERP BRACKET	Not Necessary	26.00 FS	*- FS
53	1		*N/S FRONT DOOR COMPANY REGISTRATION STICKER	Necessary	25.00 FS	*25.00 FS
<b>Supplementary #1</b>						
54	1		*N/S FRONT DOOR STEP GARNISH (WCP)	Dented	105.00 F	*105.00 F
55	1		*N/S HEADLAMP CLIP (WCP)	Necessary	4.50 F	*4.50 F

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>11,825.50</b>	<b>8,489.50</b>
<b>+ Margin on L,N Items 15.00/15.00% (S\$)</b>	1,722.68	1,269.68
<b>Total Parts (S\$)</b>	<b>13,548.18</b>	<b>9,759.18</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	900.00	900.00
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	50.00	20.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	120.00	60.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	120.00	100.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS	New	100.00	100.00
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	350.00	250.00
7	TO REMOVE DOORS FITTINGS	New	100.00	60.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	1,100.00	1,000.00
9	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	100.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,940.00</b>	<b>2,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >