

CO. REG. NO: 199402370D

GST NO: M2-0123250-3


KIM HIN AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: **EQ Insurance Company Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCPHQ18-001014	Date of Loss:	25/03/2018
Vehicle Reg. No.:	GBE4115B	Driveable?	
Driver Age/Info:	34 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	THRONE LANDSCAPE & CONSTRUCTION PTE LTD		
Driver:	SIVALINGAM SURESH		

Make/Model:	TOYOTA DYNA, 3.0 D TURBO M/T 2WD (M)	Vehicle Reg. Date:	24/11/2015
Vehicle Colour:	SILVER	Chassis No:	KDY2318021649
Engine No:	1KD2557124		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 ✓		

Paints


*Not Authorized
1.3.1
Resurvey B4 paint
Ex @ 500.*

Part 62564315

Description of Accident/Loss: PLEASE REFER TO SKETCH PLAN.

Remarks: VEHICLE IS IN THE WORKSHOP AWAITING FOR SURVEY AND REPAIRS. PLS KINDLY APPOINT SURVEYOR TODAY. MANY THANKS - SANDRA

Present Location: K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS	Amount
Parts	13,422.25
Miscellaneous Items	0.00
Labour	2,940.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,362.25
+ GST 7.00% (S\$)	1,145.36
Nett Amount (S\$)	17,507.61

This claim is handled by: **SANDRA KHONG YEE TENG**

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 29 Mar 2018)**Parts:** N/A TOYOTA DYNA 3.0 D TURBO M/T 2WD (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for GBE4115B)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT BUMPER	R1	0.00	0.00	*280.00 F	✓
2	1		*N/S FRONT BUMPER BRACKET	R1	0.00	0.00	*100.00 F	✓
3	1		*N/S FRONT BUMPER FOGLAMP		0.00	0.00	*120.00 F	✓
4	1		*N/S FRONT BUMPER FOGLAMP COVER		0.00	0.00	*135.00 F	✓
5	1		*FRONT GRILLE	M3 CMA	0.00	0.00	*160.00 F	✓
6	10		*FRONT GRILLE CLIPS	NR	0.00	0.00	*15.00 F	✓
7	1		*FRONT GRILLE LOGO	NR	0.00	0.00	*35.00 F	✓
8	1		*FRONT GRILLE TOP SEAL	CR	0.00	0.00	*30.00 F	✓
9	1		*FRONT PANEL	R1	0.00	0.00	*380.00 F	✓
10	1		*FRONT PANEL DYNA STICKER	NR	0.00	0.00	*30.00 F	✓
11	1		*FRONT PANEL TOP CENTRE GARNISH (BLACK)	SR	0.00	0.00	*110.00 F	X
12	1		*N/S FRONT CORNER PANEL	R1 CR	0.00	0.00	*75.00 F	✓
13	1		*N/S FRONT CORNER PANEL PROTECTOR	CR	0.00	0.00	*110.00 F	✓
14	1		*N/S FRONT CORNER PANEL TOP GARNISH (BLACK)	CMA	0.00	0.00	*110.00 F	✓
15	1		*FRONT WINDSCREEN GLASS	SR	0.00	0.00	*480.00 F	X
16	1		*FRONT WINDSCREEN GLASS RUBBER	NR	0.00	0.00	*115.00 F	✓
17	1		*N/S FRONT DOOR	BUR	0.00	0.00	*600.00 F	✓
18	1		*N/S FRONT DOOR HINGES - TOP	R1	0.00	0.00	*55.00 F	✓
19	1		*N/S FRONT DOOR HINGES - BOTTOM	R1	0.00	0.00	*55.00 F	✓
20	1		*N/S FRONT DOOR CHECKER	R1	0.00	0.00	*65.00 F	✓
21	1		*N/S FRONT DOOR WINDOW GLASS	SR	0.00	0.00	*220.00 F	X
22	1		*N/S FRONT DOOR WINDOW GLASS RUN CHANNEL		0.00	0.00	*80.00 F	✓
23	1		*N/S FRONT DOOR WINDOW GLASS OUTER MOULDING	BUR	0.00	0.00	*55.00 F	✓
24	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR	B1 SR	0.00	0.00	*120.00 F	✓
25	1		*N/S FRONT DOOR WINDOW GLASS REGULATOR MOTOR	TR	0.00	0.00	*200.00 F	✓
26	1		*N/S FRONT DOOR SIGNALLAMP	SR	0.00	0.00	*30.00 F	X
27	1		*N/S FRONT DOOR WEATHERSTRIP	CR	0.00	0.00	*75.00 F	✓
28	1		*N/S FRONT DOOR LOWER SEAL	BUR	0.00	0.00	*45.00 F	✓
29	1		*N/S FRONT DOOR FRONT SEAL		0.00	0.00	*45.00 F	✓
30	1		*N/S FRONT DOOR OUTER 1/4 GARNISH	SR	0.00	0.00	*75.00 F	X
31	1		*N/S FRONT DOOR OUTER HANDLE	SR	0.00	0.00	*85.00 F	X
32	1		*N/S FRONT DOOR INNER HANDLE		0.00	0.00	*35.00 F	✓
33	1		*N/S FRONT DOOR LOCK	NR	0.00	0.00	*185.00 F	✓
34	1		*N/S FRONT DOOR LOCK CATCH	R	0.00	0.00	*35.00 F	X
35	1		*N/S FRONT DOOR LOCK ACTUATOR		0.00	0.00	*85.00 F	✓
36	1		*N/S FRONT DOOR INNER TRIM BOARD	BUR	0.00	0.00	*650.00 F	✓
37	1		*N/S FRONT DOOR SPEAKER		0.00	0.00	*215.00 F	✓
38	1		*N/S FRONT DOOR PILLAR		0.00	0.00	*220.00 F	✓
39	1		*N/S HEADLAMP ASSY	CMA	0.00	0.00	*400.00 F	✓
40	1		*N/S HEADLAMP LOWER RUBBER LID	TR	0.00	0.00	*30.00 F	✓
41	1		*AIR CON CONDENSER C/W BRACKET	R1	0.00	0.00	*980.00 F	✓
42	1		*AIR CON CONDENSER FAN ASSY	CMA	0.00	0.00	*300.00 F	✓
43	1		*AIR CON CONDENSER DISCHARGE PIPE		0.00	0.00	*380.00 F	✓
44	1		*AIR CON CONDENSER LIQUID PIPE	R1	0.00	0.00	*550.00 F	✓
45	1		*AIR CON CONDENSER SUCTION PIPE		0.00	0.00	*550.00 F	✓

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*AIR CON BLOWER C/W COOLING COIL	0.00	0.00	*1,700.00 F ?
47	1		*DASHBOARD	0.00	0.00	*650.00 F ?
48	1		*N/S DASHBOARD COMPARTMENT BOX	0.00	0.00	*180.00 F ?
49	1		*N/S DASHBOARD LOWER COVER	<i>Dis</i> 0.00	0.00	*140.00 F ✓
50	1		*FRONT NUMBER PLATE	<i>Sm</i> 0	0.00	*40.00 FS X
51	1		*FRONT PANEL INSULATOR COAT	0	0.00	*250.00 FS ?
52	1		*ERP BRACKET	<i>nn</i> 0	0.00	*26.00 FS X
53	1		*N/S FRONT DOOR COMPANY REGISTRATION STICKER	<i>nc</i> 0	0.00	*25.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	11,716.00
+ Margin on L,N Items 15.00% (\$\$)	1,706.25
Total Parts (\$\$)	13,422.25

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW AFFECTED PARTS.	New	900.00 ✓
2	TO FOCUS HEADLAMPS. TO CHECK FRONT WIRING AND LIGHTING OPERATION.	New	201 50.00
3	TO REMOVE AND RENEW FRONT WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	601 120.00
4	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	1001 120.00
5	TO REMOVE AIRCON CONDENSER, PIPES AND DRIERS. VACCUM AND RECHARGE GAS	New	100.00 ✓
6	TO REMOVE FRONT INSTRUMENT PANEL ASSY AND REWIRING TO FACILITATE REPAIR WORKS.	New	2501 350.00
7	TO REMOVE DOORS FITTINGS	New	601 100.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	10001 1,100.00
9	TO CONDUCT FRONT WHEEL ALIGNMENT TEST.	New	nn 100.00 X
Gross Labour Cost (S\$)			2,940.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: