

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Francis Ng

Date: 02 Apr 2018

**Preliminary Advice**

Vehicle No	: GBE4115B	Accident Date	: 25/03/2018
Make	: TOYOTA DYNA	Policy No.	: DMCPHQ18-001014
Assignment Date	: 29/03/2018	Excess	: S\$500.00
Date of Inspection	: 29/03/2018	Est. Duration of Repair	: 8.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,362.25
Revised Amount	:S\$	9,507.00
Check Items (Estimated)	:S\$	5,149.00
Total	:S\$	14,656.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	35,142.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,858.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :