Page 1 of 4 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI18005878/KRBE2

3 Anson Road, #16-00 Springleaf Tower

Date: 14/03/2019 Singapore 079909

REFERENCE

Insured/Claimant: DMPCSN3118701600 SHIRIN BINTE YAHYA Policy No:

Date of Loss: 17/03/2018 Nature of Claim: Claim No: SNM18D01596C01

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SJX1237H** 

PROTON EXORA, 1.6 AT (M-LINE) ABS D/AB 2WD Engine No: Make & Model:

S4PHQG9616 5DR (A)

Reg. Date: 29/03/2010 (Man. Year: 2010) Chassis No: PL1FZ6YRRAF028017

Colour: Odometer: 113577 km White

**Engine Capacity:** 1597 cc Market Value/New Car Price: S\$27,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

205/55 R16 Front Tyre Size: 205/55 R16 Rear Tyre Size: Front Left Side: Linglong 8 mm Rear Left Side: Linglong 7 mm Front Right Side: Linglong 8 mm Rear Right Side: Linglong 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	962.00	917.00	45.00	4.68
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	948.93	801.93	147.00	15.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,010.93	1,818.93	192.00	9.55
+ GST 7.00/7.00% (S\$)	140.77	127.33	13.44	9.55
Nett Amount (S\$)	2,151.70	1,946.26	205.44	9.55

**INSPECTION** 

29/03/2018 Date of Assignment:

04/04/2018 Inspected At: 10 ANG MO KIO IND PARK 2A #01-04 Date Inspected:

Repairer: Cheng Hoe Motor Pte Ltd

(Yishun)

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: Janice Lee Si Hua Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference			
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 14 Mar 2019)	
Parts:	M1-MPV	PROTON EXORA 1.6 AT (M-LINE) ABS D/AB 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted,	no print-code for SJX1237H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.			

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BUMPER COVER	Buckled	220.00 F	*220.00 F
2	1	NA	*FRT BUMPER REINF	Bent	190.00 F	*190.00 F
3	1	NA	*R/F BUMPER BRACKET	Distorted	32.00 F	*32.00 F
4	1	NA	*R/F FOG LAMP GRILLE	Serviceable	45.00 F	*- F
5	1	NA	*R/F HEADLAMP CPL	Cut	240.00 F	*240.00 F
6	1	NA	*R/F WING	Buckled	160.00 F	*160.00 F
7	1	NA	*R/WING SPLASH SHIELD	Distorted	75.00 F	*75.00 F
F=Franchise part.						
				Total Parts (S\$)	962.00	917.00

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cellar	neous Items			
1	1	SUNDRY PARTS (NECESSARY)		100.00	100.00
			Sub Total (S\$)	100.00	100.00

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	Total Paint Labour	New	331.80	331.80
2	Total Paint Materials	New	163.53	163.53
3	Total Panel/Mechanical Labour	New	453.60	306.60
		Gross Labour Cost (S\$)	948.93	801.93

Report was unsubmitted during this print-out.

< END OF ESTIMATES >