

ASS. REC. BY:

REF: CS/ALH18005938 / Arb n2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person):

Darshene Supramaniam

ALH

Date/Time:

29/03/2018 3:59 pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJC 1205K

Insured:

SLB 8808G

at Workshop m/s

YSK Auto

Tel:

9640 2544

of

No. 1 Kaki Bukit Ave 6 #01-71

Policy No:

1800021914

Claim No:

3071323946 SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

28/03/2018

(Client's Record)

02/04/2018

@

90075148 -

Ah Chai

CA / REV / REP. / REV 24 HRS 'Wp'

H.O.D. Endorsement:

Date/Time:

29/03/2018 4:26 pm

Person Contacted:

Danny

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJC 1205K - x
	SLB 8808G - x
31/8/18	@ 11:21 am Danny said pending Adrian finalise
12/9/18	Adrian confirmed LS \$ 5,500 = (Recd 8057.73, 59/0)

Summary

REF:

AIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJC 1205K
 at Workshop m/s YSL Auto
 of No. 1 Kaki Bukit Ave 6 #01-71
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJC 1205K Yr Regn: 12 / 17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Voxy Hybrid C.C. 1797
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 6988 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZWR800 27 7772
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 175/65R15
 R: 175/65R15
 BS / DUN / EXNOVA (GY) / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A.		D.O.I. <u>02/07/18</u>	

Survey held at YSL

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPALG.

RECEIVED 13 SEP 2018

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 12/9- typist

Report Format : merimen

Lump Sum / I.B.I: (\$) 5500/2

Days Of Repair: 7

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: 250

20 S - RS St

Photos

Others

TOTAL

270



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18005938/Avb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 02-04-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 8808G	Veh. Inspected	SJC 1205K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	DARSHENE SUPRAMANIAM	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/03/2018	Inspection Date	02/04/2018
Survey held at	Y S K AUTO WORKSHOP 1 KAKI BUKIT AVE 6 AUTOBAY #01-71 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018 Edit Reg		02 Apr 2018 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Foong Boon Tat (Hong Wenda)		
Main Claimant:	TAN EU JIN (CHEN YOUJUN)		
Vehicle Reg. No.:	SJC1205K	Date of Loss:	28/03/2018 00:00 - :59
Claim Type:	TP / 3071323946SG	Policy/Cover Note No.:	1800021914 (Comprehensive) Coverage: 02/03/2018 - 28/02/2019
Vehicle Reg. No. (Insured):	SLB8808G	Policy No. (Claimant):	
		Excess:	
Repairer:	Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-71 Autobay, 417883 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Mohd-Rasheed, Rashidah - 64191767] Rashidah.Mohamedrasheed@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 11/04/2018]		
Claimant's Solicitor:	CENTRO-LEGAL LAW CORPORATION - Tel: 6235 0633		

ASSOCIATED MAIL RECEIVED

View All Compose Case Mail

- AIG_SG (03/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS

View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Catherine Chong (LKK Auto)

From: Supramaniam, Darshene <Darshene.Supramaniam@aig.com>
Sent: Thursday, 29 March, 2018 3:59 PM
To: 'admin-a@lkkauto.com'; assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB8808G & SJC1205K ON 28 MARCH 2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLB88... (38.1 KB); PRI - AIG-YSK (DANNY).docx
Importance: High

Hi,

Please refer to the enclosed request from **Centro-Legal Law Corporation Advocates & Solicitors**.

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Ma Chin Fook** as Single Joint Expert as requested.

Thank you.

Best Regards,

Darshene Supramaniam

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto

Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang. 55100 Kuala Lumpur, Malaysia

Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Your ref : SLB8808G (To be advised)

Our ref : CLLC.0280.2018

29th March 2018

AIG ASIA PACIFIC INSURANCE PTE LTD

BY FAX & HAND

78 Shenton Way
#07-16 AIG Building
Singapore 079120
Fax: 6835 7416

Attn: **Officer-In-Charge**

Dear Sirs,

**NOTICE TO INSURANCE TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2
WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION
PROTOCOL FOR NIMA CASE**

We act for TAN EU JIN (CHEN YOUJUN), the owner of motor vehicle SJC1205K who has appointed us to act on his behalf to claim against your insured's vehicle no SKB8808G in regards to the road traffic accident on 28.03.2018.

Please be informed that the said motor vehicle can be inspected at:-

YSK AUTO WORKSHOP

No. 1 Kaki Bukit Ave 6
#01-71 AutoBay, Singapore 417883
Tel: 9640 2541 Fax: 6556 0801
Email: dannyseyo@gmail.com

Kindly contact Danny Yeo HP: 96402541

Please note that if you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

CENTRO-LEGAL LAW CORPORATION

Cc **Mr Danny Yeo**
FAX NO: 6556 0801

UEN NO.201302032G

CENTRO-LEGAL LAW CORPORATION is incorporated as a company in Singapore

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4987H
Vehicle Details	
Vehicle No.:	SJC1205K
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Sep 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VOXY HYBRID V 1.8 CVT
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	2ZR0A16380
Chassis No.:	ZWR800277772
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,552.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$7,573.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$5,679.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,002.00
COE Rebate Amount:	\$43,590.00
Total Rebate Amount:	\$49,269.00

The information contained herein is correct as at 12 Sep 2018

OK

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SJC1205K		
Vehicle Type :	P11 - Passenger Station Wagon/Jeep/Land Rover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	VOXY HYBRID V 1.8 CVT		
Chassis No. :	ZWR800277772		
Propellant :	Petrol-Electric		
Engine No. :	2ZR0A16380		
Motor No. :	317H04958		
Engine Capacity :	1797 cc		
Power Rating :	60.0 kW		
Maximum Power Output :	100.0 kW (134 bhp)		
Maximum Laden Weight :	2005 kg		
Unladen Weight :	1620 kg		
Year Of Manufacture :	2017		
Original Registration Date :	22 Dec 2017		
Lifespan Expiry Date :	-		
COE Category :	B - Car above 1600cc or 97kW (130bhp)		
Quota Premium :	\$47,002.00		
COE Expiry Date :	21 Dec 2027		
Road Tax Expiry Date :	21 Dec 2018		
PARF Eligibility Expiry Date :	21 Dec 2027		
Inspection Due Date :	21 Dec 2020		
Intended Transfer Date :	12 Sep 2018		
CO2 Emission :	94.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$30,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

ESTIMATE

YSK AUTO WORKSHOP

NO. 1 KAKI BUKIT AVE 6, #01-49 AUTOBAY

SINGAPORE 417883

Date: 07/05/2018

TPA 14

Veron

Vehicle No.: SJC1205K

Chassis: ZWR80-0277772

DESCRIPTIONS	QUANTITY	UNIT PRICE	AMOUNT
Parts			
Rear bumper <i>behind</i>	1	\$ 1,217.45	\$ 1,217.45 ✓
Rear bumper clip <i>new</i>	10	\$ 5.50	\$ 55.00 <i>30</i>
Rear bumper side retainer RH (short) <i>band</i>	1	\$ 132.25	\$ 132.25 ✓ <i>15.00</i>
Rear bumper side retainer LH (short) <i>new</i>	1	\$ 132.25	\$ 132.25 ✓
Rear bumper side retainer RH (long) <i>band</i>	1	\$ 141.45	\$ 141.45 ✓
Rear bumper side retainer LH (long) <i>new</i>	1	\$ 141.45	\$ 141.45 ✓
Rear bumper reflector RH <i>no new</i>	1	\$ 182.10	\$ 182.10 ✓
Rear bumper reflector LH <i>new</i>	1	\$ 182.10	\$ 182.10 ✓
Tail gate <i>Distorted</i>	1	\$ 1,855.35	\$ 1,855.35 ✓
Tail gate weatherstrip <i>it</i>	1	\$ 374.45	\$ 374.45 ✓
Tail gate lock <i>Damaged</i>	1	\$ 381.90	\$ 381.90 ✓
Tail gate striker <i>not new</i>	1	\$ 61.10	\$ 61.10 ✓
Tail gate "Toyota" logo <i>not new</i>	1	\$ 121.25	\$ 121.25 ✓
Tail gate chrome - bottom <i>behind</i>	1	\$ 132.10	\$ 132.10 ✓
Tail gate trimboard <i>new new</i>	1	\$ 974.45	\$ 974.45 ✓
Tail gate trimboard clip	10	\$ 5.50	\$ 55.00 ✓
Tail lamp RH <i>cracked</i>	1	\$ 581.45	\$ 581.45 ✓
Tail lamp RH lower panel <i>behind</i>	1	\$ 671.45	\$ 671.45 <i>525</i>
Rear fender RH <i>repair</i>	1	\$ 1,218.45	\$ 1,218.45 ✓
Rear fender trimboard RH <i>cracked</i>	1	\$ 974.45	\$ 974.45 <i>681</i>
Rear fender trimboard clip <i>new</i>	8	\$ 5.50	\$ 44.00 <i>30</i>
Rear fender lining clip <i>new</i>	8	\$ 5.50	\$ 44.00 ✓
Rear end panel <i>repair</i>	1	\$ 781.10	\$ 781.10 ✓
Rear end panel garnish <i>behind</i>	1	\$ 374.40	\$ 374.40 ✓
Rear air-con cooling coil assy <i>not new</i>	1	\$ 2,821.35	\$ 2,821.35 ✓
			\$ 13,650.30
		Less 25%	\$ 3,412.58
		Sub-Total 1	\$ 10,237.73
Special Nett			
Reverse sensor (set) <i>Damaged</i>	1	\$ 280.00	\$ 280.00 <i>200</i>
Sealant <i>new new</i>	1	\$ 80.00	\$ 80.00 ✓
		Sub-Total 2	\$ 360.00
Labour			
Rewiring			\$ 60.00 <i>30</i>
Panel beating to remove and replace, to knock and reshape damaged parts & areas.			\$ 1,000.00 <i>800</i>

DESCRIPTIONS	QUANTITY	UNIT PRICE	AMOUNT
To putty and spray paint the repaired parts, cleaning and sanding of surfaces, final polishing and waxing.		\$	1,000.00 800
Anti-rust undercoating.		\$	90.00 X
To remove and refit tail gate glass.	1 830	\$	150.00 120
Remove and refit rear fender quarter glass RH.		\$	120.00 X
Remove and replace air-con cooling coil.		\$	280.00 X
Remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.		\$	260.00 80
Sub-Total 3		\$	2,960.00
Total repair cost		\$	13,557.73

total: 687260

L/S: S.S.K.

07 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature: _____
Date: _____

S.S.K.
07 Days.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18005938/AVBN2

Date: 18/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800021914
 Claimant Vehicle No: SJC1205K Insured Vehicle No: SLB8808G
 Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: 3071323946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJC1205K Engine No: 2ZR0A16380
 Make & Model: TOYOTA VOXY HYBRID, 1.8 (A) Chassis No: ZWR800277772
 Reg. Date: 22/12/2017 (Man. Year: 2017) Odometer: 6988 km
 Colour: Black
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,597.72	5,042.60	5,555.12	52.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,830.00	1,130.00	38.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,557.72	6,872.60	6,685.12	49.31
Approved Total (Overridden) (\$\$)		5,500.00		
Nett Amount (\$\$)	13,557.72	5,500.00	8,057.72	59.43

INSPECTION

Date of Assignment: 29/03/2018
 Date Inspected: 02/04/2018 Inspected At: Ysk Auto Workshop (HQ)
 No.1 Kaki Bukit Avenue 6, #01-71
 Autobay
 Singapore 417883
 Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,217.45 FL	*1,217.45 FL
2	10		*REAR BUMPER CLIP	Necessary	55.00 FL	*30.00 FL
3	1		*REAR BUMPER SIDE RETAINER RH (SHORT)	Damaged	132.25 FL	*132.25 FL
4	1		*REAR BUMPER SIDE RETAINER LH (SHORT)	Not Necessary	132.25 FL	*- FL
5	1		*REAR BUMPER SIDE RETAINER RH (LONG)	Damaged	141.45 FL	*141.45 FL
6	1		*REAR BUMPER SIDE RETAINER LH (LONG)	Not Necessary	141.45 FL	*- FL
7	1		*REAR BUMPER REFLECTOR RH	Not Necessary	182.10 FL	*- FL
8	1		*REAR BUMPER REFLECTOR LH	Not Necessary	182.10 FL	*- FL
9	1		*TAIL GATE	Distorted	1,855.35 FL	*1,855.35 FL
10	1		*TAIL GATE WEATHERSTRIP	Cut	374.45 FL	*374.45 FL
11	1		*TAIL GATE LOCK	Damaged	381.90 FL	*381.90 FL
12	1		*TAIL GATE STRIKER	Not Necessary	61.10 FL	*- FL
13	1		*TAIL GATE TOYOTA LOGO	Not Necessary	121.25 FL	*- FL
14	1		*TAIL GATE CHROME-BOTTOM	Deformed	132.10 FL	*132.10 FL
15	1		*TAIL GATE TRIMBOARD	Not Necessary	974.45 FL	*- FL
16	10		*TAIL GATE TRIMBOARD CLIP	Not Necessary	55.00 FL	*- FL
17	1		*TAIL LAMP RH	Cracked	581.45 FL	*581.45 FL
18	1		*TAIL LAMP RH LOWER PANEL	Deformed	671.45 FL	*525.00 FL
19	1		*REAR FENDER RH	Repair	1,218.45 FL	*- FL
20	1		*REAR FENDER TRIMBOARD RH	Cracked	974.45 FL	*681.00 FL
21	8		*REAR FENDER TRIMBOARD CLIP	Necessary	44.00 FL	*30.00 FL
22	8		*REAR FENDER LINING CLIP	Not Necessary	44.00 FL	*- FL
23	1		*REAR END PANEL	Repair	781.10 FL	*- FL
24	1		*REAR END PANEL GARNISH	Deformed	374.40 FL	*374.40 FL
25	1		*REAR AIR-CON COOLING COIL ASSY	Not Necessary	2,821.35 FL	*- FL
26	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*200.00 FS
27	1		*SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,010.30	6,656.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	3,412.58	1,614.20
Total Parts (\$\$)	10,597.72	5,042.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REWIRING	New	60.00	30.00
2	PANEL BEATING TO REMOVE AND REPLACE, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS	New	1,000.00	800.00
3	TO PUTTY AND SPRAY PAINT THE REPAIRED PARTS, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING	New	1,000.00	800.00
4	ANTI-RUST UNDERCOATING	New	90.00	-
5	TO REMOVE AND REFIT TAIL GATE GLASS	New	150.00	120.00
6	REMOVE AND REFIT REAR FENDER QUARTER GLASS RH	New	120.00	-
7	REMOVE AND REPLACE AIR-CON COOLING COIL	New	280.00	-
8	REMOVE AND REFIT REAR SEATS, REAR WHEELHOUSE INNER GARNISH, FLOOR CARPET & UPHOLSTERY TO FACILITATE REPAIRS	New	260.00	80.00
Gross Labour Cost (S\$)			2,960.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >