

22/03/2002

ASS. REC. BY:

REF: CS/SMD18005946/Gqbnz

Special Instruction:

Surveyor:

(12)

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMD

Date/Time:

29032018 4.08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGS 3056L

Insured:

FS 4742U

at Workshop m/s

Ryder Auto

Tel:

90908777 Orson

of

Bldg 1 Kaki Bukit Ave 6 #01-56

Policy No:

Claim No:

CMTD1801383/AGC

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29032018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

02 04 2018 @ morning

H.O.D. Endorsement:

Date/Time:

29032018 4.10pm

Person Contacted:

June

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGS 3056L - NA/LIP 18005361/KU DA: 29032018
	FS 4742U - NS/CNC 12006291/Hlgm DA: 28032012
04/4/18 @ 2.15pm	informed Agnes, we have pending estimate from repairer.
03/4/18 @ 12.03pm	revised to Agnes Chan by email.
20/4/18 @ 12.37pm	confirmed with Orson is to 4800, 5 days by email.
	(Red B 10813.70, 6.9%.)

REF:

SMD

2188

(-2022)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SAS 3056L

at Workshop m/s Ryder Auto.

of 1 Kaki Bukit Ave 6 #01-56.

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGS 3056L

Yr Regn:

12 Mar 2007

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Yaris

C.C.

1497

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

147897

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR054HY910 4020718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F:

205/45R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

02-04-18

Survey held at

w/s

12:15pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 SEP 2010

Date/Time, File Pass to?



Prefi. Report

1) 21/9 4:30pm



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S+RS \$

) Photos

) Others

)

TOTAL

450

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Weekend (\$

Report Format:

TP

Lump Sum / I.B. (\$

480



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18005946/Gqb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-04-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FS 4742U	Veh. Inspected	SGS 3056L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801383/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	29/03/2018	Inspection Date	02/04/2018
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1801383/AGC

Date: 03rd September 2018

Our Ref: CS/SMO18005946/Gqb

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SGS 3056L


We thank you for the instruction on 29/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 02/04/2018 at the premises of M/s RYDER AUTO and have the following to report:-

Workshop Estimate Amount	: S\$ <u>15,613.70</u>
Revised Estimate Amount	: S\$ <u>8,027.30</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorized repair.

Yours faithfully

Guo Qiang
Automobile Assessor

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 29 March, 2018 4:08 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Ryder Auto workshop; Chan, Shu Hui Agnes
Subject: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018
Attachments: RYDER.pdf

Our Reference: CMTD1801383/AGC

Dear LKK AUTO/ Marcus,

Please make arrangement to conduct the survey for SGS3056L.

Please be informed that Agnes Chan the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ryder Auto workshop [mailto:ryderautoworkshop@gmail.com]

Sent: Thursday, March 29, 2018 3:54 PM

To: Teo, Grace

Subject: Re: CMTD1801383/AGC - PRI/ FS4742U & SGS3056L ON 29.03.2018

Please arrange marcus chua of lkk.

Tks

san choon

On Thu, 29 Mar 2018, 15:44 Teo, Grace, <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD1801383/AGC
Your Reference: SGS3056L

Without Prejudice

Date: 29th March 2018

Attention:
RYDER AUTO PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING FS4742U & SGS3056L ON 29.03.2018

We refer to your Notice of Accident dated 29/03/2018.

Please be informed that Agnes Chan the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

Shiau Chan (LKKAuto)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Monday, 3 September 2018 1:19 PM
To: Shiau Chan (LKKAuto)
Subject: Re: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018
Attachments: 3056L(330)SGS SG CAR MART.PNG

Please see attached sgccarmart screenshot.

The record of the market value on 29/3/18 shows \$24,000 for September 2006 Yaris. Ours is March 2007 Yaris. Therefore, accordingly it should be \$27,000 after adding in 6 months of depreciation..

Please adjust your repair limit to \$7,800 and the lump sum repair to the same amount.

rgds

san choon
Director
mobile 97924673



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Mon, Sep 3, 2018 at 12:17 PM, Ryder Auto workshop <ryderautoworkshop@gmail.com> wrote:
rcvd with tks



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Mon, Sep 3, 2018 at 11:55 AM, Shiao Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear San Choon,

As per your requested.

Best Regards,

Shiao Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Guo Qiang (LKKAuto)

Sent: Monday, 3 September 2018 9:36 AM

To: ryderautoworkshop@gmail.com

Cc: Shiao Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Hi ,

Market value \$24000. Repair limit \$4800.

Regards,

Guo Qiang

From: Shiao Chan (LKKAuto)

Sent: Monday, 3 September, 2018 9:30 AM

To: Guo Qiang (LKKAuto)

Subject: FW: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Guo Qiang,

Shiau Chan (LKKAUTO)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Monday, 3 September 2018 9:26 AM
To: Shiau Chan (LKKAUTO)
Subject: Re: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

No need for me to contact surveyor. He must put it in this email to show me how he calculated the repair limit. I want this to be on record



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Mon, Sep 3, 2018 at 9:22 AM, Shiau Chan (LKKAUTO) <siewsc@lkkauto.com> wrote:

Dear San Choon,

This amount is advise by our surveyor. Or you want direct contact our surveyor for discuss.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Monday, 3 September 2018 9:18 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 3 September 2018 12:03 PM
To: 'Teo, Grace'; assignments; 'Chan, Shu Hui Agnes'
Cc: SUR
Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018
Attachments: CSSMO18005946Gqb.pdf

Dear Agnes,

Enclosed herewith preliminary advice of SGS 3056L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 April 2018 2:15 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Agnes,

Please be informed that we have inspected the vehicle SGS 3056L on 02/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 29 March 2018 4:18 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Grace,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer arrange survey on 02.04.2018.

Best Regards,

Catherine Chong | Admin

Shiau Chan (LKKAuto)

From: Ryder Auto workshop <ryderautoworkshop@gmail.com>
Sent: Thursday, 20 September 2018 12:32 PM
To: Shiau Chan (LKKAuto)
Cc: Guo Qiang (LKKAuto)
Subject: Re: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Shiau Chan,

We gladly accept the offer Lump Sum \$4,800.00 and 5 repair days , kindly advise when to LOD LKK.

Thank You

Best regards

Orson



1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Fax: 64815390



5 Tuas Ave 3 BS Logistics Hub Singapore 639405
Fax: 64815390



On Thu, Sep 20, 2018 at 11:43 AM, Shiau Chan (LKKAuto) <siewsc@lkkauto.com> wrote:

Dear Orson,

Please find the attached of our surveyor's marking.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 4 April 2018 2:15 PM
To: 'Teo, Grace'; assignments; 'Chan, Shu Hui Agnes'
Cc: SUR
Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Agnes,

Please be informed that we have inspected the vehicle SGS 3056L on 02/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 29 March 2018 4:18 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Chan, Shu Hui Agnes' <agnes.chan@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Dear Grace,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer arrange survey on 02.04.2018.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Thursday, 29 March, 2018 4:08 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Ryder Auto workshop <ryderautoworkshop@gmail.com>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>
Subject: CMTD1801383/AGC - SUV/ FS4742U & SGS3056L ON 29.03.2018

Our Reference: CMTD1801383/AGC

Dear LKK AUTO/ Marcus,

Please make arrangement to conduct the survey for SGS3056L.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2118Z
Vehicle Details	
Vehicle No.:	SGS3056L
Vehicle to be Exported:	No
Intended De-registration Date:	04 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	YARIS E AUTO
Primary Colour:	Silver
Manufacturing Year:	2006
Engine No.:	1NZX500369
Chassis No.:	MR054HY9104020718
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,933.00
Original Registration Date:	12 Mar 2007
First Registration Date:	12 Mar 2007
Transfer Count:	2
Actual ARF Paid:	\$16,427.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Mar 2022
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$19,453.00
Total Rebate Amount:	\$19,453.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 04 Apr 2018

OK

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883
Email: ryderautoworkshop@gmail.com
Fax: 64815390

WITHOUT PREJUDICE

Veh # : SGS3056L Model : TOYOTA YARIS E AUTO

Date Of Accident: 29/3/2018

Location : BKE TOWARDS PIE BEFORE KJE EXIT ON LANE 3

Qty	List Items	Description	Amount \$
1 pc	Rear bumper / RE	/	469.80
10 pcs	Rear bumper clips / MCL	/	38.00
2 pcs	Rear bumper o/s & n/s corner clips X MCL NN	X	182.10
2 pcs	Rear bumper o/s & n/s stay X NN	X	264.50
2 pcs	Rear bumper o/s & n/s retainer / MCL	/	175.20
1 pc	Rear bumper spoiler (lower) / CPA	/	1,620.00
1 pc	Rear tail-gate lower panel X BUC	/	426.20
1 pc	Rear tail-gate lower panel inner trim X / RE	/	226.00
4 pcs	Rear tail-gate lower panel inner trim clips X MCL	/	15.20
1pc	Rear tail-gate / BUC	/	1,020.00
1 pc	Rear tail-gate weather-strip X - Twi	/	201.60
1 pc	Rear tail-gate emblem / MCL	/	61.40
1 pc	Rear tail-gate YARIS emblem / MCL	/	58.20
1 pc	Rear tail-gate E emblem / MCL	/	38.20
1 pc	Rear tail-gate lock (upper) X - BT	/	422.60
1 pc	Rear tail-gate lock (lower) X / MCL	X	101.20
1 pc	Rear tail-gate lock (Outer) X / MCL	X	289.60
1 pc	Rear tail-gate inner trim X / MCL	X	301.20
12 pcs	Rear tail-gate inner trim clips X X / MCL	X	45.60
2 pcs	Rear tail-gate o/s & n/s shock absorber X / MCL	X	428.20
2 pcs	Rear tail-gate o/s & n/s stopper X / MCL	X	87.10
1 pc	Rear boot floor X Repair	X	992.20
1 pc	Rear spare wheel board cover X / MCL	/	303.60
1 pc	Rear n/s fender inner board X / MCL	/	426.20
6 pcs	Rear n/s fender inner board clips X / MCL	/	22.80

Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: ryderautoworkshop@gmail.com

Fax: 64815390

4001.8
25%: 3001.25

2 pcs	Rear o/s & n/s tail-lamp	X - CFA	/	684.10	R /
4 pcs	Rear o/s & n/s tail-lamp clips	X	X	15.20	
2 pcs	Rear o/s & n/s tail-lamp sealant	X	X	100.00	
1 pc	Rear reg. no. plate lamp	X	X	202.70	
1 pc	Rear reg. no. plate bracket (inner)	X	X	62.00	
1 pc	Rear boot floor insulator	X	X	120.00	NF
1 set	Rear windscreen moulding	/ MC	/	268.20	103.1
16 pcs	Rear windscreen moulding clips	X NN	X	60.80	
				9,729.70	

Special Nett Items

1pc	Rear windscreen inner seal	/ MC	/	50.00	20
1pc	Rear windscreen sealant	X NN	X	60.00	
1 pc	Rear reg. no. plate	/ CFA	/	45.00	40
1 pc	Rear reg. no. plate bracket (outer)	X NN	X	29.00	
1 set	Rear reverse sensor	/ PM	/	380.00	200
				564.00	260

Labour

1	To remove, straighten & welding above parts		2,200.00	1500	400
2	To spray painting (metallic paint)		1,800.00	1000	600
3	To re-align rear chassis frame		380.00		X NN
4	To remove & refit rear windscreen		180.00		120
5	To remove & replace rear tail-gate		200.00		60
6	To remove & replace rear reverse sensor		180.00		40
7	To check wiring		100.00		30
8	To re-seal anti-rust		280.00		80
			5,320.00		
	Total		15,613.70		1690

5 Days.

Lumpsum repair
After repair photos.

Guo Qiao.

02/4/18

601 557.75

2%: 4200 4800

29/8/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18005946/Gqbn2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 26-09-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FS 4742U	Veh. Inspected	SGS 3056L
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1801383/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	29/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA YARIS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR054HY9104020718	Colour	SILVER
Odometer	147897	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/45 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/45 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/45 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/03/2018	Inspection Date	02/04/2018
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGS 3056L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	469.80	469.80
10	REAR BUMPER CLIPS	NECESSARY	38.00	38.00
2	REAR BUMPER O/S & N/S CORNER CLIPS	NOT NECESSARY	182.10	-
2	REAR BUMPER O/S & N/S STAY	NOT NECESSARY	264.50	-
2	REAR BUMPER O/S & N/S RETAINER	NECESSARY	175.20	110.00
1	REAR TAIL-GATE LOWER PANEL	BUCKLED	426.20	426.20
1	REAR TAIL-GATE LOWER PANEL INNER TRIM	DEFORMED	226.00	226.00
4	REAR TAIL-GATE LOWER PANEL INNER TRIM CLIPS	NECESSARY	15.20	15.20
1	REAR TAIL-GATE	BUCKLED	1,020.00	750.00
1	REAR TAIL-GATE WEATHER-STRIP	TWISTED	201.60	201.60
1	REAR TAIL-GATE EMBLEM	NECESSARY	61.40	61.40
1	REAR TAIL-GATE YARIS EMBLEM	NECESSARY	58.20	58.20
1	REAR TAIL-GATE E EMBLEM	NECESSARY	38.20	38.20
1	REAR TAIL-GATE LOCK (UPPER)	BENT	422.60	236.00
1	REAR TAIL-GATE LOCK (LOWER)	NOT NECESSARY	101.20	-
1	REAR TAIL-GATE LOCK (OUTER)	NOT NECESSARY	289.60	-
1	REAR TAIL-GATE INNER TRIM	NOT NECESSARY	301.20	-
12	REAR TAIL-GATE INNER TRIM CLIPS	NOT NECESSARY	45.60	-
2	REAR TAIL-GATE O/S & N/S SHOCK ABSORBER	NOT NECESSARY	428.20	-
2	REAR TAIL-GATE O/S & N/S STOPPER	NOT NECESSARY	87.10	-
1	REAR BOOT FLOOR	TO REPAIR SEE LABOUR	992.20	-
1	REAR SPARE WHEEL BOARD COVER	CRACKED	303.60	135.00
1	REAR N/S FENDER INNER BOARD	CRACKED	426.20	426.20
6	REAR N/S FENDER INNER BOARD CLIPS	NECESSARY	22.80	22.80
2	REAR O/S & N/S TAIL-LAMP	CRACKED	684.10	684.10
4	REAR O/S & N/S TAIL-LAMP CLIPS	NOT NECESSARY	15.20	-
2	REAR O/S & N/S TAIL-LAMP SEALANT	NOT NECESSARY	100.00	-
1	REAR REG.NO. PLATE LAMP	NOT NECESSARY	202.70	-
1	REAR REG.NO. PLATE BRACKET (INNER)	NOT NECESSARY	62.00	-
1	REAR BOOT FLOOR INSULATOR	NOT FITTED	120.00	-
1	SET REAR WINDSCREEN MOULDING	NECESSARY	268.20	103.10
16	REAR WINDSCREEN MOULDING CLIPS	NOT NECESSARY	60.80	-

Report Ref No. CS/SMO18005946/Gqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 25% DISCOUNT		-	-1,000.45
			8,109.70	3,001.35
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SPOILER (LOWER)(SN)	CRACKED	1,620.00	600.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	20.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR REG.NO.PLATE (SN)	CUT	45.00	40.00
1	REAR REG.NO.PLATE BRACKET (OUTER)(SN)	NOT NECESSARY	29.00	-
1	SET REAR REVERSE SENSOR (SN)	DAMAGED	380.00	220.00
			2,184.00	880.00
	<u>LABOUR</u>			
	TO REMOVE,STRAIGHTEN & WELDING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BOOT FLOOR.		2,200.00	800.00
	TO SPRAY PAINTING (METALLIC PAINT).		1,800.00	1,000.00
	TO RE-ALIGN REAR CHASSIS FRAME.	NOT NECESSARY	380.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		180.00	120.00
	TO REMOVE & REPLACE REAR TAIL-GATE.		200.00	60.00
	TO REMOVE & REPLACE REAR REVERSE SENSOR.		180.00	40.00
	TO CHECK WIRING.		100.00	30.00
	TO RE-SEAL ANTI-RUST.		280.00	80.00
			5,320.00	2,130.00
	GRAND TOTAL		15,613.70	6,011.35
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,800.00

Report Ref No. CS/SMO18005946/Gqbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.