

Claim Reference:

Full Report - V1

Assessment Number: LHM61039


Registration: SGN 9919J

Version: LKKAUTOC/2


Printed: 30/08/2018 11:50

Date Calculated: 30/08/2018 04:50

Damage Areas:



Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$2,704.80
Total Paint/Material	\$405.19
Total Parts	\$17,506.00
Total of Additional Costs	\$350.00
Repair Cost Exc GST:	\$20,965.99
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,500.00
After Deduction -	
Grand Total Exc GST:	\$19,465.99
7 % GST:	\$1,362.62
Grand Total Inc GST:	\$20,828.61

Repair Information**LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair /**Guide Number Repair Details**

		WU	Cost Price (\$)
40-6500 01	ALIGN VEHICLE	9.0	37.80
	DOES NOT INCLUDE: ADJUSTMENTS		
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	37.80
60-1331 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT (FOR RENEWAL OF THE FRONT MODULE) INCLUDES: R + R CHARGE AIR COOLER IF NECESSARY	8.0	33.60
88-1964 02	ADD/WORK R + R FRONT MODULE (VEHICLE WITH HEADLAMP WASHER)	2.0	8.40
88-1102 03	R + R COMPLETE FRONT BUMPER INCLUDES: R + R L/F AND R/F PARTITION AND FOG LAMPS	9.0	37.80
88-1105 03	DIS + ASS FRONT BUMPER (REMOVED) INCLUDES: R + R FOG LAMPS, RENEW PARTS AFTER CHECK	7.0	29.40
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	8.40
88-2506 02	RENEW BONNET INCLUDES: R + R BONNET, CONVERT ALL PARTS	18.0	75.60
88-2652 02	RENEW RIGHT BONNET HINGE	3.0	12.60

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore**Claim Reference:****Full Report - V1****Assessment Number: LHM61039****Registration: SGN 9919J****Version: LKKAUTOC/2****Printed: 30/08/2018 11:50****Date Calculated: 30/08/2018 04:50**

60-2297 01	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)	4.0	16.80
62-1270 01	RENEW RADIATOR CARRIER (STRIPPED)	3.0	12.60
20-1140 02	DRAIN + REFILL COOLANT	6.0	25.20
09-6820 03)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	3.0	12.60
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	7.0	29.40
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	25.20
83-6523 03	R + R AIR CONDITIONING FLUID RESERVOIR, RENEW AFTER CHECK	4.0	16.80
83-6545 01	CONDENSER REMOVE AND REFIT/RENEW (RADIATOR REMOVED)	3.0	12.60
61-1091 02	R + R R/ENGINE COMPARTMENT SIDE COVER	3.0	12.60
83-7825 ZAX	RENEW REFRIGERANT PIPE	3.0	12.60
83-7805 ZAX	RENEW REFRIGERANT PIPE A	3.0	12.60
20-6461 01	R + R FAN UNIT	7.0	29.40
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	63.00
82-7200 02	R + R WASHER RESERVOIR	5.0	21.00
88-5205 02	R + R L/SILL SIDEMEMBER TRIM	6.0	25.20
88-5232 02	R + R R/SILL SIDEMEMBER TRIM	6.0	25.20
88-8802 03	R + R REAR BUMPER INCLUDES: R + R REAR CENTREPIECE PANELLING	7.0	29.40
88-8805 03	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)	2.0	8.40
88-8883 02	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)	3.0	12.60
68-3055 02)	R + R R/BOOT TRIM	3.0	12.60
88-3501 01	R + R TAILGATE MERCEDES STAR	3.0	12.60
88-3512 01	RENEW TAILGATE BADGE	4.0	16.80
82-4903 03	R + R RIGHT REAR TAILLAMP	3.0	12.60
91-1042 01)	R + R L/F SEAT BELT	2.0	8.40
91-1012 01)	R + R R/F SEAT BELT	2.0	8.40
91-5414 02	R + R R/R SEAT BACKREST	7.0	29.40
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
91-1097 01)	R + R RIGHT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
68-4605 01	R + R INSTRUMENT PANEL	25.0	105.00
68-4635 01	RENEW INSTRUMENT PANEL (REMOVED)	7.0	29.40
68-4727 01	R + R L/LOWER INSTRUMENT PANEL COVER	2.0	8.40
68-4910 01	ADDITION TO R + R GLOVE BOX (VEHICLE WITH CD CHANGER)	1.0	4.20
68-4745 01	R + R L/INSTRUMENT PANEL COVER	1.0	4.20
68-1093 01	R + R L/B-PILLAR TRIM	5.0	21.00
68-1093 01	R + R R/B-PILLAR TRIM	5.0	21.00
68-1110 02	R + R LEFT C-PILLAR TRIM	5.0	21.00
68-1110 02	R + R RIGHT C-PILLAR TRIM	5.0	21.00
91-2162 01)	R + R PASSENGER AIRBAG UNIT	3.0	12.60

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LKKAUTOC/2

Printed: 30/08/2018 11:50

Date Calculated: 30/08/2018 04:50

91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	75.60
22-1260 02)	RENEW F/ENGINE MOUNTS ASS WORK	3.0	12.60
22-1268 01	RENEW FRONT ENGINE SUSPENSION BEARING	5.0	21.00
NO NUMBER	R + R ENGINE COVER	3.0	12.60
09-1030 01	R + R AIR FILTER CPL	5.0	21.00
09-8680 01)	R + R L/AIR CHANNEL	4.0	16.80
33-1835 01)	R + R FRONT AXLE CARRIER	38.0	159.60
33-1840 01	RENEW FRONT AXLE CARRIER (REMOVED)	7.0	29.40
	INCLUDES : R + R ALL ATTACHED PARTS AND RENEW ACCORDING TO CONDITION		
32-2050 01	R + R FRONT STABILIZER	14.0	58.80
49-5585 02	R + R PRIMARY CATALYST (ADD/WORK)	20.0	84.00
9973	CARRY OUT TEST DRIVE	5.0*	21.00
2102	REPAIR R/SILL PANEL	15.0*	63.00
2237	REPAIR L/A-PILLAR PANEL	10.0*	42.00
2931	REPAIR TAILGATE	15.0*	63.00
3482	REPAIR R/R WING	40.0*	168.00
1000	REPAIR WIRING + SUPPLY CONNECTOR	20.0*	84.00

LABOUR COST

Total Work Units	475.0	
Panel / Mechanical Labour	46.6HRS	\$1,957.20
Visual Alignment Labour	0.9HRS	\$37.80
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	47.5HRS	\$1,995.00
Paint Labour	16.9HRS	\$709.80
Total Labour	64.4HRS	\$2,704.80

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- WATER BASED PAINT		
471	BONNET NEW PART PAINTING	24.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
2205	L/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2206	R/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	13.0	
1482	RIGHT FRONT DOOR REPAIR PAINTING <50%	17.0	
2102	R/SILL PANEL REPAIR PAINTING <50%	10.0	
2237	L/A-PILLAR PANEL REPAIR PAINTING <50%	8.0	
2931	TAILGATE REPAIR PAINTING <50%	22.0	
3482	R/R WING REPAIR PAINTING <50%	11.0	
1782	R/R DOOR SURFACE PAINT	8.0	

LABOUR COST - PAINT

TIME(PAINT)	143.0
Preparation Main Work Metal	21.0
Preparation Comp. Work Plastic	5.0

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LKKAUTOC/2

Printed: 30/08/2018 11:50

Date Calculated: 30/08/2018 04:50

Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	169.0	
Total Paintwork Labour	16.9HRS	\$709.80
MATERIAL COST - PAINT		Cost Price
New Part Painting		\$79.98
New Part Painting - Plastic K1R		\$178.09
Surface-/Blend Paint		\$22.16
Repair Painting		\$97.86
Material-Const Main Work Metal		\$18.10
Material-Const Comp. Work Plastic		\$9.00
Total Excluding Pearlescent Uplift		\$405.19
Pearlescent Uplift @ 0.0%		\$0.00
Total Paint Material Cost		\$405.19

PARTS

Price Valid: 01/06/2015

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1000	1	AIR CON DECAL	Renew		0%	18.00*
8391	1	AIR FILTER ASSY	266 090 0101		0%	173.00*
7751	1	AIR GUIDE PANEL	169 505 0930		0%	170.00*
1392	1	AIR INTAKE GRILLE	169 836 0018		0%	110.00*
471	1	BONNET	169 880 0257		0%	590.00*
1017	1	BONNET LANDING PANEL	169 620 1634		0%	410.00*
4483	1	COMPR-/CONDENS PIPE	169 830 1615		0%	142.00*
4485	1	COMPR/EXP VALVE PIPE	169 830 1815		0%	120.00*
4465	1	CONDENSER	169 500 1254		0%	560.00*
7445	1	DRIVER AIRBAG	164 860 1902 9051		0%	1,360.00*
7792	1	ELECTRIC FAN	169 820 3642		0%	880.00*
1000	1	ENG TOP CVR BUSH	Renew		0%	3.00*
8820	1	EXH PIPE/CATALYST	169 490 0619		0%	525.00*
7011	1	FRONT AXLE SUPPORT	169 620 0787		0%	1,085.00*
283	1	FRONT BUMPER	169 885 2825		0%	950.00*
8777	1	FRONT CENTRE TRIM	169 524 1430		0%	49.00*
8624	1	FRONT ENGINE SUPPORT	266 223 0604		0%	50.00*
7261	1	FRONT STABILISER	169 323 0965		0%	140.00*
432	1	FRONT STAR EMBLEM	207 817 0316		0%	33.00*
293	1	FRT BUMPER GRILLE	169 885 0123		0%	64.00*
8631	1	FRT ENGINE MOUNTING	169 240 1517		0%	50.00*
8633	1	FRT G-BOX RUBBER BRG	169 240 1517		0%	0.00F
320	1	FRT LWR BUMPER SUPP	169 885 0136		0%	111.00*
1001	1	FRT LWR CROSSMEMBER	169 620 1734		0%	375.00*
8888	1	GEARBOX OIL COOLER	169 500 0600		0%	585.00*
1000	1	HID WARNING DECALX2	Renew		0%	8.00*
9645	1	HIGH TONE HORN	006 542 4420		0%	93.00*
4331	1	INSTRUMENT PANEL	169 680 2287 9D84		0%	1,020.00*
8730	1	INTERCOOLER	169 500 0900		0%	505.00*
8737	1	L/CHARGE AIR HOSE	169 528 0582		0%	130.00*
303	1	L/F BUMPER GRILLE	169 885 1122		0%	45.00*
313	1	L/F BUMPER TRIM	169 885 1374		0%	59.00*
1393	1	L/F COVER	169 830 0375		0%	15.00*
637	1	L/F FOG LAMP	251 820 0756		0%	138.00*
4661	1	L/F SEAT BELT	169 860 8385		0%	295.00*

51 Ubi Avenue 1, #01-25 Paya Ubi Industrial Park Singapore

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LKKAUTOC/2

Printed: 30/08/2018 11:50

Date Calculated: 30/08/2018 04:50

7047	1	L/F TRACK CONT ARM	169 330 0907	0%	330.00*
559	1	L/HEADLAMP COVER	169 821 0336	0%	10.00*
2615	1	L/R BUMPER TRIM	169 885 1574	0%	72.00*
4841	1	L/R SEAT BELT	169 860 7985	0%	170.00*
2205	1	L/SILL PANEL COVER	169 611 1308	0%	180.00*
561	1	LEFT HEADLAMP ASSY	169 820 6961	0%	1,450.00*
493	1	LOWER BONNET LOCK	169 880 0560	0%	89.00*
4325	1	PASSENGER AIRBAG	169 860 0600	0%	1,110.00*
8228	1	R/ENGINE COVER	266 141 0121	0%	75.00*
304	1	R/F BUMPER GRILLE	169 885 1222	0%	45.00*
314	1	R/F BUMPER TRIM	169 885 1474	0%	59.00*
1394	1	R/F COVER	169 830 0275	0%	15.00*
638	1	R/F FOG LAMP	251 820 0856	0%	138.00*
4662	1	R/F SEAT BELT	169 860 6885	0%	295.00*
7048	1	R/F TRACK CONT ARM	169 330 1007	0%	330.00*
560	1	R/HEADLAMP COVER	169 821 0436	0%	10.00*
3012	1	R/R BADGE	202 817 2115	0%	52.00*
3282	1	R/R OUTER LAMP	169 820 2664	0%	180.00*
4842	1	R/R SEAT BELT	169 860 8085	0%	170.00*
2206	1	R/SILL PANEL COVER	169 611 1408	0%	180.00*
2622	1	R/STICKER REFLECTING	169 989 0285	0%	22.00*
1000	1	RAD COOLANT	Renew	0%	40.00*
1000	1	RAD SUPP BOLT	Renew	0%	12.00*
7761	1	RADIATOR	169 500 2103	0%	400.00*
7772	1	RADIATOR CROSSMEMBER	169 620 0485	0%	245.00*
2583	1	REAR BUMPER COVER	169 885 2138	0%	735.00*
476	1	RIGHT BONNET HINGE	169 880 0428	0%	42.00*
1000	1	SILL PNL CLIPS(B)	Renew	0%	24.00*
1000	1	SILL PNL CLIPS(W)	Renew	0%	30.00*
1000	1	SILL PNL CVR CLIPSX2	Renew	0%	8.00*
3010	1	STAR EMBLEM	221 758 0058	0%	24.00*
492	1	UPPER BONNET LOCK	169 880 0160	0%	18.00*
1000	1	WARNING DECAL - 1	Renew	0%	5.00*
1000	1	WARNING DECAL - 2	Renew	0%	3.00*
1435	1	W-WASHER BOTTLE	169 869 0320	0%	77.00*

f: OEM Parts

g: Original

h: Secondhand

p: Parallel

x: Exchange

Saving

Sub Total

Sundry Parts

Total Parts

(Fixed)

\$31.01

\$17,506.00

\$0.00

\$17,506.00

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
AIR CON GAS SPECIALIST		\$50.00
SRS CONTROL UNIT REPROGRAM	0%	\$120.00
SUNDRY PARTS SPECIALIST		\$100.00
Total Extras		\$350.00

Final Calculation

Total Parts

Labour

\$17,506.00

Claim Reference:

Full Report - V1

Assessment Number: LHM61039

Registration: SGN 9919J

Version: LKKAUTOC/2

Printed: 30/08/2018 11:50

Date Calculated: 30/08/2018 04:50

Total Panel/Mechanical	\$1,957.20	
Total Paintwork	\$709.80	
Total Visual Alignment work	\$37.80	
Total Labour		\$2,704.80
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$350.00	
Total of Additional Costs		\$350.00
Total Paint/Material Costs		\$405.19
Repair Costs Excludes GST		\$20,965.99
Deductions		
Deduction for Excess (Fixed)	-\$1,500.00	
Total Deductions		-\$1,500.00
Grand Total Excludes GST (After Deduction)		\$19,465.99
GST @ 7 %		\$1,362.62
Grand Total Includes GST (After Deduction)		\$20,828.61

Assessment Notes

Veron Chen (LKKAUTO)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, 29 August 2018 3:08 PM
To: Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: Finalisation - SGN 9919J / Mercedes Benz B200
Attachments: SGN 9919J.pdf; 2ebe650e-5719-444f-9747-a20e56ffccbb.jpg; 421527f5-235b-4f24-b278-22cfc9693e78.jpg; d0ac6f6f-4a0b-4bfb-9c2d-4b5ac8b3ce67.jpg; f44618d3-7874-43fb-be57-db490ba0da36.jpg

Dear Sir

For your confirmation, please:

- Parts: \$19,423.00
- SN: \$ 368.00
- L&P: \$ 3,217.09

Sub-total: \$23,008.09

LS -20%: (\$4601.62) = \$18,406.47

Lump sum: \$18,000.00 / Excess cost: \$1,500.00

Supporting document are enclosed for your reference. Photographs will send to you in separate email.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity
Singapore 575722
Tel: 64538110
Fax: 64596267

**LAI HUAT (MENG KEE)
MOTOR PTE LTD
SIN MING INDUSTRIAL
ESTATE SECTOR A
BLK 21 #01-58
SINGAPORE 575679**

Workshop

Claim Reference:
Assessment Number: LHM61039
Version: LAI HUAT/6
Date Calculated: 28/08/2018 10:10

Full Report - V1
Registration: SGN 9919J
Printed: 28/08/2018 17:11

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jenny Lim	Date of Incident:	22/03/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	China Taiping Insurance (S) Pt	Repairs Authorised:	TBA
Claim Reference:		Estimated Repair Time:	
Policy Number:	DMPCSN3099651701	Quote Due Date:	
Other Reference:	OD CLAIM	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	MERCEDES
Model:	B Class
Sub Model:	B 200 TURBO
Model Sheet Number:	322 44
Registration:	SGN 9919J
Registration Month:	
Registration Year:	
VIN Number:	WDD2452342J144783
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

Model Specs

FROM VIN J 136548	AIR CONDITIONING
WINDSCREEN	SMOKER PACKAGE
RAIN SENSOR	FRT/RR ELECT WINDOWS
INTERIOR LAMP PACK	PARKTRONIC SYSTEM
LIGHT-/VIEW PACKAGE	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CD	CD AUTO CHANGER
SOUND SYSTEM	BI-XENON HEADLAMPS
FOG LAMPS	LEATHER TRIM
MOBILE PREPARATION	SPORT PACKAGE
CHILD SEAT MOUNTING	ILLUM SUN VISORS
FRT SEAT LUGGAGE NET	DIPPING INT MIRROR
FR SEAT COMFORT PACK	ELEC ADJ DRIVER SEAT
ELECT PASSENGER SEAT	LUGGAGE COMP COVER
ST/WHEEL/LEV LEATHER	S/WHEEL TIP SWITCHES
AUTOM-GEAR VARIABLE	ADJ STEERING COLUMN
SPORTS SUSPENSION	TYRES 215/45 ZR 17
WHEELS 7J X 17 ALLOY	SPARE WHEEL
BLADE SUNROOF	TWO COAT METALLIC
WATER BASED PAINT	

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:
Steering:	Vehicle Status on
	Inspection:
Brakes Pedal Travel:	Date of Inspection:
Place of Inspection:	28/03/2018
Pre-Accident Damage:	

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/6

Date Calculated: 28/08/2018 10:10

Full Report - V1

Registration: SGN 9919J

Printed: 28/08/2018 17:11

Tyres Condition:

Tread Depth LHF:



Tread Depth LHR:

Damage Areas:

Tread Depth RHF:

Tread Depth RHR:

Direction of Impact:

**Addresses****Cost Summary**

Total Labour	\$2,826.60
Total Paint/Material	\$390.49
Total Parts	\$19,423.00
Total of Additional Costs	\$368.00
Repair Cost Exc GST:	\$23,008.09
Overall Discount (0.0%):	- \$0.00
Excess:	-\$1,500.00
After Deduction -	
Grand Total Exc GST:	\$21,508.09
7 % GST:	\$1,505.57
Grand Total Inc GST:	\$23,013.66

Repair Information**LABOUR**Time Basis 10 WU = 1 HR. Price/CL 1 = \$42.00/HR
Price/Dent = \$42.00/HR

Repair / Guide Number	Repair Details	WU	Cost Price (\$)
40-6500 01	ALIGN VEHICLE DOES NOT INCLUDE: ADJUSTMENTS	9.0	37.80
83-1762 01	AIR-CONDITIONING SYSTEM DRAIN FLUID, EXHAUST, REFILL, PRESSURE TEST (FOR ALL WORK ON THE SYSTEM)	9.0	37.80
60-1331 02	R + R ATTACHED PARTS OF THE ENGINE COMPARTMENT (FOR RENEWAL OF THE FRONT MODULE) INCLUDES: R + R CHARGE AIR COOLER IF NECESSARY	8.0	33.60
88-1964 02	ADD/WORK R + R FRONT MODULE (VEHICLE WITH HEADLAMP WASHER)	2.0	8.40
88-1102 03	R + R COMPLETE FRONT BUMPER INCLUDES: R + R L/F AND R/F PARTITION AND FOG LAMPS	9.0	37.80
88-1105 03	DIS + ASS FRONT BUMPER (REMOVED) INCLUDES: R + R FOG LAMPS, RENEW PARTS AFTER CHECK	7.0	29.40
88-1358 01	ADD TO DIS + ASS FRONT BUMPER (VEHICLE WITH PARKING SYSTEM)	2.0	8.40
88-2506 02	RENEW BONNET	18.0	75.60

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/6

Date Calculated: 28/08/2018 10:10

Full Report - V1

Registration: SGN 9919J

Printed: 28/08/2018 17:11

	INCLUDES: R + R BONNET, CONVERT ALL PARTS		
88-2657 02	RENEW BONNET HINGE/S	5.0	21.00
60-2297 01	R + R BOTH XENON HEADLAMPS (BUMPER REMOVED)	4.0	16.80
88-4666 02	REMOVE/REFIT BULKHEAD PANEL BELOW LH FRONT WING	6.0	25.20
88-4702 02)	RENEW L/F PARTITION SECTION (REMOVED)	1.0	4.20
88-4704 02)	RENEW R/F PARTITION SECTION (REMOVED)	1.0	4.20
62-1270 01	RENEW RADIATOR CARRIER (STRIPPED)	3.0	12.60
20-1140 02	DRAIN + REFILL COOLANT	6.0	25.20
09-6820 03)	R + R CHARGE AIR COOLER (BUMPER REMOVED)	3.0	12.60
20-4300 01	ADDITIONAL TO R + R RADIATOR (VEHICLE WITH AUTOMATIC GEARBOX)	7.0	29.40
20-4008 01	RENEW RADIATOR (RADIATOR CARRIER REMOVED)	6.0	25.20
83-6523 03	R + R AIR CONDITIONING FLUID RESERVOIR, RENEW AFTER CHECK	4.0	16.80
83-6545 01	CONDENSER REMOVE AND REFIT/RENEW (RADIATOR REMOVED)	3.0	12.60
61-1091 02	R + R R/ENGINE COMPARTMENT SIDE COVER	3.0	12.60
83-7820 ZAX	RENEW REFRIGERANT PIPE D	3.0	12.60
20-6461 01	R + R FAN UNIT	7.0	29.40
20-6465 01	RENEW FAN UNIT PARTS (REMOVED)	3.0	12.60
20-6470 01	ADDITION TO R + R FAN UNIT (VEHICLE WITH AUTOMATIC GEARBOX)	3.0	12.60
62-1266 01	RENEW FRONT CROSSMEMBER AND REINFORCEMENT BETWEEN WHEELHOUSES CPL	15.0	63.00
82-7200 02	R + R WASHER RESERVOIR	5.0	21.00
88-5205 02	R + R L/SILL SIDEMEMBER TRIM	6.0	25.20
88-5232 02	R + R R/SILL SIDEMEMBER TRIM	6.0	25.20
88-8802 03	R + R REAR BUMPER INCLUDES: R + R REAR CENTREPIECE PANELLING	7.0	29.40
88-8805 03	DIS + ASS REAR BUMPER AFTER FINDING: RENEW PARTS (REMOVED)	2.0	8.40
88-8883 02	ADDITIONAL FOR DISS/ASS REAR BUMPER (VEHICLE WITH PARK ASSISTENT)	3.0	12.60
68-3055 02)	R + R R/BOOT TRIM	3.0	12.60
72-6700 01	R + R TAILGATE TRIM	4.0	16.80
88-3501 01	R + R TAILGATE MERCEDES STAR	3.0	12.60
88-3512 01	RENEW TAILGATE BADGE	4.0	16.80
88-3511 01	R + R TAILGATE TYPE BADGE	3.0	12.60
82-4912 02)	R + R L/BOOT LID LAMP UNIT	1.0	4.20
82-4914 02)	R + R R/BOOT LID LAMP UNIT	1.0	4.20
82-4903 03	R + R RIGHT REAR TAILLAMP	3.0	12.60
91-1042 01)	R + R L/F SEAT BELT	2.0	8.40
91-1012 01)	R + R R/F SEAT BELT	2.0	8.40
91-5414 02	R + R R/R SEAT BACKREST	7.0	29.40
91-1087 01)	R + R LEFT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:
Assessment Number: LHM61039
Version: LAI HUAT/6
Date Calculated: 28/08/2018 10:10

Full Report - V1
Registration: SGN 9919J
Printed: 28/08/2018 17:11

91-1097 01)	R + R RIGHT REAR SEAT BELT (TRIM REAR PILLAR AND REAR SEAT REMOVED)	2.0	8.40
68-4605 01	R + R INSTRUMENT PANEL	25.0	105.00
68-4635 01	RENEW INSTRUMENT PANEL (REMOVED)	7.0	29.40
68-4727 01	R + R L/LOWER INSTRUMENT PANEL COVER	2.0	8.40
68-4910 01	ADDITION TO R + R GLOVE BOX (VEHICLE WITH CD CHANGER)	1.0	4.20
68-4745 01	R + R L/INSTRUMENT PANEL COVER	1.0	4.20
68-1093 01	R + R L/B-PILLAR TRIM	5.0	21.00
68-1093 01	R + R R/B-PILLAR TRIM	5.0	21.00
68-1110 02	R + R LEFT C-PILLAR TRIM	5.0	21.00
68-1110 02	R + R RIGHT C-PILLAR TRIM	5.0	21.00
91-2162 01)	R + R PASSENGER AIRBAG UNIT	3.0	12.60
91-2157 01	R + R DRIVER AIRBAG	3.0	12.60
61-1124 01	R + R L/UNDERBODY COVER (EXHAUST SYSTEM REMOVED)	5.0	21.00
61-1117 02	R + R R/UNDERFLOOR COVER	3.0	12.60
NO NUMBER	LOWER + LIFT ENGINE AND FRONT AXLE BRACKET	18.0	75.60
22-1260 02)	RENEW F/ENGINE MOUNTS ASS WORK	3.0	12.60
22-1268 01	RENEW FRONT ENGINE SUSPENSION BEARING	5.0	21.00
NO NUMBER	R + R ENGINE COVER	3.0	12.60
27-7215 ZAX	RENEW AUTOMATIC GEARBOX OUTLET OIL PIPE	3.0	12.60
27-7216 ZAX	RENEW AUTOMATIC GEARBOX RETURN OIL PIPE	3.0	12.60
09-1030 01	R + R AIR FILTER CPL	5.0	21.00
09-8680 01)	R + R L/AIR CHANNEL	4.0	16.80
33-1835 01)	R + R FRONT AXLE CARRIER	38.0	159.60
33-1840 01	RENEW FRONT AXLE CARRIER (REMOVED)	7.0	29.40
	INCLUDES : R + R ALL ATTACHED PARTS AND RENEW ACCORDING TO CONDITION		
32-2050 01	R + R FRONT STABILIZER	14.0	58.80
49-7000 02	R + R EXHAUST SYSTEM CPL	9.0	37.80
49-4831 01	RENEW SILENCER	7.0	29.40
9973	CARRY OUT TEST DRIVE	5.0*	21.00
2102	REPAIR R/SILL PANEL	15.0*	63.00
2237	REPAIR L/A-PILLAR PANEL	10.0*	42.00
2931	REPAIR TAILGATE	15.0*	63.00
3482	REPAIR R/R WING	40.0*	168.00
1000	REPAIR WIRING + SUPPLY CONNECTOR	20.0*	84.00
LABOUR COST			
	Total Work Units	507.0	
	Panel / Mechanical Labour	49.8HRS	\$2,091.60
	Visual Alignment Labour	0.9HRS	\$37.80
	Corrosion Protection External Labour	0.0HRS	0.00
	Corrosion Protection Internal Labour	0.0HRS	0.00
	Sub Total	50.7HRS	\$2,129.40
	Paint Labour	16.6HRS	\$697.20
	Total Labour	67.3HRS	\$2,826.60

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$42.00/HR

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/6

Date Calculated: 28/08/2018 10:10

Full Report - V1

Registration: SGN 9919J

Printed: 28/08/2018 17:11

Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- WATER BASED PAINT		
471	BONNET NEW PART PAINTING	24.0	
475	LEFT BONNET HINGE SURFACE PAINT	4.0	
476	RIGHT BONNET HINGE SURFACE PAINT	4.0	
283	FRONT BUMPER NEW PART PAINT K1R	14.0	
2205	L/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2206	R/SILL PANEL COVER NEW PART PAINT K1R	6.0	
2583	REAR BUMPER COVER NEW PART PAINT K1R	13.0	
2102	R/SILL PANEL REPAIR PAINTING <50%	10.0	
2237	L/A-PILLAR PANEL REPAIR PAINTING <50%	8.0	
2931	TAILGATE REPAIR PAINTING <50%	22.0	
3482	R/R WING REPAIR PAINTING <50%	11.0	
741	L/F WING SURFACE PAINT	5.0	
742	R/F WING SURFACE PAINT	5.0	
1782	R/R DOOR SURFACE PAINT	8.0	
LABOUR COST - PAINT			
	TIME(PAINT)	140.0	
	Preparation Main Work Metal	21.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	166.0	
	Total Paintwork Labour	16.6HRS	\$697.20
MATERIAL COST - PAINT			Cost Price
	New Part Painting		\$79.98
	New Part Painting - Plastic K1R		\$178.09
	Surface-/Blend Paint		\$36.85
	Repair Painting		\$68.47
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$390.49
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$390.49

PARTS

				Price Valid: 01/06/2015	
Guide No.	Qty	Description	Part Number	Supplier	Bet. Price (\$)
1000	1	AIR CON DECAL	Renew		0% 18.00*
8391	1	AIR FILTER ASSY	266 090 0101		0% 173.00*
7751	1	AIR GUIDE PANEL	169 505 0930		0% 170.00*
1392	1	AIR INTAKE GRILLE	169 836 0018		0% 110.00*
8396	1	AIR INTAKE HOSE	266 094 0287		0% 42.00*
471	1	BONNET	169 880 0257		0% 590.00*
1017	1	BONNET LANDING PANEL	169 620 1634		0% 410.00*
4465	1	CONDENSER	169 500 1254		0% 560.00*
7445	1	DRIVER AIRBAG	164 860 1902 9051		0% 1,360.00*
4482	1	DRYER/EXP VALVE PIPE	169 830 1715		0% 142.00*
7792	1	ELECTRIC FAN	169 820 3642		0% 880.00*
1000	1	ENG TOP CVR BUSH	Renew		0% 3.00*
7767	1	FAN SHROUD	169 505 0255		0% 93.00*
7011	1	FRONT AXLE SUPPORT	169 620 0787		0% 1,085.00*
283	1	FRONT BUMPER	169 885 2825		0% 950.00*

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/6

Date Calculated: 28/08/2018 10:10

Full Report - V1

Registration: SGN 9919J

Printed: 28/08/2018 17:11

8777	1	FRONT CENTRE TRIM	169 524 1430	0%	49.00*
8624	1	FRONT ENGINE SUPPORT	266 223 0604	0%	50.00*
7261	1	FRONT STABILISER	169 323 0965	0%	140.00*
432	1	FRONT STAR EMBLEM	207 817 0316	0%	33.00*
293	1	FRT BUMPER GRILLE	169 885 0123	0%	64.00*
8631	1	FRT ENGINE MOUNTING	169 240 1517	0%	50.00*
8633	1	FRT G-BOX RUBBER BRG	169 240 1517	0%	0.00F
320	1	FRT LWR BUMPER SUPP	169 885 0136	0%	111.00*
1001	1	FRT LWR CROSSMEMBER	169 620 1734	0%	375.00*
319	1	FRT/CTR IMPACT DAMP	169 885 0137	0%	96.00*
8888	1	GEARBOX OIL COOLER	169 500 0600	0%	585.00*
1000	1	HID WARNING DECALX2	Renew	0%	8.00*
9645	1	HIGH TONE HORN	006 542 4420	0%	93.00*
4331	1	INSTRUMENT PANEL	169 680 2287	0%	1,020.00*
			9D84		
8730	1	INTERCOOLER	169 500 0900	0%	505.00*
8737	1	L/CHARGE AIR HOSE	169 528 0582	0%	130.00*
303	1	L/F BUMPER GRILLE	169 885 1122	0%	45.00*
313	1	L/F BUMPER TRIM	169 885 1374	0%	59.00*
1393	1	L/F COVER	169 830 0375	0%	15.00*
369	1	L/F CTR PARKING SENS	169 542 0518 9761	0%	90.00*
637	1	L/F FOG LAMP	251 820 0756	0%	138.00*
371	1	L/F INNER SENSOR	169 542 0518 9761	0%	90.00*
4661	1	L/F SEAT BELT	169 860 8385	0%	295.00*
7263	1	L/F STABILISER ARM	169 320 0989	0%	36.00*
7047	1	L/F TRACK CONT ARM	169 330 0907	0%	330.00*
833	1	L/F W-HOUSE FRT CVR	169 698 2530	0%	44.00*
8961	1	L/GEARBOX OIL PIPE	169 270 0896 28	0%	82.00*
559	1	L/HEADLAMP COVER	169 821 0336	0%	10.00*
625	1	L/HEADLAMP WASH JET	169 860 1147	0%	125.00*
605	1	L/HEADLAMP WASH TRIM	169 887 0325 9696	0%	44.00*
2615	1	L/R BUMPER TRIM	169 885 1574	0%	72.00*
4841	1	L/R SEAT BELT	169 860 7985	0%	170.00*
3011	1	L/R TYPE BADGE	169 817 1315	0%	38.00*
2205	1	L/SILL PANEL COVER	169 611 1308	0%	180.00*
4259	1	L/UNDERB HEAT SHIELD	169 610 3708	0%	260.00*
475	1	LEFT BONNET HINGE	169 880 0328	0%	42.00*
561	1	LEFT HEADLAMP ASSY	169 820 6961	0%	1,450.00*
493	1	LOWER BONNET LOCK	169 880 0560	0%	89.00*
8829	1	MAIN SILENCER	169 490 1122	0%	400.00*
377	1	PARKTRONIC WIRING	169 540 6805	0%	82.00*
4325	1	PASSENGER AIRBAG	169 860 0600	0%	1,110.00*
8228	1	R/ENGINE COVER	266 141 0121	0%	75.00*
304	1	R/F BUMPER GRILLE	169 885 1222	0%	45.00*
314	1	R/F BUMPER TRIM	169 885 1474	0%	59.00*
1394	1	R/F COVER	169 830 0275	0%	15.00*
370	1	R/F CTR PARKING SENS	169 542 0518 9761	0%	90.00*
638	1	R/F FOG LAMP	251 820 0856	0%	138.00*
372	1	R/F INNER SENSOR	169 542 0518 9761	0%	90.00*
4662	1	R/F SEAT BELT	169 860 6885	0%	295.00*
7264	1	R/F STABILISER ARM	169 320 0989	0%	36.00*
7048	1	R/F TRACK CONT ARM	169 330 1007	0%	330.00*

LAI HUAT (MENG KEE) MOTOR PTE LTD

Claim Reference:

Assessment Number: LHM61039

Version: LAI HUAT/6

Date Calculated: 28/08/2018 10:10

Full Report - V1

Registration: SGN 9919J

Printed: 28/08/2018 17:11

834	1	R/F W-HOUSE FRT CVR	169 698 2630	0%	44.00*
836	1	R/F W-HOUSE RR COVER	169 698 2830	0%	65.00*
764	1	R/F WING BRACKET FRT	169 885 0414	0%	12.00*
8962	1	R/GEARBOX OIL PIPE	169 270 0496 28	0%	42.00*
560	1	R/HEADLAMP COVER	169 821 0436	0%	10.00*
606	1	R/HEADLAMP WASH TRIM	169 887 0425 9696	0%	44.00*
3012	1	R/R BADGE	202 817 2115	0%	52.00*
2616	1	R/R BUMPER TRIM	169 885 1674	0%	72.00*
3282	1	R/R OUTER LAMP	169 820 2664	0%	180.00*
4842	1	R/R SEAT BELT	169 860 8085	0%	170.00*
2206	1	R/SILL PANEL COVER	169 611 1408	0%	180.00*
4260	1	R/UNDERBODY	169 610 0908	0%	105.00*
1000	1	RAD COOLANT	Renew	0%	40.00*
1000	1	RAD SUPP BOLT	Renew	0%	12.00*
1000	1	RAD SUPP RUBB MOUNT	Renew	0%	8.00*
7761	1	RADIATOR	169 500 2103	0%	400.00*
405	1	RADIATOR COVER	169 880 0883	0%	300.00*
7772	1	RADIATOR CROSSMEMBER	169 620 0485	0%	245.00*
1000	1	RADIATOR TOP CLIP	Renew	0%	14.00*
2583	1	REAR BUMPER COVER	169 885 2138	0%	735.00*
2617	1	REAR DECAL STRIPE	169 698 0062	0%	98.00*
476	1	RIGHT BONNET HINGE	169 880 0428	0%	42.00*
1000	1	SILL PNL CLIPS(B)	Renew	0%	24.00*
1000	1	SILL PNL CLIPS(W)	Renew	0%	30.00*
1000	1	SILL PNL CVR CLIPX2	Renew	0%	8.00*
3010	1	STAR EMBLEM	221 758 0058	0%	24.00*
492	1	UPPER BONNET LOCK	169 880 0160	0%	18.00*
1000	1	WARNING DECAL - 1	Renew	0%	5.00*
1000	1	WARNING DECAL - 2	Renew	0%	3.00*
1435	1	W-WASHER BOTTLE	169 869 0320	0%	77.00*
f: OEM Parts			Saving		\$31.01
g: Original			Sub Total		\$19,423.00
h: Secondhand			Sundry Parts	(Fixed)	\$0.00
p: Parallel			Total Parts		\$19,423.00
x: Exchange					

THIS ASSESSMENT CONTAINS UNPRICED PARTS
NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
WHEEL ALIGNMENT SPECIALIST	0%	\$80.00
AIR CON GAS SPECIALIST		\$50.00
SRS CONTROL UNIT REPROGRAM	0%	\$120.00
SUNDRY PARTS SPECIALIST		\$100.00
GEARBOX FLUID SPECIALIST	0%	\$18.00
Total Extras		\$368.00

Final Calculation

Total Parts	\$19,423.00
Labour	
Total Panel/Mechanical	\$2,091.60
Total Paintwork	\$697.20
Total Visual Alignment work	\$37.80
Total Labour	\$2,826.60

LAI HUAT (MENG KEE) MOTOR PTE LTD**Claim Reference:****Assessment Number: LHM61039****Version: LAI HUAT/6****Date Calculated: 28/08/2018 10:10****Full Report - V1****Registration: SGN 9919J****Printed: 28/08/2018 17:11****Additional Costs**

Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$368.00	
Total of Additional Costs		\$368.00
Total Paint/Material Costs		\$390.49
Repair Costs Excludes GST		\$23,008.09
Deductions		
Deduction for Excess (Fixed)	-\$1,500.00	
Total Deductions		-\$1,500.00
Grand Total Excludes GST (After Deduction)		\$21,508.09
GST @ 7 %		\$1,505.57
Grand Total Includes GST (After Deduction)		\$23,013.66

Assessment Notes

Work Order: R025525
 VIN: SGN9919J
 Year: 09
 Date: 31.5.18 17:38



SGN9919J

Mercedes-Benz : 245 (B Class (CST) 2005-11) : Standard Suspension

Front : Left

Actual	Before	Specified Range
-0°52'	-1°48'	-1°00' -0°20'
3°42'	3°42'	
0°04'	0°00'	0°01' 0°11'
10°56'	11°53'	
10°04'	10°04'	
		-1°24' -0°24'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°41'	0°08'	-1°00' -0°20'
3°43'	3°43'	
0°05'	0°18'	0°01' 0°11'
13°08'	12°19'	
12°27'	12°27'	
		-1°24' -0°24'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°11'	-1°57'	-0°20' 0°20'
-0°01'	-0°01'	-0°30' 0°30'
-2°12'	-0°26'	
0°10'	0°17'	0°02' 0°22'

Rear : Left

Actual	Before	Specified Range
-2°11'	-2°15'	-2°00' -1°00'
-0°12'	-0°14'	-0°13' 0°17'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-2°29'	-2°28'	-2°00' -1°00'
-0°05'	-0°04'	-0°13' 0°17'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°18'	0°13'	-0°30' 0°30'
-0°18'	-0°18'	-0°09' 0°21'
-0°03'	-0°05'	-0°15' 0°15'

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 30 August 2018 12:08 PM
To: Jenny Lim; Kenneth Kong (LKKAUTO)
Cc: SUR
Subject: RE: Finalisation - SGN 9919J / Mercedes Benz B200

Dear Jenny,

We spoke.

Confirmed Lump Sum \$16,000 before excess \$1500

No of days: 21 days

Will offer in merimen shortly.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Lim <jenny.lim@laihuat.com.sg>
Sent: Wednesday, 29 August 2018 3:08 PM
To: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Finalisation - SGN 9919J / Mercedes Benz B200

Dear Sir

For your confirmation, please:

- Parts: \$19,423.00
- SN: \$ 368.00
- L&P: \$ 3,217.09

Sub-total: \$23,008.09

LS -20%: (\$4601.62) = \$18,406.47

Lump sum: \$18,000.00 / Excess cost: \$1,500.00

Supporting document are enclosed for your reference. Photographs will send to you in separate email.

Thank you.

Kind regards.

Jenny Lim
for LAI HUAT (MENG KEE) MOTOR PTE LTD
160 Sin Ming Drive
#04-01, #04-02 & #07-03
Sin Ming Autocity

Singapore 575722
Tel: 64538110
Fax: 64596267

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Mar 2018 Sendback Est	29 Mar 2018 10:54 S\$23,028.04	29 Mar 2018 15:12 Edit Adj Rpt	S\$16,000.00 Edit Estimates	S\$16,000.00 View Rpt		Pending for Survey Report Cancel Case
Supp #1	28 Aug 2018 17:14	31 Aug 2018 12:14 S\$1,274.00	31 Aug 2018 12:14			(Combined)	Combined with Main Uncombine Suppl.

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	YONG MEI YOKE VIOLA , ID: S1363856Z		
Vehicle Reg. No.:	SGN9919J	Date of Loss:	22/03/2018 15:00 - :59 [137 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM18D01599C01	Policy/Cover Note No.:	DMPCSN3099651701 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64538110		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 10/04/2018]		
Driver/Custodian:	YONG KIM YOONG RAYMOND (66 / Male), NRIC: S1140718H, Tel: +6596670230		
Adj Asg. Remarks:	SURVEY REVERT ECONOMICAL TO REPAIR		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (05/04/2018): Alert - Adj Mandate Approved (S\$18100.00) - SGN9919J - Claim Handler: Chong Boon...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

SGN9919J (SNM18D01599C01)
 OD
 Mar 22 2018 3:00PM
 [YONG MEI YOKE VIOLA]
 Lai Huat (Meng Kee) Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser

Assessment Reports				1 per page	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	26/03/18 17:23	Accident Statement	1	Load HTM	
2	29/03/18 10:54	Repairer Estimates	1	Load HTM	
3	31/08/18 12:14	Repairer Estimates Suppl. #1	1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/04/18 16:25	Adjuster Immediate Advice	1	Load HTM	

Photos/Images				3 per page	
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)		Thumbnail	Print
1	26/03/18 16:57	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
2	26/03/18 16:57	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
3	26/03/18 16:57	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
4	26/03/18 16:57	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
5	26/03/18 16:57	Accident Photo [Linked Accident Report Documents]	1	Load JPG	
6	26/03/18 16:57	Accident Scene [Linked Accident Report Documents]	1	Load JPG	
7	26/03/18 16:57	Accident Scene [Linked Accident Report Documents]	1	Load JPG	
8	26/03/18 16:57	Accident Scene [Linked Accident Report Documents]	1	Load JPG	
9	29/03/18 10:51	Rear View Right	1	Load JPG	
10	29/03/18 10:51	Front View Left	1	Load JPG	
11	29/03/18 10:51	Front View Right	1	Load JPG	
12	29/03/18 10:51	Chassis Number	1	Load JPG	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	03/04/18 11:14	General View	1	Load JPG	
2	03/04/18 11:14	General View	1	Load JPG	
3	03/04/18 11:14	General View	1	Load JPG	
4	03/04/18 11:14	General View	1	Load JPG	
5	03/04/18 11:14	General View	1	Load JPG	
6	03/04/18 11:14	General View	1	Load JPG	
7	03/04/18 11:14	General View	1	Load JPG	
8	03/04/18 11:14	General View	1	Load JPG	
9	03/04/18 11:14	General View	1	Load JPG	
10	03/04/18 11:14	General View	1	Load JPG	
11	03/04/18 11:14	General View	1	Load JPG	
12	03/04/18 11:14	General View	1	Load JPG	
13	03/04/18 11:14	General View	1	Load JPG	
14	03/04/18 11:14	General View	1	Load JPG	
15	03/04/18 11:14	General View	1	Load JPG	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
16	03/04/18 11:14	General View	 Load JPG	✓
17	03/04/18 11:14	General View	 Load JPG	✓
18	03/04/18 11:14	General View	 Load JPG	✓
19	03/04/18 11:14	General View	 Load JPG	✓
20	03/04/18 11:14	General View	 Load JPG	✓
21	03/04/18 11:14	General View	 Load JPG	✓
22	03/04/18 11:14	General View	 Load JPG	✓
23	03/04/18 11:14	General View	 Load JPG	✓
24	03/04/18 11:14	General View	 Load JPG	✓
25	03/04/18 11:14	General View	 Load JPG	✓
26	03/04/18 11:14	General View	 Load JPG	✓
27	03/04/18 11:14	General View	 Load JPG	✓
28	03/04/18 11:14	General View	 Load JPG	✓
29	03/04/18 11:14	General View	 Load JPG	✓
30	03/04/18 11:14	General View	 Load JPG	✓
31	03/04/18 11:14	General View	 Load JPG	✓
32	03/04/18 11:14	General View	 Load JPG	✓
33	03/04/18 11:14	General View	 Load JPG	✓
34	03/04/18 11:14	General View	 Load JPG	✓
35	03/04/18 11:14	General View	 Load JPG	✓
36	03/04/18 11:14	General View	 Load JPG	✓
37	03/04/18 11:14	General View	 Load JPG	✓
38	03/04/18 11:14	General View	 Load JPG	✓
39	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
40	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
41	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
42	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
43	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
44	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
45	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
46	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
47	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
48	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
49	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
50	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
51	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
52	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
53	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
54	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
55	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
56	30/08/18 10:43	Reinspection Photo	 Load JPG	✓
57	30/08/18 10:43	Reinspection Photo	Load JPG	✓
58	30/08/18 10:43	Reinspection Photo	Load JPG	✓
59	30/08/18 10:43	Reinspection Photo	Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/03/18 17:22	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
2	26/03/18 17:23	Police Report [Linked Accident Report Documents]	Load TIF	
3	26/03/18 17:23	Driver's Driving License [Linked Accident Report Documents]	Load TIF	
4	29/03/18 10:54	E-filed GIA report	Load PDF	
5	29/03/18 10:54	Driver's Driving License	Load PDF	
6	29/03/18 10:54	Enquire PARF / COE Rebate for Registered Vehicle	Load PDF	
7	24/04/18 10:43	Malaysia Towing Receipt	Load PDF	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/03/18 15:12	REBATE FORM	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/04/18 11:22	MARK ESTIMATE	Load PDF	
2	03/04/18 16:23	AUDATEX	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/03/18 17:23	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/03/18 16:57	Accident Photo	Load JPG	☒
2	26/03/18 16:57	Accident Photo	Load JPG	☒
3	26/03/18 16:57	Accident Photo	Load JPG	☒
4	26/03/18 16:57	Accident Photo	Load JPG	☒
5	26/03/18 16:57	Accident Photo	Load JPG	☒
6	26/03/18 16:57	Accident Scene	Load JPG	☒
7	26/03/18 16:57	Accident Scene	Load JPG	☒
8	26/03/18 16:57	Accident Scene	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/03/18 17:22	Sketch Plan Sketch Plan	Load TIF	
2	26/03/18 17:23	Police Report	Load TIF	
3	26/03/18 17:23	Driver's Driving License	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☒ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT18005959/KVBS2

Date: 10/09/2018

REFERENCE

Insured/Claimant: YONG MEI YOKE VIOLA Policy No: DMPCSN3099651701
Date of Loss: 22/03/2018 Nature of Claim: OD Claim No: SNM18D01599C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGN9919J**
Make & Model: MERCEDES-BENZ B200, 2.0 Turbo (A) Engine No: 26698030265046
Reg. Date: 13/10/2006 (Man. Year: 2006) Chassis No: WDD2452342J144783
Colour: Metallic Grey Odometer: 0 km
Engine Capacity: 2035 cc
Market Value/New Car Price: S\$68,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,384.00	17,506.00	2,878.00	14.12
Miscellaneous Items	350.00	350.00	0.00	0.00
Labour	3,568.04	3,109.99	458.05	12.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,302.04	20,965.99	3,336.05	13.73
Approved Total (Overridden) (S\$)		16,000.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	22,802.04	14,500.00	8,302.04	36.41
+ GST 7.00/7.00% (S\$)	1,596.14	1,015.00	581.14	36.41
Nett Amount (S\$)	24,398.18	15,515.00	8,883.18	36.41

INSPECTION

Date of Assignment: 29/03/2018 Present Location: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Date Inspected: 02/04/2018 Inspected At: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming)
Estimated Period of Repair: 21.0 days 160 Sin Ming Drive #04-01, Sin Ming AutoCity
Singapore 575722

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 10 Sep 2018)

Parts: 144 MERCEDES-BENZ B200 2.0 Turbo (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGN9919J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*AIR CON DECAL	Necessary	18.00 F	*18.00 F
2	1	NA	*AIR FILTER ASSY	Cracked	173.00 F	*173.00 F
3	1	NA	*AIR GUIDE PANEL	Bent	170.00 F	*170.00 F
4	1	NA	*AIR INTAKE GRILLE	Missing	110.00 F	*110.00 F
5	1	NA	*BONNET	Bent	590.00 F	*590.00 F
6	1	NA	*BONNET LANDING PANEL	Bent	410.00 F	*410.00 F
7	1	NA	*COMPR-/CONDENS PIPE	Bent	142.00 F	*142.00 F
8	1	NA	*COMPR/EXP VALVE PIPE	Bent	120.00 F	*120.00 F
9	1	NA	*CONDENSER	Bent	560.00 F	*560.00 F
10	1	NA	*DRIVER AIRBAG	Burst	1,360.00 F	*1,360.00 F
11	1	NA	*DRYER/EXP VALVE PIPE	Serviceable	142.00 F	*- F
12	1	NA	*ELECTRIC FAN	Jammed	880.00 F	*880.00 F
13	1	NA	*ENG TOP CVR BUSH	Necessary	3.00 F	*3.00 F
14	1	NA	*EXH PIPE/CATALYST	Dented	525.00 F	*525.00 F
15	1	NA	*EXT FRT PIPE BOLT	Serviceable	5.00 F	*- F
16	1	NA	*FRONT AXLE SUPPORT	Bent	1,085.00 F	*1,085.00 F
17	1	NA	*FRONT BUMPER	Missing	950.00 F	*950.00 F
18	1	NA	*FRONT CENTRE TRIM	Missing	49.00 F	*49.00 F
19	1	NA	*FRONT ENGINE SUPPORT	Missing	50.00 F	*50.00 F
20	1	NA	*FRONT STABILISER	Bent	140.00 F	*140.00 F
21	1	NA	*FRONT STAR EMBLEM	Missing	33.00 F	*33.00 F
22	1	NA	*FRT BUMPER GRILLE	Missing	64.00 F	*64.00 F
23	1	NA	*FRT ENGINE MOUNTING	Cracked	50.00 F	*50.00 F
24	1	NA	*FRT LWR BUMPER SUPP	Malfunction	111.00 F	*111.00 F
25	1	NA	*FRT LWR CROSSMEMBER	Bent	375.00 F	*375.00 F
26	1	NA	*GEARBOX OIL COOLER	Bent	585.00 F	*585.00 F
27	1	NA	*HID WARNING DECALX2	Necessary	8.00 F	*8.00 F
28	1	NA	*HIGH TONE HORN	Cracked	93.00 F	*93.00 F
29	1	NA	*INSTRUMENT PANEL	Torn	1,020.00 F	*1,020.00 F
30	1	NA	*INTERCOOLER	Twisted	505.00 F	*505.00 F
31	1	NA	*L/CHARGE AIR HOSE	Dented	130.00 F	*130.00 F
32	1	NA	*L/F BUMPER GRILLE	Missing	45.00 F	*45.00 F
33	1	NA	*L/F BUMPER TRIM	Missing	59.00 F	*59.00 F
34	1	NA	*L/F COVER	Missing	15.00 F	*15.00 F
35	1	NA	*L/F FOG LAMP	Missing	138.00 F	*138.00 F
36	1	NA	*L/F SEAT BELT	Jammed	295.00 F	*295.00 F
37	1	NA	*L/F TRACK CONT ARM	Distorted	330.00 F	*330.00 F
38	1	NA	*L/F W-HOUSE FRT CVR	Serviceable	44.00 F	*- F
39	1	NA	*L/HEADLAMP COVER	Missing	10.00 F	*10.00 F
40	1	NA	*L/HEADLAMP WASH TRIM	Serviceable	44.00 F	*- F
41	1	NA	*L/R BUMPER TRIM	Missing	72.00 F	*72.00 F
42	1	NA	*L/R SEAT BELT	Jammed	170.00 F	*170.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1	NA	*L/R TYPE BADGE	Serviceable	38.00 F	*- F
44	1	NA	*L/SILL PANEL COVER	Buckled	180.00 F	*180.00 F
45	1	NA	*L/UNDERB HEAT SHIELD	Repair	260.00 F	*- F
46	1	NA	*L/UPP RADIATOR HOSE	Serviceable	44.00 F	*- F
47	1	NA	*LEFT BONNET HINGE	Serviceable	42.00 F	*- F
48	1	NA	*LEFT HEADLAMP ASSY	Mtg Cracked	1,450.00 F	*1,450.00 F
49	1	NA	*LOW TONE HORN	Serviceable	93.00 F	*- F
50	1	NA	*LOWER BONNET LOCK	Distorted	89.00 F	*89.00 F
51	1	NA	*MAIN SILENCER	Repair	400.00 F	*- F
52	1	NA	*NOZZLE CVR SPRING LH	Serviceable	5.00 F	*- F
53	1	NA	*NOZZLE CVR SPRING RH	Serviceable	5.00 F	*- F
54	1	NA	*PASSENGER AIRBAG	Burst	1,110.00 F	*1,110.00 F
55	1	NA	*R/ENGINE COVER	Missing	75.00 F	*75.00 F
56	1	NA	*R/F BUMPER GRILLE	Missing	45.00 F	*45.00 F
57	1	NA	*R/F BUMPER TRIM	Missing	59.00 F	*59.00 F
58	1	NA	*R/F COVER	Missing	15.00 F	*15.00 F
59	1	NA	*R/F FOG LAMP	Missing	138.00 F	*138.00 F
60	1	NA	*R/F SEAT BELT	Jammed	295.00 F	*295.00 F
61	1	NA	*R/F TRACK CONT ARM	Distorted	330.00 F	*330.00 F
62	1	NA	*R/F W-HOUSE FRT CVR	Serviceable	44.00 F	*- F
63	1	NA	*R/HEADLAMP COVER	Missing	10.00 F	*10.00 F
64	1	NA	*R/HEADLAMP WASH TRIM	Serviceable	44.00 F	*- F
65	1	NA	*R/R BADGE	Necessary	52.00 F	*52.00 F
66	1	NA	*R/R BUMPER TRIM	Serviceable	72.00 F	*- F
67	1	NA	*R/R OUTER LAMP	Cracked	180.00 F	*180.00 F
68	1	NA	*R/R SEAT BELT	Jammed	170.00 F	*170.00 F
69	1	NA	*R/SILL PANEL COVER	Dented / Cracked	180.00 F	*180.00 F
70	1	NA	*R/STICKER REFLECTING	Necessary	22.00 F	*22.00 F
71	1	NA	*RAD COOLANT	Necessary	40.00 F	*40.00 F
72	1	NA	*RAD SUPP BOLT	Necessary	12.00 F	*12.00 F
73	1	NA	*RAD SUPP RUBB MOUNT	Serviceable	8.00 F	*- F
74	1	NA	*RADIATOR	Punctured	400.00 F	*400.00 F
75	1	NA	*RADIATOR COVER	Serviceable	300.00 F	*- F
76	1	NA	*RADIATOR CROSSMEMBER	Bent	245.00 F	*245.00 F
77	1	NA	*RADIATOR TOP CLIP	Not Necessary	14.00 F	*- F
78	1	NA	*REAR BUMPER COVER	Buckled	735.00 F	*735.00 F
79	1	NA	*RIGHT BONNET HINGE	Distorted	42.00 F	*42.00 F
80	1	NA	*SILL PNL CLIPS(B)	Necessary	24.00 F	*24.00 F
81	1	NA	*SILL PNL CLIPS(W)	Necessary	30.00 F	*30.00 F
82	1	NA	*SILL PNL CVR CLIPSX2	Necessary	8.00 F	*8.00 F
83	1	NA	*STAR EMBLEM	Necessary	24.00 F	*24.00 F
84	1	NA	*UPPER BONNET LOCK	Distorted	18.00 F	*18.00 F
85	1	NA	*WARNING DECAL - 1	Necessary	5.00 F	*5.00 F
86	1	NA	*WARNING DECAL - 2	Necessary	3.00 F	*3.00 F
87	1	NA	*W-WASHER BOTTLE	Dented	77.00 F	*77.00 F
Supplementary #1						
88	1		*AIR INTAKE HOSE	Not Necessary	42.00 F	*- F
89	1		*FAN SHROUD	Not Necessary	93.00 F	*- F
90	1		*FRT/CTR IMPACT DAMP	Not Necessary	96.00 F	*- F
91	1		*L/F CTR PARKING SENS	Not Necessary	90.00 F	*- F
92	1		*L/F INNER SENSOR	Not Necessary	90.00 F	*- F
93	1		*L/F STABILISER ARM	Not Necessary	36.00 F	*- F
94	1		*L/GEARBOX OIL PIPE	Not Necessary	82.00 F	*- F
95	1		*L/HEADLAMP WASH JET	Not Necessary	125.00 F	*- F
96	1		*PARKTRONIC WIRING	Not Necessary	82.00 F	*- F
97	1		*R/F CTR PARKING SENS	Not Necessary	90.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*R/F INNER SENSOR	Not Necessary	90.00 F	*- F
99	1		*R/F STABILISER ARM	Not Necessary	36.00 F	*- F
100	1		*R/F W-HOUSE RR COVER	Not Necessary	65.00 F	*- F
101	1		*R/F WING BRACKET FRT	Not Necessary	12.00 F	*- F
102	1		*R/GEARBOX OIL PIPE	Not Necessary	42.00 F	*- F
103	1		*R/UNDERBODY	Not Necessary	105.00 F	*- F
104	1		*REAR DECAL STRIPE	Not Necessary	98.00 F	*- F

F=Franchise part.

Total Parts (S\$)	20,384.00	17,506.00
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	AIR CON GAS	50.00	50.00
2	1	REPROGRAM SRS CONTROL UNIT	120.00	120.00
3	1	SUNDRY PARTS	100.00	100.00
4	1	WHEEL ALIGNMENT	80.00	80.00
Sub Total (S\$)			350.00	350.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	Total Paint Labour	New	726.60	709.80
2	Total Paint Materials	New	405.44	405.19
3	Total Panel/Mechanical Labour	New	2,436.00	1,957.20
4	Total Visual Alignment work	New	-	37.80
Gross Labour Cost (S\$)			3,568.04	3,109.99

Report was unsubmitted during this print-out.

< END OF ESTIMATES >