LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road 51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Adeline Chng Pei Wen Date: 03 Apr 2018

Preliminary Advice

Vehicle No : SLC4569S Accident Date : 26/03/2018

Make : FORD MONDEO Policy No.

DMPCSN3056941701

Date of Inspection: 02/04/2018 Est. Duration of Repair: 0.00

Inspection At : S & H MOTOR PTE LTD (SIN MING)

160 SIN MING DRIVE #07-02, SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ TOTAL LOSS
Revised Amount :S\$ TOTAL LOSS
Check Items (Estimated) :S\$ 0.00

Total :S\$

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 15,000.00 COE / PARF Rebate :S\$ 11,946.00

Salvage Value :S\$

Margin for Repair :S\$ 3,054.00

Brake System : In Order Steering System : Jammed Tyre Condition (Front) : 7/7 mm Tyre Condition (Rear) : 8/8 mm

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(x)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :