

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III18005969/GSBS2**Date:** 04/06/2018REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No :	FBA6275E	Insured Vehicle No :	SHC8204R
Date of Loss:	29/03/2018	Nature of Claim:	TP
		Claim No:	MCT18030933

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBA6275E	Engine No:	5YP203513
Make & Model:	YAMAHA 135LC, 135cc ES	Chassis No:	5YP203513
Reg. Date:	28/06/2006 (Man. Year: 2006)	Odometer:	78251 km
Colour:	White		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,230.00	2,451.30	3,778.70	60.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	630.00	720.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,580.00	3,081.30	4,498.70	59.35
Approved Total (Overridden) (S\$)		2,450.00		
Nett Amount (S\$)	7,580.00	2,450.00	5,130.00	67.68

INSPECTION

Date of Assignment:	15/05/2018		
Date Inspected:	02/04/2018	Inspected At:	Bike Image Motor Trading (HQ) 466 UPPER SERANGOON Singapore 534500
Estimated Period of Repair:	3.0 days		

Adjuster: XING GUO QIANG**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jun 2018)	
Parts:	N/A	YAMAHA 135LC 135cc ES (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBA6275E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK	Bent	620.00 F	*620.00 FL
2	1		*HEADLAMP ASSY	Cut	189.00 F	*189.00 FL
3	1		*HEADLAMP BRACKET	Serviceable	45.00 F	*- FL
4	2		*FRONT SIGNAL LAMP	Cut	186.00 F	*186.00 FL
5	1		*STEERING CONE W/BEARING	Necessary	68.00 F	*68.00 FL
6	1		*UNDER BRACKET	Repair	125.00 F	*- FL
7	1		*FRONT MUDGUARD	Cut	185.00 F	*185.00 FL
8	1		*HEADLAMP COWLING	Cut	165.00 F	*165.00 FL
9	2		*HANDLE BAR	Bent	160.00 F	*160.00 FL
10	2		*HANDLE GRIP	Necessary	48.00 F	*48.00 FL
11	2		*MIRROR	Cut	98.00 F	*98.00 FL
12	1		*ON/OFF SWITCH	Serviceable	155.00 F	*- FL
13	1		*METER ASSY	Serviceable	450.00 F	*- FL
14	1		*FRONT WHEEL ASSY	Repair	385.00 F	*- FL
15	1		*FRONT WHEEL RIM SHAFT	Cut	58.00 F	*58.00 FL
16	1		*GEAR PEDAL	Bent	68.00 F	*68.00 FL
17	1		*CLUTCH LEVER	Cut	58.00 F	*58.00 FL
18	1		*BRAKE PEDAL	Cut	58.00 F	*58.00 FL
19	1		*FRONT BRAKE CALIPER	Serviceable	265.00 F	*- FL
20	1		*FRONT BRAKE DISC PLATE	Not Necessary	125.00 F	*- FL
21	1		*BRAKE LEVER	Cut	58.00 F	*58.00 FL
22	1		*R/H FAIRING	Cut	165.00 F	*165.00 FL
23	1		*L/H FAIRING	Cut	165.00 F	*165.00 FL
24	1		*R/H FAIRING INNER GARNISH	Serviceable	48.00 F	*- FL
25	1		*L/H FAIRING INNER GARNISH	Serviceable	48.00 F	*- FL
26	1		*L/H FRONT FOOT REST	Serviceable	45.00 F	*- FL
27	1		*R/H FRONT FOOT REST	Serviceable	45.00 F	*- FL
28	1		*R/H REAR FOOT REST	Serviceable	45.00 F	*- FL
29	1		*REAR SWING ARM	Repair	625.00 F	*- FL
30	1		*R/H SEAT LOWER COVER	Serviceable	105.00 F	*- FL
31	1		*L/H SEAT LOWER COVER	Serviceable	105.00 F	*- FL
32	1		*FRONT COVER	Repair	125.00 F	*- FL
33	1		*EXHAUST MUFFLER	Serviceable	460.00 F	*- FL
34	2		*EXHAUST PROTECTOR	Scratched / Cut	48.00 F	*48.00 FL
35	1		*REAR MUDGUARD	Serviceable	72.00 F	*- FL
36	1		*FRONT NUMBER PLATE	Necessary	20.00 FS	*18.00 FS
37	1		*REAR NUMBER PLATE	Serviceable	20.00 FS	*- FS
38	1		*IU UNIT	Cut / Scratched	160.00 FS	*156.00 FS
39	1		*REAR BOX	Cut / Scratched	200.00 FS	*120.00 FS
40	1		*REAR BOX BRACKET	Repair	160.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,230.00	2,691.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	239.70
Total Parts (\$\$)	6,230.00	2,451.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	New	550.00	300.00
2	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	New	400.00	200.00
3	TO ALIGN MAIN BODY FRAME.	New	350.00	100.00
4	TRANSPORTATION CHARGES.	New	50.00	30.00
Gross Labour Cost (S\$)			1,350.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >