

Surveyor

Kundh

ASSIGNMENT (Office)

CWS

From (Person):

May chua

of

FCI

Date/Time: 03/04/18 @ 8:43am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 2780T

Insured:

SHA 7850S

at Workshop m/s:

Pang & Tan Vehicle

Tel:

62555711

of

160 Sin Ming Drive # 04-03

Policy No:

Claim No:

D18002595MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 30/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 8:56am 3/4/18

Person Contacted:

Michelle

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SJY 2780T-CS/AXA15619276/GHBC2

D.O.A. 9/11/15

28/10/18 1/1 Lm 832001 email (Red: 6949.58! 68%)

ASS. REC. BY:

REF: 1021

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 3/21 _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJY 2780T Yr Regn: 06, 06

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Camry G c.c. 2362

Colour: M. Silver A/C: Insured / Std / NI / NA

Sp. Reading: 240709 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ACV40 3021859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 30/3/18

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 3/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/4 File sent to Catherine, not ready

RECEIVED 31 OCT 2018

Date/Time, File Pass to?

11/30/10 Typist

Date/Time, File Return to?

☐ : Prell. Report☒ : Final Report

Days Of Repair: 7

Resurvey No. of Trip: 1+1

Survey Fee:

Transportation:

S - RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$) 32007

170
50
50+50
39
359



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18006061/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 03-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7850S	Veh. Inspected	SJY 2780T
Policy No.		Coverage (\$)	0.00
Claim No.	D18002595MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	30/03/2018	Inspection Date	03/04/2018
Survey held at	160 SIN MING DRIVE #04-03		
Repairer	PANG & TAN VEHICLE SERVICE CENTRE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	02-04-2018	Our Ref No. D18002595MFSH
Accident Date	30-03-2018	Claim Type. Third Party
Insured Vehicle	SHA7850S	Third Party Vehicle. SJY2780T
Survey Location	160 SIN MING DRIVE #04-03 SIN MING AUTOCITY	
Contact Person.	MR PANG	
Contact No.	62555711/ 97318588	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PANG & TAN VEHICLE SERVICE CENTRE	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236548)



PRI Documents



Close



PRI Header Details

Claim No	D18002595MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CHEONGH
Workshop Name	PANG & TAN VEHICLE SERVICE CENTRE (Contact Person : MR PANG)	Survey Location & Contact Details	160 SIN MING DRIVE #04-03 SIN MING AUTOCITY Mobile: 97318588 , Phone: 62555711 , Fax: 0 EmailId: MAIL@CHEONGHOH.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA7850S	TP Vehicle No	SJY2780T
PRI Recieved Date	02-04-2018 05:50:00 PM	Surveyor Appointed Date	03-04-2018 08:42:12 AM	Surveyor Accept Date	03-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Kenneth Kong (LKKAUTO)

From: Pang & Tan Michelle <pangtan_michelle@yahoo.com.sg>
Sent: Tuesday, 23 October, 2018 10:37 AM
To: Kenneth Kong (LKKAUTO)
Subject: Re: After paint photos for SJY2780T

Dear Kenneth

We confirmed to accept COR @ Lump Sum \$3,200.00 (before GST) and 07 working days.

Thank you.

Best Regards
Michelle Tan
Pang & Tan Vehicle Service Centre

On Monday, 17 September 2018, 9:23:42 AM GMT+8, Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com> wrote:

Attach finalised for SJY 2780T. Kenneth

From: Pang & Tan Michelle [mailto:pangtan_michelle@yahoo.com.sg]
Sent: Thursday, 2 August, 2018 5:43 PM
To: Kenneth Kong (LKKAUTO)
Subject: Fw: After paint photos for SJY2780T

Dear Kenneth

Please see attached Estimate and After paint photos.

Thank you.

Best Regards

Michelle Tan

Pang & Tan Vehicle Service Centre

160 Sin Ming Drive #04-03

Sin Ming AutoCity

Singapore 575722

PANG & TAN VEHICLE

160 SIN MING DRIVE #04-03

Not Authorized
*11 May @ 320dp**7 days*Quotation for Accident Repair - SJY 2780 T (TOYOTA CAMRY 2.4)

Date: 04/05/2018

S/N	Parts Replacement - List	QTY	Price SGD\$	
1	BOOTLID	1	<i>fl</i> \$896.70	<i>X</i>
2	BOOTLID TOYOTA LOGO	1	<i>na</i> \$51.50	
3	BOOTLID "CAMRY" EMBLEM	1	<i>na</i> \$55.60	
4	BOOTLID "2.4" EMBLEM	1	<i>na</i> \$41.90	
5	BOOTLID "VVT-I" EMBLEM	1	<i>na</i> \$36.00	
6	BOOTLID WEATHERSTRIP	1	<i>su</i> \$188.95	
7	BOOTLID LOCK	1	<i>fl</i> \$496.50	
8	BOOTLID LOCK CATCH	1	<i>fl</i> \$56.97	
9	BOOTLID OUTER GARNISH	1	<i>su</i> \$182.80	
10	BOOTLID REFLECTOR LH/RH	2	<i>su</i> \$385.80	
11	REAR BUMPER	1	<i>bu</i> \$755.85	<i>✓</i>
12	REAR BUMPER SCREW CAP COVER	2	<i>su</i> \$36.90	<i>X</i>
13	REAR BUMPER CLIPS	10	<i>na</i> \$30.00	<i>✓</i>
14	REAR BUMPER SIDE RETAINER LH (LONG)	1	<i>diy</i> \$61.90	<i>✓</i>
15	REAR BUMPER SIDE RETAINER RH (LONG)	1	<i>su</i> \$61.90	<i>X</i>
16	REAR BUMPER SIDE RETAINER LH (SHORT)	1	<i>diy</i> \$55.60	<i>✓</i>
17	REAR BUMPER SIDE RETAINER RH (SHORT)	1	<i>su</i> \$55.60	<i>X</i>
18	REAR END PANEL	1	<i>fl</i> \$795.60	<i>X</i>
19	REAR END PANEL TOP GARNISH	1	<i>fl</i> \$391.90	<i>X</i>
20	REAR END PANEL TOP GARNISH CLIPS	6	<i>su</i> \$18.00	<i>X</i>
21	REAR EXHAUST MUFFLER	1	<i>na</i> \$915.00	<i>X</i>
22	REAR EXHAUST MUFFLER RUBBER MOUNTING	3	<i>su</i> \$55.60	<i>✓</i>
23	REAR EXHAUST MUFFLER OUTER CHROME	1	<i>su</i> \$108.90	<i>✓</i>
24	TAILLAMP LH	1	<i>mg & m</i> \$425.60	<i>✓</i>
25	TAILLAMP RH	1	<i>su</i> \$425.60	<i>X</i>
26	TAILLAMP CLIPS	<i>2/1</i>	<i>na</i> \$18.90	<i>✓ 945</i>
27	REAR FENDER INNER TRIM LINING LH	1	<i>su</i> \$574.60	<i>X</i>
28	REAR FENDER INNER TRIM LINING RH	1	<i>su</i> \$574.60	<i>✓</i>
29	REAR FENDER INNER TRIM LINING CLIPS	10	<i>na</i> \$30.00	<i>✓</i>
30	REAR SPARE TYRE TOP BOARD	1	<i>su</i> \$289.10	<i>X</i>
31	REAR FENDER LH	1	<i>bu</i> \$882.00	<i>✓</i>
32	REAR WINDSCREEN GLASS MOULDING	1	<i>na</i> \$256.90	<i>✓</i>
			\$9,212.77	
Less 25%			\$2,303.19	
Subtotal			\$6,909.58	

S/N	Parts Replacement - S/Nett	QTY	Price SGD\$
1	REAR NUMBER PLATE	1	<i>su</i> \$60.00 <i>X</i>

2 REVERSE SENSOR

1	<i>Shan</i>	\$250.00	<i>2005</i>
Subtotal		\$310.00	
Parts Total		\$7,219.58	

1	Check rear wiring and lighting system	\$100.00	<i>201</i>
2	To remove and refix rear windscreen glass	\$80.00	<i>✓</i>
4	To rust proof on affected areas	\$150.00	<i>301</i>
5	Labour to renew and panel beating affected areas	\$1,200.00	<i>1000</i>
6	To remove and renew reverse sensor	\$100.00	<i>501</i>
7	To dismantle and renew rear exhaust muffler	<i>nn</i> \$100.00	<i>x</i>
8	To putty, spray paint and polish affected areas	\$1,200.00	<i>800</i>
Labour Total		\$2,930.00	
Parts & Labour Total		\$10,149.58	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118006061/Ktd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-11-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7850S	Veh. Inspected	SJY 2780T	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002595MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY G (A)	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	ACV403021859	Colour	METALLIC SILVER	
Odometer	240709	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	MICHELIN	7 mm	
L/H Front Tyre	215/60 R16	MICHELIN	7 mm	
R/H Rear Tyre	215/60 R16	MICHELIN	7 mm	
L/H Rear Tyre	215/60 R16	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/03/2018	Inspection Date	03/04/2018	
Survey held at	160 SIN MING DRIVE #04-03			
Repairer	PANG & TAN VEHICLE SERVICE CENTRE			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 2780T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	TO REPAIR SEE LABOUR	896.70	-
1	BOOTLID TOYOTA LOGO	NOT NECESSARY	51.50	-
1	BOOTLID "CAMRY" EMBLEM	NOT NECESSARY	55.60	-
1	BOOTLID "2.4" EMBLEM	NOT NECESSARY	41.90	-
1	BOOTLID "VVT-I" EMBLEM	NOT NECESSARY	36.00	-
1	BOOTLID WEATHERSTRIP	SERVICEABLE	188.95	-
1	BOOTLID LOCK	TO REPAIR SEE LABOUR	496.50	-
1	BOOTLID LOCK CATCH	TO REPAIR SEE LABOUR	56.97	-
1	BOOTLID OUTER GARNISH	SERVICEABLE	182.80	-
2	BOOTLID REFLECTOR LH/RH	SERVICEABLE	385.80	-
1	REAR BUMPER	BUCKLED	755.85	755.85
2	REAR BUMPER SCREW CAP COVER	SERVICEABLE	36.90	-
10	REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR BUMPER SIDE RETAINER LH (LONG)	DISTORTED	61.90	61.90
1	REAR BUMPER SIDE RETAINER RH (LONG)	SERVICEABLE	61.90	-
1	REAR BUMPER SIDE RETAINER LH (SHORT)	DISTORTED	55.60	55.60
1	REAR BUMPER SIDE RETAINER RH (SHORT)	SERVICEABLE	55.60	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	795.60	-
1	REAR END PANEL TOP GARNISH	TO REPAIR SEE LABOUR	391.90	-
6	REAR END PANEL TOP GARNISH CLIPS	SERVICEABLE	18.00	-
1	REAR EXHAUST MUFFLER	NOT NECESSARY	915.00	-
3	REAR EXHAUST MUFFLER RUBBER MOUNTING	SERVICEABLE	55.60	-
1	REAR EXHAUST MUFFLER OUTER CHROME	SERVICEABLE	108.90	-
1	TAILLAMP LH	MTG CRACKED	425.60	425.60
1	TAILLAMP RH	SERVICEABLE	425.60	-
2	TAILLAMP CLIPS	NECESSARY (1 PC ONLY)	18.90	9.45
1	REAR FENDER INNER TRIM LINING LH	SERVICEABLE	574.60	-

Report Ref No. CS/FC118006061/Ktd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER TRIM LINING RH	SERVICEABLE	574.60	-
10	REAR FENDER INNER TRIM LINING CLIPS	NOT NECESSARY	30.00	-
1	REAR SPARE TYRE TOP BOARD	SERVICEABLE	289.10	-
1	REAR FENDER LH	BUCKLED	882.00	882.00
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	256.90	256.90
	LESS 25% DISCOUNT		-2,303.19	-619.33
			6,909.58	1,857.97
	SPECIAL NETT ITEMS			
1	REAR NUMBER PLATE (SN)	SERVICEABLE	60.00	-
1	REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			310.00	200.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		100.00	20.00
	TO REMOVE AND REFIX REAR WINDSCREEN GLASS.		80.00	80.00
	TO RUST PROOF ON AFFECTED AREAS.		150.00	30.00
	LABOUR TO RENEW AND PANEL BEATING AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF BOOTLID,BOOTLID LOCK,BOOTLID LOCK CATCH,REAR END PANEL AND REAR END PANEL TOP GARNISH.		1,200.00	1,000.00
	TO REMOVE AND RENEW REVERSE SENSOR.		100.00	50.00
	TO DISMANTLE AND RENEW REAR EXHAUST MUFFLER.	NOT NECESSARY	100.00	-
	TO PUTTY,SPRAY PAINT AND POLISH AFFECTED AREAS.		1,200.00	800.00
			2,930.00	1,980.00
	GRAND TOTAL		10,149.58	4,037.97
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,200.00

Report Ref No. CS/FCI18006061/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.