

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2918P

DATE 2/4/2018 11:25

MAKE :

MODEL : HYUNDAI i40

AIG/LKK
RIGHT REAR

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) Left Rear		\$ 100.00	\$ 200.00	Nett
	Rear Bumper x repair Rear Fender x repair			\$ 300.00	
	Labour Charge				
	Panel Beating			\$ 250.00 ²⁰⁰	
	Spray Painting Charge			\$ 250.00 ²⁰⁰	
	Remove/Refix Reverse Sensor			\$ 120.00	
	TOTAL LABOUR			\$ 620.00	
	ESTIMATE TOTAL			\$ 920.00	
<p>Kahin Ullas A 2/4/18 12:00h 2 Rep. P/P After Repair gll</p>					
<div> <p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					