

LKK

All

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3865R

DATE 2/4/2018 10:59

MAKE :

MODEL : HYUNDAI i40

Cheng

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper X repair			\$ 603.60
	Rear Bumper Reinforcement X			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) X		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket X			\$ 49.00
	Rear Bumper Clips X			\$ 22.00
	Rear Bumper Sponge X			\$ 143.40
	Rear Bumper Under Cover X			\$ 225.00
	SUB TOTAL			\$ 1,907.35
	LESS 20%			\$ 381.47
	DISCOUNTED TOTAL			\$ 1,525.88
	Rear Bumper Reverse Sensor X			\$ 135.70
				Nett
				\$ 135.70
	Labour Charge			
	Panel Beating			\$ 250.00 100
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 50.00 X
	R/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 670.00
	ESTIMATE TOTAL			\$ 2,331.58
<p>Ka hui 1 (KK)</p> <p>2/4/18 1345hrs</p> <p>2 Days</p> <p>4s</p> <p>After Repair photo</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				