



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/05/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0098864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System,

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

Alan 96869276

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/17/VC00/100847	Date of Loss:	26/03/2018
Vehicle Reg. No.:	GQ8208T	Driveable?	
Driver Age/Info:	58 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SNOWY SERVICES		
Driver:	WOO SIEW KHUEN DERRICK		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Vehicle Reg. Date:	30/05/2014
Vehicle Colour:	LIGHT GREY	Chassis No:	JTFHT02P300141088
Engine No:	1KD2404478		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	12,302.95
Miscellaneous Items	0.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,682.95
+ GST 7.00% (S\$)	1,167.81
Nett Amount (S\$)	17,850.76

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)
Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GQ8208T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP LH	0.00	0.00	CR4 / *190.00F
2	1		*TAILLAMP PANEL LH	0.00	0.00	PA / *160.00F
3	1		*LH REAR FENDER	0.00	0.00	TOR / *958.00F
4	1		*LH REAR FENDER DOOR RAIL	0.00	0.00	RA / *495.00F
5	1		*LH REAR FENDER RAIL COVER	0.00	0.00	CA / *60.00F
6	1		*LH REAR FENDER INNER BOARD	0.00	0.00	PA / *310.00F
7	1		*LH SIDE DOOR	0.00	0.00	PA / *850.00F
8	1		*LH FRONT DOOR	0.00	0.00	PA / *750.00F
9	2		*LH FRONT DOOR HINGE	0.00	0.00	PA / *140.00F
10	1		*LH FRONT DOOR RUBBER	0.00	0.00	neu / *210.00F
11	1		*LH FRONT DOOR STEP GARNISH	0.00	0.00	neu / *210.00F
12	1		*LH FRONT CORNER PANEL	0.00	0.00	PA / *210.00F
13	1		*FRONT WIPER COWLING	0.00	0.00	neu / *230.00F
14	1		*BONNET	0.00	0.00	PA / *350.00F
15	2		*BONNET HINGE	0.00	0.00	X / *140.00F
16	1		*HEADLAMP LH	0.00	0.00	CR4 / *580.00F
17	1		*HEADLAMP PANEL LH	0.00	0.00	X / *160.00F
18	1		*FRONT BUMPER	0.00	0.00	DE / *260.00F
19	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	DE / *190.00F
20	1		*FRONT GRILLE ASSY	0.00	0.00	CR4 / *380.00F
21	1		*FRONT BUMPER FOG LAMP COVER LH	0.00	0.00	X / *50.00F
22	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	PA / *290.00F
23	1		*FRONT BUMPER SIDE BRACKET LH	0.00	0.00	neu / *50.00F
24	1		*FRONT SUPPORT PANEL	0.00	0.00	neu / *450.00F
25	1		*FRONT DOOR PILLAR LH	0.00	0.00	PA / *680.00F
26	1		*LH FRONT DOOR LOCK	0.00	0.00	X / *260.00F
27	1		*LH FRONT DOOR INNER TRIM	0.00	0.00	X / *570.00F
28	1		*LH FRONT DOOR REGULATOR WITH MOTOR	0.00	0.00	PA / *480.00F
29	1		*RAD COOLANT	0	0.00	neu / *30.00FS
30	1		*LH FRONT DOOR LICENSE STICKER	0	0.00	neu / *20.00FS
31	1		*BONNET LOGO	0.00	0.00	neu / *40.00F
32	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	neu / *130.00F
33	1		*FRONT WINDSCREEN SEALANT	0	0.00	neu / *40.00FS
34	1		*ACCIDENT TOWING TO FAN YOONG	0	0.00	/ *55.00FS
35	1		*LH FRONT LOWER ECU CONTROL UNITS	0	0.00	CR4 / *850.00

F=Franchise part. S=SpcNell.

Sub Total (S\$)	10,828.00
+ Margin on L,N Items 15.00% (S\$)	1,474.95
Total Parts (S\$)	12,302.95

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

P-9763
+158
P-11,227.45
SM-145.00
LC-3520
14,892.45
20614-# 11,913.96

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT & REAR LIGHTING WATER & LEAKAGE TEST	New	40.00 ✓
2	TO REMOVE & INSTALL FRONT WINDSCREEN IN ORDER TO CUT OFF FRONT DOOR PILLAR LH	New	120.00 ✓
3	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	100.00 60
4	TO REMOVE & TRANSFER ITEMS TO LH SIDE NEW DOOR	New	100.00 60
5	TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO CUT OFF SUPPORT PANEL	New	160.00 280
6	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET, ROOF LINING IN ORDER TO CUT OFF LH REAR FENDER	New	200.00 100
7	TO CUT OFF LH FRONT DOOR PILLAR SUPPORT PANEL LH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW ALL DAMAGES PARTS	New	2,000.00 1700
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00 ✓
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,300 1,600.00
Gross Labour Cost (S\$)			4,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LC-3520
Rasul
Hp 90010068
14 days
43
EXCESS: 700
05/04/18 @ 1220
Revert
Resurvey after repair