

Surveyor

Merimen

From (Person)

Rasul

Gerald Poh

ASSIGNMENT (Office)

LPC

Date/Time 3/4/18 @ 2.47pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GQ 8208T

Insured:

at Workshop m/s

Mova Automotive

Tel:

G2723892 / 96869276

of

No. 22 Jln Kilang #07-01

Alan

Policy No:

Z117/VCOO1100847

Claim No:

17/18/18/VCOO/020489

Sum Insured:

Excess:

\$700.00

Make of Vcl:

(Client's Record)

D.O.A. 26/03/2018

CA (REV) / REP. / REV 24 HRS

05042018 @ 15 Pan Yang Rd

H.O.B. Endorsement

Date/Time:

3:06pm @ 3/4/18

Person Contacted:

Nitha

Vehicle IN

OUT

Date/Time

Action/Instruction (✓) Estimate

GQ 8208T - (CA/LPC18005816/R1p43

D.O.A. 26/3/18

6/4/18

Revert by merimen

9/4/18

Recd authorise repair from Gerald by email

9/4/18

Informed Nitha C/A on LS repair ex \$700 by email

22/5/18

@ 2:12pm Alan will email us finalise

REF: LPC 0654 9551A

ASSIGNMENT

From: Date: 5/4/18 Veh No: GQ 8208T Yr Regn: 2014 MYA

Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or

To inspect Vehicle No: GQ 8208T Make: TOYOTA HILUX C.C. 2982

at Workshop no: Mova Colour: Grey A/C Insured / Std / NI / NA

of: 15 Fan Yong Rd Sp. Reading: 159384 T/Radio: Insured / Std / NI / NA

Insured: Eng/No:

Policy No: C/No: STFHT027300141088

Claims No: Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: Excess: \$700.00 Steering: In order / Jammed / Leaked / Burnt or

(Client's Record) Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition) Tyre Size: F: 195/80R15 R:

Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / OKO or

Bal. or Market Value: 57K

IDAC Accident Report: Consistent? : Yes or No

GIA / FR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No


Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or N/S Frt & N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.



6/6/18 LS \$11,900 confirmed by email (Ref 4782.95, 2990)

RECEIVED 07 JUN 2018

Date/Time: File Pass to? ☐ : Preli. Report

is ☐ : Final Report

Date/Time: File Return to?

to: 716- typist

Report Format: maximen

Lump Sum / I.B.I: 11,900/-

Days Of Repair: 14

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp: IS

☐ Interview: IS

☐ Tech. Invs: IS

☐ Wheel and: IS

Survey Fee:

Transportation:

100 - 100

852

11618

TOTAL:

6x15=90
170+90=260
260+20%=312

312
50
50
108
520+10

(530)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CS/LPC18006098/R1vd3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 03-04-2018



Code : LPC2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	GQ 8208T
Policy No. Z/17/VC00/100847	Coverage (\$)	0.00
Claim No. 17/18/18/VC00/020489	Excess (\$)	700.00
Assign From MERIMEN (GERALD POH)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Report Date 26/03/2018	Inspection Date
Report held at MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722	

5a. Remarks

1) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
2) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018 Sendback Est	03 Apr 2018 13:30 S\$16,682.95	03 Apr 2018 14:47 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SNOWY SERVICES , Co. Reg. No.: 53150654A		
Vehicle Reg. No.:	GQ8208T	Date of Loss:	26/03/2018 15:00 - :59 [45 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 17/18/18/VC00/020489	Policy/Cover Note No.:	Z/17/VC00/100847 (Comprehensive)
		Excess:	S\$700.00
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/04/2018]		
Driver/Custodian:	WOO SIEW KHUEN DERRICK (58 / Male), NRIC: S1394871B, Tel: +6591445922		
Adj Asg. Remarks:	SURVEY & REVERT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 9 April 2018 10:36 AM
To: 'nitha@nova.com.sg'; SUR
Subject: GQ 8209T-DOA: 26/3/2018 (LONPAC OD)

Dear Nitha,

As instructed by our client , please proceed to repair the insured vehicle **GQ 8208T on Lump Sum basis (Excess \$700/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Monday, 9 April 2018 9:37 AM
To: 'GERALD POH WEE BIN'; SUR
Cc: 'MT_Claim_SG'; assignments
Subject: RE: OD CLAIM - GQ8208T

Dear Mr Gerald,

Thank you for your email.

Dear Veron,

FYNA. Our ref: CS/LPC18006098/R1vd3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]
Sent: Monday, 9 April, 2018 9:02 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: FW: OD CLAIM - GQ8208T

Dear Catherine,

Your letter of 6 April 2018 refers.

You may proceed to authorize repair as adjusted.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN
Sent: Tuesday, 3 April, 2018 2:50 PM
To: assignments@lkkauto.com
Cc: 'mt_claim@lonpac.com'
Subject: OD CLAIM - GQ8208T

Our Ref : 17/18/18/VC00/020489

Dear Catherine,

Kindly proceed to survey and revert.

The details are in Merimen.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse Singapore 199555	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Gerald Poh	Date: 06 Apr 2018

Preliminary Advice

Vehicle No	: GQ8208T	Accident Date	: 26/03/2018
Make	: TOYOTA HIACE	Policy No.	: Z/17/VC00/100847
Assignment Date	: 03/04/2018	Excess	: S\$700.00
Date of Inspection	: 05/04/2018	Est. Duration of Repair	: 14.00
Inspection At	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) NO. 22 JALAN KILANG, #07-01, MOVA BUILDING SINGAPORE 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front and n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,682.95
Revised Amount	:S\$	12,309.70
Check Items (Estimated)	:S\$	1,725.00
Total	:S\$	14,034.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	57,000.00
COE / PARF Rebate	:S\$	22,307.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,693.00

Remarks

☒ (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

☐ () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

☐ () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9551A
Vehicle Details	
Vehicle No.:	GQ8208T
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2404478
Chassis No.:	JTFHT02P300141088
Maximum Power Output:	-
Open Market Value:	\$27,502.00
Original Registration Date:	30 May 2014
First Registration Date:	30 May 2014
Transfer Count:	1
Actual ARF Paid:	\$1,376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$36,301.00
COE Rebate Amount:	\$22,307.00
Total Rebate Amount:	\$22,307.00

The information contained herein is correct as at 06 Apr 2018

OK

57,000
22,307
34,693

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	GQ8208T
Vehicle Type:	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA HIACE VAN TURBO 5 DR MANUAL
Chassis No.:	JTFHT02P300141088
Propellant:	Diesel
Engine No.:	1KD2404478
Engine Capacity:	2982 cc
Maximum Power Output:	-
Maximum Laden Weight:	2800 kg
Unladen Weight:	1740 kg
Year Of Manufacture:	2014
Original Registration Date:	30 May 2014
Lifespan Expiry Date:	29 May 2034
COE Category:	C - Goods Vehicle & Bus
Quota Premium:	\$36,301.00
COE Expiry Date:	29 May 2024
Road Tax Expiry Date:	29 May 2018
Inspection Due Date:	29 May 2018
Intended Transfer Date:	29 Mar 2018
CO2 Emission:	216.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 29 May 2018. You may renew the road tax from 28 Feb 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 29 May 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable (From 30 May 2018 to 29 Nov 2018)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	0.00	-	0.00
Total Amount Payable:			25.00

Amount Payable (From 30 May 2018 to 29 May 2019)

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	0.00	-	0.00
Total Amount Payable:			25.00

Message

This vehicle has a road tax Over Payment of \$341.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.

You may print this page for reference.

OK

Print

OD Lompce

MMQV18041401 / Nova Automotive Pte Ltd - Bukit Merah
ENTRY DATE & TIME: 27/03/2018 15:34
SUBMITTED BY: Chio Ziling

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 29/03/2018 09:53

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/03/2018 15:34
Date Of Accident	26/03/2018 15:40
Exact Location Of Accident	JURONG WEST AVE 2 TOWARDS PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GQ8208T
Insured/Policyholder	
Name Of Registered Owner	SNOWY SERVICES
Co Reg No	53150654A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91445922
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE DIESEL
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/17/VC00/100847
Cover Note Number	

Driver

Name of Driver	WOO SIEW KHUEN DERRICK
NRIC No	S1394871B
Date Of Birth	14/05/1959
Occupation	INDOOR
Date Of Driving Pass	09/12/1982
Driving Experience	35 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91445922
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 642 PASIR RIS DRIVE 10
#07-38
Postcode 510642
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : UNKNOWN
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMB3032Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category BUS
Name of Driver HOO LAI KHANG
NRIC/Passport Number S8869997A
Contact Number 93848598
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reputate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GRI Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report as the terms and conditions of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA):**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes (mail packages), and/or
(v) complying with applicable law, in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law/lawyer firms), which may be sited outside of Singapore, for one or more of the above Purposes.

SWIFT SERVICES

X  31445922
Policyholder's Signature / Date & Time

 31445922
Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Sketch Plan

REFER TO ATTACHED SKETCH PLAN



Sketch Plan #2



①
- RECORDS

②
- PROJECT

Sketch Plan #3

Describe Circumstances of the Accident

On 26/03/2016 at about 15:00hrs I was driving Honda CG 125 on
 Tuong Vuong Avenue towards P.E. As I was journeying heavily I was
 going slowly as the left side was a bus station. As the
 bus SMR 30322 coming towards I slow down to allow the bus SMR 30322
 to pass ahead of my car CG 125. As I was slowing down my van 14936
 skidded towards the bus SMR 30322 & hit it on the right side.
 There was no injuries for the van driver Mr. Van Hung & myself.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO
 SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY
 FOR MORE INFORMATION.

Please State:

☒ Claim Own Policy ☐ Claim Third Party ☐ Claim OD/TP at other workshop ☐ Reporting only

Declaration

We declare the foregoing particulars are true in every respect.

Signature

X

Policyholder's Signature (Date & Time)

Driver's Signature (If driver is not the policyholder) (Date & Time)

Witnessed by Reporting Centre Personnel





Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/05/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0098864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

*Alan 96869276***PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/17/VC00/100847	Date of Loss:	26/03/2018
Vehicle Reg. No.:	GQ8208T	Driveable?	
Driver Age/Info:	58 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SNOWY SERVICES		
Driver:	WOO SIEW KHUEN DERRICK		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Vehicle Reg. Date:	30/05/2014
Vehicle Colour:	LIGHT GREY	Chassis No:	JTFHT02P300141088
Engine No:	1KD2404478		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	12,302.95
Miscellaneous Items	0.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	16,682.95
+ GST 7.00% (\$\$)	1,167.81
Nett Amount (\$\$)	17,850.76

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GQ8208T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP LH	0.00	0.00	CAH / *190.00 F
2	1		*TAILLAMP PANEL LH	0.00	0.00	PH / *160.00 F
3	1		*LH REAR FENDER	0.00	0.00	7000 / *958.00 F
4	1		*LH REAR FENDER DOOR RAIL	0.00	0.00	DE / R / *495.00 F ✓
5	1		*LH REAR FENDER RAIL COVER	0.00	0.00	CAH / *60.00 F
6	1		*LH REAR FENDER INNER BOARD	0.00	0.00	7000 / *310.00 F ✓
7	1		*LH SIDE DOOR	0.00	0.00	PH / *850.00 F
8	1		*LH FRONT DOOR	0.00	0.00	PH / *750.00 F
9	2		*LH FRONT DOOR HINGE	0.00	0.00	N / *140.00 F ✓
10	1		*LH FRONT DOOR RUBBER	0.00	0.00	NE / *210.00 F
11	1		*LH FRONT DOOR STEP GARNISH	0.00	0.00	SUL / *210.00 F
12	1		*LH FRONT CORNER PANEL	0.00	0.00	PH / *210.00 F
13	1		*FRONT WIPER COWLING	0.00	0.00	CAH / *230.00 F
14	1		*BONNET	0.00	0.00	PH / *350.00 F
15	2		*BONNET HINGE	0.00	0.00	SUL X / *140.00 F X
16	1		*HEADLAMP LH	0.00	0.00	CAH / *580.00 F
17	1		*HEADLAMP PANEL LH	0.00	0.00	SUL X / *160.00 F X
18	1		*FRONT BUMPER	0.00	0.00	DE / *260.00 F
19	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	DE / *190.00 F
20	1		*FRONT GRILLE ASSY	0.00	0.00	CAH / *380.00 F
21	1		*FRONT BUMPER FOG LAMP COVER LH	0.00	0.00	SUL X / *50.00 F X
22	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	PH / *290.00 F
23	1		*FRONT BUMPER SIDE BRACKET LH	0.00	0.00	PH / *50.00 F
24	1		*FRONT SUPPORT PANEL	0.00	0.00	PH / *450.00 F ✓
25	1		*FRONT DOOR PILLAR LH	0.00	0.00	PH / *680.00 F
26	1		*LH FRONT DOOR LOCK	0.00	0.00	PH / *260.00 F ✓
27	1		*LH FRONT DOOR INNER TRIM	0.00	0.00	PH / *570.00 F X
28	1		*LH FRONT DOOR REGULATOR WITH MOTOR	0.00	0.00	PH / *480.00 F ✓
29	1		*RAD COOLANT	0	0.00	NE / *30.00 FS
30	1		*LH FRONT DOOR LICENSE STICKER	0	0.00	NE / *20.00 FS
31	1		*BONNET LOGO	0.00	0.00	NE / *40.00 F
32	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	NE / *130.00 F
33	1		*FRONT WINDSCREEN SEALANT	0	0.00	NE / *40.00 FS
34	1		*ACCIDENT TOWING TO FAN YOONG	0	0.00	/ *55.00 FS
35	1		*LH FRONT LOWER ECU CONTROL UNITS	0	0.00	CAH / *650.00 FS

F=Franchise part. S=Spec/Natl.

Sub Total (\$S)	10,828.00
+ Margin on L,N Items 15.00% (\$S)	1,474.95
Total Parts (\$S)	12,302.95

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT & REAR LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN IN ORDER TO CUT OFF FRONT DOOR PILLAR LH	New	120.00
3	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	100.00
4	TO REMOVE & TRANSFER ITEMS TO LH SIDE NEW DOOR	New	100.00
5	TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO CUT OFF SUPPORT PANEL	New	160.00
6	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET, ROOF LINING IN ORDER TO CUT OFF LH REAR FENDER	New	200.00
7	TO CUT OFF LH FRONT DOOR PILLAR SUPPORT PANEL LH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW ALL DAMAGES PARTS	New	2,000.00
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,600.00
Gross Labour Cost (\$\$)			4,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 9010068

14 days

43

EXCESS: 700

05/04/18 @ 1220

Revert

Resey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 6 June 2018 5:50 PM
To: Alan Chng; Rasul (LKKAuto)
Cc: Admin A; SUR
Subject: RE: finalization for vhe no:GQ8208T *** LKK REF : CS/LPC18006098/R1vd3

Dear Alan,

Confirmed lump sum \$11,900 before excess \$700 @ 14 days working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Wednesday, 6 June 2018 1:15 PM
To: Alan Chng <tuckmeng@nova.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>; Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: finalization for vhe no:GQ8208T *** LKK REF : CS/LPC18006098/R1vd3

Dear Alan,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CS/LPC18006098/R1vd3	Veron

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Alan Chng [<mailto:tuckmeng@nova.com.sg>]
Sent: Wednesday, 6 June, 2018 12:55 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: finalization for vhe no:GQ8208T

Dear.Rasul,

Please refer the estimate FYI.

Repair cost lump sum \$11,900

Please confirm and return by email by ASAP.

Thanks!

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151

4/3/2018


MOVA

Automotive Pte Ltd

\$11,900

 FAN YONG
 Estimate Report

 Main Office : No. 22, Jalan Klang, Singapore 159419
 Tel: 6476 3333 Fax: 6271 5531

 Service Centre : Block 100B, Bukit Merah Lane 3,
 #01-04/05/08/116, Singapore 159722
 Tel: (65) 6476 3333 (B Lines) Fax: (65) 6270 8314
 www.mova.com.sg
 GST Reg. No: M2-0088854-2

 Mova Spray Centre
 2K Oven Spray Painting System

 Power-M Automotive Pte Ltd
 Specialise in Car Air-con Services,
 Car Audio & Hi-Fi System.

 Hilton Car Rental Centre
 Hilton Auto Trading
 Dealing in New/Used Cars, Hire Purchase & Insurance.


INSURER:

Lonpac Insurance Bhd (HQ)

Alan 96869276
PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/17/VC00/100847	Date of Loss:	26/03/2018
Vehicle Reg. No.:	GQ8208T	Driveable?	
Driver Age/Info:	58 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SNOWY SERVICES		
Driver:	WOO SIEW KHUEN DERRICK		
Make/Model:	TOYOTA HIACE, 3.0 D TURBO 5 DR (M)	Vehicle Reg. Date:	30/05/2014
Vehicle Colour:	LIGHT GREY	Chassis No:	JTFHT02P300141088
Engine No:	1KD2404478		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	12,302.95
Miscellaneous Items	0.00
Labour	4,380.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	16,682.95
+ GST 7.00% (S\$)	1,167.81
Nett Amount (S\$)	17,850.76

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)

Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GQB205T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILLAMP LH	0.00	0.00	CAH / *190.00F
2	1		*TAILLAMP PANEL LH	0.00	0.00	PH / *160.00F
3	1		*LH REAR FENDER	0.00	0.00	John / *258.00F
4	1		*LH REAR FENDER DOOR RAIL	0.00	0.00	R / *495.00F
5	1		*LH REAR FENDER RAIL COVER	0.00	0.00	CAH / *60.00F
6	1		*LH REAR FENDER INNER BOARD	0.00	0.00	PH / *310.00F
7	1		*LH SIDE DOOR	0.00	0.00	PH / *850.00F
8	1		*LH FRONT DOOR	0.00	0.00	PH / *750.00F
9	2		*LH FRONT DOOR HINGE	0.00	0.00	PH / *140.00F
10	1		*LH FRONT DOOR RUBBER	0.00	0.00	new / *210.00F
11	1		*LH FRONT DOOR STEP GARNISH	0.00	0.00	Seal / *210.00F
12	1		*LH FRONT CORNER PANEL	0.00	0.00	PH / *210.00F
13	1		*FRONT WIPER COWLING	0.00	0.00	Out / *230.00F
14	1		*BONNET	0.00	0.00	PH / *350.00F
15	2		*BONNET HINGE	0.00	0.00	X / *140.00F
16	1		*HEADLAMP LH	0.00	0.00	CAH / *580.00F
17	1		*HEADLAMP PANEL LH	0.00	0.00	X / *160.00F
18	1		*FRONT BUMPER	0.00	0.00	DE / *290.00F
19	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	DE / *190.00F
20	1		*FRONT GRILLE ASSY	0.00	0.00	CAH / *380.00F
21	1		*FRONT BUMPER FOG LAMP COVER LH	0.00	0.00	X / *50.00F
22	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	PH / *290.00F
23	1		*FRONT BUMPER SIDE BRACKET LH	0.00	0.00	PH / *50.00F
24	1		*FRONT SUPPORT PANEL	0.00	0.00	PH / *450.00F
25	1		*FRONT DOOR PILLAR LH	0.00	0.00	PH / *680.00F
26	1		*LH FRONT DOOR LOCK	0.00	0.00	X / *260.00F
27	1		*LH FRONT DOOR INNER TRIM	0.00	0.00	X / *570.00F
28	1		*LH FRONT DOOR REGULATOR WITH MOTOR	0.00	0.00	PH / *480.00F
29	1		*RAD COOLANT	0	0.00	new / *30.00FS
30	1		*LH FRONT DOOR LICENSE STICKER	0	0.00	new / *20.00FS
31	1		*BONNET LOGO	0.00	0.00	new / *40.00F
32	1		*FRONT WINDSCREEN MOULDING	0.00	0.00	new / *130.00F
33	1		*FRONT WINDSCREEN SEALANT	0	0.00	new / *40.00FS
34	1		*ACCIDENT TOWING TO FAN YOONG	0	0.00	/ *55.00FS
35	1		*LH FRONT LOWER ECU CONTROL UNITS	0	0.00	CAH / *850.00

F=Franchise part S=Spares

Sub Total (\$S)	10,828.00
+ Margin on L/N Items 15.00% (\$S)	1,474.95
Total Parts (\$S)	12,302.95

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

P-9763
+158
P-11,227.45
SM-145.00
LC-3520
14,892.45
20614 = \$ 11,913.96

4/3/2018

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT FRONT & REAR LIGHTING WATER & LEAKAGE TEST	New	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN IN ORDER TO CUT OFF FRONT DOOR PILLAR LH	New	120.00
3	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	100.00
4	TO REMOVE & TRANSFER ITEMS TO LH SIDE NEW DOOR	New	100.00
5	TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO CUT OFF SUPPORT PANEL	New	160.00
6	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET, ROOF LINING IN ORDER TO CUT OFF LH REAR FENDER	New	200.00
7	TO CUT OFF LH FRONT DOOR PILLAR SUPPORT PANEL LH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW ALL DAMAGES PARTS	New	2,000.00
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,300.00
Gross Labour Cost (\$\$)			4,380.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LC-3520
Rasul
Hp 90010068
14 days
43
EXCESS: 700
05/04/18 @ 1220
Revert
Resurvey after repair

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018 Sendback Est	03 Apr 2018 13:30 S\$16,682.95	03 Apr 2018 14:47 Edit Adj Rpt	S\$11,900.00 Edit Estimates	S\$11,900.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: SNOWY SERVICES , Co. Reg. No.: 53150654A									
Vehicle Reg. No.: GQ8208T		Date of Loss: 26/03/2018 15:00 - :59 [45 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 17/18/18/VC00/020489		Policy/Cover Note No.: Z/17/VC00/100847 (Comprehensive)							
		Excess: S\$700.00							
Repairer: Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333									
Handling Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Gerald Poh - 6250 7388 ext 240]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/04/2018]									
Driver/Custodian: WOO SIEW KHUEN DERRICK (58 / Male) , NRIC: S13948718, Tel: +6591445922									
Adj Asp. Remarks: SURVEY & REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• LONPAC_HQ (11/04/2018): Alert - Adj Mandate Approved (S\$14034.70) - GQ8208T - Claim Handler: Gerald Poh									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GQ8208T (17/18/18/VC00/020489)

OD

Mar 26 2018 3:00PM

[SNOWY SERVICES]

Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	03/04/18 13:30	Repairer Estimates	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 10:30	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 10:31	General View	 Load JPG	☒
2	06/04/18 10:31	General View	 Load JPG	☒
3	06/04/18 10:31	General View	 Load JPG	☒
4	06/04/18 10:31	General View	 Load JPG	☒
5	06/04/18 10:31	General View	 Load JPG	☒
6	06/04/18 10:31	General View	 Load JPG	☒
7	06/04/18 10:31	General View	 Load JPG	☒
8	06/04/18 10:31	General View	 Load JPG	☒
9	06/04/18 10:31	General View	 Load JPG	☒
10	06/04/18 10:31	General View	 Load JPG	☒
11	06/04/18 10:31	General View	 Load JPG	☒
12	06/04/18 10:31	General View	 Load JPG	☒
13	06/04/18 10:31	General View	 Load JPG	☒
14	06/04/18 10:31	General View	 Load JPG	☒
15	06/04/18 10:31	General View	 Load JPG	☒
16	06/04/18 10:31	General View	 Load JPG	☒
17	06/04/18 10:31	General View	 Load JPG	☒
18	06/04/18 10:31	General View	 Load JPG	☒
19	06/04/18 10:31	General View	 Load JPG	☒
20	06/04/18 10:31	General View	 Load JPG	☒
21	06/04/18 10:31	General View	 Load JPG	☒
22	06/04/18 10:31	General View	 Load JPG	☒
23	06/04/18 10:31	General View	 Load JPG	☒
24	06/04/18 10:31	General View	 Load JPG	☒
25	06/04/18 10:31	General View	 Load JPG	☒
26	06/04/18 10:31	General View	 Load JPG	☒
27	06/04/18 10:31	General View	 Load JPG	☒
28	06/04/18 10:31	General View	 Load JPG	☒
29	06/04/18 10:31	General View	 Load JPG	☒
30	06/04/18 10:31	General View	 Load JPG	☒
31	06/04/18 10:31	General View	 Load JPG	☒
32	06/04/18 10:31	General View	 Load JPG	☒
33	06/04/18 10:31	General View	 Load JPG	☒
34	06/04/18 10:31	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
				☒
35	06/04/18 10:31	General View	 Load JPG	☒
36	06/04/18 10:31	General View	 Load JPG	☒
37	06/04/18 10:31	General View	 Load JPG	☒
38	06/04/18 10:31	General View	 Load JPG	☒
39	06/04/18 10:31	General View	 Load JPG	☒
40	06/04/18 10:31	General View	 Load JPG	☒
41	06/04/18 10:31	General View	 Load JPG	☒
42	06/04/18 10:31	General View	 Load JPG	☒
43	06/04/18 10:31	General View	 Load JPG	☒
44	06/04/18 10:31	General View	 Load JPG	☒
45	06/04/18 10:31	General View	 Load JPG	☒
46	06/04/18 10:31	General View	 Load JPG	☒
47	06/04/18 10:31	General View	 Load JPG	☒
48	06/04/18 10:31	General View	 Load JPG	☒
49	06/04/18 10:31	General View	 Load JPG	☒
50	06/04/18 10:31	General View	 Load JPG	☒
51	06/04/18 10:31	General View	 Load JPG	☒
52	06/04/18 10:31	General View	 Load JPG	☒
53	06/04/18 10:31	General View	 Load JPG	☒
54	06/04/18 10:31	General View	 Load JPG	☒
55	06/04/18 10:31	General View	 Load JPG	☒
56	06/04/18 10:31	General View	 Load JPG	☒
57	06/04/18 10:31	General View	 Load JPG	☒
58	06/04/18 10:31	General View	 Load JPG	☒
59	06/04/18 10:31	General View	 Load JPG	☒
60	06/04/18 10:31	General View	 Load JPG	☒
61	06/04/18 10:31	General View	 Load JPG	☒
62	06/04/18 10:31	General View	 Load JPG	☒
63	06/04/18 10:31	General View	 Load JPG	☒
64	06/04/18 10:31	General View	 Load JPG	☒
65	06/04/18 10:31	General View	 Load JPG	☒
66	06/04/18 10:31	General View	 Load JPG	☒
67	06/04/18 10:31	General View	 Load JPG	☒
68	06/04/18 10:31	General View	 Load JPG	☒
69	06/04/18 10:31	General View	 Load JPG	☒
70	06/04/18 10:31	General View	 Load JPG	☒
71	06/04/18 10:31	General View	 Load JPG	☒
72	06/04/18 10:31	General View	 Load JPG	☒
73	06/04/18 10:31	General View	 Load JPG	☒
74	06/04/18 10:31	General View	 Load JPG	☒
75	06/04/18 10:31	General View	 Load JPG	☒
76	06/04/18 10:31	General View	 Load JPG	☒
77	06/04/18 10:31	General View	 Load JPG	☒
78	06/04/18 10:31	General View	 Load JPG	☒
79	06/04/18 10:31	General View	 Load JPG	☒
80	06/04/18 10:31	General View	 Load JPG	☒
81	06/04/18 10:31	General View	 Load JPG	☒
82	06/04/18 10:31	General View	 Load JPG	☒
83	06/04/18 10:31	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
84	06/04/18 10:31	General View	 Load JPG	☒
85	06/04/18 10:31	General View	 Load JPG	☒
86	06/04/18 10:31	General View	 Load JPG	☒
87	06/04/18 10:31	General View	 Load JPG	☒
88	06/04/18 10:31	General View	 Load JPG	☒
89	06/04/18 10:31	General View	 Load JPG	☒
90	06/04/18 10:31	General View	 Load JPG	☒
91	06/04/18 10:31	General View	 Load JPG	☒
92	06/04/18 10:31	General View	 Load JPG	☒
93	06/04/18 10:31	General View	 Load JPG	☒
94	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
95	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
96	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
97	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
98	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
99	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
100	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
101	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
102	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
103	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
104	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
105	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
106	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
107	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
108	06/06/18 13:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	03/04/18 13:29	Certificate of Insurance	 Load PDF	
2	03/04/18 13:29	Driver's Driving License	 Load PDF	
3	03/04/18 13:29	E-filed GIA report	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 10:34	MARK ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/03/18 09:53	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/03/18 09:51	INSURANCE CERT	 Load JPG	☒
2	29/03/18 09:51	DL & IC	 Load JPG	☒
3	29/03/18 09:51	Accident Photo	 Load JPG	☒
4	29/03/18 09:51	Accident Photo	 Load JPG	☒
5	29/03/18 09:51	Accident Photo	 Load JPG	☒
6	29/03/18 09:51	Accident Photo	 Load JPG	☒
7	29/03/18 09:51	Accident Photo	 Load JPG	☒
8	29/03/18 09:51	Accident Photo	 Load JPG	☒
9	29/03/18 09:51	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
10	29/03/18 09:51	Accident Photo		Load JPG ☒
11	29/03/18 09:51	Accident Photo		Load JPG ☒
12	29/03/18 09:51	Accident Photo		Load JPG ☒
13	29/03/18 09:51	Accident Photo		Load JPG ☒
14	29/03/18 09:51	Accident Photo		Load JPG ☒
15	29/03/18 09:51	Accident Photo		Load JPG ☒
16	29/03/18 09:51	Accident Photo		Load JPG ☒
17	29/03/18 09:51	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	29/03/18 09:49	Sketch Plan		Load JPG ☒
2	29/03/18 09:49	Sketch Plan #2		Load JPG ☒
3	29/03/18 09:49	Sketch Plan #3		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lompac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18006098/R1VD3E2

Date: 11/06/2018

REFERENCE

Insured/Claimant: SNOWY SERVICES Policy No: Z/17/VC00/100847

Date of Loss: 26/03/2018 Nature of Claim: OD Claim No: 17/18/18/VC00/020489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GQ8208T**
 Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2404478
 Reg. Date: 30/05/2014 (Man. Year: 2014) Chassis No: JTFHT02P300141088
 Colour: Grey Odometer: 159384 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: S\$57,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,302.95	11,372.45	930.50	7.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	3,520.00	860.00	19.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,682.95	14,892.45	1,790.50	10.73
Approved Total (Overridden) (S\$)		11,900.00		
- Excess (S\$)	0.00	700.00	-700.00	
(S\$)	16,682.95	11,200.00	5,482.95	32.87
+ GST 7.00/7.00% (S\$)	1,167.81	784.00	383.81	32.87
Nett Amount (S\$)	17,850.76	11,984.00	5,866.76	32.87

INSPECTION

Date of Assignment: 03/04/2018

Date Inspected: 05/04/2018 Inspected At:

15 Fan Yong Road
 Repairer : Mova Automotive Pte Ltd (Bukit Merah)

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jun 2018)
Parts:	213	TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GQ8208T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP LH (WCP)	Cracked	190.00 F	*190.00 F
2	1		*TAILLAMP PANEL LH (WCP)	Bent	160.00 F	*160.00 F
3	1		*LH REAR FENDER (WCP)	Torn	958.00 F	*958.00 F
4	1		*LH REAR FENDER DOOR RAIL (WCP)	Deformed	495.00 F	*495.00 F
5	1		*LH REAR FENDER RAIL COVER (WCP)	Cracked	60.00 F	*60.00 F
6	1		*LH REAR FENDER INNER BOARD (WCP)	Deformed	310.00 F	*310.00 F
7	1		*LH SIDE DOOR (WCP)	Bent	850.00 F	*850.00 F
8	1		*LH FRONT DOOR (WCP)	Bent	750.00 F	*750.00 F
9	2		*LH FRONT DOOR HINGE (WCP)	Bent	140.00 F	*140.00 F
10	1		*LH FRONT DOOR RUBBER (WCP)	Necessary	210.00 F	*210.00 F
11	1		*LH FRONT DOOR STEP GARNISH (WCP)	Cut	210.00 F	*210.00 F
12	1		*LH FRONT CORNER PANEL (WCP)	Bent	210.00 F	*210.00 F
13	1		*FRONT WIPER COWLING (WCP)	Cut	230.00 F	*230.00 F
14	1		*BONNET (WCP)	Bent	350.00 F	*350.00 F
15	2		*BONNET HINGE (WCP)	Serviceable	140.00 F	*- F
16	1		*HEADLAMP LH (WCP)	Cracked	580.00 F	*580.00 F
17	1		*HEADLAMP PANEL LH (WCP)	Serviceable	160.00 F	*- F
18	1		*FRONT BUMPER (WCP)	Deformed	260.00 F	*260.00 F
19	1		*FRONT BUMPER LOWER GRILLE (WCP)	Deformed	190.00 F	*190.00 F
20	1		*FRONT GRILLE ASSY (WCP)	Cracked	380.00 F	*380.00 F
21	1		*FRONT BUMPER FOG LAMP COVER LH (WCP)	Serviceable	50.00 F	*- F
22	1		*FRONT BUMPER REINFORCEMENT (WCP)	Bent	290.00 F	*290.00 F
23	1		*FRONT BUMPER SIDE BRACKET LH (WCP)	Necessary	50.00 F	*50.00 F
24	1			Cracked	450.00 F	*450.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT SUPPORT PANEL (WCP)			
25	1		*FRONT DOOR PILLAR LH (WCP)	Bent	680.00 F	*680.00 F
26	1		*LH FRONT DOOR LOCK (WCP)	Bent	260.00 F	*260.00 F
27	1		*LH FRONT DOOR INNER TRIM (WCP)	Serviceable	570.00 F	*- F
28	1		*LH FRONT DOOR REGULATOR WITH MOTOR (WCP)	Jammed	480.00 F	*480.00 F
29	1		*RAD COOLANT	Necessary	30.00 FS	*30.00 FS
30	1		*LH FRONT DOOR LICENSE STICKER	Necessary	20.00 FS	*20.00 FS
31	1		*BONNET LOGO (WCP)	Necessary	40.00 F	*40.00 F
32	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	130.00 F	*130.00 F
33	1		*FRONT WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
34	1		*ACCIDENT TOWING TO FAN YOONG		55.00 FS	*55.00 FS
35	1		*LH FRONT LOWER ECU CONTROL UNITS (WCP)	Cracked	850.00 FS	*850.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	10,828.00	9,908.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,474.95	1,464.45

Total Parts (S\$)	12,302.95	11,372.45
-------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO INSPECT FRONT & REAR LIGHTING WATER & LEAKAGE TEST	New	40.00	40.00
2	TO REMOVE & INSTALL FRONT WINDSCREEN IN ORDER TO CUT OFF FRONT DOOR PILLAR LH	New	120.00	120.00
3	TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR	New	100.00	60.00
4	TO REMOVE & TRANSFER ITEMS TO LH SIDE NEW DOOR	New	100.00	60.00
5	TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO CUT OFF SUPPORT PANEL	New	160.00	80.00
6	TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET, ROOF LINING IN ORDER TO CUT OFF LH REAR FENDER	New	200.00	100.00
7	TO CUT OFF LH FRONT DOOR PILLAR SUPPORT PANEL LH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW ALL DAMAGES PARTS	New	2,000.00	1,700.00
8	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	60.00	60.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,600.00	1,300.00
Gross Labour Cost (S\$)			4,380.00	3,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >