

4/3/2018

Estimate Report



Main Office : No. 22, Jalan Kilang, Singapore 159419  
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,  
#01-04/06/08/115, Singapore 159722  
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314  
www.mova.com.sg  
GST Reg. No: M2-0088864-2

Mova Spray Centre  
2K Oven Spray Painting System

Power-M Automotive Pte Ltd  
Specialise In Car Air-con Services,  
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading

Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

Lonpac Insurance Bhd (HQ)

*Alan 96869276*

**PARTICULARS OF CLAIM**

|                               |                                       |                       |                   |
|-------------------------------|---------------------------------------|-----------------------|-------------------|
| Claim Type:                   | OD (OWN DAMAGE)                       | Ref. No:              |                   |
| Policy No:                    | Z/17/VCO0/100847                      | Date of Loss:         | 26/03/2018        |
| Vehicle Reg. No.:             | GQ8208T                               | Driveable?            |                   |
| Driver Age/Info:              | 58 / MALE                             | Party At Fault:       | UNKNOWN           |
| TP Injury Involved?           | NO                                    | Third Party Involved? | YES               |
| Insured/Claimant:             | SNOWY SERVICES                        |                       |                   |
| Driver:                       | WOO SIEW KHUEN DERRICK                |                       |                   |
| Make/Model:                   | TOYOTA HIACE, 3.0 D TURBO 5 DR (M)    | Vehicle Reg. Date:    | 30/05/2014        |
| Vehicle Colour:               | LIGHT GREY                            | Chassis No:           | JTFHT02P300141088 |
| Engine No:                    | 1KD2404478                            |                       |                   |
| Odometer:                     | 0 KM                                  |                       |                   |
| Paint Type:                   |                                       |                       |                   |
| Total Loss?                   | NO                                    |                       |                   |
| Est. Duration of Repair (day) | 15                                    |                       |                   |
| Description of Accident/Loss  | REFER TO SKETCH PLAN.                 |                       |                   |
| Present Location:             | MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) |                       |                   |

**COST OF CLAIMS**

|                          | Amount           |
|--------------------------|------------------|
| Parts                    | 12,302.95        |
| Miscellaneous Items      | 0.00             |
| Labour                   | 4,380.00         |
| Paintwork Labour         | 0.00             |
| Towing                   | 0.00             |
| <b>Gross Total (S\$)</b> | <b>16,682.95</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>1,167.81</b>  |
| <b>Nett Amount (S\$)</b> | <b>17,850.76</b> |

This claim is handled by: ALAN

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)  
Parts: 213 TOYOTA HIACE 3.0 D TURBO 5 DR (M) (Catalogue:Merimen Singapore 1.0)  
Labour: Repairer's (Price-denominated Standard List)  
Print Code: (Unsubmitted, no print-code for GQ8208T)  
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

| No. | Qty | Part No. | Particulars                         | %Disc | %Depr | Amount           |
|-----|-----|----------|-------------------------------------|-------|-------|------------------|
| 1   | 1   |          | *TAILLAMP LH                        | 0.00  | 0.00  | CRA / *190.00 F  |
| 2   | 1   |          | *TAILLAMP PANEL LH                  | 0.00  | 0.00  | PH / *160.00 F   |
| 3   | 1   |          | *LH REAR FENDER                     | 0.00  | 0.00  | 7000 / *958.00 F |
| 4   | 1   |          | *LH REAR FENDER DOOR RAIL           | 0.00  | 0.00  | R / *495.00 F    |
| 5   | 1   |          | *LH REAR FENDER RAIL COVER          | 0.00  | 0.00  | CRA / *60.00 F   |
| 6   | 1   |          | *LH REAR FENDER INNER BOARD         | 0.00  | 0.00  | 7000 / *310.00 F |
| 7   | 1   |          | *LH SIDE DOOR                       | 0.00  | 0.00  | PH / *850.00 F   |
| 8   | 1   |          | *LH FRONT DOOR                      | 0.00  | 0.00  | PH / *750.00 F   |
| 9   | 2   |          | *LH FRONT DOOR HINGE                | 0.00  | 0.00  | PH / *140.00 F   |
| 10  | 1   |          | *LH FRONT DOOR RUBBER               | 0.00  | 0.00  | new / *210.00 F  |
| 11  | 1   |          | *LH FRONT DOOR STEP GARNISH         | 0.00  | 0.00  | Seal / *210.00 F |
| 12  | 1   |          | *LH FRONT CORNER PANEL              | 0.00  | 0.00  | PH / *210.00 F   |
| 13  | 1   |          | *FRONT WIPER COWLING                | 0.00  | 0.00  | CRA / *230.00 F  |
| 14  | 1   |          | *BONNET                             | 0.00  | 0.00  | PH / *350.00 F   |
| 15  | 2   |          | *BONNET HINGE                       | 0.00  | 0.00  | X / *140.00 F    |
| 16  | 1   |          | *HEADLAMP LH                        | 0.00  | 0.00  | CRA / *580.00 F  |
| 17  | 1   |          | *HEADLAMP PANEL LH                  | 0.00  | 0.00  | X / *160.00 F    |
| 18  | 1   |          | *FRONT BUMPER                       | 0.00  | 0.00  | DE / *260.00 F   |
| 19  | 1   |          | *FRONT BUMPER LOWER GRILLE          | 0.00  | 0.00  | DE / *190.00 F   |
| 20  | 1   |          | *FRONT GRILLE ASSY                  | 0.00  | 0.00  | CRA / *380.00 F  |
| 21  | 1   |          | *FRONT BUMPER FOG LAMP COVER LH     | 0.00  | 0.00  | X / *50.00 F     |
| 22  | 1   |          | *FRONT BUMPER REINFORCEMENT         | 0.00  | 0.00  | PH / *290.00 F   |
| 23  | 1   |          | *FRONT BUMPER SIDE BRACKET LH       | 0.00  | 0.00  | new / *50.00 F   |
| 24  | 1   |          | *FRONT SUPPORT PANEL                | 0.00  | 0.00  | R / *450.00 F    |
| 25  | 1   |          | *FRONT DOOR PILLAR LH               | 0.00  | 0.00  | PH / *680.00 F   |
| 26  | 1   |          | *LH FRONT DOOR LOCK                 | 0.00  | 0.00  | X / *260.00 F    |
| 27  | 1   |          | *LH FRONT DOOR INNER TRIM           | 0.00  | 0.00  | X / *570.00 F    |
| 28  | 1   |          | *LH FRONT DOOR REGULATOR WITH MOTOR | 0.00  | 0.00  | PH / *480.00 F   |
| 29  | 1   |          | *RAD COOLANT                        | 0     | 0.00  | new / *30.00 FS  |
| 30  | 1   |          | *LH FRONT DOOR LICENSE STICKER      | 0     | 0.00  | new / *20.00 FS  |
| 31  | 1   |          | *BONNET LOGO                        | 0.00  | 0.00  | new / *40.00 F   |
| 32  | 1   |          | *FRONT WINDSCREEN MOULDING          | 0.00  | 0.00  | new / *130.00 F  |
| 33  | 1   |          | *FRONT WINDSCREEN SEALANT           | 0     | 0.00  | new / *40.00 FS  |
| 34  | 1   |          | *ACCIDENT TOWING TO FAN YOONG       | 0     | 0.00  | / *55.00 FS      |
| 35  | 1   |          | *LH FRONT LOWER ECU CONTROL UNITS   | 0     | 0.00  | CRA / *850.00 FS |

F=Franchise part. S=SpcNett.

|                                     |                  |
|-------------------------------------|------------------|
| Sub Total (\$\$)                    | 10,828.00        |
| + Margin on L,N Items 15.00% (\$\$) | 1,474.95         |
| <b>Total Parts (\$\$)</b>           | <b>12,302.95</b> |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

4/3/2018

## Estimate Report

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

| No                      | Particulars                                                                                                          | Lab.Type | Amount                               |
|-------------------------|----------------------------------------------------------------------------------------------------------------------|----------|--------------------------------------|
| <u>Labour Items</u>     |                                                                                                                      |          |                                      |
| 1                       | TO INSPECT FRONT & REAR LIGHTING WATER & LEAKAGE TEST                                                                | New      | 40.00 ✓                              |
| 2                       | TO REMOVE & INSTALL FRONT WINDSCREEN IN ORDER TO CUT OFF FRONT DOOR PILLAR LH                                        | New      | 120.00 ✓                             |
| 3                       | TO REMOVE & TRANSFER ITEMS TO LH FRONT NEW DOOR                                                                      | New      | 100.00 <del>100.00</del> 60 ✓        |
| 4                       | TO REMOVE & TRANSFER ITEMS TO LH SIDE NEW DOOR                                                                       | New      | 100.00 <del>100.00</del> 60 ✓        |
| 5                       | TO REMOVE & INSTALL A/C CONDENSER, RADIATOR IN ORDER TO CUT OFF SUPPORT PANEL                                        | New      | 160.00 <del>160.00</del> 80 ✓        |
| 6                       | TO REMOVE & INSTALL REAR COMPARTMENT GARNISHES, CARPET, ROOF LINING IN ORDER TO CUT OFF LH REAR FENDER               | New      | 200.00 <del>200.00</del> 100 ✓       |
| 7                       | TO CUT OFF LH FRONT DOOR PILLAR SUPPORT PANEL LH REAR FENDER & STRAIGHTEN AFFECTED AREAS AND RENEW ALL DAMAGES PARTS | New      | 2,000.00 <del>2,000.00</del> 1,700 ✓ |
| 8                       | TO APPLY BODY JOINT SEALANT ON CUTTING AREAS                                                                         | New      | 60.00 ✓                              |
| 9                       | TO SPRAY PAINT ON REPLACED, REPAIRED AREAS                                                                           | New      | 1,300 <del>1,600.00</del> ✓          |
| Gross Labour Cost (S\$) |                                                                                                                      |          | 4,380.00                             |

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

Rasul  
Hp 90010068

14 days

43

EXCESS: 700

05/04/18 @ 1220

Reveal

Resurvey after repair

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: