



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18006149/R1ga3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Date : 13-04-2020	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCF 6164D	Veh. Inspected	SHA 8981R
	Policy No.		Coverage (\$)	0.00
	Claim No.	S8M00CS4	Excess (\$)	0.00
	Assign From		Assign Date	03/04/2018
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI SONATA 2.0	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	2010
	Chassis No.	KMHET41VMAA785857	Colour	YELLOW
	Odometer	477130	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	TRIANGLE	5 mm
	L/H Front Tyre	215/60 R16	TRIANGLE	5 mm
	R/H Rear Tyre	215/60 R16	TRIANGLE	5 mm
	L/H Rear Tyre	215/60 R16	TRIANGLE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/03/2018	Inspection Date	04/04/2018
	Survey held at	DING AUTOMOTIVE PTE LTD BLK 10 #01-20 SIN MING IND EST SEC C SINGAPORE 575645		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	