

AXIA

COMFORTDELGRO ENGINEERING PTE LTD

Jumani

REPAIR ESTIMATE*

VEHICLE NO : SHC 8911H

DATE 2/4/2018 13:14

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Reverse Sensor <i>X 500</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>acc</i>			\$ 50.00	Nett
	<i>Rear Bumper - Refurb</i>		<i>\$ 603.60</i>	<i>20%</i>	
				\$ 185.70	
	Labour Charge			<i>200</i>	
	Panel Beating			\$ 250.00	
	Spray Painting Charge-Bumper			\$ 250.00	<i>200</i>
	Wiring Charge			\$ 50.00	<i>X 10</i>
	R/Refix Reverse Sensor			\$ 120.00	<i>20</i>
	TOTAL LABOUR			\$ 670.00	
	ESTIMATE TOTAL			\$ 855.70	
<i>Kalvi 1/1/18</i> <i>3/4/18 11:20</i> <i>2 Rys</i> <i>P/P</i> <i>Before paint p/h</i>					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
REAR BUMPER ASSY		\$603.60	
LABOUR			
TOTAL:		\$603.60	JUMANI