

EDIT

SR
NO

NAME

ACTION

AMOUNT

COMMENT

REMOVE



6

REAR
REVERSE
CAMERA

Reviewing

300

SHORTED



7

SET FRONT
BUMPER CLIP

Reviewing

50

NECESSARY



8

FRONT
NUMBER
PLATE WITH
HOLDER

Reviewing

40

CRACKED



9

SET FRONT
FENDER
INNER
SHIELD CLIP

Reviewing

0

NOT
NECESSARY

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐		34	1			FRONT BUMPER (DISC 25%)			Dented	793.57		0		793.57
☐		35	1			FRONT BUMPER CENTRE AIR GRILLE (DISC 25%)			Deformed	70.87		0		70.87
☐		36	2			FRONT BUMPER FOG LAMP SIDE GARNISHES			Serviceable	0		0		0
☐		37	2			FRONT BUMPER FOG LAMPS			Serviceable	0		0		0
☐		38	1			FRONT BUMPER INNER SPONGE (DISC 25%)			Damaged	61.2		0		61.2
☐		39	1			FRONT BUMPER REINFORCEMENT (DISC 25%)			Bent	218.92		0		218.92
☐		40	2			FRONT BUMPER SIDE RETAINERS (DISC 25%)			Bent	53.17		0		106.34
☐		41	1			FRONT FENDER			Serviceable	0		0		0
☐		42	1			FRONT FENDER INNER SHIELD			Serviceable	0		0		0
☐		43	1			FRONT SUPPORT PANEL			Repair	0		0		0
☐		44	1			FRONT BRACE PANEL			Serviceable	0		0		0
☐		45	1			HORN			Serviceable	0		0		0
☐		46	1			AIR CON CONDENSER			Serviceable	0		0		0
☐		47	1			RADIATOR			Serviceable	0		0		0

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIRUREPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐	 10	2			REAR TAILGATE NUMBER PLATE LAMPS			Serviceable	0		0		0
☐	 11	2			REAR TAILLAMPS (DISC 25%)			Cracked	350.4		0		700.8
☐	 12	1			REAR END PANEL (DISC 25%)			Dented	574.58		0		574.58
☐	 13	1			REAR END PANEL INNER GARNISH (DISC 25%)			Damaged	166.13		0		166.13
☐	 14	1			REAR SMART KEYLESS SENSOR			Serviceable	0		0		0
☐	 15	2			REAR FENDERS			Serviceable	0		0		0
☐	 16	2			REAR FENDER INNER TRIM BOARDS (DISC 25%)			Deformed	521.62		0		1043.24
☐	 17	1			REAR BUMPER (DISC 25%)			Damaged	366.53		0		366.53
☐	 18	2			REAR BUMPER BRACKETS (DISC 25%)			Bent	73.87		0		147.74
☐	 19	1			REAR BUMPER CENTRE PAD (DISC 25%)			Damaged	168.75		0		168.75
☐	 20	2			REAR BUMPER REFLECTORS			Serviceable	0		0		0
☐	 21	1			REAR BUMPER REFLECTOR OUTER GARNISHES (N/S) (DISC 25%)			Deformed	135.38		0		135.38

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *

04/04/2018



General condition

Good

Total Loss

Yes No

Steering (Serviceable)

Yes No

Towing Charges

0

Footbrake (Serviceable)

Yes No

Voluntary Excess

0

Handbrake (Serviceable)

Yes No

Compulsory Excess

0

Engine Modification

Yes No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good

Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/60R15

Rear Tyre Size

185/60R15

.....

POST SURVEY INF... ▼

Gender

CATEGORY

FNOL INFORMATI...

POST SURVEY INF... ▼

Marital status

CATEGORY

FNOL INFORMATI...

POST SURVEY INF... ▼

Identification #

CATEGORY

FNOL INFORMATI...

POST SURVEY INF...

POLICY INFORMAT...	TPVD TOYOTA	CATEGORY	Date of Birth
ASSESSMENT INFO...	TOYOTA	FNOL INFORMATI...	
		POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Model	CATEGORY	Age
POLICY INFORMAT...	SIENTA	FNOL INFORMATI...	
ASSESSMENT INFO...	SIENTA HYBRID 1.5X A	POST SURVEY INF...	
CATEGORY	Type	CATEGORY	Occupation
POLICY INFORMAT...		FNOL INFORMATI...	
ASSESSMENT INFO...		POST SURVEY INF...	
CATEGORY	Type of Paint	CATEGORY	Education Qualification
POLICY INFORMAT...		FNOL INFORMATI...	
ASSESSMENT INFO...		POST SURVEY INF...	
CATEGORY	Chassis No	CATEGORY	Driving Experience
POLICY INFORMAT...		FNOL INFORMATI...	
ASSESSMENT INFO...	NHP1707036934	POST SURVEY INF...	
		CATEGORY	Driver License #

Pending verification -
Direct Settlement

Claim Handler

CHUA Ruth
6568804087
ruth.chua@axa.com.sg

Additional Instructions

- Messages
 - Assessment
 - Invoices
 - Metrics
 - History
 - Notes
 - Documents
- Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
User Portal	6/11/18 5:49 PM	10500	10500	Open	Share	Clone
SHAH Kushal	4/2/18 9:06 AM	13168.32	13168.32	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP GIA REPORT (SKA 8182U) - 4th & last vehicle - S8M00CQ1.PDF	Reports & Statement	GIA Report	HO Winnie	April 3, 2018
TP GIA REPORT (SLD4551L) - 2nd vehicle.PDF	Reports & Statement	GIA Report	HO Winnie	April 3, 2018
Video - Accident.AVI	Evidence	Videos	HO Winnie	April 3, 2018
EMAIL WITH GIA REPORT.msg	Other	Other	SHAH Kushal	April 2, 2018

Pending verification -
Direct Settlement

Claim Handler

CHUA Ruth
6568804087
ruth.chua@axa.com.sg

Additional Instructions

Messages Invoices History Documents

Assessment Metrics Notes

Document Type

Document SubType

Upload Documents

NAME	TYPE	SUB- TYPE	AUTHOR	DATE UPLOADED
MANDATE REQUEST.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 16, 2018
RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018
LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018