

ASS. REC. BY:

REF:

CS/MSCH18006193/Kldp

Special Instruction:

Surveyor

Mehmen

KALVIN

ASSIGNMENT (Office)

From (Person):

Jasmine Lok

of

MSU1

Date/Time:

04/04/2018 9:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 7816S

Insured:

GBE 44Z

at Workshop m/s

Comfort Delgro

Tel:

of

55 Layang Drive

Policy No:

JSS 76563 MKC

Claim No:

534360

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/04/2018

CA / REV / REP. / REV 24 HRS WP1

H.O.D. Endorsement:

Date/Time:

04-04/2018 10am.

Person Contacted:

Jumani

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SHA 7816S NA/TNC17017500/mibee2

REF: 250617

GBE 44Z - CS/MSCH18006193/Kldp

REF: 11/01/2018

05/04/18 @ 17:08 revised to Jasmine Lok Kheng Kwei via mehmeh



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006193/K1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 44Z	Veh. Inspected	SHA 7816S
Policy No.	28876563MKC	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (JASMINE LOK)	Assign Date	04/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/04/2018	Inspection Date	04/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		04 Apr 2018 09:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:		DE51ST, Co. Reg. No.: 53278619W [Created by insurer]							
Main Claimant:		COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R							
Vehicle Reg. No.:	SHA7816S	Date of Loss:	01/04/2018 00:00 - :59 [33 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	28876563MKC Coverage: 11/01/2018 - 10/01/2019						
Vehicle Reg. No. (Insured):	G8E44Z	Policy No. (Claimant):							
Repairer:		ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwel - 6594 2550]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 05/04/2018]							
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.			View All	Compose Case Mail					
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Kwong

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: GBE44Z		
TP Vehicle No	: SHA7816S	Accident Date	: 01/04/2018
Make	: HYUNDAI I40	Assignment Date	: 04/04/2018
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 3 days
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,132.56
Revised Amount	:S\$	5,362.40
Check Items (Estimated)	:S\$	1,831.04
Total	:S\$	7,193.44

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 13:19
Date Of Accident	01/04/2018 16:30
Exact Location Of Accident	BLK 308C ANG MO KIO AVE - MSCP
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA7816S
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	

Driver

Name of Driver	OH KUAN HUI
NRIC No	S7514110F
Date Of Birth	15/05/1975
Occupation	OUTDOOR
Date Of Driving Pass	22/03/1997
Driving Experience	21 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	KUANHUIOH@YAHOO.COM

Address	BLK 310B ANG MO KIO AVENUE 1 #19-373
Postcode	562310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE44Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	JUSTIN NG YUN GUANG
NRIC/Passport Number	S9148947C
Contact Number	97977671
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	NOT SURE
No. Of Passenger (Including Driver)	

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO REG. NO 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:


R Moorthy
CSO



SKETCH PLAN

A) SHA 78165	
B) GBE 44Z	
No Sketch	
But Witness Video Available	

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1/4/18 at about 1630^h I Vek A was contacted by neighbour with regards to an accident on my parked vehicle. I went to the location and realized that the Vek B driver had left a rope on the windscreen of my vehicle to contact him. I called and exchanged particulars accordingly. I also got a ~~see~~ witness video footage from my neighbour attached with some photos of Vehicle B damages.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SIMRAC SketchPlanForm_V2

SR
CSO
2/4/18

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO 305138058

CUSTOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

VARS

L (R) (O)
(P)

SCOUNT CARD NO.

REGN NO.

SHA7816S

MILEAGE

MAKE

HYUNDAI

FUEL

E 1/2 F

MODEL

I-40

DATE/TIME IN
01.04.2018 16:30

YR OF MANU

30.06.2015

TARGET DATE

CHASSIS CODE

KMHLE41UMGU075088

COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 01.04.2018

NATURE: 3P 01.04.2018

LABOR CODE

DESCRIPTION

MSG - Front Left, Underbody

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: SHA7816S
LARRY

Vehicle No.: SHA7816S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7816S

MODEL : HYUNDAI i40

MSIG

DATE 3/4/2018 9:56

DPA: 01.04.18

PP

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>X Rep-2</i>			\$ 1,526.00
	Bonnet Hinge (LH/RH) <i>- 2nd</i>		\$ 91.30	\$ 182.60
	Radiator Grille <i>- 1st</i>			\$ 1,480.00
	Radiator Grille H Emblem <i>X A1</i>			\$ 290.80
	Radiator Grille Chrome Moulding <i>X A1</i>			\$ 395.50
	Front Bumper Cover <i>- 1st</i>			\$ 1,052.20
	Front Bumper Sponge <i>- 1st</i>			\$ 142.20
	Front Bumper Reinforcement <i>X 1st</i>			\$ 526.10
	Front Bumper Grille (LH) <i>X 1st</i>			\$ 285.50
	Front Bumper Grille Airduct (LH) <i>X 1st</i>			\$ 155.00
	Front Bumper Lip <i>X 1st</i>			\$ 62.50
	Front Bumper Bracket Top (LH) <i>X 1st</i>			\$ 22.40
	Front Bumper Bracket (LH) <i>- 1st</i>			\$ 24.60
	Headlamp Support Panel Assy <i>2 1st</i>			\$ 1,067.50
	Headlamp (LH/RH) <i>LH 1st RH X 1st</i>		\$ 1,388.00	\$ 2,776.00
	Headlamp Halogen Bulb (LH) <i>+ 1st</i>			\$ 14.40
	Front Fender (LH) <i>- 1st</i>			\$ 619.00
	Front Fender Shield (LH) <i>X 1st</i>			\$ 169.80
	Front Wheel Hub Cap (LH) <i>X 1st</i>			\$ 150.70
	Front Wheel Bearing <i>X 1st</i>			\$ 258.50
	Front Shock Absorber (Assy) (LH) <i>X 1st</i>			\$ 342.20
	Front Shock Absorber Mounting (LH) <i>X 1st</i>			\$ 75.10
	Front Suspension Lower Arm (LH) <i>X 1st</i>			\$ 715.10
	Knuckle Arm (LH) <i>X 1st</i>			\$ 582.95
	Inter Cooler <i>X 1st</i>			\$ 921.90
	Inter Cooler Mounting (2 PCS) <i>X 1st</i>			\$ 25.90
	SUB TOTAL			\$ 13,864.45
	LESS 20%			\$ 2,772.89
	DISCOUNTED TOTAL			\$ 11,091.56
	Front Number Plate <i>X 1st</i>			\$ 25.00
	Front No Plate Trim Cover <i>X 1st</i>			\$ 30.00
	Frt Tyre (LH) <i>X 1st</i>			\$ 216.00
				\$ 271.00
	Labour Charge			600
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 750.00
	Wiring Charge			\$ 50.00
	Tuff Coat			\$ 100.00
	Towing fees			\$ 50.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	TOWING Fee - <i>1st</i>			\$ 150.00
	TOTAL LABOUR			\$ 2,620.00
	ESTIMATE TOTAL			\$ 13,982.56

SUB TOTAL

LESS 20%

DISCOUNTED TOTAL

Front Number Plate

Front No Plate Trim Cover

Frt Tyre (LH)

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Coat

Towing fees

Remove/Refix Undercarriage (FRT)

FRT Wheel Alignment

Remove/Refix Aircon & Refill Gas

TOWING Fee -

TOTAL LABOUR

ESTIMATE TOTAL

Nett

Nett

Nett

Katin 16/11/18

4/4/18 11:45L

3 0-71

P/P

Before Post P/LH

9/4/18

Larry Ng

Ackno

Signature

Date:

Signature

2,770.2

14,132.5

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: 1-4-18 Time Received: 1705		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)	4. Type of Towing: <input type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input checked="" type="checkbox"/> Crane-up
2. <input type="checkbox"/> New <input type="checkbox"/> SPARK Kakis Name of Customer : Contact No. : Vehicle No. : Make / Model / Colour : Email :		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: 38C AMK AVE 1		8. Vehicle Tow - In Workshop: <input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi	
9. Preferred Workshop: <input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Senoko <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:			
10. Odometer Reading : 520598 Fuel Level : F 1/4 1/2 3/4 E		11. Radio / CD Player <input type="checkbox"/> OK <input type="checkbox"/> Faulty <input type="checkbox"/> Not tested	
Job Attended			
12. Tow Truck / Recovery Van : <input type="checkbox"/> VRS <input checked="" type="checkbox"/> QA <input type="checkbox"/> GAO <input type="checkbox"/> TZ <input type="checkbox"/> YISHUN <input type="checkbox"/> OTHERS Name of Driver : Vehicle No. : Time Dispatch : Time of Arrival : Time Completed :		TOWING #: Cracked X: Dented /: Scatched O: Missing Signature of Customer	
Cash Invoice Details (if applicable)			
13. Cash Invoice No. :			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
Date: 1-4-18		Time: 1750	
		Signature of Customer: X 81	
14. WORKSHOP			
Name of Attending Staff/Guard		Date & Time of Arrival	
		Signature of Attending Staff/Guard	

LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
182.60	1526.00
1480.00	290.80
1052.20	395.50
142.20	526.10
24.60	285.50
1388.00	155.00
14.40	62.50
619.00	22.40
	1067.50
	1388.00
	169.80
	150.70
	258.50
	342.20
	75.10
	715.10
	582.95
	921.90
	25.90

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
	25.00
	30.00
	216.00

LABOUR

<u>PAY</u>	<u>UNPAID</u>
600.00	400.00
600.00	150.00
20.00	30.00
20.00	80.00
50.00	50.00
150.00	400.00
	120.00
	100.00

0.00

271.00

4903.00

8961.45

1440.00

1330.00

13864.45

0.00

2770.00

4903.00

0.00

1440.00

8961.45

0.00

1330.00

4903.00

980.60 (20% DISC)

3922.40 LIST ITEM AFTER DISC (PAY)

0.00 NETT ITEM (PAY)

1440.00 LABOUR (PAY)

5362.40

526.10	}	CHECK ITEM
285.50		
155.00		
62.50		
22.40		
1067.50		
169.80		

2288.80


457.76 (20% DISC)



1831.04 LIST ITEM AFTER DISC (CHECK ITEM)

0.00 LABOUR (CHECK ITEM)

1831.04

TOTAL = 7193.44 (PAY ITEM + CHECK ITEM)





COMFORTDELGRO ENGINEERING

Our Job Ref No : 305138058

Date : 6. Apr. 2018

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No. : SHA7816S

Date of Accident: 01/04/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: **MSIG** **GBE44Z**

2. The finalized amount shall be:

(a) Spare Parts after List discount \$4,764.88

(b) Labour Charges \$1,390.00

Total for Part-By-Part Repair Cost \$6,154.88

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: _____

Final Lumpsum Repair cost _____

3. Estimated normal period for repairs: **3** working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : Kahr

Date : 6/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee				
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305138058
 REGN NO : SHA7816S
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 30.06.2015
 DATE/TIME IN : 01.04.2018 16:30
 ACCIDENT DATE : 01.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER	1	1,052.20	20.00	841.76
0002 04-01-0103-2164-G	I40V3 GRILLE ASSY-RADIATO	1	1,480.00	20.00	1,184.00
0003 04-01-0103-2294-G	I40V3 ABSORBER-FRONT BUMP	1	142.20	20.00	113.76
0004 04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	619.00	20.00	495.20
0005 04-01-0103-0781-A	I40V2 LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40
0006 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68
0007 04-01-0103-0651-G	I40VC HINGE ASSY-BONNET L	1	91.30	20.00	73.04
0008 04-01-0103-0652-G	I40VC HINGE ASSY-BONNET R	1	91.30	20.00	73.04
0009 04-01-0103-0641-G	I40VC CARRIER ASSY-FR END	1	1,067.50	20.00	854.00

SUB-TOTAL : 4,764.88

JOB NATURE

0000 L	PANEL BEATING	600.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	600.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305138058
REGN NO : SHA7816S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 30.06.2015
DATE/TIME IN : 01.04.2018 16:30
ACCIDENT DATE : 01.04.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0002	17-01	WIRING CHARGE		20.00		
0003	20-00	TUFF COAT ON AFFECTED PARTS.		20.00		
0004	23-01	TOWING FEE (CRANE UP)		150.00		
SUB-TOTAL						: 1,390.00
TOTAL						: 6,154.88

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :


































...CLAIM SUBFOLDER...(Pending for Survey Report)


















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018		04 Apr 2018 09:44 Edit Adj Rpt	S\$6,154.88 Edit Estimates	S\$6,154.88 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	DESIST , Co. Reg. No.: 53278619W								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA7816S	Date of Loss:	01/04/2018 00:00 - :59 [33 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554360	Policy/Cover Note No.:	28876563MKC Coverage: 11/01/2018 - 10/01/2019						
Vehicle Reg. No. (Insured):	GBE44Z	Policy No. (Claimant):							
		Excess:							
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Final Rpt due 04/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA7816S (554360)
[GBE44Z]
TP
COMFORT TRANSPORTATION PTE LTD
Apr 1 2018 12:00AM
[DESIST]
ComfortDelGro Engineering Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	05/04/18 17:08	Adjuster Immediate Advice					 Load HTM			
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail		Print	
1	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
2	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
3	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
4	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
5	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
6	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
7	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
8	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
9	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
10	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
11	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
12	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
13	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
14	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
15	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
16	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
17	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
18	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
19	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
20	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
21	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
22	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
23	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
24	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
25	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
26	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
27	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
28	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
29	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
30	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
31	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
32	04/04/18 17:58	General View					 Load JPG		<input checked="" type="checkbox"/>	
33	04/04/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>	
34	04/04/18 17:58	General View					Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	04/04/18 17:58	General View	 Load JPG	<input checked="" type="checkbox"/>
36	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	05/04/18 17:36	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	04/04/18 09:49	PRI	 Load PDF	
2	04/04/18 09:49	Estimate	 Load PDF	
3	04/04/18 09:49	TP GIA Rpt	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006193/K1QBQ2

Date: 12/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28876563MKC

Claimant Vehicle No : SHA7816S

Insured Vehicle No : GBE44Z

Date of Loss: 01/04/2018

Nature of Claim: TP

Claim No: 554360

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHA7816S**

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDEU411840

Reg. Date: 30/06/2015 (Man. Year: 2015)

Chassis No: KMHLB41UMGU075088

Colour: Blue

Odometer: 520599 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 7 mm

Rear Left Side: West Lake 7 mm

Front Right Side: West Lake 7 mm

Rear Right Side: West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,362.56	4,764.88	6,597.68	58.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,770.00	1,390.00	1,380.00	49.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,132.56	6,154.88	7,977.68	56.45
+ GST 7.00/7.00% (S\$)	989.28	430.84	558.44	56.45
Nett Amount (S\$)	15,121.84	6,585.72	8,536.12	56.45

INSPECTION

Date of Assignment: 04/04/2018

Date Inspected: 04/04/2018 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts:	143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA7816S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	1,526.00 FL	*- FL
2	2		*BONNET HINGE (LH/RH)	Bent	182.60 FL	*182.60 FL
3	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
4	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	290.80 FL	*- FL
5	1		*RADIATOR GRILLE CHROME MOULDING	Not Necessary	395.50 FL	*- FL
6	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
7	1		*FRONT BUMPER SPONGE	Torn	142.20 FL	*142.20 FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	526.10 FL	*- FL
9	1		*FRONT BUMPER GRILLE (LH)	Serviceable	285.50 FL	*- FL
10	1		*FRONT BUMPER GRILLE AIRDUCT(LH)	Serviceable	155.00 FL	*- FL
11	1		*FRONT BUMPER LIP	Serviceable	62.50 FL	*- FL
12	1		*FRONT BUMPER BRACKET TOP (LH)	Serviceable	22.40 FL	*- FL
13	1		*FRONT BUMPER BRACKET (LH)	Cracked	24.60 FL	*24.60 FL
14	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	1,067.50 FL	*1,067.50 FL
15	1		*HEADLAMP (LH/RH)	N/S Cracked / O/S Serviceable	2,776.00 FL	*1,388.00 FL
16	1		*HEADLAMP HALOGEN BULB (LH)	Not Necessary	14.40 FL	*- FL
17	1		*FRONT FENDER (LH)	Dented	619.00 FL	*619.00 FL
18	1		*FRONT FENDER SHIELD (LH)	Serviceable	169.80 FL	*- FL
19	1		*FRONT WHEEL HUB CAP (LH)	Serviceable	150.70 FL	*- FL
20	1		*FRONT WHEEL BEARING	Old Damaged	258.50 FL	*- FL
21	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Old Damaged	342.20 FL	*- FL
22	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Old Damaged	75.10 FL	*- FL
23	1		*FRONT SUSPENSION LOWER ARM (LH)	Old Damaged	715.10 FL	*- FL
24	1		*KNUCKLE ARM (LH)	Old Damaged	582.95 FL	*- FL
25	1		*INTER COOLER	Old Damaged	921.90 FL	*- FL
26	1		*INTER COOLER MOUNTING	Old Damaged	25.90 FL	*- FL
27	1		*FRONT NUMBER PLATE	Serviceable	25.00 FS	*- FS
28	1		*FRONT NO PLATE TRIM COVER	Serviceable	30.00 FS	*- FS
29	1		*FRT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **14,135.45** **5,956.10**
 - List Item Discount on L Items 20.00/20.00% (S\$) **2,772.89** **1,191.22**

Total Parts (S\$) **11,362.56** **4,764.88**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING CHARGE	New	750.00	600.00
3	WIRING CHARGE	New	50.00	20.00
4	TUFF KOTE	New	100.00	20.00
5	TOWING FEES	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	0.00
7	FRT WHEEL ALIGNMENT	New	120.00	0.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	TOWING FEE	New	150.00	150.00
Gross Labour Cost (S\$)			2,770.00	1,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >