

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Apr 2018 Edit Reg		04 Apr 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	ADE ADLI PUTRA AZMAN , ID: -		
Vehicle Reg. No.:	FBL9540L	Date of Loss:	02/04/2018 00:00 - :59 [183 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18040046	Policy/Cover Note No.:	MCT18040046
Vehicle Reg. No. (Insured):	SHB4314M	Policy No. (Claimant):	
		Excess:	
Repairer:	Mcs Auto (HQ) 1100 Serangoon Rd, 328195 Serangoon - Tel: 62969939		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 11/05/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBL9540L (MCT18040046)

[SHB4314M]

TP

ADE ADLI PUTRA AZMAN

Apr 2 2018 12:00AM

[COMFORT TRANSPORTATION PTE LTD]

Mcs Auto

Upload Documents Upload Photos Compose New Letter

View View in Browser ▾

Video			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 11:37	Video - Accident	Load MP4	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/05/18 10:05	General View	Load JPG	<input checked="" type="checkbox"/>
23	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
24	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
25	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
26	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
31	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
33	07/05/18 10:08	Photographs of Damaged Parts	Load JPG	✓
34	07/05/18 10:08	Photo After Spray	Load JPG	✓
35	07/05/18 10:08	Photo After Spray	Load JPG	✓
36	07/05/18 10:08	Photo After Spray	Load JPG	✓
37	07/05/18 10:08	Photo After Spray	Load JPG	✓
38	07/05/18 10:08	Photo After Spray	Load JPG	✓
39	07/05/18 10:08	Photo After Spray	Load JPG	✓
Documentation			1 per page	✓
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 15:17	EMAIL FROM III	Load PDF	
2	02/05/18 15:21	Letter of Demand from Third Party CATHERINE LIM LLC	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III18006202/GBS2

Date: 14/05/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCT18040046
Claimant Vehicle No :	FBL9540L	Insured Vehicle No :	SHB4314M
Date of Loss:	02/04/2018	Nature of Claim:	TP
		Claim No:	MCT18040046

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL9540L	Engine No:	KR150EEA55770
Make & Model:	KAWASAKI KKRZX150M, 148cc (M)	Chassis No:	KR150KA55770
Reg. Date:	31/12/2002 (Man. Year: 2002)	Odometer:	90054 km
Colour:	Red		
Engine Capacity:	148 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Corsa 5 mm	Rear Left Side:	Corsa 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/04/2018	Inspected At:	Mcs Auto (HQ) 1100 Serangoon Rd Singapore 328195
Date Inspected:	05/04/2018		
Estimated Period of Repair:	0.0 days		

Adjuster: XING GUO QIANG

Manager: CATHERINE CHONG KAI LING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 May 2018)

Parts: N/A KAWASAKI KKRZX150M 148cc (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBL9540L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >