



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005155
INV Date 23/07/2020
Reference CC6/CTI18006221/Aea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBG 1202S
Insured Veh. SGR 8829X
Claim No. SNM18D01746C02
Policy No. DMPCSN3013021802
Accident Date 01/04/2018
Inspection Date 03/04/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18006221/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 23-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGR 8829X	Veh. Inspected	GBG 1202S
Policy No.	DMPCSN3013021802	Coverage (\$)	0.00
Claim No.	SNM18D01746C02	Excess (\$)	0.00
Assign From		Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0145324	Colour	BLACK
Odometer	37080	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Front Tyre	175/70 R14C	GOODYEAR	6 mm
R/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm
L/H Rear Tyre	175/70 R14C	GOODYEAR	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/04/2018	Inspection Date	03/04/2018
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 1202S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	566.80	566.80
2	REAR BUMPER SIDE RETAINER @\$52.90	NECESSARY	105.80	105.80
1	REAR BUMPER SPONGE	CRACKED	128.90	128.90
2	TAIL LAMP PANEL @\$271.50	TO REPAIR SEE LABOUR	543.00	-
1	REAR DOOR LH	DISTORTED	2,250.00	1,481.60
1	REAR DOOR RH	DENTED	2,200.00	1,153.70
1	REAR DOOR NUMBER PLATE LAMP GARNISH	CRACKED	379.50	379.50
	LESS 30% DISCOUNT		-1,852.20	-1,144.89
			4,321.80	2,671.41
<u>NETT ITEMS</u>				
2	REAR BUMPER REFLECTOR @\$41.60 (N)	NOT NECESSARY	83.20	-
1	REAR DOOR EMBLEM "NV200" (N)	NECESSARY	87.90	87.90
1	REAR DOOR LOGO (N)	NECESSARY	63.90	63.90
2	REAR DOOR UPPER LOCK @\$128.50 (N)	NOT NECESSARY	257.00	-
2	REAR DOOR LOWER LOCK @\$128.50 (N)	DAMAGED	257.00	257.00
2	REAR DOOR MECHANISM @\$128.50 (N)	NOT NECESSARY	257.00	-
4	REAR DOOR HINGE @\$99.60 (N)	NOT NECESSARY	398.40	-
2	REAR DOOR CHECKER @\$87.00 (N)	NOT NECESSARY	174.00	-
2	REAR DOOR GLASS MOULDING @\$150.00 (N)	NECESSARY	300.00	170.00
2	TAILLAMP @\$280.90 (N)	N/S CRACKED	561.80	280.90
1	REAR END PANEL (N)	DENTED	630.00	630.00
1	REAR END PANEL TOP GARNISH (N)	DEFORMED	120.00	120.00
1	REAR END PANEL WEATHERSTRIP (N)	CUT	124.20	124.20
	LESS 10% DISCOUNT		-331.44	-173.39
			2,982.96	1,560.51
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER PLATE (SN)	BENT	30.00	30.00
10	SET REAR BUMPER CLIP @\$6.50 (SN)	NECESSARY	65.00	30.00
2	TAIL LAMP PANEL SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-

Report Ref No. CC6/CTI18006221/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR DOOR SEALANT @\$80.00 (SN)	NOT NECESSARY	160.00	-
1	REAR DOOR STICKER "70KM/H" LH (SN)	NECESSARY	40.00	15.00
1	REAR DOOR STICKER "6 PAX" RH (SN)	NECESSARY	40.00	15.00
1	REAR DOOR NUMBER PLATE LAMP GARNISH CLIP (SN)	NOT NECESSARY	20.00	-
2	REAR DOOR GLASS SEALANT @\$60.00 (SN)	NECESSARY	120.00	80.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	120.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,145.00	510.00
	LABOUR			
	PANEL BEATING, REMOVING AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAIL LAMP PANEL.		1,600.00	850.00
	SPRAY PAINTING TO AFFECTED AREA.		1,200.00	700.00
	TUFF COAT.		250.00	40.00
	WIRING CHECK.		80.00	30.00
	TO REMOVE AND REFIX REAR DOOR MECHANISM (2 DOORS).		320.00	120.00
	REMOVE & REINSTALL REAR DOOR WINDOW GLASS.		160.00	120.00
	TO REMOVE AND REFIX REVERSE SENSOR.		120.00	40.00
			3,730.00	1,900.00
GRAND TOTAL			12,179.76	6,641.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,300.00

Report Ref No. CC6/CT118006221/Aea3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 1202S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 1202S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

