

ASS. REC. BY:

REF: CS/MSG18006239/Krd3

n2

Special Instruction:

Surveyor
Meimien

ASSIGNMENT (Office)

From (Person): Catherine Thia

of

MSG

Date/Time: 5/4/18 @ 10:25am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 8897Y

Insured:

SLV 3726L

at Workshop m/s

Alan's United Auto

Tel:

6453 8686

of

Blk 7, Sin Ming Ind. Est #01-76

Policy No:

29040254Mcy

Claim No:

554151

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 29/03/2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 10:56am @ 5/4/18

Person Contacted:

kenny

Vehicle IN / ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJB 8897Y - X
	SLV 3726L - X
13/4/18	@ 14:05 p.m. revised to Catherine Thia Sh. Y. via meimien.

ASS. REC. BY:

REF: *msc /**Kennerh*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STB 88977

Yr Regn:

*01, 08*Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS 1910

c.c:

1498

Colour:

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

154782

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

*JN/BAAC1170007561*Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModl: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

29/3/18

D.O.I.

11/4/18

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*12/4**File pass to Catherine**Confirm U/S 1950 @ 4 days**Red: \$1877.14, 491*

RECEIVED 09 SEP 2018

Date/Time, File Pass to?



: Prell. Report

1) *typical*

: Final Report

Date/Time, File Return to?

Days Of Repair: *4*Resurvey No. of Trip: *1*

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech Invs (\$)



: Weekend (\$)

Survey Fee:

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format :

TP

Lump Sum / I.B.t. (\$)

1950

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		05 Apr 2018 10:25 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PERFORMANCE MOTORS LIMITED, Co. Reg. No.: 197401559W		
Main Claimant:	SOH GIM HAN, ID: S1125858A		
Vehicle Reg. No.:	SJB8897Y	Date of Loss:	29/03/2018 12:00 - :59 [122 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554151	Policy/Cover Note No.:	29040254MCY Coverage: 01/10/2017 - 30/09/2018
Vehicle Reg. No. (Insured):	SLV3726L	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76, 575642 Sin Ming - Tel: 6453 8686		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/04/2018]		
Driver/Custodian (Insured):	SIA BOON LI (), NRIC: S7682611J, Tel: +6591729711		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_SG (05/04/2018): Cancellation of Assignment: SJB8897Y

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 13 Apr 2018

Preliminary Advice

Insured Vehicle No	: SLV3726L	Accident Date	: 29/03/2018
TP Vehicle No	: SJB8897Y	Assignment Date	: 05/04/2018
Make	: NISSAN LATIO	Est. Duration of Repair	: 4 days
Date of Inspection	: 11/04/2018		
Inspection At	: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,827.14
Revised Amount	:S\$	2,106.66
Check Items (Estimated)	:S\$	499.95
Total	:S\$	2,606.61

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05758

Date : 04-Apr-2018

PAGE : 1

Vehicle Insured : SLV3726L
Accident Date : 29-Mar-2018

Our Ref : 218062 (MSIG) / CHAN

SOH GIM HIAN
4 LUCKY GARDENS
Singapore 467653

*Not Authorise
L1Png & ?
Resurvey After Paint*

ESTIMATED COST OF REPAIR FOR NISSAN LATIO 1.5 SJB8897Y

- | | |
|-------|----------------------------|
| 1 pc | Front bumper fascia |
| 1 pc | Front bumper sponge |
| 1 pc | Front bumper reinforcement |
| 1 pc | Front bumper logo |
| 1 pc | Front bumper tow cover |
| 2 pcs | Radiator grille |
| 1 pc | N/s headlamp |
| 1 pc | N/s headlamp lower bracket |
| 2 pcs | Front bumper side retainer |
| 1 pc | Bonnet |

at \$157.50

@ S\$ 23.00

<i>B</i>	456.30	n	✓
<i>sn</i>	45.80	n	X
<i>Bu</i>	446.90	n	✓
<i>na</i>	50.70	n	✓
<i>sn</i>	22.00	n	X
	315.00	n	<i>4 c/s 3.50 X</i>
<i>m/cm</i>	372.00	n	✓
<i>cm</i>	26.00	n	✓
<i>diy</i>	46.00	n	✓
<i>n</i>	893.90	n	X

2,674.60

Less 10% : 267.46

B 2,407.14
45sn 50.00 sn

1 pc Front no.plate with box

To rewire damaged parts and refocus headlamp beam.

20.00 ✓

To putty and spray replaced parts

650.00 *500*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

700.00 *500*

Total : S\$ 3,827.14

Singapore Dollars Three Thousand Eight Hundred and Twenty Seven and Cents Fourteen Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLV3726L
Accident Date : 29-Mar-2018

No. : 05758

Date : 04-Apr-2018

Our Ref : 218062 (MSIG) / CHAN

PAGE : 1

SOH GIM HIAN
4 LUCKY GARDENS
Singapore 467653

Not Authorised
11/10/18 ?
Reserve After Paint

ESTIMATED COST OF REPAIR FOR NISSAN LATIO 1.5 SJB8897Y

pc	Front bumper fascia	R	456.30	n	✓
1 pc	Front bumper sponge	Sn	45.80	n	X
1 pc	Front bumper reinforcement	Bn	446.90	n	2
1 pc	Front bumper logo	Rn	50.70	n	✓
1 pc	Front bumper tow cover	Sn	22.00	n	X
2 pcs	Radiator grille	Nissan @ S\$157.50 ✓	315.00	n	4 0/15? X
1 pc	N/s headlamp		372.00	n	7 ✓
1 pc	N/s headlamp lower bracket		26.00	n	7 ✓
2 pcs	Front bumper side retainer	@ S\$ 23.00	46.00	n	✓
1 pc	Bonnet	R	893.90	n	X
			2,674.60		1555.40
Less 10% :			267.46		155.54
					1399.86
					2,407.14
1 pc	Front no.plate with box	R	45.00	sn	
To rewire damaged parts and refocus headlamp beam.				20.00	✓
To putty and spray replaced parts				650.00	500/
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts				700.00	500/
Total :			S\$ 3,827.14		

Singapore Dollars Three Thousand Eight Hundred and Twenty Seven and Cents Fourteen Only

4 sum 4
1950 @ 5 days
↑ Kenneth PLS
confirm
the

P 1399.86
SN 45
L 1020.00
2464.86
492.92
1971.88

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006239/KRD3N2

Date: 07/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29040254MCY
Claimant Vehicle No :	SJB8897Y	Insured Vehicle No :	SLV3726L
Date of Loss:	29/03/2018	Nature of Claim:	TP
		Claim No:	554151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB8897Y	Engine No:	HR15235721A
Make & Model:	NISSAN LATIO, 1.5 L (A)	Chassis No:	JN1BAAC11Z0007561
Reg. Date:	28/01/2008 (Man. Year: 2007)	Odometer:	154782 km
Colour:	Metallic Silver		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Linglong 4 mm	Rear Left Side:	Linglong 3 mm
Front Right Side:	Linglong 4 mm	Rear Right Side:	Linglong 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,457.14	1,444.86	1,012.28	41.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,370.00	1,020.00	350.00	25.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,827.14	2,464.86	1,362.28	35.60
Approved Total (Overridden) (\$\$)		1,950.00		
(\$\$)	3,827.14	1,950.00	1,877.14	49.05
+ GST 7.00/7.00% (\$\$)	267.90	136.50	131.40	49.05
Nett Amount (\$\$)	4,095.04	2,086.50	2,008.54	49.05

INSPECTION

Date of Assignment:	05/04/2018	
Date Inspected:	11/04/2018 Inspected At:	Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)
Parts:	143	NISSAN LATIO 1.5 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJB8897Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER FASCIA	Bent	456.30 FN	*456.30 FN
2	1	*FRONT BUMPER SPONGE	Serviceable	45.80 FN	*- FN
3	1	*FRONT BUMPER REINFORCEMENT	Buckled	446.90 FN	*446.90 FN
4	1	*FRONT BUMPER LOGO	Necessary	50.70 FN	*50.70 FN
5	1	*FRONT BUMPER TOW COVER	Serviceable	22.00 FN	*- FN
6	1	*RADIATOR GRILLE	Ns Mtg Cracked/Os Serviceable	315.00 FN	*157.50 FN
7	1	*N/S HEADLAMP	Mtg Cracked	372.00 FN	*372.00 FN
8	1	*N/S HEADLAMP LOWER BRACKET	Cracked	26.00 FN	*26.00 FN
9	2	*FRONT BUMPER SIDE RETAINER	Distorted	46.00 FN	*46.00 FN
10	1	*BONNET	Repair	893.90 FN	*- FN
11	1	*FRONT NO PLATE WITH BOX	Bent	50.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,724.60	1,600.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	267.46	155.54
Total Parts (\$\$)	2,457.14	1,444.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	20.00	20.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	650.00	500.00
3	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	700.00	500.00
Gross Labour Cost (S\$)			1,370.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >