

ASS. REC. BY

REP: CS/FCI18006256/Klad3ⁿ²

Special Instruction

Surveyor

Kalvin

ASSIGNMENT (Office)

From (Person)

Serene Ler

of FCI

Date/Time 05/04/18 @ 11:34am

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SHB 8002L

Insured: SHD 34094

at Workshop m/:

Premier Automotive

Tel: 6544 6671

of 23 Changi South Ave 2 # 03-02

Policy No: D-18088936MFSH

Claim No: D18602710MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 04/04/18

CA / REV / REP. / REV 24 HRS ^{wp}

H.O.D. Endorsement:

Date/Time: 12:55pm @ 5/4/18

Person Contacted:

Gary

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 8002L - CC3/AG17003860/H/cg3g2 D.O.A. 23/2/17
	SHD 34094 - CC3/AG13002432/H/g2f2y D.O.A. 2/2/13
06/4/18 @ 3.17pm	revised to Serene Ler by email.

06/1/13

Driver: Kelvin

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimate to Cost: _____
 OD / TP / INS / TP RES / OD RES / EVA / INV / MV
 To Insp: _____ Vehicle No: _____
 at Work: _____ Shop no: _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 80021 Yr Regt: 6 Nov 2015
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: KIA optima C.C. 1685
 Colour: Silver A/C: Ins / Std / NI / NA
 Sp. Reading: 2800 bl T/Radio: Ins / Std / NI / NA
 Eng/No: _____
 C/No: 1CNA6M41XMF5 642341
 Gen. Cond: Good / F / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD Rim or
 Tyre Size: F: 205/65 R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or maxxis
 Front _____ Rear _____
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. + mm L/Bal. 2 mm
 D.O.A. 4/4/18 D.O.I. 5/4/18
 Survey held at Premier
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
11/4/18	Lat 4/5 \$7800/ 6 Rys (fed to 4571.70, 377/0) FCI PIP

RECEIVED 13 APR 2018

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report
 1) 13/4 17:15
 Date/Time, File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Insp (\$ _____)
☐ : Other (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS: _____
 Phone: _____
 Other: _____
 TOTAL: _____

170 + 30
50
50
68
368

2x15 = 30

Return to: _____

By: _____

7P
7800



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18006256/K1qd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-04-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3409U	Veh. Inspected	SHB 8002L
Policy No.		Coverage (\$)	0.00
Claim No.	D18002710MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/04/2018	Inspection Date	05/04/2018
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

MOTOR SURVEY ASSIGNMENT

Date	04-04-2018	Our Ref No. D18002710MFSH
Accident Date	04-04-2018	Claim Type. Third Party
Insured Vehicle	SHD3409U	Third Party Vehicle. SHB8002L
Survey Location	23 CHANGI SOUTH AVENUE 2 #03-02	
Contact Person.	GARY SHI	
Contact No.	62148880/ 65446671	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED (NO EST. COR)	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236691)



PRI Documents



Close



PRI Header Details

Claim No	D18002710MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & PREMIER AU PREMIER TAXIS I KOK ENG]
Workshop Name	PREMIER AUTOMOTIVE SERVICES PTE LTD (Contact Person : GARY SHI)	Survey Location & Contact Details	23 CHANGI SOUTH AVENUE 2 #03-02 Mobile: 65446671 , Phone: 62148880 , Fax: 62141511 EmailId: GARY.SHI@PREMIERTAXI.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM COR)		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3409U	TP Vehicle No	SHB8002L
PRI Recieved Date	04-04-2018 09:00:06 PM	Surveyor Appointed Date	05-04-2018 11:33:08 AM	Surveyor Accept Date	05-04-2018 01:5

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	05-04-2018	Upload Survey Report *:	Choose File No
-----------------------------	----------------------	----------------------	------------	-------------------------	---

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
------	---	-------	--	------	--

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 April 2018 3:17 PM
To: 'Claim Workflow System'; assignments
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002710MFSH/1
Attachments: CSFCI18006256K1qd3.pdf

Dear Serene,

Enclosed herewith preliminary advice of SHB 8002L.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 5 April 2018 12:59 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SERENELER@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002710MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 5 April 2018 11:33 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SERENELER@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002710MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002710MFSH

Date: 06 April 2018

Our Ref: CS/FC118006256/K1qd3

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SHB 8002L .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/04/2018 at the premises of M/s PREMIER AUTOMOTIVE, and have the following to report:-

Workshop Estimate Amount	: S\$ 11,647.80 .
Revised Estimate Amount	: S\$ 8,950.90 .
"Check" Items Amount	: S\$ 66.60 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:
The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

Kalvin Ang
Automotive Assessor

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	06 Nov 2015 / 08:53:19	Receipt No.:	AACCK001-AX239-151106-000007
Asset Type:	Vehicle	Transaction Amount:	\$68,872.00
Asset ID:	SHB8002L	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20151106085319402101		

Vehicle No.:	SHB8002L
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)
First Registration Date:	06 Nov 2015
Original Registration Date:	06 Nov 2015
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414MF5642371
Engine No.:	D4FDFH314173
Motor No.:	-
Trailer Chassis No.:	-
Propellant:	Diesel
Passenger Capacity:	4
Engine Capacity:	1685
Power Rating:	-
Unladen Weight:	1584
Maximum Laden Weight:	2050
Primary Color:	Silver
Secondary Color:	-
Manufacturing Year:	2015
Open Market Value:	\$22,475.00
Minimum PARF Benefit:	\$14,079.00
PARF Eligibility:	Y
No. of Transfer:	0
Effective Ownership Date/Time:	06 Nov 2015 08:53:19
COE No.:	2015110601003461C
COE Expiry Date:	05 Nov 2023
COE Bid Category:	-
Actual QP/PQP Paid Amount:	\$45,267.00
Lifespan Expiry Date:	05 Nov 2023



Victory Recovery (Business Reg No.: 53096358B)

65 Teban Gardens Rd #23-617, Singapore 600065.

Mobile: 9618 0311 Fax: 6267 8996

CASH /
W.O. No. 92212

TOW JOB WORKS ORDER

M. Premier Taxi Svc Date 4-4-18
Car Make/Model KIA Vehicle No. SHB8002 L
M'ship/NRIC No./Card No. _____ Contact No. _____
Time - Rec'd 1135 Arrived 1150 Completed 1250
Amount Charge S\$ _____ Tow Truck No YG6835K
Destination (from) Hill St (to) 23 Changi South Ave 2
Remark (if any) Accident

Tow Driver's Signature _____

Member's Signature _____

- ☐ Change Tyres & Towing
- ☐ Basement / Multi Carpark
- ☐ Causeway / 2nd Link

- ☐ Using King Dolley
- ☐ Low Spoiler / Low Oil Sump
- ☐ Accident / Over-turn

- ☐ Use Car Carrier
- ☐ Release Brake / Shaft
- ☐ Loaded

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:20070743D GST REG:20070743D

4-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8002 L

1 pc	Boot lid	✓ <i>Bad</i>	\$	1,119.00
1 pc	Boot lid lock	X <i>me</i>	\$	99.00
1 pc	Bootlid striker	X <i>me</i>	\$	21.00
1 pc	Bootlid emblem	✓ <i>me</i>	\$	27.00
1 pc	Bootlid CRDi	✓ <i>me</i>	\$	29.00
1 pc	Boot lid rubber weatherstrip	✓ <i>born</i>	\$	96.00
1 pc	Boot lid lower garnish	✓ <i>me</i>	\$	290.00
2 pcs	Bootlid hinge @ \$66.00	✓ <i>Bad</i>	\$	132.00
1 pc	End panel	✓ <i>Bad</i>	\$	250.00
1 pc	End panel garnish	✓ <i>me</i>	\$	74.00
1 pc	Spare tyre clamp	X <i>me</i>	\$	6.00
1 pc	Rear muffler assy	✓ <i>Bad</i>	\$	1,009.00
1 pc	Rear exhaust pipe hanger	X <i>me</i>	\$	49.00
1 pc	Rear floorboard compartment panel	X <i>me</i>	\$	625.00
1 pc	Rear o/s fender	✓ <i>dd</i>	\$	1,205.00
1 pc	Rear o/s fender inner shield	✓ <i>me</i>	\$	120.00
1 pc	Rear windscreen moulding	✓ <i>me</i>	\$	87.00
1 pc	Rear o/s side panel	X <i>me</i>	\$	65.00
1 pc	Rear o/s air vent	✓ <i>me</i>	\$	34.00
1 pc	Rear o/s tail lamp panel	X <i>me</i>	\$	134.00
1 pc	Rear bumper	✓ <i>Bad</i>	\$	696.00
1 pc	Rear bumper lower cover	✓ <i>me</i>	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	✓ <i>me</i>	\$	58.00
1 pc	Rear bumper inner sponge	✓ <i>me</i>	\$	114.00
1 pc	Rear bumper reinforcement	✓ <i>me</i>	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	✓ <i>me</i>	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	✓ <i>me</i>	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	✓ <i>me</i>	\$	36.00
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	✓ <i>me</i>	\$	92.00
	<i>Rear o/s Tail lamp</i>	✓ <i>me</i>	\$	7,422.00
	<i>Rear Bootlid o/s lamp</i>	✓ <i>me</i>	\$	742.20
		Less 10%	\$	6,679.80

S/NETT

1 set	Rear bumper clips	✓ <i>me</i>	\$	48.00
1 set	End panel inner garnish clips	✓ <i>me</i>	\$	30.00
1 set	Bootlid lower garnish clips	✓ <i>me</i>	\$	60.00
1 set	Bootlid stickers	✓ <i>me</i>	\$	100.00
1 set	Reverse sensor	✓ <i>me</i>	\$	280.00
1 pc	Rear bumper top protector	✓ <i>me</i>	\$	80.00
1 set	Insulating padding	✓ <i>me</i>	\$	120.00
	<i>Rear Number plate casing</i>	✓ <i>me</i>	\$	30.00

4-Apr-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8002 L

Towing Fee	\$ 50.00 ✓
Sundry <i>nec</i>	\$ 50.00 20
To dismantle / replace exhaust pipe	\$ 120.00 50
To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 80.00 20
To dismantle and refit the rear windscreen	\$ 120.00 100
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the the end panel, floorboard compartment, rear o/s fender, rear o/s side panel, rear o/s taillamp panel. Including knock-out, straighten, repair, reshape and adjust of the same	\$ 1,800.00 1200
To putty and spray painting on bootlid, bootlid lower garnish, rear bumper, floorboard compartment, end panel, rear o/s fender, rear o/s side panel, rear o/s tail lamp panel	\$ 1,600.00 1150
To apply rustproofing on the repaired and replaced panels.	\$ 250.00 50
	<u>\$ 11,647.80</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

*Kaka' (LKK)
✓ 5/4/18 1530hrs.
6 Days.
P/P
Before Part 1/10*

12371.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006256/K1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3409U	Veh. Inspected	SHB 8002L	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002710MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	05/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5642371	Colour	SILVER	
Odometer	280061	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R16	MAXXIS	7 mm	
L/H Front Tyre	205/65 R16	MAXXIS	7 mm	
R/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
L/H Rear Tyre	205/65 R16	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2018	Inspection Date	05/04/2018	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 8002L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	1,119.00	1,119.00
1	BOOT LID LOCK	SERVICEABLE	99.00	-
1	BOOTLID STRIKER	SERVICEABLE	21.00	-
1	BOOTLID EMBLEM	NECESSARY	27.00	27.00
1	BOOTLID CRDI	NECESSARY	29.00	29.00
1	BOOT LID RUBBER WEATHERSTRIP	TORN	96.00	96.00
1	BOOT LID LOWER GARNISH	CRACKED	290.00	290.00
2	BOOTLID HINGE @\$66.00	BENT	132.00	132.00
1	END PANEL	DENTED	250.00	250.00
1	END PANEL GARNISH	CRACKED	74.00	74.00
1	SPARE TYRE CLAMP	SERVICEABLE	6.00	-
1	REAR MUFFLER ASSY	BENT	1,009.00	1,009.00
1	REAR EXHAUST PIPE HANGER	SERVICEABLE	49.00	-
1	REAR FLOORBOARD COMPARTMENT PANEL	TO REPAIR SEE LABOUR	625.00	-
1	REAR O/S FENDER	DENTED	1,205.00	1,205.00
1	REAR O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR O/S SIDE PANEL	TO REPAIR SEE LABOUR	65.00	-
1	REAR O/S AIR VENT	CRACKED	34.00	34.00
1	REAR O/S TAIL LAMP PANEL	TO REPAIR SEE LABOUR	134.00	-
1	REAR BUMPER	DEFORMED	696.00	696.00
1	REAR BUMPER LOWER COVER	CRACKED	206.00	206.00
2	REAR BUMPER SIDE BRACKET O/S & N/S @\$29.00	CRACKED	58.00	58.00
1	REAR BUMPER INNER SPONGE	TORN	114.00	114.00
1	REAR BUMPER REINFORCEMENT	CRACKED	607.00	607.00
2	REAR BUMPER STAY O/S & N/S @\$53.00	CRACKED	106.00	106.00
2	REAR BUMPER REINFORCEMENT LOWER BRACKET @\$18.00	CRACKED	36.00	36.00
2	REAR BUMPER REINFORCEMENT UPPER BRACKET @\$18.00	CRACKED	36.00	36.00

Report Ref No. CS/FCI18006256/K1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR BUMPER REFLECTOR N/S & O/S @\$46.00	O/S CRACKED / N/S SERVICEABLE	92.00	46.00
1	REAR O/S TAILLAMP	CRACKED	421.00	421.00
1	REAR BOOTLID O/S LAMP	CRACKED	350.00	350.00
	LESS 10% DISCOUNT		-819.30	-714.80
			7,373.70	6,433.20
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	48.00	48.00
1	SET END PANEL INNER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET BOOTLID LOWER GARNISH CLIPS (SN)	NECESSARY	60.00	60.00
1	SET BOOTLID STICKERS (SN)	NECESSARY	100.00	100.00
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP PROTECTOR (SN)	NECESSARY	80.00	50.00
1	SET INSULATING PADDING (SN)	NECESSARY	120.00	120.00
1	REAR NUMBER PLATE CASING (SN)	CRACKED	30.00	30.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			798.00	658.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO DISMANTLE/REPLACE EXHAUST PIPE.		120.00	50.00
	TO DISMANTLE/REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.		80.00	20.00
	TO DISMANTLE AND REFIT THE REAR WINDSCREEN.		120.00	100.00
	TO DISMANTLE/REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT/WELD, CUT-OFF THE END PANEL, FLOORBOARD COMPARTMENT, REAR O/S FENDER, REAR O/S SIDE PANEL, REAR O/S TAILLAMP PANEL, INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME. INCLUSIVE OF THE REPAIR OF REAR FLOORBOARD COMPARTMENT PANEL, REAR O/S SIDE PANEL AND REAR O/S TAIL LAMP PANEL.		1,800.00	1,200.00

Report Ref No. CS/FCI18006256/K1qd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND SPRAY PAINTING ON BOOTLID,BOOTLID LOWER GARNISH,REAR BUMPER,FLOORBOARD COMPARTMENT,END PANEL,REAR O/S FENDER,REAR O/S SIDE PANEL,REAR O/S TAIL LAMP PANEL.		1,600.00	1,150.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		250.00	50.00
			4,200.00	2,670.00
GRAND TOTAL			12,371.70	9,761.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,800.00

Report Ref No. CS/FCI18006256/K1qd3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.