

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00

SPRINGLEAF TOWER SINGAPORE 079909

INV No. AC2003847

INV Date 13/05/2020

Reference CC6/CTI18006279/Uba3q2

Code CT

PROFESSIONAL SERVICE FEE

Vehicle No. PC 5420H

Insured Veh. CB 4111R

Claim No. SNM18D01754C02/1/LKKDS

Policy No. DMB1SN1749251700

Accident Date 28/03/2018

Inspection Date 05/04/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile					
CHIN	NA TAIPING INSURANCE (S) PTE LTD Ref : CC6/CTI18006279/Uba3q2				
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date: 13-05-2020 Code: CTI			
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	CB 4111R	Veh. Inspected	PC 5420H	
	Policy No.	DMB1SN1749251700	Coverage (\$)	0.00	
	Claim No.	SNM18D01754C02/1/LKKDS	Excess (\$)	0.00	
	Assign From		Assign Date	05/04/2018	
2.		Vehicle Partic	culars & Condition		
	Make & Model	TOYOTA HIACE COMMUTER (A)	c.c	2982	
	Engine No.	HIDDEN	Year of Reg. 2017		
	Chassis No.	KDH2230027204	Colour	WHITE	
	Odometer	58029	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General GOOD				
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE	7 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE	7 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE	7 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE	7 mm	
4.		•	on of Damages		
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.		
	DAMAGES SEE DI	ETAILS.			
5.		General	Information		
	Accident Date	28/03/2018	Inspection Date	05/04/2018	
	Survey held at	LEE BROTHERS AUTOMOTIVE	PTE LTD		
	1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883				
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 5420H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR TAILGATE	BADLY DENTED	2,150.70	2,150.70
2	REAR TAILGATE HINGE RH/LH @\$68.95	NOT NECESSARY	137.90	-
2	REAR TAILGATE DAMPER RH/LH @\$399.15	NOT NECESSARY	798.30	-
1	REAR TAILGATE RUBBER	TWISTED	399.45	399.45
1	REAR TAILGATE LOCK	TWISTED / JAMMED	509.10	509.10
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	59.10	-
1	REAR TAILGATE INNER TRIM	DEFORMED / TORN	688.90	688.90
1	REAR TAILGATE EMBLEM 'LOGO'	NECESSARY	78.10	78.10
1	REAR TAILGATE EMBLEM 'HIACE'	NECESSARY	65.10	65.10
1	REAR TAILGATE EMBLEM 'GL'	NECESSARY	40.20	40.20
1	REAR TAILGATE CHROME MOULDING	CRACKED	210.20	210.20
2	REAR TAILGATE NUMBER PLATE LAMP @\$79.10	NOT NECESSARY	158.20	-
1	REAR BUMPER	DISTORTED	517.10	517.10
4	REAR BUMPER BRACKET @\$65.10	BENT	260.40	260.40
2	REAR BUMPER SIDE RETAINER LH/RH @\$145.20	NOT NECESSARY	290.40	-
2	REAR TAILLAMP RH/LH @\$325.50	CRACKED	651.00	651.00
1	REAR SPARE WHEEL CARRIER	NOT NECESSARY	355.10	-
1	REAR SPARE WHEEL CARRIER BOLT	NOT NECESSARY	49.10	-
1	REAR END PANEL -OUTER	BADLY DENTED	694.10	694.10
1	REAR END PANEL -INNER	BADLY DENTED	759.20	759.20
1	REAR END PANEL STEEL PAD	DEFORMED / TORN	295.20	295.20
1	REAR EXHAUST BOX	NOT NECESSARY	1,981.72	-
3	REAR EXHAUST BOX MOUNTING @\$35.20	NOT NECESSARY	105.60	-
	LESS 25% DISCOUNT		-2,813.54	-1,829.69
			8,440.63	5,489.06
	SPECIAL NETT ITEMS			
1	SET REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	30.00	30.00
	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
l	REAR TAILGATE STICKER '70KM/H' (SN)	NECESSARY	20.00	10.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00

Report Ref No. CC6/CTI18006279/Uba3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR NUMBER PLATE (SN)	CRACKED	50.00	40.00
1	SET REAR REVERSE CAMERA (SN)	SHORTED	280.00	280.00
1	REAR DOOR EMERGENCY DOOR STICKER (SN)	NECESSARY	30.00	15.00
			815.00	660.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT ,CUT /WELD REAR END PANEL AND REPLACE ACCIDENT PARTS .		1,200.00	900.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		1,200.00	800.00
	TO CHECK WIRING .		30.00	20.00
	TO TRANSFER REAR TAILGATE PARTS.		120.00	60.00
	TO REMOVE, REPLACE REVERSE SENSOR .		100.00	50.00
	TO REMOVE ,REFIX CUSHION AND INNER TRIM .		180.00	60.00
	TO REMOVE ,REFIX REAR WINDSCREEN .		180.00	100.00
	TO REMOVE,REPLACE EXHAUST SYSTEM.	NOT NECESSARY	180.00	-
	TO TUFF KOTE.		120.00	80.00
			3,310.00	2,070.00
	GRAND TOTAL		12,565.63	8,219.06

RECOMMENDED COST OF LUMP SUM REPAIRS		6,500.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/CTI18006279/Uba3q2

CHUA KANG SENG

Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. PC 5420H

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3591 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi hdustrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315







