

ASS. REC. BY:

REF: CS/CTI18006283/ Ugd3 n2 Special Instruction:

Surveyor

ASSIGNMENT (Office)

Menimen

From (Person)

Adeline chng

of CTI

Date/Time 5/4/18 @ 1.57pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJV 6253M

Insured:

SLK 4169X

at Workshop m/s

Hock wah Motor (Bedok)

Tel:

64415655

of

Bik 3011 Bedok Ind. Park E #01-2008

Policy No:

DMHCSN743921801

Claim No:

SNM18D01695C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

02/04/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

2.04pm @ 5/4/18

Person Contacted:

MAVIS

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate	
	SJV 6253M - NBA/CTI18005428/Y	D.O.A: 02/04/18
	SLK 4169X - NBA/CTI18005428/Y	D.O.A: 02/04/18

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 6253M

at Workshop m/s Woolworth

of _____

Insured: SLK 4169X

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

G/A / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJV6253M Yr Regn: 210

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stream c.c. 1799

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 116126 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMRN686095200902

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Worder / Jammed / Leaked / Burnt or

Brake: Worder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205-65-R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 2/4/18 D.O.I. 6/4/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/4/18 Confirmed L/S & 2000 with Anys.a.
(held by 3457.16, 63/1)

RECEIVED 10 APR 2018

Date/Time, File Pass to? : Preli. Report

11/04/18 : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS: \$ _____

Photos _____

Others _____

TOTAL

220

Report Format: MER-TP
Lump Sum / I.B.I: (\$ 2000)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18006283/Uqd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 05-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLK 4169X	Veh. Inspected	SJV 6253M
Policy No.	DMHCSN743921801	Coverage (\$)	0.00
Claim No.	SNM18D01695C02	Excess (\$)	0.00
Assign From	MERIMEN (ADELINE CHNG)	Assign Date	05/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/04/2018	Inspection Date	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2018		05 Apr 2018 13:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	PURPLUSH PRO SERVICES, Co. Reg. No.: 53281623D		
Main Claimant:	LIM&TANG MANAGEMENT SERVICES, Co. Reg. No.: 53349074W		
Vehicle Reg. No.:	SJV6253M	Date of Loss:	02/04/2018 11:00 - :59
Claim Type:	TP / SNM18D01695C02	Policy/Cover Note No.:	DMHCSN743921801 (Comprehensive)
Vehicle Reg. No. (Insured):	SLK4169X	Policy No. (Claimant):	5085752160-01
		Excess:	S\$0.00
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2018]		
Driver/Custodian (Insured):	SEENIVASAN S/O PARAMANANTHAN (31 / Male), NRIC: S8701579C, Tel: +6590487710		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	9074W
Vehicle Details	
Vehicle No.:	SJV6253M
Vehicle to be Exported:	No
Intended De-registration Date:	06 Apr 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A13800912
Chassis No.:	JHMRN68609S200902
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$25,100.00
Original Registration Date:	02 Feb 2010
First Registration Date:	02 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$25,100.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2020
PARF Rebate Amount:	\$13,805.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,190.00
COE Rebate Amount:	\$3,492.00
Total Rebate Amount:	\$17,297.00

The information contained herein is correct as at 06 Apr 2018

OK

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 3655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53349074W
 LIM&TANG MANAGEMENT SERVICES
 NO

SINGAPORE
 TEL : FAX :
 PH :
 ATTN :

Term:

*Not Authorized
 hkk
 2/5 or 2000/2
 4 day.
 6/4/18
 take photo after repair*

ESTIMATE BILL

Number : EB00004794
 Date : 05/04/2018
 Case No : AD00009653
 Vehicle No : SJV6253M
 Chassis : JHMRN68609S200902
 Year of Mfr : 2008
 Policy No : 5085752160-01
 Model : HONDA STREAM

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	REAR DOOR RH <i>DO/ret</i>	1.0	836.40	20	669.12
2	REAR DOOR TOP STICKER RH <i>rec</i>	1.0	35.10	20	28.08
3	REAR FENDER RH <i>n</i>	1.0	858.30	20	686.64
4	REAR FENDER QUATER GLASS RH <i>n</i>	1.0	381.50	20	305.20
5	REAR WHEEL RIM RH <i>cu 7 4005-N</i>	1.0	861.50	20	689.20
6	REAR WHEEL HUB BEARING RH <i>n</i>	1.0	367.40	20	293.92
List Price - Parts Sub Total					2,672.16
7	FRONT DOOR RH - REPAIR <i>n x</i>	1.0			
8	ROCKER PANEL RH - REPAIR <i>n x</i>	1.0			
9	REAR BUMPER - REPAIR <i>n x</i>	1.0			
10	REAR TYRE RH <i>n</i>	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					2,952.16
11	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	450 600.00
12	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,000.00	0	800 1,000.00
13	ANTI-RUST COATING	1.0	120.00	0	30 120.00
14	TO REMOVE & REFIT UNDERCARRIAGE	1.0	300.00	0	11 300.00
15	FOUR WHEEL ALIGNMENT	1.0	180.00	0	60 180.00
16	TO REMOVE & REFIT QUARTER GLASS	1.0	100.00	0	11 100.00
17	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	200.00	0	10 200.00
Labour 1 Sub Total					2,500.00
SINGAPORE DOLLARS : FIVE THOUSAND EIGHT HUNDRED THIRTY-THREE AND CENTS EIGHTY-ONE ONLY					
					2517.2
			Less Excess		0.00
			SUBTOTAL		5,452.16
			GST 7.00%		381.65
			TOTAL		5,833.81

Date of accident : 02/04/2018 11:00 AM. Place : LOWER DELTA ROAD > KEPPEL

E. & O. E.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Acknowledged by Repairer

Page 1 of 1

* N = Item not subjected to GST

Issued by : Anysia

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118006283/UQD3N2

Date: 12/04/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN743921801	
Claimant Vehicle No :	SJV6253M	Insured Vehicle No :	SLK4169X	
Date of Loss:	02/04/2018	Nature of Claim:	TP	Claim No: SNM18D01695C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV6253M	Engine No:	R18A13800912
Make & Model:	HONDA STREAM, 1.8 (A)	Chassis No:	JHMRN68609S200902
Reg. Date:	02/02/2010 (Man. Year: 2008)	Odometer:	116126 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/65R15	Rear Tyre Size:	205/65R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,952.16	1,097.20	1,854.96	62.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,420.00	1,080.00	43.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,452.16	2,517.20	2,934.96	53.83
Approved Total (Overridden) (\$\$)		2,000.00		
	(\$\$)	5,452.16	2,000.00	3,452.16
	+ GST 7.00/7.00% (\$\$)	381.65	140.00	241.65
	Nett Amount (\$\$)	5,833.81	2,140.00	3,693.81

INSPECTION

Date of Assignment:	05/04/2018	
Date Inspected:	06/04/2018 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 12 Apr 2018)
Parts: M1-MPV	HONDA STREAM 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV6253M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented/Bent	836.40 FL	*836.40 FL
2	1		*REAR DOOR TOP STICKER RH	Necessary	35.10 FL	*35.10 FL
3	1		*REAR FENDER RH	Repair	858.30 FL	*- FL
4	1		*REAR FENDER QUARTER GLASS RH	Not Necessary	381.50 FL	*- FL
5	1		*REAR WHEEL HUB BEARING RH	Not Necessary	367.40 FL	*- FL
6	1		*REAR WHEEL RIM RH	Cut	689.20 FS	*400.00 FS
7	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS
8	1		*ROCKER PANEL RH (NPA)	Repair	0.00 FS	*- FS
9	1		*REAR BUMPER (NPA)	Repair	0.00 FS	*- FS
10	1		*REAR TYRE RH	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,447.90	1,271.50
- List Item Discount on L Items 20.00/20.00% (S\$)	495.74	174.30
Total Parts (S\$)	2,952.16	1,097.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	600.00	450.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	800.00
3	ANTI-RUST COATING	New	120.00	30.00
4	TO REMOVE & REFIT UNDERCARRIAGE	New	300.00	-
5	FOUR WHEEL ALIGNMENT	New	180.00	60.00
6	TO REMOVE & REFIT QUARTER GLASS	New	100.00	-
7	TO REMOVE & REFIT CUSHION & UPHOSTERY	New	200.00	80.00
Gross Labour Cost (S\$)			2,500.00	1,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >