

ASS. REC. BY:

REF:

CS / SPF 18006295 / *Sqbert*

Special Instruction:

Surveyor:

Sebastian

ASSIGNMENT (Office)

From (Person):

Lim Wei Yea

of

SPF

Estimated Cost:

Date/Time:

04042018 5.24pm

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

QX 4823M

at Workshop m/s

SMRT

Insured:

of

60 Woodlands Ind Park E

Tel:

Policy No:

Sum Insured:

Claim No:

HOMSPFETQ17300218

Make of Veh:

Excess:

(Client's Record)

D.O.A.

CA / *REV* / REP. / REV 24 HRS

Date/Time:

Person Contacted:

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate

*09/4/18 @**QX 4823M - X**5.71pm revert to Wei Yea by email.**man hours = 56.5 hrs.*

REF: **SPF****ASSIGNMENT**From: Date: **05042018**

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: **QX 4823m**at Workshop m/s: **SMRT**

of

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: **QX 4823m** Yr Regn: **14 Mar 2001**Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Toyota Hiace** C.C. **2986**Colour: **Blue** A/C: Insured / Std / NI / NASp. Reading: **220621** T/Radio: Insured / Std / NI / NAEng/No: **5L5033622**C/No: **L11740066131**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: **NA** / S/Rim / STD A/Rim orTyre Size: F: **185R14C**R: **11**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Budgestore**

Front

R/Bal. **6** mmL/Bal. **6** mm

D.O.A.

Rear

R/Bal. **6** mmL/Bal. **6** mmD.O.I. **1/4/18**Survey held at **28 Sg Kadit Dr**Des. of Damages: ☒ Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 MAY 2018

Date/Time, File Pass to?

1) **17/5 11:15 AM**

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

☐ : Preli. Report☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

) S + RS. (\$)

) Photos

) Other's

TOTAL

280**280**




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18006295/Sqb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 05-04-2018		
Code : SPF				
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 4823M	
Policy No.	Coverage (\$)		0.00	
Claim No. HOMSPFETQ17300218	Excess (\$)		0.00	
Assign From LIM WEI YEA	Assign Date		04/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	Inspection Date		05/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 4 April, 2018 5:24 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto'; 'Shiau Chan (LKKAuto'
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218
Attachments: QX4823M.XLSX

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 4823M

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Do let me know if you have difficulty in arranging a viewing session with SMRT.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Shiau Chan (LKKAuto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 16 May 2018 5:11 PM
To: Shiau Chan (LKKAuto); assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Hi Shiau Chan,

Yes, please proceed to submit the report.
Thank you!

Best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Wednesday, 16 May 2018 09:26
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Dear Wei Yea,

Please advise whether can we submit our report of QX 4823M accordingly.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Monday, 9 April 2018 5:31 PM
To: 'Wei Yea LIM (SPF)'; assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); SUR
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218
Attachments: QX4823M PHOTO.pdf; QX 4823M.xls

Dear Wei Yea,

Please find the attached of QX 4823M.

Best Regards,

Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Wednesday, 4 April 2018 5:24 PM
To: assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Appraisal Services for SPF vehicles at SMRT Automotive Services - HOMSPFETQ17300218

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 4823M

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Do let me know if you have difficulty in arranging a viewing session with SMRT.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	MB	UNIT :	HTA / PDC
VEH NO :	QX4823M	REPAIR TYPE :	ACCIDENT		
VEH MAKE/MODEL :	TOYOTA HIACE	ODOMETER :	220620		

Reference No.
4823/SPF/4W/18/03/20

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Panel ✓ BT		1		0.00	0.00
1.2	RHS Signal Lamp Housing ✓ BT		1		0.00	0.00
1.3	RHS Signal Lamp ✓ CRK		1		0.00	0.00
1.4	RHS Head Lamp ✓ CRK X		1		0.00	0.00
1.5	LHS Signal Lamp Housing ✓ CRK		1		0.00	0.00
1.6	LHS Signal Lamp ✓ CRK		1		0.00	0.00
1.7	Front Bumper ✓ Defcon		1		0.00	0.00
1.8	Radiator Grill ✓ CRK		1		0.00	0.00
1.9	"TOYOTA" Emblem ✓ NEC		1		0.00	0.00
1.10	Front Windscreen Moulding ✓ NEC		1		0.00	0.00
1.11	Sealant for Front Windscreen ✓ NEC		1		0.00	0.00
1.12	Primer for Front Windscreen ✓ NEC		1		0.00	0.00
2	Additional Services					
2.1	NA			0%	0.00	0.00
Remarks:					Parts Total:	\$ -

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Panel:			
	Cut, Remove & Replace Front Panel	8	10	0.00
	Remove & Re-Install back Dashboard to facilitate repair for Front Panel	16	18	0.00
	Remove & Re-Install back Air-Con Unit to facilitate repair for Front Panel (Top Up Air-Con Gas after reinstalling)	12	18	0.00
	Replace "POLICE" Wording on Front Panel (To be provided by AEMD)		0.5 ✓	0.00
	Putty & Spray Paint for Front Panel	5	6	0.00
1.2	Front Windscreen:	4	5	0.00
	Remove & Re-Install back Front Windscreen to facilitate repair for Front Panel (On work progress, does not include Front Windscreen Cracked)			
	Remove & Replace Front Windscreen Moulding			
	Water Seepage for Front Windscreen			
1.2	RHS Signal & Head Lamp:	3	5	0.00
	Remove & Replace RHS Signal Lamp Housing			
	Remove & Replace RHS Signal Lamp			
	Remove & Replace RHS Head Lamp			
	Wiring for RHS Signal Lamp & Head Lamp			
1.3	LHS Signal Lamp:	2	3	0.00
	Remove & Replace LHS Signal Lamp Housing			
	Remove & Replace LHS Signal Lamp			
	Wiring for LHS Signal Lamp & Head Lamp			
1.4	Front Bumper:		5 ✓	0.00
	Remove & Replace Front Bumper			
	Putty & Spray Paint for Front Complete Bumper			
1.5	Radiator Grill & Emblem:		1 ✓	0.00
	Remove & Replace Radiator Grill			
	Remove & Replace "TOYOTA" Emblem			
SUB-TOTAL			71.5	0.00
2	Additional Services			
2.1	Towing Service From Station to Workshop (SOR 8)	138.60	1	138.60
2.2	Return Service From Workshop to Station (SOR 7)	44.10	1	44.10
SUB-TOTAL			2	182.70
		Labour Total:	\$	182.70
		GRAND TOTAL :	\$	182.70
		Total sum billed under SOR only :	\$	182.70
		Total sum billed under CVR only :	\$	-
Contractor shall complete the entire repair within <u>40</u> working days upon quotation approval date . (Include parts awaiting time)				

Verification of Scope of Work

Contractor QC	Vetted By:	Approved By:
---------------	------------	--------------

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT PANEL	1	BENT			
1.2	RHS SIGNAL LAMP HOUSING	1	BENT			
1.3	RHS SIGNAL LAMP	1	CRACKED			
1.4	RHS HEAD LAMP	1	NOT NECESSARY			
1.5	LHS SIGNAL LAMP HOUSING	1	SCRATCHED			
1.6	LHS SIGNAL LAMP	1	CRACKED			
1.7	FRONT BUMPER	1	DEFORMED			
1.8	RADIATOR GRILL	1	CRACKED			
1.9	TOYOTA' EMBLEM	1	NECESSARY			
1.10	FRONT WINDSCREEN MOULDING	1	NECESSARY			
1.11	SEALANT FOR FRONT WINDSCREEN	1	NECESSARY			
1.12	PRIMER FOR FRONT WINDSCREEN	1	NECESSARY			
2	LABOUR					
2.1	FRONT PANEL:					
	PANEL					8
	DASHBOARD TO FACILITATE REPAIR FOR FRONT PANEL					16
	CON UNIT TO FACILITATE REPAIR TO FRONT PANEL (TOP UP AIR-CON GAS AFTER REINSTALLING)					12
	FRONT PANEL (TO BE PROVIDED BY AEMD)					0.5
	PANEL					5
2.2	FRONT WINDSCREEN:					4
	WINDSCREEN TO FACILITATE REPAIR FOR FRONT PANEL (ON WORK PROGRESS, DOES NOT INCLUDE					
	WINDSCREEN MOULDING					
	WINDSCREEN					
2.3	RHS SIGNAL & HEAD LAMP:					3
	LAMP HOUSING					
	LAMP					
	LAMP					
	HEAD LAMP					
2.4	LHS SIGNAL LAMP:					2


	LAMP HOUSING					
	LAMP					
	HEAD LAMP					
2.5	FRONT BUMPER:					5
	REMOVE & REPLACE FRONT BUMPER					
	PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER					
2.6	RADIATOR GRILL & EMBLEM:					1
	GRILLE					
	EMBLEM					
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				56.5

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18006295/Sqbe2		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 24-05-2018		
		Code : SPF3		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	QX 4823M	
Policy No.		Coverage (\$)	0.00	
Claim No.	HOMSPFETQ17300218	Excess (\$)	0.00	
Assign From	LIM WEI YEA	Assign Date	04/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2986	
Engine No.	HIDDEN	Year of Reg.	2001	
Chassis No.	LH1740006131	Colour	BLUE	
Odometer	220621	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185 R14C	BRIDGESTONE	6 mm	
L/H Front Tyre	185 R14C	BRIDGESTONE	6 mm	
R/H Rear Tyre	185 R14C	BRIDGESTONE	6 mm	
L/H Rear Tyre	185 R14C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date		Inspection Date	06/04/2018	
Survey held at	2B SUNGEI KADUT DR			
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				

Registration No. QX 4823M

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	FRONT PANEL	1	BENT			
1.2	RHS SIGNAL LAMP HOUSING	1	BENT			
1.3	RHS SIGNAL LAMP	1	CRACKED			
1.4	RHS HEAD LAMP	1	NOT NECESSARY			
1.5	LHS SIGNAL LAMP HOUSING	1	SCRATCHED			
1.6	LHS SIGNAL LAMP	1	CRACKED			
1.7	FRONT BUMPER	1	DEFORMED			
1.8	RADIATOR GRILL	1	CRACKED			
1.9	TOYOTA' EMBLEM	1	NECESSARY			
1.10	FRONT WINDSCREEN MOULDING	1	NECESSARY			
1.11	SEALANT FOR FRONT WINDSCREEN	1	NECESSARY			
1.12	PRIMER FOR FRONT WINDSCREEN	1	NECESSARY			
2	LABOUR					
2.1	FRONT PANEL:					
	CUT, REMOVE & REPLACE FRONT PANEL					8
	REMOVE & RE-INSTALL BACK DASHBOARD TO FACILITATE REPAIR FOR FRONT PANEL					16
	REMOVE & RE-INSTALL BACK AIR-CON UNIT TO FACILITATE REPAIR TO FRONT PANEL (TOP UP AIR-CON GAS AFTER REINSTALLING)					12

	REPLACE 'POLICE' WORDING ON FRONT PANEL (TO BE PROVIDED BY AEMD)					0.5
	PUTTY & SPRAY PAINT FOR FRONT PANEL					5
2.2	FRONT WINDSCREEN:					4
	REMOVE & RE-INSTALL BACK FRONT WINDSCREEN TO FACILITATE REPAIR FOR FRONT PANEL (ON WORK PROGRESS, DOES NOT INCLUDE FRONT WINDSCREEN CRACKED)					
	REMOVE & REPLACE FRONT WINDSCREEN MOULDING					
	WATER SEEPAGE FOR FRONT WINDSCREEN					
2.3	RHS SIGNAL & HEAD LAMP:					3
	REMOVE & REPLACE RHS SIGNAL LAMP HOUSING					
	REMOVE & REPLACE RHS SIGNAL LAMP					
	REMOVE & REPLACE RHS HEAD LAMP					
	WIRING FOR RHS SIGNAL LAMP & HEAD LAMP					
2.4	LHS SIGNAL LAMP:					2
	REMOVE & REPLACE LHS SIGNAL LAMP HOUSING					
	REMOVE & REPLACE LHS SIGNAL LAMP					
	WIRING FOR LHS SIGNAL LAMP & HEAD LAMP					
2.5	FRONT BUMPER:					5
	REMOVE & REPLACE FRONT BUMPER					
	PUTTY & SPRAY PAINT FOR FRONT COMPLETE BUMPER					
2.6	RADIATOR GRILL & EMBLEM:					1
	REMOVE & REPLACE RADIATOR GRILLE					
	REMOVE & REPLACE 'TOYOTA' EMBLEM					
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				56.5

Registration No. QX 4823M

Registration No. QX 4823M

Vehicle Inspected By

YEANG WAI KEEN
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.