



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



INDIA INTERNATIONAL INSURANCE P/L 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Prasad S/O Gobinathan ADDRESS : 928 YISHUN CENTRAL 1 #02-133 Singapore 760928 TEL : 92341434 rekha	WIP : 16229 EXCESS : DATE: 4-Apr-18
VEH NO :	SGS7786L	DATE IN :	CONTACT PERSON : JESS 6395 7874
CHASSIS NO :	JM6GG10F270534455	MILEAGE : 323694	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA 6 2.0 HB	DATE REG.: 23-Mar-07	POLICY NO. :

Amid 5, 2018

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER / <i>Re</i>	1	MGR1A-50-221ABB \$ 913.30
2	RETAINER(LHS), REAR BUMPER / <i>ABC</i>	1	MGJ6A-50-2J1E \$ 34.90
3	RETAINER(RHS), REAR BUMPER <i>X NN</i>	1	MGJ6A-50-2H1E \$ 34.90
4	REFLECTOR LHS / <i>MS</i>	1	MGJ6A-51-5L0B \$ 33.30
5	REFLECTOR RHS <i>X NN</i>	1	MGJ6A-51-5M0B \$ 34.40
6	REAR REINFORCEMENT ?	1	MGJ6A-50-260C \$ 247.70
7	FASTENER, REAR BUMPER /	4	MGD7A-50-EA1 \$ 12.00
8	GROMMET, REAR BUMPER /	2	MBP4K-50-0Z5 \$ 5.60
9	GROMMET, REAR BUMPER /	4	MBP4K-50-ES1 \$ 17.60
10	GROMMET, REAR BUMPER / <i>ABC.</i>	2	MH260-50-6K8 \$ 6.40
11	PIN LOCATOR, REAR BUMPER /	1	MGK2A-50-1K5A \$ 6.30
12	PIN LOCATOR, REAR BUMPER /	3	MGK2E-50-1K5A \$ 12.00
13	RIVET, REAR BUMPER /	2	MGJ6A-50-0Z1 \$ 6.00
14	SEAL, REAR BUMPER /	1	MGR1A-50-2G2 \$ 16.20
15	SEAL, REAR BUMPER /	1	MGR1A-50-2G1 \$ 16.20
16	PANEL, REAR END / <i>Bul</i>	1	MGJ6J-70-750D \$ 305.60
17	TAILGATE / <i>BT</i>	1	MGKYG-62-02XB \$ 1,129.70
18	VALVE ONEWAY, TAILGATE /	2	MBBN7-58-867 \$ 26.20
19	TAPE PROTECTOR, REAR BUMPER / <i>ABC</i>	4	MG043-62-864A \$ 13.20
20	TRIM LOWER, TAILGATE <i>X</i>	1	MGJ6J-68-960L02 \$ 429.00
21	LOCK, TAILGATE <i>X</i>	1	MG22G-62-310M \$ 300.50
22	MAZDA, EMBLEM /	1	MGJ6A-51-711 \$ 32.40
23	6, EMBLEM /	1	MGJ6A-51-721 \$ 24.10
24	MASCOT, REAR / <i>ABC.</i>	1	MGJ6J-51-730C \$ 41.30
25	MOULD LOWER, REAR WINDSCREEN /	1	MGJ8J-50-614C \$ 49.40
26	MOULD (LHS), REAR WINDSCREEN /	1	MGJ8J-50-613D \$ 47.30
27	MOULD (LHS), REAR WINDSCREEN /	1	MGJ8J-50-612D \$ 47.30
28	PIN STUD, REAR WINDSCREEN /	2	MGJ8J-63-938 \$ 30.20
29	SPACER, REAR WINDSCREEN /	1	MC001-50-897 \$ 4.40
30	CLIP, REAR WINDSCREEN /	6	MGJ8J-50-899 \$ 15.60

31	PROTECTOR, GARNISH TAILGATE /		1	MG14P-50-814		\$ 2.20
32	PROTECTOR, GARNISH TAILGATE /		1	MGJ6A-50-814		\$ 9.60
33	CLIP, GARNISH TAILGATE /		1	MG18K-51-SJ3		\$ 6.10
34	GASKET(LHS), TAILLAMP /		1	MGJ6A-51-163A		\$ 73.90
35	GASKET(RHS), TAILLAMP /		1	MGJ6A-51-153A		\$ 73.90
36	FASTENER, TAILLAMP /		2	MGJ6A-51-14Y		\$ 29.80
37	GASKET(LHS), TAILGATE LAMP /		1	MGJ6A-51-3J8B		\$ 73.90
38	GASKET(RHS), TAILGATE LAMP /		1	MGJ6A-51-3H8B		\$ 73.90
39	LHS TAILGATE LAMP X	NN	1	MGR1A-51-3J0B		\$ 175.30
40	RHS TAILGATE LAMP X	NN	1	MGR1A-51-3H0B		\$ 191.60
41	SILENCER(LHS), EXHAUST /	McC	1	ML3A7-40-200A		\$ 1,093.20
42	SILENCER(RHS), EXHAUST ?		1	ML3A6-40-100A		\$ 1,093.20
43	GASKET, SILENCER /	McC	2	MFSB8-40-305		\$ 35.60
44	PIPE, MIDDLE (EXHAUST) ?		1	ML303-40-600D		\$ 937.40
45	SP, EMBLEM X	NN	1	MGR1A-L3-730		\$ 45.30
TOTAL PARTS						\$ 7,807.90
LESS 10%						\$ 780.79
TOTAL PARTS COST						\$ 7,027.11

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	2640	\$ 3,960.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE.	630	2550 ²	\$ 3,150.00
3	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING		150	\$ 350.00
4	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		150	\$ 250.00
5	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		330	\$ 660.00
6	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS.	/	NETT	\$ 560.00
7	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	/	NETT	\$ 120.00
8	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		330	\$ 660.00
9	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS.		330	\$ 660.00
10	MZ-BR-EXASSY	TO REMOVE & INSTALL REAR EXHAUST ASSY.		330	\$ 660.00
11	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	NN X	NETT	\$ 70.00

12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
14	MZ-BR-TOW-IN	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	✓	NETT \$ 120.00
15	MZ-BR-SUNDRI	SUNDRIES.	10	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 11,920.00
TOTAL PARTS	\$ -	\$ 7,027.11
TOTAL	\$ -	\$ 18,947.11
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:
 THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

 Authorised Signature

8 Days.
 before paint photos.
 Gano @iap
 05/4/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: