

SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



1/122: General View



2/122: General View

3/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)




4/122: General View



5/122: Photographs of Damaged Parts

6/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



7/122: Photographs of Damaged Parts



8/122: Photographs of Damaged Parts

9/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



10/122: Photographs of Damaged Parts



11/122: Photographs of Damaged Parts


12/122: Photographs of Damaged Parts



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



13/122: Photographs of Damaged Parts



Rear door inner lock twisted.

14/122: General View

15/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



16/122: General View




17/122: General View

18/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



19/122: Photographs of Damaged Parts



20/122: Photographs of Damaged Parts

21/122: General View



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



22/122: General View




23/122: General View

24/122: Odometer
Reading



SJJ3789S (SHA3942L1) - Submitted by: VICOM Ltd (HQ)



25/122: Chassis Number



26/122: SJJ3789S_RESURVEY

27/122: SJJ3789S_RESURVEY



Front bumper reinforcement dented

SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



28/122:
SJJ3789S_RESURVEY



29/122:
SJJ3789S_RESURVEY

30/122:
SJJ3789S_RESURVEY



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



31/122:
SJJ3789S_RESURVEY



32/122:
SJJ3789S_RESURVEY

33/122:
SJJ3789S_RESURVEY



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



34/122:
SJJ3789S_RESURVEY



35/122:
SJJ3789S_RESURVEY

36/122:
SJJ3789S_RESURVEY



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



37/122:
SJJ3789S_RESURVEY



38/122:
SJJ3789S_RESURVEY

39/122:
SJJ3789S_RESURVEY



fuel filler
holder cracked
missing study

SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



40/122:
SJJ3789S_RESURVEY



41/122:
SJJ3789S_RESURVEY

42/122:
SJJ3789S_RESURVEY



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



43/122:
SJJ3789S_RESURVEY



44/122:
SJJ3789S_RESURVEY

45/122:
SJJ3789S_RESURVEY



SJJ3789S [SHA3942L] - Submitted by: VICOM Ltd (HQ)



46/122:
SJJ3789S_RESURVEY



47/122:
SJJ3789S_RESURVEY

48/122:
SJJ3789S_RESURVEY