

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)
☐	 11	1			REAR WINDSCREEN SEALANT			Serviceable	0				0
☐	 12	2			TAIL LIGHT UNIT RH & LH ("CHECK \$290.00)				0				0
☐	 13	1			REAR BUMPER			Deformed	290				290
☐	 14	10			REAR BUMPER CLIP			Necassary	2				20
☐	 15	2			REAR BUMPER SIDE RETAINER RH & LH			Necessary	20				40
☐	 16	2			REAR BUMPER REFLECTOR RH & LH ("CHECK \$36.00)				0				0
☐	 17	1			REAR END PANEL			Bent	245				245
☐	 18	1			REAR END PANEL GARNISH			Deformed	50				50
☐	 19	8			REAR END PANEL GARNISH CLIP			Necessary	2.5				20
☐	 20	1			SPARE TYRE BOARD			Cracked	140				140
☐	 21	1			SPARE TYRE WELL / PANEL			Repair	0				0

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR RAR	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------

Detailed Assessment

Inspection Date *

04/06/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

400

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

185/55R15

Rear Tyre Size

185/55R15

FNOL INFORMATI... 148 #13-08, SILAT AVENUE, 160148,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Residential

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Female

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Single

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S1532049D

CATEGORY

Make

POLICY INFORMAT... MITSUBISHI

ASSESSMENT INFO...

MITSUBISHI

CATEGORY

Model

POLICY INFORMAT... ATTRAGE 1.2

ASSESSMENT INFO...

ATTRAGE 1.2 CVT

CATEGORY

Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT... MMBSTA13AHH000343

CATEGORY

Date of Birth

CATEGORY

FNOL INFORMATI... May 13, 1962

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

FNOL INFORMATI... 56

POST SURVEY INF...

CATEGORY

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY

Driving Experience

Accelerated survey
and authorize

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes
- Add

EXCESS 400

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
ANG Yvonne	4/5/18 5:49 PM	3076	3076	Open	Share	Clone

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

Accelerated survey
and authorize

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

Documents

Messages

Invoices

History

EXCESS 400

Assessment

Metrics

Notes

Document SubType

Document Type

Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
SLC 4051T photo.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (OD)	April 20, 2018
SAS2394070 ADDENDUM OD- RO.pdf	Reports & Statement	GIA Report	HIN LUNG WORKSHOP	April 20, 2018
SLC 4051T EST.pdf	Forms / Claim Documents	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (OD)	April 9, 2018