

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18006395/DKA3Q2

Date: 17/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700071219

Claimant
Vehicle No : SLQ8765S **Insured Vehicle No :** SKS791U

Date of Loss: 05/04/2018 Nature of Claim: TP Claim No: 8649053587SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ8765S		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5928542
Reg. Date:	25/07/2017 (Man. Year: 2016)	Chassis No:	RU31228530
Colour:	Silver	Odometer:	73179 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,985.60	4,739.20	5,246.40	52.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,360.00	2,420.00	2,940.00	54.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,345.60	7,159.20	8,186.40	53.35
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	15,345.60	5,700.00	9,645.60	62.86
+ GST 7.00/7.00% (S\$)	1,074.19	399.00	675.19	62.86
Nett Amount (S\$)	16,419.79	6,099.00	10,320.79	62.86
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,466.45		
Global Sum Settlement (S\$)		6,460.00		

INSPECTION

Date of Assignment: 06/04/2018

Date Inspected: 06/04/2018 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,055.00 FL	*1,055.00 FL
2	4		*TAILGATE GLASS MOULDING	Necessary	160.00 FL	*160.00 FL
3	1		*TAILGATE LOGO	Not Necessary	58.00 FL	*- FL
4	1		*TAILGATE EMBLEM -VEZEL	Necessary	48.00 FL	*48.00 FL
5	1		*TAILLAMP N/S	Mounting Cracked	504.00 FL	*504.00 FL
6	1		*TAILLAMP O/S	Not Necessary	504.00 FL	*- FL
7	1		*TAILGATE OUTER GARNISH	Serviceable	225.00 FL	*- FL
8	1		*TAILGATE LOCK	Not Necessary	175.00 FL	*- FL
9	1		*TAILGATE LOCK STRIKER	Repair	55.00 FL	*- FL
10	1		*TAILGATE RUBBER	Deformed	205.00 FL	*205.00 FL
11	2		*TAILGATE DAMPER	Not Necessary	390.00 FL	*- FL
12	1		*TAILGATE INNER TRIM	Mounting Broken	234.00 FL	*234.00 FL
13	1		*TAILGATE WIPER MOTOR	Not Necessary	301.00 FL	*- FL
14	1		*REAR BUMPER	Dented	751.00 FL	*751.00 FL
15	2		*REAR BUMPER SIDE RETAINER	Serviceable	68.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR N/S	Mounting Cracked	89.50 FL	*89.50 FL
17	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	89.50 FL	*- FL
18	1		*REAR EXHAUST SILENCER	Not Necessary	638.00 FL	*- FL
19	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	60.00 FL	*- FL
20	2		*REAR EXHAUST MOUNTING	Not Necessary	70.00 FL	*- FL
21	1		*REAR INNER LAMP N/S	Mounting Cracked	318.00 FL	*318.00 FL
22	1		*REAR INNER LAMP O/S	Not Necessary	318.00 FL	*- FL
23	1		*REAR LH FENDER	Repair	886.00 FL	*- FL
24	1		*REAR LH INNER FENDER	Repair	699.00 FL	*- FL
25	1		*REAR LH FENDER INNER TRIM	Deformed	201.00 FL	*201.00 FL
26	1		*END PANEL	Dented	685.00 FL	*685.00 FL
27	1		*END PANEL TOP GARNISH	Serviceable	165.00 FL	*- FL
28	1		*SPARE TYRE TOP BOARD	Not Necessary	389.00 FL	*- FL
29	1		*FLOOR PANEL COMPARTMENT	Dented	801.00 FL	*801.00 FL
30	1		*SPARE TYRE UNDER COVER	Deformed	155.00 FL	*155.00 FL
31	1		*REAR CORNER BUMPER	N/s Cut/O/s Not Necessary	310.00 FL	*155.00 FL
32	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
33	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	50.00 FS	*20.00 FS
34	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	40.00 FS	*20.00 FS
35	1		*SET REAR REVERSE SENSOR	Damaged	400.00 FS	*220.00 FS
36	1		*REVERSE CAMERA	Not Necessary	500.00 FS	*- FS
37	1		*JOINT SEALANT	Necessary	150.00 FS	*40.00 FS
38	1		*WINDSCREEN SEALANT	Necessary	150.00 FS	*40.00 FS
39	1		*FLOOR INSULATOR	Necessary	150.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 12,107.00 5,811.50
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,121.40 1,072.30

Total Parts (\$\$) 9,985.60 4,739.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND REFIT REAR LINING,TRIM AND GARNISH	New	200.00	120.00
3	REMOVE AND RENEW REAR REVERSE SENSOR	New	150.00	40.00
4	REMOVE AND RENEW REAR EXHAUST ASSY	New	150.00	60.00
5	REMOVE AND REFIT FUEL TANK	New	150.00	0.00
6	REMOVE AND RENEW FLOOR INSULATOR	New	150.00	50.00
7	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
8	TRANSFER PARTS,ATTACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
9	PANEL BEATING ON AFFECTED AREAS	New	2,200.00	1,000.00
10	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	900.00
11	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	40.00
Gross Labour Cost (S\$)			5,360.00	2,420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >