



Pte Ltd

TeamWork Garage Pte Ltd
53 Ubi Avenue 1 #01-23/24 Spore 408934
Paya Ubi Industrial Park
Tel : 6844 2475
E-mail : claims@teamworkgarage.com
ROC: 201015366H

3RD PARTY CLAIM ESTIMATION

AIG Building
78 Shenton Way #07-16
Singapore 079120

Vehicle number	SLQ8765S
Make / Model	HONDA/VEZEL 1.5X
Chassis number	RU31228530
Accident date	05 April 2018
Reference	1804-07

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS			
1	TAILGATE <i>Dented</i>	1055.00	✓
4	TAILGATE GLASS MOULDING <i>Nec</i>	160.00	✓
1	TAILGATE LOGO <i>NH</i>	58.00	X
1	TAILGATE EMBLEM -VEZEL <i>Nec</i>	48.00	✓
2	TAILLAMP <i>N/S mounting crack o/s NH</i>	1008.00	✓
1	TAILGATE OUTER GARNISH <i>SVC</i>	225.00	X
1	TAILGATE LOCK <i>NH</i>	175.00	X
1	TAILGATE LOCK STRIKER <i>req</i>	55.00	X
1	TAILGATE RUBBER <i>damaged</i>	205.00	✓
2	TAILGATE DAMPER <i>NH</i>	390.00	X
1	TAILGATE INNER TRIM <i>mounting broken</i>	234.00	✓
1	TAILGATE WIPER MOTOR <i>NH</i>	301.00	X
1	REAR BUMPER <i>Dented</i>	751.00	✓
2	REAR BUMPER SIDE RETAINER <i>SVC</i>	68.00	X
2	REAR BUMPER REFLECTOR <i>N/S mounting crack o/s NH</i>	179.00	✓
1	REAR EXHAUST SILENCER <i>NH</i>	638.00	X
1	REAR EXHAUST HEAT SHIELD <i>NH</i>	60.00	X
2	REAR EXHAUST MOUNTING <i>NH</i>	70.00	X
2	REAR INNER LAMP <i>N/S mounting crack o/s NH</i>	636.00	✓
1	REAR LH FENDER <i>req</i>	886.00	X
1	REAR LH INNER FENDER <i>req</i>	699.00	X
1	REAR LH FENDER INNER TRIM <i>damaged</i>	201.00	✓
1	END PANEL <i>Dented</i>	685.00	✓
1	END PANEL TOP GARNISH <i>SVC</i>	165.00	X
1	SPARE TYRE TOP BOARD <i>NH</i>	389.00	X
1	FLOOR PANEL COMPARTMENT <i>Dented</i>	801.00	✓
1	SPARE TYRE UNDER COVER <i>damaged</i>	155.00	✓
2	REAR CORNER BUMPER <i>N/S cut o/s NH</i>	310.00	✓
		10607.00	
Less 20 %		2121.40	
Subtotal		8485.60	

5361.50
4289.20

504.00

89.50

318.00

155.00

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	8485.60
1 SET	REAR BUMPER CLIP <i>Hec</i>	60.00 30/-
1 SET	REAR FENDER INNER TRIM CLIP <i>Hec</i>	50.00 20/-
1 SET	REAR TAILGATE INNER TRIM CLIP <i>Hec</i>	40.00 20/-
1 SET	REAR REVERSE SENSOR <i>Dam</i>	400.00 220/-
1	REVERSE CAMERA <i>Hd</i>	500.00 X
1	JOINT SEALANT <i>Nec</i>	150.00 40/-
1	WINDSCREEN SEALANT <i>Hec</i>	150.00 40/-
1	FLOOR INSULATOR <i>Hec</i>	150.00 80/-
	Subtotal	1500.00
	Balance C/F	9985.60
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
	Balance B/F	9985.60
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 30/-
2	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 120/-
3	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
4	REMOVE AND RENEW REAR EXHAUST ASSY	150.00 60/-
5	REMOVE AND REFIT FUEL TANK	150.00 44
6	REMOVE AND RENEW FLOOR INSULATOR	150.00 50/-
7	REMOVE AND REFIT REAR WINDSCREEN	150.00 120/-
8	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00 60/-
9	PANEL BEATING ON AFFECTED AREAS	2200.00 1000/-
10	SPRAY PAINTING ON AFFECTED AREAS	1800.00 900/-
11	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	5360.00
	Grand total	15345.60

06/04/2018 @ 1300hrs

Not Antimal

2/sun 6 days.

7159.20

1/s 5700/-

P
yan

LKK Auto

[Signature]

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--