

INS. CASE OWNER:

CC 4 / ASM1800

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(S x days) 114.49

Loss of Use (LOU):

S\$

(S x days)

Loss of Income (LOI):

S\$

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

4,958.43

Global Sum S\$:

4950.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

4950.00

Name 1:

SMART TAXI PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

LIS - \$ 4150.00 (Red: \$ 6500+ [60%])

Date/Time. File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation.

) \$ + RS. \$

: Photos

: Others

TOTAL

Veh No.

SHB 375M

Yr Regn:

6/11/2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

C.C.

1798

Colour

Maroon

A/C: Insured / Std / NI / NA

Sp. Reading

367985

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKN 364 60575217

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fallon

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

3/4/13

D.O.I.

6/4/13

Survey held at

SMRT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt, O/S

The U/C / Chassis frame / Body Structure affected due to collision.

TAX / 04 / 18 / 2014

Lick

AVA

SLX3588H



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/ASM18006405/Swa3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 06-04-2018	
			Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 3588H	Veh. Inspected	SHB 375M	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00CWV	Excess (\$)	0.00	
Assign From		Assign Date	06/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	03/04/2018	Inspection Date	06/04/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

SMRT Accident Vehicle Repair Estimates

AxA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB375M
 Ref. No : TAX/04/18/2014
 Reg. Date : 06/11/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : YEO BOK HUA(YANG MUHUA)
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 03/04/2018 11:35:00 PM
 Accident Reported Date / Time : 04/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095355
 Special Instruction to ARC,if any :
 TOWED \$40 / SLX3588H
 Prepared Date : 04/04/2018 11:25:28 AM



Sebastian
 6/4/18

- Lump Sum Repair
- Question Mark Item
- Photo
- Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

13/4
13-4-18/10:46
13-4-18/14:46

Reg. No : SHB375M
Ref. No : TAX/04/18/2014
Reg. Date : 06/11/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : YEO BOK HUA (YANG MUHUA)
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 03/04/2018 11:35:00 PM
Accident Reported Date / Time : 04/04/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No Yes
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095355
Special Instruction to ARC, if any :
TOWED \$40 / SLX3588H - AXA
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang@lkkauto.com HP: 90036121
LUMP SUM REPAIR
Prepared Date : 04/04/2018 11:25:28 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date 6-4-18

2nd witness

Date

QC 13/4/18 12.12.2018
Frt Bumper Reinforcement
wiper so what they re

RAR Lens & Body NO Lig Mt

171 18 P953

Vehicle Return Date:

13-4-2018

Vehicle Return Time:

10:36 am

SMRT staff sign:

[Signature]

367987

1 1 1 1
1/4 1/2 3/4 1

Supplementary

368055

to the supplementary part 1812

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605752617

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,352.00	800.00
Total Spray Painting Charges :	2,034.00	650.00
Total Material Charges :	6,252.22	2,772.16
Other Charges :	1,220.00	110.00
TOTAL :	10,858.22	4,332.16
Lum Sum Total :	10,850.00	4,350.00
No. of Repair Days :	8.00	6.00
Prepared / Adjusted By :		SEBASTIAN(LKK)
Arc / Surveyor Sign Off Date :	04/04/2018 01:50:15 PM	06/04/2018 02:46:41 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 01:50:15 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0372

Invoice No :

Quotation Date : 17/4

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,352.00	800.00 /
Total Labour	1,352.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	200.00 /
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 /
TO RESPRAY FRONT FENDER RH	378.00	200.00 /
TO RESPRAY APRON PANEL RH	180.00	0.00 /
TO RESPRAY RIM	180.00	0.00 /
TO REPSRAY FRONT BUMPER	378.00	200.00 /
TO RESPRAY FRONT SUPPORT PANEL	180.00	50.00 /
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00 /
Total Spray Painting & Panel Beating	2,034.00	650.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	40.00 /
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40.00 /
TO TRANSFER DOOR MECHANISM	120.00	0.00 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 /
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 /
TO REMOVE AND REFIT TYRE	120.00	0.00 /
TO TOP UP A/C GAS	120.00	0.00 /
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00 /
TO WASH AND VACUUM	60.00	0.00 /
Total Other Costs	1,220.00	110.00

4606

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace	No <i>✓</i>
75851-47900			MOULDING BODY, RH	0	673.60	25.00	0.00	Replace	Not given	No <i>X</i>
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.38	Replace	Check	No <i>X</i>
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.58	Replace	Check	No <i>X</i>
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.73	Replace	Check	No <i>X</i>
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No <i>✓</i>
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No <i>✓</i>
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Check	No <i>X</i>
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace	No <i>✓</i>
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace	No <i>✓</i>
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	0	1,484.20	25.00	0.00	Replace	Not given	No <i>X</i>
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No <i>X</i>
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>✓</i>
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Check	No <i>X</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>S</i>	No <i>✓</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>S</i>	No <i>✓</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Check	No <i>X</i>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Check	No <i>X</i>
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No <i>X</i>
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No <i>✓</i>
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Check	No <i>X</i>
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Check	No <i>X</i>
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Check	No <i>X</i>
76851-47020		6505616	BUMPER LIP FRT	0	139.60	25.00	0.00	Replace	Not given	No <i>X</i>
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78	Replace	Check	No <i>X</i>
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Check	No <i>X</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.33	Replace	Check	No <i>X</i>
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.23	Replace	Replace	No <i>✓</i>

8648.44

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.23	Replace	Check	No ☒
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.93	Replace	Check	No ☒
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace	No ☒
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Check	No ☒
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Check	No ☒
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Check	No ☒
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No ☒
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No ☒
			NUMBER PLATE	0	15.00	0.00	0.00	Replace	Not given	No ☒
			NUMBER PLATE FRAME	0	12.00	0.00	0.00	Replace	Not given	No ☒
TOTAL MATERIALS					4710.30		7,815.30	3,465.21		
TOTAL MATERIALS(Discounted)							6,252.22	2,772.16		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3465.21
 - 20.7
 2772.16
 + 800.00
 + 760.00
 4332.16
 US \$4350/-

2964.74

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605752617

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,352.00	0.00
Total Spray Painting Charges	: 2,034.00	0.00
Total Material Charges	: 8,299.86	8,299.86
Other Charges	: 1,220.00	0.00
TOTAL	: 12,905.86	0.00
Lum Sum Total	: 12,900.00	0.00
No. of Repair Days	: 8.00	0.00
Prepared / Adjusted By	:	6 days
Arc / Surveyor Sign Off Date	: 04/04/2018 01:50:15 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/04/2018 01:50:15 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,352.00	0.00 800
Total Labour	1,352.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY APRON PANEL RH	180.00	0.00 ?
TO RESPRAY RIM	180.00	0.00 X
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 50
TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	0.00 X
Total Spray Painting & Panel Beating	2,034.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 40
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO TOP UP A/C GAS	120.00	0.00 ?
TO CONDUCT RADIATOR PRESSURE CHECK	100.00	0.00 ?
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,220.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace R	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace ✓ NIS	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace X	No
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.37	Replace	Replace ?	No
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.57	Replace	Replace ?	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace ?	No
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace ✓ Deform	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ NIS	No
53701-47050			FENDER APRON SUB FRT/RH	1	637.80	25.00	478.35	Replace	Replace ?	No
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace ✓ MS	No
53851-47040			FENDER LINER PAD, FR WHEEL, RH	1	49.30	25.00	36.97	Replace	Replace ✓ MS	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace X	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace ✓	No
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace ?	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ?	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace ✓ SCR	No
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace ?	No
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace ?	No
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Replace ?	No
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace ✓	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace ?	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ?	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace ?	No
57104-47020		6505507	RADIATOR LOWER SUPPORT	1	876.30	25.00	657.22	Replace	Replace ?	No
88710-47150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace	Replace ?	No
85315-47140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace ?	No
85330-47010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace ?	No
85330-60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace ?	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace ✓	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ✓	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace ✓	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace X	No
TOTAL MATERIALS							10,362.89	10,362.83		
TOTAL MATERIALS(Discounted)							8,299.86	8,299.86		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

PAGE 1

R	?	X	
800.00		552.00	
800.00	-	552.00	1,352.00
200.00	180.00	178.00	
200.00		180.00	
200.00		178.00	
50.00		180.00	
		178.00	
		130.00	
		180.00	
650.00	180.00	1,204.00	2,034.00
80.00	120.00	50.00	
30.00	100.00	160.00	
40.00		120.00	
		120.00	
		120.00	
		120.00	
		100.00	
		60.00	
150.00	220.00	850.00	1,220.00

PAGE 2

R	?	X	
60.00	60.37	670.80	
542.55	67.57	505.20	
38.92	112.72	1,113.15	
128.77	478.35	126.74	
36.97	57.30	104.70	
361.50	57.30	15.00	
460.62	373.80	12.00	
135.07	59.10		
850.68	187.80		
82.80	187.80		
	19.50		
	18.30		
	43.65		
	95.77		
	70.95		
	233.32		
	336.22		
	657.22		
	473.92		
	215.10		
	216.00		
	1,095.30		
2,697.88	5,117.36	2,547.59	10,362.83
80.00	80.00	80.00	80.00
2,158.30	4,093.89	2,038.07	8,290.26

R	?	X	T
800.00	-	552.00	1,352.00
650.00	180.00	1,204.00	2,034.00
150.00	220.00	850.00	1,220.00
2,158.30	4,093.89	2,038.07	8,290.26
3,758.30	4,493.89	4,644.07	12,896.26

16/4/1010



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: S8M00CWV
Our ref: CC4/ASM18006405/Swa3

Date: 09.04.2018

The Motor Claims Department
M/s AXA INSURANCE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHB 375M

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 06.04.2018 at the premises of M/s SMRT Automotive Services Pte Ltd (Woodlands) and have the following to report:-

Workshop Estimate Amount	: S\$	12,905.86
Revised Estimate Amount	: S\$	3,758.32
"Check" Items Amount	: S\$	4,493.92
Total (Including Check Items)	: S\$	8,252.24

Market Value	: S\$	-	(est.)
LTA Reimbursement Value	: S\$	-	(est.)
Nett Value	: S\$	-	(est.)

Description of Damage:

The vehicle sustained damages at the
O/S front portion & O/S



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6.0 days

Yours faithfully,

SEBASTIAN YEANG
Licensed Appraiser



Service Request Details

Claim

S8M00CWV

Reference

None 

Sebastian

Loss Date

April 3, 2018

Request Date

April 5, 2018

Due Date

April 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SHB375M

Make

TPVD TOYOTA

Service Address

...

Primary Contact/Insured

THIO SHEN YI

69A CORONATION ROAD, 269467, Singapore

62169466

SHENYI.THIO@TSMP.COM.SG

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



RE: Claim Status

Type

🔔 Question

Message

Dear Jas, We refer to our tele-conversation this morning. TP repairer refused to accept for LOR 6 days and insisted for 7 days. Please refer to the mileage record uploaded. We re-seek your approval as follow. COR \$4150.00 LOR \$ 801.43 (\$114.49 x 7 days) LTA \$ 7.00 \$4958.43 ===== Thank you. Mkwana

Reply



Re:RE: Claim Status

Type

🔗 Question

Message

please proceed

Reply



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 4883
www.police.gov.sg

Our Ref : TP/IP/23625/2018
Date : 10 JULY 2018

YEO BOK HUA
BLK 484B CHOA CHU KANG AVENUE 5
#05-42
SINGAPORE 682484

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING SLX 3588 H AND SHB 375 M ALONG EAST COAST
PARKWAY ON 03/04/2018 AT ABOUT 11.35PM**

I refer to the above accident.

Please be informed that we have completed our investigations which revealed that the driver of SLX 3588 H had committed an offence of **Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276**. Action has been initiated against the driver for the said offence.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLX 3588H (Insd veh)	Model:	TOYOTA PRIUS
	SHB 375M (TP veh)		
Date of Accident:	03/04/2018		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	17,964.74
Final Repair Cost	:	\$	4,150.00
Loss of Token Sum	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	801.43 7 days
LTA / GIA Search Fee	:	\$	7.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum (GLOBAL SUM)	:	\$	4,950.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 4,950.00

NUR SHAQILAH BTE ABDOL
WAHAB

13/12/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18006405/K1wa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 13-12-2018	
ATTN: JAS TAN		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLX 3588H	Veh. Inspected	SHB 375M
Policy No.	CN884299	Coverage (\$)	0.00
Claim No.	S8M00CWV	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	05/04/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U605752617	Colour	MAROON
Odometer	367985	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65R15	FALKEN	6 mm
L/H Front Tyre	195/65R15	FALKEN	6 mm
R/H Rear Tyre	195/65R15	FALKEN	6 mm
L/H Rear Tyre	195/65R15	FALKEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	03/04/2018	Inspection Date	06/04/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 375M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FENDER FRT/RH (DISC 25%) (CONSISTENT)	DEFORMED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%) (CONSISTENT)	NECESSARY	51.90	38.92
1	FENDER LINER FRT/RH (DISC 25%) (CONSISTENT)	MISSING	171.70	128.77
1	FENDER LINER PAD, FR WHEEL. RH (DISC 25%) (CONSISTENT)	MISSING	49.30	36.97
1	BUMPER FRT (DISC 25%) (CONSISTENT)	CRACKED	482.00	361.50
1	BUMPER SUPPORT F/RH (DISC 25%) (CONSISTENT)	CRACKED	76.40	57.30
1	BUMPER REINFORCEMENT FRT (DISC 25%) (CONSISTENT)	BENT	498.40	373.80
1	UNDER COVER CENTER (DISC 25%) (CONSISTENT)	CRACKED	448.30	336.23
1	WIPER WASHER JAR (DISC 25%) (CONSISTENT)	CRACKED	180.10	135.07
1	BRACKET, FR BUMPER (DISC 25%) (CONSISTENT)	CRACKED	110.40	82.80
1	LENS & BODY, FR TURN RH (DISC 10%) (CONSISTENT)	CRACKED	511.80	460.62
1	HEAD LAMP RH (DISC 10%) (CONSISTENT)	CRACKED	945.20	850.68
1	STICKER DECAL SMRT (DOOR) (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	BUMPER ENERGY ABSORBER FRT (CONSISTENT)	SERVICEABLE	78.80	-
1	ARM SUB-ASSY, FR BUMPER LH (CONSISTENT)	SERVICEABLE	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH (CONSISTENT)	SERVICEABLE	250.40	-
1	BRACKET, FR TURN LOWER RH (CONSISTENT)	SERVICEABLE	26.00	-
1	BRACKET, FR TURN UPPER RH (CONSISTENT)	SERVICEABLE	24.40	-
1	BRACKET, FR TURN (CONSISTENT)	SERVICEABLE	58.20	-
1	BUMPER LIP FRT (CONSISTENT)	SERVICEABLE	139.60	-
1	BUMPER FRT ABSORBER LOWER (CONSISTENT)	SERVICEABLE	127.70	-
1	GRILLE RADIATOR LOWER NO.2 (CONSISTENT)	SERVICEABLE	94.60	-
1	BUMPER GRILLE SUB-ASSY, LOWER (CONSISTENT)	SERVICEABLE	311.10	-
1	RADIATOR LOWER SUPPORT (CONSISTENT)	SERVICEABLE	876.30	-
1	TUBE & ACCESSORY (CONSISTENT)	SERVICEABLE	631.90	-
1	MOTOR NO.1, WIPER WASHER JAR (CONSISTENT)	SERVICEABLE	239.00	-
1	MOTOR NO.2, WIPER WASHER JAR (CONSISTENT)	SERVICEABLE	240.00	-
1	SUPPORT SUB-ASSY (CONSISTENT)	SERVICEABLE	1,460.40	-
1	NUMBER PLATE (CONSISTENT)	SERVICEABLE	15.00	-

Report Ref No. CC4/ASM18006405/K1wa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NUMBER PLATE FRAME (CONSISTENT)	SERVICEABLE	12.00	-
1	MOULDING BODY, RH (CONSISTENT)	NOT NECESSARY	673.60	-
1	HINGE UPPER RHF, DOOR (CONSISTENT)	NOT NECESSARY	80.50	-
1	HINGE LOWER RHF, DOOR (CONSISTENT)	NOT NECESSARY	90.10	-
1	CHECK ASSY, FR DOOR (CONSISTENT)	NOT NECESSARY	150.30	-
1	FENDER APRON SUB FRT/RH (CONSISTENT)	NOT NECESSARY	637.80	-
1	WHEEL DISC, FRONT (CONSISTENT)	NOT NECESSARY	1,484.20	-
1	TYRE (CONSISTENT)	NOT NECESSARY	126.74	-
1	BUMPER SUPPORT F/LH (CONSISTENT)	NOT NECESSARY	76.40	-
1	DOOR FRT/RH (CONSISTENT)	TO REPAIR SEE LABOUR	894.40	-
			13,358.74	3,465.21
	LABOUR			
	PANEL BEATING & BODYWORK. INCLUSIVE OF THE REPAIR OF DOOR FRT/RH.		1,352.00	800.00
	SPRAY PAINT.		2,034.00	650.00
	TOWING CHARGE.		80.00	40.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	40.00
	TO TRANSFER DOOR MECHANISM.	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIT TYRE.	NOT NECESSARY	120.00	-
	TO TOP UP A/C GAS.	NOT NECESSARY	120.00	-
	TO CONDUCT RADIATOR PRESSURE CHECK.	NOT NECESSARY	100.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			-	-
			-	-
			-	-
			4,606.00	1,560.00
	GRAND TOTAL		17,964.74	5,025.21

Report Ref No. CC4/ASM18006405/K1wa3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,150.00
---	--	--	----------

Report Ref No. CC4/ASM18006405/K1wa3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.