

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18006419/KVD3E2
Date: 07/06/2018

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : JRA355 **Insured Vehicle No :** SCP4444G
 Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: DMPC1800123H/DL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JRA355**
 Make & Model: MERCEDES-BENZ E300, 3.0 W212 (A) Engine No: 05192432704118
 Reg. Date: 13/08/2016 (Man. Year: 2016) Chassis No: WDD212098GL062021
 Colour: Metallic Silver Odometer: 43971 km
 Engine Capacity: 2143 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18 Rear Tyre Size: 245/40Z R18
 Front Left Side: Michelin 5 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 5 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,541.90	6,205.50	4,336.40	41.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,650.00	1,270.00	2,380.00	65.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	14,191.90	7,475.50	6,716.40	47.33
+ GST 7.00/7.00% (\$\$)	993.43	523.29	470.14	47.32
Nett Amount (\$\$)	15,185.33	7,998.79	7,186.54	47.33

INSPECTION

Date of Assignment: 06/04/2018
 Date Inspected: 10/04/2018 Inspected At: BH Auto Services Pte Ltd (Sin Ming)
 Estimated Period of Repair: 4.0 days Blk 1 Sin Ming Industrial Estate Sector C,
 Singapore 575636

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jun 2018)

Parts: 143 MERCEDES-BENZ E300 3.0 W212 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: LKK Auto Consultants Pte Ltd/JRA355/07/06/2018 07:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Cracked	1,940.00 FL	*1,940.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	35.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	35.00 FL	*- FL
4	1		*REAR BUMPER CENTRE BRACKET	Cracked	184.00 FL	*184.00 FL
5	1		*REAR BUMPER LOWER BRACKET	Repair	107.00 FL	*- FL
6	1		*REAR BUMPER LOWER GARNISH	Dented	300.00 FL	*300.00 FL
7	1		*REAR BUMPER LOWER LINING CHROME	Serviceable	320.00 FL	*- FL
8	1		*REAR BUMPER TOW COVER	Dented	70.00 FL	*70.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	835.00 FL	*835.00 FL
10	1		*REAR BUMPER SENSOR (6 pcs)	Malfunction-2PCS ONLY	1,110.00 FL	*370.00 FL
11	6		*REAR BUMPER SENSOR RING	Not Necessary	84.00 FL	*- FL
12	1		*REAR END PANEL	Repair	1,300.00 FL	*- FL
13	1		*REAR END PANEL TOP GARNISH	Serviceable	135.00 FL	*- FL
14	1		*REAR TAIL LAMP ASSY RH	Serviceable	740.00 FL	*- FL
15	1		*BOOTLID	Bent	2,860.00 FL	*2,860.00 FL
16	1		*BOOTLID EMBLEM	Necessary	50.00 FL	*50.00 FL
17	1		*BOOTLID LETTERING E300	Necessary	86.00 FL	*86.00 FL
18	1		*BOOTLID LETTERING BLUETEC	Necessary	100.00 FL	*100.00 FL
19	1		*BOOTLID LETTERING CYCLE & CARRIGE	Necessary	100.00 FL	*100.00 FL
20	1		*BOOTLID FINISHER CHROME PLATE	Serviceable	105.00 FL	*- FL
21	1		*SPARE TYRE PANEL	Serviceable	595.00 FL	*- FL
22	1		*SPARE TYRE COVER BOARD	Serviceable	400.00 FL	*- FL
23	1		*REAR NUMBER PLATE WITH CASING	Serviceable	100.00 FS	*- FS
24	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,691.00	6,895.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,149.10	689.50
Total Parts (\$\$)	10,541.90	6,205.50

LKK Auto Consultants Pte Ltd/JRA355/07/06/2018 07:59. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING	New	160.00	30.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	New	1,800.00	500.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	New	1,200.00	600.00
4	PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	New	60.00	20.00
5	REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING AND OR UPHOLSTERY TO FACILITATE REPAIRS	New	150.00	0.00
6	DISMANTLE AND TRANSFER BOOTLID FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR	New	80.00	60.00
7	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE BUMPER SENSORS	New	80.00	60.00
8	REMOVE AND REFIT EXHAUST PIPE / SYSTEM TO FACILITATE REPAIR	New	120.00	0.00
Gross Labour Cost (\$\$)			3,650.00	1,270.00

LKK Auto Consultants Pte Ltd/JRA355/07/06/2018 07:59. Not valid without Reference section.

< END OF ESTIMATES >