

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0209/18

DATE : 02-APR-2018

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET

#04-05 IOB BUILDING

S(049711)

TEL : 63476100

FAX : 62244174

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR YIN CHENGYAN

ADDRESS : BLK 553 PASIR RIS STREET 51

#10-105

S(510553)

TELEPHONE NO : 83686436

TYPE OF CLAIM : THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SLE5353E

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2277526A

CHASSIS NO : SJNFEAJ11U1659805

MILEAGE : 38469 KM

DATE IN : 02/04/2018

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 30/03/2018

- 96450079

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLE5353E

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOUR CHARGES TO REPAIR LH FRONT DOOR, RENEW LH FRONT DOOR MIRROR AND LH FRONT FENDER.	450.00	
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME.	700.00	
	TOTAL LABOUR CHARGES	1150.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLE5353E

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			60.00	
2	L/F DOOR MIRROR CASING	96374-4EABE	105.70			
3	L/F DOOR MIRROR	96302-4EA6E	644.80			
4	L/F FENDER ARC MLDG	63811-4EA0A	463.00			
5	FENDER-FRONT LH	F3101-4EAMB	622.70			
SUB TOTAL			1856.20	0.00	60.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-1.00%)			371.24	0.00	0.00	
GRAND TOTAL			1484.96	0.00	60.00	
OVERALL TOTAL			1544.96			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLE5353E

TOTAL LABOUR CHARGES	1150.00
TOTAL SPARE PARTS CHARGES	1544.96

GRAND TOTAL	2694.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.