



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 6082U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER (CONSISTENT)	CRACKED	497.50	497.50
10	REAR BUMPER CLIP (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR BUMPER SIDE RETAINER LH (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER SIDE RETAINER RH (CONSISTENT)	SERVICEABLE	112.70	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	398.90	-
1	REAR BUMPER LOWER GARNISH CENTRE (CONSISTENT)	SERVICEABLE	582.60	-
1	REAR BUMPER LOWER GARNISH RH (CONSISTENT)	TO REPAIR SEE LABOUR	149.70	-
1	REAR BUMPER TOW COVER (CONSISTENT)	SERVICEABLE	31.70	-
1	REAR BUMPER UNDER COVER (CONSISTENT)	SERVICEABLE	355.20	-
4	REAR BUMPER UNDER COVER CLIP (CONSISTENT)	NOT NECESSARY	14.00	-
1	TAIL END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	596.60	-
1	TAIL END PANEL GARNISH (CONSISTENT)	SERVICEABLE	151.60	-
8	TAIL END PANEL GARNISH CLIP (CONSISTENT)	NOT NECESSARY	24.00	-
1	TAIL LAMP RH -UPPER (CONSISTENT)	CRACKED	498.75	498.75
1	TAIL LAMP RH -LOWER (CONSISTENT)	CRACKED	533.60	533.60
	LESS 25% DISCOUNT		-1,024.89	-392.46
			3,074.66	1,177.39
	<b><u>LABOUR</u></b>			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA .(REAR BUMPER ,END PANEL ,RH REAR FENDER).INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT ,REAR BUMPER LOWER GARNISH RH AND TAIL END PANEL .		1,000.00	200.00
	TO PUTTY ,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA .(REAR BUMPER ,END PANEL ,RH REAR FENDER).		1,000.00	220.00
	TO CHECK WIRING .		50.00	20.00
	TO REMOVE & REFIT REVERSE SENSOR TO ASSIST WORK LOAD.		120.00	50.00
	TO TUFF COAT.	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM18006526/Kga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT SPARE TYRE ,SPARE TYRE BOARD ,CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
			2,420.00	490.00
GRAND TOTAL			5,494.66	1,667.39
RECOMMENDED COST OF REPAIRS				1,667.39

Report Ref No. CC4/ASM18006526/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.