



FBE 7938Z




FBE 7938Z




















FBE 7938Z



















































Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Company
Owner ID: 7051N

Vehicle Details

Vehicle No.: FBE7938Z
Vehicle to be Exported: No
Intended De-registration Date: 10 Apr 2018
Vehicle Make: SYM
Vehicle Model: GTS200
Primary Colour: Black
Manufacturing Year: 2010
Engine No.: KB604818
Chassis No.: RFGLM18WXAS001232
Maximum Power Output: -
Open Market Value: \$2,409.00
Original Registration Date: 23 Sep 2010
First Registration Date: 23 Sep 2010
Transfer Count: 0
Actual ARF Paid: \$362.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 22 Sep 2020
COE Category: D - Motorcycle
COE Period(Years): 10
QP Paid: \$1,452.00
COE Rebate Amount: \$374.00
Total Rebate Amount: \$374.00

The information contained herein is correct as at 10 Apr 2018.

OK

AXA INSURANCE PTE LTD
8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel: (65) 63387288 Fax: (65) 63382522
Website: www.axa.com.sg
GST Registration Number: 199903512M
customer.service@axa.com.sg



DUPLICATE COPY

CERTIFICATE OF INSURANCE

*Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) *Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 *Road Transport Act, 1987 (Malaysia) *Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VME/P1444651 Account No. : 03375
Coverage : Third Party Fire & Theft Only
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : GE CHEMICALS PTE LTD
Vehicle Registration No. : FBE7938Z
Period of Insurance : From 04/12/2017 To 03/12/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any other person provided he is in the Policyholder's employ and is driving on their order or with their permission

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

- (a) Use only for the Policyholder's business or profession
- (b) Use for social, domestic, and pleasure purposes by the Policyholder

The Policy does not cover use for the carriage of passengers for hire or reward, racing, pace-making, reliability trial or speed testing

(13)

Fire&Theft - Within Singapore : SGD 300.00

THEFT OUTSIDE SINGAPORE : SGD 600.00

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGRAN01 on 29/11/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

ANDA INSURANCE AGENCIES PTE LTD
(MOTOR DEPARTMENT)
190 MacPherson Road
#03-01 Wisma Gulab
Singapore 348548
Tel: 6554 2288 Fax: 6453 4466
Email: thomson@anda.com.sg

WARRANTED ALL
ACCIDENT REPAIRS
MUST BE CARRIED
OUT ONLY AT OUR
AUTHORISED
WORKSHOPS

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Mar 2018		10 Apr 2018 09:48 Edit Adj Rpt	S\$5,100.00 Edit Estimates	S\$5,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CWT INTEGRATED PTE. LTD. , Co. Reg. No.: NA									
Main Claimant: GB CHEMICALS PTE LTD , Co. Reg. No.: 199607051N									
Vehicle Reg. No.: FBE7938Z		Date of Loss: 16/03/2018 20:00 - :59 [89 Months and 21 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 553118		Policy/Cover Note No.: B28718557MKF (Third Party Only) Coverage: 01/04/2017 - 31/03/2018							
Vehicle Reg. No. (Insured): XB9083G		Policy No. (Claimant):							
		Excess:							
Repairer: Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road, 368182 Macpherson - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 11/04/2018]									
Driver/Custodian (Insured): KUEH CHOONG HON, STEVEN () , NRIC: S8212512D, Tel: +6596247067									
Adj Asg. Remarks: Please contact Jacky Siah (tel: 8380 2233).									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (18/06/2018): < No subject >									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBE7938Z (553118)
[XB9083G]
TP
GB CHEMICALS PTE LTD
Mar 16 2018 8:00PM
[CWT INTEGRATED PTE. LTD.]
Ong Motor Trading

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		☒	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)				Thumbnail		Print	
1	09/04/18 10:23	Accident Statement From: SC - Reg. No: XB9083G, Claimant: CWT INTEGRATED PTE. LTD.				 Load HTML		☐	
Photos/Images						3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail		Print	
1	18/04/18 11:37	General View				 Load JPG		☒	
2	18/04/18 11:37	General View				 Load JPG		☒	
3	18/04/18 11:37	General View				 Load JPG		☒	
4	18/04/18 11:37	General View				 Load JPG		☒	
5	18/04/18 11:37	General View				 Load JPG		☒	
6	18/04/18 11:37	General View				 Load JPG		☒	
7	18/04/18 11:37	General View				 Load JPG		☒	
8	18/04/18 11:37	General View				 Load JPG		☒	
9	18/04/18 11:37	General View				 Load JPG		☒	
10	18/04/18 11:37	General View				 Load JPG		☒	
11	18/04/18 11:37	General View				 Load JPG		☒	
12	18/04/18 11:37	General View				 Load JPG		☒	
13	18/04/18 11:37	General View				 Load JPG		☒	
14	18/04/18 11:37	General View				 Load JPG		☒	
15	18/04/18 11:37	General View				 Load JPG		☒	
16	18/04/18 11:37	General View				 Load JPG		☒	
17	18/04/18 11:37	General View				 Load JPG		☒	
18	18/04/18 11:37	General View				 Load JPG		☒	
19	18/04/18 11:37	General View				 Load JPG		☒	
20	18/04/18 11:37	General View				 Load JPG		☒	
21	18/04/18 11:37	General View				 Load JPG		☒	
22	18/04/18 11:37	General View				 Load JPG		☒	
23	18/04/18 11:37	General View				 Load JPG		☒	
24	18/04/18 11:37	General View				 Load JPG		☒	
25	18/04/18 11:37	General View				 Load JPG		☒	
26	18/04/18 11:37	General View				 Load JPG		☒	
27	18/04/18 11:37	General View				 Load JPG		☒	
28	18/04/18 11:37	General View				Load JPG		☒	
29	18/04/18 11:37	General View				Load JPG		☒	
30	18/04/18 11:37	General View				Load JPG		☒	
31	18/04/18 11:37	General View				Load JPG		☒	
32	18/04/18 11:37	General View				Load JPG		☒	
33	18/04/18 11:37	General View				Load JPG		☒	

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	18/04/18 11:37	General View		☒
35	18/04/18 11:37	General View		☒
36	18/04/18 11:37	General View		☒
37	18/04/18 11:37	General View		☒
38	18/04/18 11:37	General View		☒
39	18/04/18 11:37	General View		☒
40	18/04/18 11:37	General View		☒
41	18/04/18 11:37	General View		☒
42	18/04/18 11:37	General View		☒
43	18/04/18 11:37	General View		☒
44	18/04/18 11:38	Dismantled Parts		☒
45	18/04/18 11:38	Dismantled Parts		☒
46	18/04/18 11:38	Dismantled Parts		☒
47	18/04/18 11:38	Dismantled Parts		☒
48	18/04/18 11:38	Dismantled Parts		☒
49	18/04/18 11:38	Dismantled Parts		☒
50	18/04/18 11:38	Dismantled Parts		☒
51	18/04/18 11:38	Dismantled Parts		☒
52	18/04/18 11:38	Dismantled Parts		☒
53	18/04/18 11:38	Dismantled Parts		☒
54	18/04/18 11:38	Dismantled Parts		☒
55	18/04/18 11:38	Dismantled Parts		☒
56	18/04/18 11:38	Dismantled Parts		☒
57	18/04/18 11:38	Dismantled Parts		☒
58	18/04/18 11:38	Dismantled Parts		☒
59	18/04/18 11:38	Dismantled Parts		☒
60	18/04/18 11:38	Dismantled Parts		☒
61	18/04/18 11:38	Dismantled Parts		☒
62	18/04/18 11:38	Dismantled Parts		☒
63	18/04/18 11:38	Dismantled Parts		☒
64	18/04/18 11:38	Dismantled Parts		☒
65	18/04/18 11:38	Dismantled Parts		☒
66	18/04/18 11:38	Dismantled Parts		☒
67	18/04/18 11:38	Dismantled Parts		☒
68	18/04/18 11:38	Dismantled Parts		☒
69	18/04/18 11:38	Dismantled Parts		☒
70	18/04/18 11:38	Dismantled Parts		☒
71	18/04/18 11:38	Dismantled Parts		☒
72	18/04/18 11:38	Dismantled Parts		☒
73	18/04/18 11:38	Dismantled Parts		☒
74	18/04/18 11:38	Dismantled Parts		☒
75	28/04/18 12:37	Photo After Spray		☒
76	28/04/18 12:37	Photo After Spray		☒
77	28/04/18 12:37	Photo After Spray		☒
78	28/04/18 12:37	Photo After Spray		☒
79	28/04/18 12:37	Photo After Spray		☒
80	28/04/18 12:37	Photo After Spray		☒
81	28/04/18 12:37	Photo After Spray		☒
82	28/04/18 12:37	Photo After Spray		☒
83	28/04/18 12:37	Photo After Spray		☒

Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
84	28/04/18 12:37	Photo After Spray	 Load JPG	☒
85	28/04/18 12:37	Photo After Spray	 Load JPG	☒
86	28/04/18 12:37	Photo After Spray	 Load JPG	☒
87	28/04/18 12:37	Photo After Spray	 Load JPG	☒
88	28/04/18 12:37	Photo After Spray	 Load JPG	☒
89	28/04/18 12:37	Photo After Spray	 Load JPG	☒
90	28/04/18 12:37	Photo After Spray	 Load JPG	☒
91	28/04/18 12:37	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	09/04/18 10:23	FBE7938Z E FILE REPORT.	 Load PDF	
2	10/04/18 09:49	Workshop contact details	 Load PDF	
3	14/06/18 16:13	images 1	 Load PDF	
4	14/06/18 16:13	images 2	 Load PDF	
5	14/06/18 16:13	images 3	 Load PDF	
6	14/06/18 16:14	police report	 Load PDF	
7	14/06/18 16:16	RENTAL INVOICE/SURVEY INVOICE/SURVEY REPORT	 Load PDF	
8	18/06/18 17:43	OI witness's police report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18006573/GVD3E2

Date: 08/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: B28718557MKF
Claimant Vehicle No: FBE7938Z	Insured Vehicle No: XB9083G
Date of Loss: 16/03/2018	Nature of Claim: TP Claim No: 553118

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBE7938Z	Engine No: KB604818
Make & Model: SYM GTS 200, 172cc	Chassis No: RFGLM18WXAS001232
Reg. Date: 23/09/2010 (Man. Year: 2010)	Odometer: 0 km
Colour: Black	
Engine Capacity: 172 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/90-13	Rear Tyre Size: 130/70-12
Front Left Side: Metzeler 4 mm	Rear Left Side: Metzeler 4 mm
Front Right Side: 0 mm	Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,722.40	5,887.80	6,834.60	53.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	520.00	1,590.00	75.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,832.40	6,407.80	8,424.60	56.80
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	14,832.40	5,100.00	9,732.40	65.62

INSPECTION

Date of Assignment: 10/04/2018	
Date Inspected: 10/04/2018	Inspected At: Ong Motor Trading (MACPHERSON RD) No. 464 Macpherson Road Singapore 368182
Estimated Period of Repair: 5.0 days	

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Aug 2018)	
Parts:	N/A	SYM GTS 200 172cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBE7938Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AIR BOX ASSY	Grazed	280.00 FL	*180.00 FL
2	1		*BRAKE CALIPER	Serviceable	265.00 FL	*- FL
3	1		*BRAKE DISC	Bent / Warped	285.00 FL	*150.00 FL
4	1		*BRAKE LEVER LH	Grazed / Bent	85.00 FL	*22.00 FL
5	1		*BRAKE LEVER RH	Broken	85.00 FL	*22.00 FL
6	1		*CENTER PANEL	Broken	295.00 FL	*195.00 FL
7	1		*CENTER PANEL COVER	Broken	85.00 FL	*85.00 FL
8	1		*EXHAUST MUFFLER	Dented / Grazed	960.00 FL	*680.00 FL
9	1		*EXHAUST MUFFLER COVER	Dented / Grazed	177.00 FL	*80.00 FL
10	2		*FORK ASSY R/L	Bent / Twisted	920.00 FL	*600.00 FL
11	1		*FRONT COWLING	Broken	360.00 FL	*360.00 FL
12	1		*FRONT COWLING STAY	Bent	160.00 FL	*160.00 FL
13	1		*FRONT FENDER	Broken	160.00 FL	*95.00 FL
14	1		*FRONT GARNISH	Not Necessary	165.00 FL	*- FL
15	2		*FRONT SIGNAL R/L	Broken	260.00 FL	*260.00 FL
16	1		*FRONT UNDER COVER	Broken	380.00 FL	*80.00 FL
17	1		*FRONT VISOR	Broken	220.00 FL	*220.00 FL
18	1		*FRONT WHEEL RIM	Not Necessary	485.00 FL	*- FL
19	1		*FRONT WHEEL SHAFT	Not Necessary	85.00 FL	*- FL
20	1		*HANDLE BAR	Bent	180.00 FL	*90.00 FL
21	1		*HANDLE BAR COVER	Broken	220.00 FL	*120.00 FL
22	1		*HEADLAMP ASSY	Broken	380.00 FL	*380.00 FL
23	1		*HORN	Not Necessary	60.00 FL	*- FL
24	1		*HORN BRACKET	Not Necessary	72.00 FL	*- FL
25	1		*INNER CENTER COWLING	Broken	399.00 FL	*312.00 FL
26	1		*LIGHT SWITCH	Damaged	205.00 FL	*105.00 FL
27	1		*LOWER SIDE COVER LH	Grazed / Broken	135.00 FL	*135.00 FL
28	1		*LOWER SIDE COVER RH	Grazed / Broken	135.00 FL	*135.00 FL
29	1		*METER ASSY	Broken	485.00 FL	*320.00 FL
30	1		*METER COVER	Broken	195.00 FL	*55.00 FL
31	2		*MIRROR R/L	Grazed / Bent	360.00 FL	*130.00 FL
32	1		*RADIATOR ASSY	Serviceable	380.00 FL	*- FL
33	1		*RADIATOR FAN ASSY	Serviceable	161.00 FL	*- FL
34	1		*RADIATOR SPARE TANK	Deformed	41.00 FL	*41.00 FL
35	1		*REAR COVER	Not Necessary	105.00 FL	*- FL
36	2		*REAR FOOTREST R/L	Grazed	290.00 FL	*60.00 FL
37	1		*REAR MUDGUARD	Serviceable	158.00 FL	*- FL
38	1		*REAR MUDGUARD REFLECTOR	Serviceable	35.00 FL	*- FL
39	1		*REAR SEAT BAR	Not Necessary	380.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*REAR SIDE COVER PROTECTOR R/L	Grazed	110.00 FL	*70.00 FL
41	2		*REAR SIDE COVER R/L	Grazed / Broken	560.00 FL	*360.00 FL
42	2		*REAR SIDE COVER STICKER R/L	Necessary	41.40 FS	*24.00 FS
43	2		*REAR SIGNAL R/L	Not Necessary	256.00 FL	*- FL
44	1		*SEAT ASSY	Not Necessary	425.00 FL	*- FL
45	1		*SEAT UNDER COVER	Not Necessary	85.00 FL	*- FL
46	1		*STEERING STEM	Bent	295.00 FL	*230.00 FL
47	1		*STEP BOARD	Grazed	244.00 FL	*170.00 FL
48	1		*STEP BOARD COVER LH	Grazed	60.00 FL	*30.00 FL
49	1		*STEP BOARD COVER RH	Grazed	60.00 FL	*30.00 FL
50	1		*STEP BOARD TOP COVER	Broken	45.00 FL	*20.00 FL
51	1		*STEP UNDER COVER	Not Necessary	290.00 FL	*- FL
52	1		*TAILLAMP ASSY	Not Necessary	142.00 FL	*- FL
53	2		*FORK OIL SEAL R/L	Necessary	50.00 FS	*20.00 FS
54	1		*FRONT NO PLATE	Necessary	25.00 FS	*10.00 FS
55	1		*FRONT TYRE	Not Necessary	220.00 FS	*- FS
56	1		*SET FRONT WHEEL RIM BEARING	Not Necessary	60.00 FS	*- FS
57	1		*SET HANDLE BAR BALANCER	Grazed / Bent	80.00 FS	*30.00 FS
58	1		*SET HANDLE BAR GRIP	Grazed / Torn	76.00 FS	*20.00 FS
59	1		*I U UNIT	Damaged	196.00 FS	*165.00 FS
60	1		*REAR BOX	Grazed	360.00 FS	*180.00 FS
61	1		*REAR NO PLATE	Serviceable	25.00 FS	*- FS
62	1		*SET STEERING CONE / BEARING	Necessary	195.00 FS	*55.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	13,988.40	6,486.00
- List Item Discount on L Items 10.00/10.00% (S\$)	1,266.00	598.20
Total Parts (S\$)	12,722.40	5,887.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (TO FR)	New	60.00	20.00
2	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	900.00	0.00
3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	700.00	250.00
4	TO STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION	New	450.00	250.00
Gross Labour Cost (\$\$)			2,110.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >