

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 733H

MAKE :

MODEL : HYUNDAI i40

Date: 09.04.2018

Qty	Parts Description / Labour	Type	Unit Price	Amount
	Boot Lid ✓			\$ 1,681.40
	Boot Lid Rubber X			\$ 115.80
	Boot Lid Hinge (LH/RH) ✓		\$178.10	\$ 356.20
	Boot Lid Lock Upper X			\$ 137.90
	Boot Lid Lock Lower X			\$ 31.70
	Boot Lid 'H' Emblem ✓			\$ 27.20
	Boot Lid CRDI Plate ✓			\$ 41.00
	Boot Lid Lamp (LH/RH) X		\$556.80	\$ 1,113.60
	Licence Lamp (LH/RH) X		\$33.95	\$ 67.90
	Boot Lid Absorber X			\$ 65.65
	Boot Lid Trimboard X			\$ 172.70
	Boot Lid Trimboard Clips 11pcs ✓			\$ 11.00
	Bootlid Moulding ✓			\$ 85.00
	Bootlid i40 Emblem ✓			\$ 41.00
	Bootlid Lower Garnish ✓			\$ 398.00
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ✓			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ✓		\$180.00	\$ 360.00
	Rear Bumper Sponge ✓			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.80
	Rear Bumper Reflector Lamp (LH/RH) ✓		\$32.00	\$ 64.00
	Rear Bumper Clips 10 pcs ✓			\$ 22.00
	Tail Lamp (LH/RH) LH? RH- ✓		\$565.60	\$ 1,131.20
	Tail Lamp Quarter Panel (LH/RH) X ✓		\$97.90	\$ 195.80
	Rear Panel ✓			\$ 592.30
	Rear Panel Garnish ✓			\$ 57.70
	Rear Panel Lower Panel ✓			\$ 495.50
	Spare Tyre Holder X			\$ 28.80
	Tail Lamp Panel Top (LH/RH) X ✓		\$545.90	\$ 1,091.80
	Spare Tyre Panel X ✓			\$ 900.50
	Spare Tyre Panel Cushion X			\$ 209.05
	Rear Towing Hook X			\$ 94.60
	Member Assy - Rear Floor Centre X			\$ 170.75
	Panel Assy - Rear Floor Side (LH/RH) X		\$92.40	\$ 184.80
	Rear Floor Chassis Member (LH/RH) X		\$1,280.50	\$ 2,561.00
	Exhaust Pipe Insulator X			\$ 58.55
	Exhaust Silencer (LH/RH) LH X RH ✓		\$954.00	\$ 1,908.00
	Exhaust Pipe Centre ?			\$ 1,150.30
	Exhaust Pipe Hanger X			\$ 58.55
	Rear Fender (LH) X ✓			\$ 2,020.10
	Rear Fender Inner Panel (LH) X			\$ 1,190.50
	Rear Fender Inner Lining (LH) X			\$ 164.40
	Rear Fender Trim Board (LH) X			\$ 188.75
	Rear Windscreen Moulding X			\$ 60.00

Qty	Parts Description / Labour	Type	Unit Price	Amount
	SUB TOTAL			\$ 20,782.15
	LESS 20%			4,156.43
	DISCOUNTED TOTAL			\$ 16,625.72
	Boot Lid Comfort Logo & Tel No. Sticker ✓			\$ 30.00
	Rear Bumper Reverse Sensor X			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Windscreen Sealant X			\$ 46.00
				\$ 261.70

Qty	Parts Description / Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 3,000.00 1000
	Spray Painting Charge			\$ 1,600.00 800
	Wiring Charge			\$ 100.00 20
	Tuff Kote			\$ 100.00 50
	Towing Charge			\$ 50.00 -
	Rear Chassis Alignment Charge			\$ 400.00 X
	Remove / Refix Cushion & Upholstery Rear			\$ 150.00 50
	Remove / Refix Rear Windscreen Glass			\$ 120.00 X
	Remove / Refix Reverse Sensor			\$ 120.00 X
	Remove / Refix Fuel Tank			\$ 150.00 X
	Remove / Refix Exhaust Pipe			\$ 150.00 50
	TOTAL LABOUR			\$ 5,940.00
	ESTIMATE TOTAL			\$ 22,827.42

Kalvin (LKK)

9/4/08 1135hrs

5 days

45

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition			
1. Date: <u>7/4/18</u> Time Received: <u>1525</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>MR CHOY</u> Contact No. : <u>96246167</u> Vehicle No. : <u>SHC733H</u> Make / Model / Colour : <u>I40</u> Email :		4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up	
7. Location: <u>AYE OPP NUH</u>		5. Nature of Service: ☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☐ Accident ☐ Engine Stalled ☐ Return Taxi	
10. Odometer Reading : <u>588</u> Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E		11. Radio / CD Player ☐ OK ☐ Faulty ☐ Not tested	
Job Attended			
12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☐ TZ ☒ YISHUN ☐ OTHERS Name of Driver : <u>Tan</u> Vehicle No. : <u>YK94095</u> Time Dispatch : <u>1435</u> Time of Arrival : <u>1525</u> Time Completed : <u>1625</u>		 #: Cracked X: Dented / : Scatched O: Missing Signature of Customer	
Cash Invoice Details (if applicable)			
13. Cash Invoice No. : _____			
Customer Acknowledgement			
a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc. b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses. c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.			
<u>7/4/18</u> Date		<u>1625</u> Time	
		Signature of Customer	
14. WORKSHOP			
Name of Attending Staff/Guard		Date & Time of Arrival	
		Signature of Attending Staff/Guard	