

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 673X

DATE 9/4/2018 12:06

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Door (RH) — <i>new</i>			\$ 1,403.00
	Front Door Mirror (RH) — <i>Broken</i>			\$ 980.50
	Front Windscreen Moulding X "			\$ 60.00
	Front Windscreen Pillar Outer(RH) X <i>repair</i>			\$ 1,843.10
	Frt Wheel Hub Cap, RH — <i>knocked</i>			\$ 150.70
	<i>Frt RH Fender X repair</i>			
	<i>Frt Bumper X repair</i>			
	SUB TOTAL			\$ 4,437.30
	LESS 20%			\$ 887.46
	DISCOUNTED TOTAL			\$ 3,549.84
	Front Door City Cab Logo (RH) — <i>new</i>			\$ 75.00
	Front Windscreen Sealant X "			\$ 46.00
				\$ 121.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 850.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Transfer Of Door			\$ 120.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Frt Wheel Alignment			\$ 80.00
	TOTAL LABOUR			\$ 2,420.00
	ESTIMATE TOTAL			\$ 6,090.84

Kali (11/11/18)

N

9/4/18 133.ks

3 days

4/5

After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental part(s) must be resurveyed and is subject to approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



DATE : 06/04/18

[illegible]